



The National Commission on the

# BP DEEPWATER HORIZON OIL SPILL AND OFFSHORE DRILLING



**The Deepwater Horizon**

Drilling Offshore Wells

Macondo Time Line

Cementing the Macondo Well

Questions About Cement

Temporary Abandonment



Kick Detection

Blowout

# The Deepwater Horizon



# Macondo Well



# Companies Involved at Macondo



Rig and drilling  **Transocean**



Surface data logging

Cementing **HALLIBURTON**

 **CAMERON** Blowout preventer

Drilling mud **Mi SWACO**  
A Schlumberger Company

 **OCEANEERING**® ROV support

Well and cement logging **Schlumberger**





Wellhead, casing hangers

 **Weatherford**® Centralizers, float collar, shoe track




# Onshore Organizational Chart




# Rig Crew Organizational Chart



Communication and coordination




## HALLIBURTON




# Deepwater Horizon




# Deepwater Horizon




# Deepwater Horizon




# Deepwater Horizon




# Deepwater Horizon



# Deepwater Horizon



# Deepwater Horizon and Macondo Well



The Deepwater Horizon

**Drilling Offshore Wells**

Macondo Time Line

Cementing the Macondo Well

Questions About Cement

Temporary Abandonment


Kick Detection

Blowout


# Drilling Offshore Wells



# Blowout Preventer 'BOP'




# Porosity of Rock Formation



00:41 | Frame: 996




# Drilling a Well



00:58 | Frame: 1400



# Pore Pressure vs. Fracture Gradient




Run Liner

Increase Mud Weight



# Drilling a Well



The Deepwater Horizon

Drilling Offshore Wells

**Macondo Time Line**

Cementing the Macondo Well

Questions About Cement

Temporary Abandonment

Kick Detection

Blowout

# Macondo Time Line



# Macondo Was a 'Difficult Well'

**October 6, 2009**

Marianas arrives at Macondo

**October 28, 2009**

Marianas reaches 9,000 feet

**November 8-9, 2009**

Marianas damaged by Hurricane Ida

**January 31, 2010**

Deepwater Horizon arrives

**February 10, 2010**

Deepwater Horizon drilling begins

**March 8, 2010**

Kick causes stuck pipe; crew begins bypass

**April 3, 2010**

Severe lost returns

**17 DAYS BEFORE BLOWOUT**

**2009**

**2010**



The Deepwater Horizon

Drilling Offshore Wells

Macondo Time Line

**Cementing the Macondo Well**

Questions About Cement

Temporary Abandonment


Kick Detection

Blowout

# Cementing the Macondo Well



# Cementing the Macondo Well



# Situation at Time of Cement Job – April 19, 2010

- **Difficult drilling conditions**
- Serious lost returns in the zone to be cemented
- Forced to stop drilling earlier than planned
- Difficulty converting float equipment
- Low circulating pressure after conversion
- No bottoms up circulation
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# Pore Pressure vs. Fracture Gradient at Macondo




▲ Casing Point - Pore Pressure   
 ● Planned Mud Weight   
 — Fracture Gradient

00:18 | Frame: 441



# Macondo Was a ‘Difficult Well’





A. It was a difficult well. I wouldn't say it was worse than others. They – it was difficult.

Testimony of Micah Burgess,  
Transocean Driller, 5/29 AM Tr. 114

Considering the narrow pore pressure and fracture gradient conditions in the Macondo well, planning the cement job to achieve effective cement placement and zonal isolation was a challenge for the BP and Halliburton personnel involved.


BP Deepwater Horizon Accident Investigation Report, Pg. 55

# Well Design – Long String Compared to Liner




## Situation at Time of Cement Job – April 19, 2010


- Difficult drilling conditions
- **Serious lost returns in the zone to be cemented**
- Forced to stop drilling earlier than planned
- Difficulty converting float equipment
- Low circulating pressure after conversion
- No bottoms up circulation
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# Fractures and/or Too High of a Mud Weight Cause 'Lost Returns' or 'Lost Circulation'



00:24 | Frame: 596



## Situation at Time of Cement Job – April 19, 2010

- Difficult drilling conditions
- Serious lost returns in the zone to be cemented
- **Forced to stop drilling earlier than planned**
- Difficulty converting float equipment
- Low circulating pressure after conversion
- No bottoms up circulation
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# The Formation at Macondo Was Tricky

April 13, 2010

From: Bodek, Robert  
Sent: Tue Apr 13 13:43:50 2010  
To: Beirne, Michael

From: Bodek, Robert  
Sent: Tue Apr 13 13:43:50 2010  
To: Beirne, Michael  
Cc: Ribeiro, Bryan; Wells, Mark E  
Subject: RE: Macondo TD  
Importance: Normal

Michael,  
While drilling in the 8.7" x 9.0" hole-section, we encountered the reservoir. It was noted that pressure indicated by pressure gauges that sand was 11.2ppg over geopotential relative to the top of the hole. This was confirmed by the fact that we took a Core Tag sand pressure at 17,717' (MD). This sand weight equivalent. At the time, we were drilling with a 14.0ppg equivalent weight density (ESD) and a -14.7 psi through the reservoir interval to a depth of 18,260' with penetration (ROP) had slowed significantly. The decision was made to discontinue hole filling. Upon pulling the riser with pumps off, we observed applications of LCM applications and cutting off losses. We also displaced the riser with base oil and 14 filter piecing several LCM applications and cutting off we pulled out of the hole for a new BHA. At this point, we had drilled out of the base of the reservoir. We had drilled out of the base of the reservoir, but the approximately 50' of rat hole we had beneath the main and completion. It was unanimously accepted amongst the team that approximately 100 more feet would allow us to make sure we had drilled through the entire reservoir package, provide sufficient rat hole for wireline evaluation operations, and provide ample rat hole for completion procedures. We had one major problem observed no additional pay intervals. We firmly believed that we were at the base of the target reservoir package. It was decided that the primary target had been reached, and we were able to conduct a comprehensive, efficient wireline evaluation. Having drilled and evaluated the entire reservoir interval would fulfill the two primary objectives of the well. Drilling ahead any further would unnecessarily jeopardize the wellbore. Having a 14.15ppg exposed sand, and taking losses in a 12.6ppg reservoir in the same hole-section had forced our hand. We had simply run out of drilling margin. At this point it became a well integrity and safety issue. TD was called at 18,360' (MD).

losses. We also displaced the riser with base oil and 14.0ppg mud to reduce the downhole hydrostatic pressure. After pumping several LCM applications and cutting mud weight in the riser, losses were no longer observed, and we pulled out of the hole for a new BHA. **At this point, the team was faced with a tough decision.** We had drilled to 18,260' (MD). At this depth, we were unsure if we had drilled through the reservoir in its entirety. It appeared as if we had drilled out of the base of the reservoir, but there was no way to be certain. Additionally, the approximately 50' of rat hole we had beneath the main sand package was insufficient for both wireline evaluation and completion. It was unanimously accepted amongst the team that approximately 100 more feet would allow us

observed no additional pay intervals. We firmly believed that we were at the base of the target reservoir package. It was decided that the primary target had been reached, and we were able to conduct a comprehensive, efficient wireline evaluation. Having drilled and evaluated the entire reservoir interval would fulfill the two primary objectives of the well. **Drilling ahead any further would unnecessarily jeopardize the wellbore. Having a 14.15ppg exposed sand, and taking losses in a 12.6ppg reservoir in the same hole-section had forced our hand. We had simply run out of drilling margin. At this point it became a well integrity and safety issue. TD was called at 18,360' (MD).**

Regards,  
**Bobby Bodek**  
BP America Inc.  
Geological Operations Coordinator  
Gulf of Mexico Exploration - Tiger Team  
PO Box 206280  
(407) 212-1553

Confidential


Confidential

BP-HZN-MBI 00125338



# Situation at Time of Cement Job – April 19, 2010


- Difficult drilling conditions
- Serious lost returns in the zone to be cemented
- Forced to stop drilling earlier than planned
- **Difficulty converting float equipment**
- Low circulating pressure after conversion
- No bottoms up circulation
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# Shoe Track



# Normal Float Valve Conversion



# Float Valve Conversion




## Third Possibility

High pressure cleared the obstruction in the reamer shoe, but float never converted because flow rate was too low

Multiple Pay Sands  
18,104' – 18,175'



Formation




Ninth attempt to  
convert float collar



## Situation at Time of Cement Job – April 19, 2010

- Difficult drilling conditions
- Serious lost returns in the zone to be cemented
- Forced to stop drilling earlier than planned
- Difficulty converting float equipment
- **Low circulating pressure after conversion**
- No bottoms up circulation
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# Low Circulating Pressure After Float Conversion



Multiple Pay Sands  
18,104' – 18,175'

18,116.5'

≈184.5'

18,301'

3'

18,304'

≈56'

18,360'



Ninth attempt to  
convert float collar

Formation

00:00 | Frame: 1



# Uncomfortable With Circulating Pressure

April 20, 2010

## HALLIBURTON

15:54 Pressure up to 2500 psi at 1 bpm while attempting to convert floats. (62 strokes / 7.8 bbls / 2500 psi).  
16:03 Unsuccessful...bleed pressure off.  
16:16 Pressure up to 2750 psi at 1 bpm while attempting to convert floats. (67 strokes / 8.44 bbls / 2750 psi). Pressure held at 2700 psi.

16:24

Company man feels uncomfortable with the circulating pressure being this low. Spoke with Jesse Gagliano about the situation.

17:00

MI Swaco model estimates circulating pressure should be about 570 psi @ 4.0 bpm.

## HALLIBURTON

BP America  
PO Box 22024  
Tulsa, Oklahoma 74121-0204  
OCS-G-32306, Macondo #1  
Mississippi Canyon Block 292  
Offshore Gulf of Mexico  
United States of America  
Rig Name: Transocean Horizon

9.875" x 7" Foam  
Casing Post Job

Prepared for: Jesse Gagliano  
April 20, 2010

Submitted by:  
Matthew Cheeson  
Technical Professional  
100 Channel Dr. Ste 200  
Lafayette, LA 70508

BP America

M.C. 252 OCS-G-32306 #1

BP-HZN-IIT-0004313

BP-HZN-MBI00137367

Confidential

BP-HZN-MBI00137364

BP-HZN-MBI00137364  
BP-HZN-IIT-0004313

Confidential

Confidential

Prepared by: JCS  
100 Channel Dr. Ste 200  
Lafayette, LA 70508



# Low Circulation Pressure: Post-Conversion Conversation

## Brett Cocalas August 27 Testimony Indicates Low Pressure Was Not Resolved

1 pressure, for them to estimate pressure was  
2 one of the most difficult things that they  
3 do. They said it's very difficult just to  
4 estimate a pressure directly.  
5 Q. And is it accurate, or do you  
6 recall -- is it fair to say that the  
7 difference in these pressures was a couple  
8 of hundred PSI? Does that fit with your  
9 recollection?  
10 A. I don't recall the exact number.  
11 Q. Was there some determination made  
12 as to whether these differences represented  
13 a problem or didn't represent a problem?  
14 How was that issue resolved?  
15 A. I did not give the rig direction  
16 myself, but I was in the area. But John  
17 Guide was having them -- well, through a  
18 conversation between John Guide and the well  
19 site leaders, they tried changing pumps, so  
20 that was the first thing, to see if the  
21 difference in pumps would make a difference.  
22 And there were some slight differences in  
23 the pressures. And then they also had tried  
24 a diagnostic test to make sure that it  
25 wasn't leaking through the diverter valve

Page 72

Page 73  
26 wasn't leaking through the diverter valve  
27 a diagnostic test to make sure that it  
28 the pressures. And then they also had tried  
29 And there were some slight differences in  
30 difference in pumps would make a difference.  
31 that was the first thing, to see if the  
32 site leaders, they tried changing pumps, so

- Q. Was there some determination made as to whether these differences represented a problem or didn't represent a problem? How was that issue resolved?
- A. I did not give the rig direction myself, but I was in the area. But John Guide was having them -- well, through a conversation between John Guide and the well site leaders, they tried changing pumps, so that was the first thing, to see if the difference in pumps would make a difference. And there were some slight differences in the pressures. And then they also had tried a diagnostic test to make sure that it wasn't leaking through the diverter valve that we have as part of the, running the casing. So they put a procedure together to check that and assess that to make sure that that was not flowing across there, at the top there.
- Q. And what were the results of those efforts?
- A. The results were negative, that there was no flow across it. The diverter valve was considered to be closed. It was not leaking.
- Q. And so what was the resolution? How did the issue get resolved?
- A. I don't believe it ever got resolved, other than they felt like the gauge pressures was inaccurate.
- Q. And the conversations you are just describing, sir, is it your recollection they occurred on April 19; is that correct?
- A. I believe it is. I don't remember exactly on that.
- Q. Did you have any conversations with anyone regarding the negative tests that were run on the rig on April 20?
- A. No, I did not.

Testimony of Brett Cocalas, BP Drilling Engineer, MBI Hearing 8/27 Tr. 72-73



# Low Circulation Pressure: Post-Conversion Conversation

## Bly Team Brian Morel Interview Note

April 27, 2010

Transcription of Brian Morel interview notes  
commenced 1040 hrs 27-Apr-2010

panel: Rex Anderson, Matt Lucas, Jim Wetherbee, Warren Winters

### Opening discussion:

prior experience Anadarko Basin (challenge), Mad Dog (challenge), planning Macondo was on rig for cleanout run (Thu), stayed thru Tue AM at start of prod hole had high FIT (formation integrity test) above OB (overburden) once drg prod hole encountered losses, so reduced MW (mud weight) from 14.5 to 14.3 ppg while drg a sand zone Gecdap showed 14.12, 14.16 ppg formation pressure while drg a deeper producing sand Gecdap showed 12.6 ppg, originally thought low hence a lost event but later confirmed correct while drg a subsequent sand, drg progress stopped (suspected underreamer failure) while using 300-400 lb/hr fluid pumped emergency lost circulation material without improvement pulled into mainline drilling meter, reduced mud weight, pumped Formcast losses stopped holding 14.2 ppg mud (surface) 14.2 ppg (bottomhole due to compressibility) ran two bottomhole assembly and drg 100 ft of reflow to provide room for logging tools

circulation ESD 14-16-14.2 ppg logging went smoothly but rotary sidewall coring experienced differential pressure problems encountered bridges at 12,272' and 12,280' recorded 1100 units gas on bottom-up, eventually decreased to 20-30 units pumped out of hole and flow-checked at liner top ran ca. 5800 ft 7" casing cross-over to 9-7/8" casing bought 7" casing from Nexen due to short lead-time the XO came from R&M Machine circulator, converted float equipment, diverter closed without issue difficulty converting Weatherford float equipment but Weatherford rep. was not on rig so Allamon rep. recommended procedure to convert called Houston (J. Guide) thinking reamer shoe was plugged so staged up pumping to clear shoe 1 bpm showed 125 psi, 4 bpm showed 400 psi which seemed low vs. modeled pressures

closed annular, pumped down C&K lines, pumped down DP and things looked okay decided rig standpipe pressure gauge was incorrect 7bbis, 20bbis of 14.3 spacer, 5bbis cement job, 39 foam, 7 shoe track, 20 bbls spacer, 20bbis 4m modeled cement job in advance w/EPT assistance did not see bottom dart release, attributed to calculation error by Allamon saw top plug release standpipe pressure and cementing unit pressure agreed but both were several hundred psi below model saw 7" plug pass thru XO

Confidential Treatment Requested

BP-HZN-CEC020232

Transcription of Brian Morel interview notes  
commenced 1040 hrs 27-Apr-2010

panel: Rex Anderson, Matt Lucas, Jim Wetherbee, Warren Winters

### Opening discussion:

prior experience Anadarko Basin (challenge), Mad Dog (challenge), planning Macondo was on rig for cleanout run (Thu), stayed thru Tue AM at start of prod hole had high FIT (formation integrity test) above OB (overburden) once drg prod hole encountered losses, so reduced MW (mud weight) from 14.5 to 14.3 ppg

decided rig standpipe pressure gauge was incorrect

encountered bridges at 12,272' and 12,280' recorded 1100 units gas on bottoms-up, eventually decreased to 20-30 units pumped out of hole and flow-checked at liner top ran ca. 5800 ft 7" casing cross-over to 9-7/8" casing bought 7" casing from Nexen due to short lead-time the XO came from R&M Machine circulator, converted float equipment, diverter closed without issue difficulty converting Weatherford float equipment but Weatherford rep. was not on rig so Allamon rep. recommended procedure to convert called Houston (J. Guide) thinking reamer shoe was plugged so staged up pumping to clear shoe 1 bpm showed 125 psi, 4 bpm showed 400 psi which seemed low vs. modeled pressures

closed annular, pumped down C&K lines, pumped down DP and things looked okay decided rig standpipe pressure gauge was incorrect 7bbis, 20bbis of 14.3 spacer, 5bbis cement job, 39 foam, 7 shoe track, 20 bbls spacer, 20bbis 4m modeled cement job in advance w/EPT assistance did not see bottom dart release, attributed to calculation error by Allamon saw top plug release standpipe pressure and cementing unit pressure agreed but both were several hundred psi below model saw 7" plug pass thru XO


Confidential Treatment Requested

BP-HZN-CEC020232



## Situation at Time of Cement Job – April 19, 2010

- Difficult drilling conditions
- Serious lost returns in the zone to be cemented
- Forced to stop drilling earlier than planned
- Difficulty converting float equipment
- Low circulating pressure after conversion
- **No bottoms up circulation**
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# Bottoms Up Circulation



## Full Bottoms Up

Sea Floor

### Benefits of full bottoms up:

1. Conditions mud to ensure uniformity
2. Circulates cuttings and fills well and riser with clean mud
3. Allows crew to examine the mud from the bottom of the well for hydrocarbons

Multiple Pay Sands

## What BP Did

### BP initiated cement job before full bottoms up circulation because:


1. Concerned about earlier lost circulation event
2. Did not want to disturb annulus more than necessary

As a result, shoe track cuttings may not have been fully cleared out and hydrocarbons in shoe track could not be tested before cementing



# BP Decides Against Bottoms Up

July 22, 2010



Q. Mr. Guide, I got one follow-up question, regarding the circulating bottoms-up on the casing run. When they landed the long string of casing, the decision was made not to circulate complete bottoms-up. What was the reasoning for that?

\* \* \*

A. The biggest risk that was associated with this cement job was losing circulation. That was the No. 1 risk.


So based on the fact that we had lost circulation just like that out of the clear blue, we decided to go ahead and get circulation established, and then because of the actual volumes, we would actually have bottoms-up above the wellhead once the cement was in place, and then we would be able to circulate that out and see if there was any gas, so that was our plan.

Testimony of John Guide, BP Wells Team Leader, MBI Hearing 7/22 Tr. 88-89



# Situation at Time of Cement Job – April 19, 2010

- Difficult drilling conditions
- Serious lost returns in the zone to be cemented
- Forced to stop drilling earlier than planned
- Difficulty converting float equipment
- Low circulating pressure after conversion
- No bottoms up circulation
- **Cement jobs are known to occasionally need further work**
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# Cement Jobs May Require Repair



Formation

Depending on depth  
and complexity,  
can take 2-5 days



01:23 | Frame: 2009



# Squeeze Jobs at This Well

24-OCT-2009

**Rig Name**

T.O. MARIANAS

**Depth**

8,011

**SIGNIFICANT WELL EVENTS**

10/23/2009 – Mixed & pumped 923.5 cu. Ft. & squeezed 22" shoe. WOC.

20-FEB-2010

**Rig Name**

T.O. DEEPWATER HORIZON

**Depth**

9,085

**SIGNIFICANT EVENTS**

02/14/10 – Mixed & pumped 1120 cu. Ft. premium cement for a cement squeeze from 9085' 7814'

06-MAR-2010

**Rig Name**

T.O. DEEPWATER HORIZON

**Depth**

11,586


**SIGNIFICANT EVENTS**

03/05/10 – Mixed & pumped 095 cu. ft. premium cement and squeezed same.

A screenshot of a well event report for the date 24-OCT-2009. The report includes a header with well name and depth, followed by a table of well events. The event described is a cement squeeze at 8,011 feet depth.A screenshot of a well event report for the date 20-FEB-2010. The report includes a header with well name and depth, followed by a table of well events. The event described is a cement squeeze at 9,085 feet depth.A screenshot of a well event report for the date 06-MAR-2010. The report includes a header with well name and depth, followed by a table of well events. The event described is a cement squeeze at 11,586 feet depth.

## Situation at Time of Cement Job – April 19, 2010

- ❑ Difficult drilling conditions
- ❑ Serious lost returns in the zone to be cemented
- ❑ Forced to stop drilling earlier than planned
- ❑ Difficulty converting float equipment
- ❑ Low circulating pressure after conversion
- ❑ No bottoms up circulation
- ❑ Cement jobs are known to occasionally need further work
- ❑ **Cement modeling perceived as unreliable by BP**
- ❑ Complicated cement job
- ❑ Low rate of cement flow
- ❑ Low cement volume
- ❑ Uncertain centralization
- ❑ No direct indicators of cementing success and no cement evaluation log



# Halliburton's OptiCem™ Software



## CEMENTING

### Integrated Cement Job Simulator

Halliburton's new OptiCem™ System helps design and simulate the optimum cement job regardless of the complexity of the wellbore or the type of program - standard or foam. Using OptiCem, you can easily identify potential problems and tune your cementing design parameters before pumping starts. OptiCem can:

- **Optimize pump rates** for maximum mud displacement, making sure that pump rates keep fluids below fracturing pressures to help ensure well integrity, and above reservoir pressures to prevent the well from coming in.
- **Dynamically simulate cement jobs** to help produce a complete picture of the program that should be run.
- **Predict circulating pressures** at any time during the job, even during "free-fall" when the well is on vacuum and surface pressure indication is zero. Each run of the program provides pressures at the bottom of the hole and forty additional points - giving the user insight into the entire well.


In addition, OptiCem includes features to address other important aspects of cementing. It can:

- **Design centralizer placement** using any combination of holes, pipe sizes and centralizers of one or more types. Given desired standoff, OptiCem yields centralizer placement; given centralizer placement, the program calculates the resulting standoff.
- **Provide real-time analysis** during cementing, using a laptop computer. At the well site, the HalWin module gathers data (including data from slurry, nitrogen and chemicals units for foam cement jobs) and formats it for analysis by the OptiCem RealTime™ module. The RealTime module reruns the cement job simulation using this actual well data, which gives the on-site specialist downhole information that is invaluable when last-minute decisions must be made.
- **Evaluate job results** by comparing the pre-job simulation to simulation based on actual recorded data. This information can be extremely useful in planning future jobs and in trouble shooting.



# BP Viewed Computer Cement Modeling as Unreliable

July 22, 2010



A. The model is – first of all, it’s not accurate all the time.... ..I put very, very little faith in the model because it’s wrong a lot.

Testimony of John Guide, BP Wells Team Leader, MBI Hearing, 7/22 PM Tr. 100




# Situation at Time of Cement Job – April 19, 2010


- Difficult drilling conditions
- Serious lost returns in the zone to be cemented
- Forced to stop drilling earlier than planned
- Difficulty converting float equipment
- Low circulating pressure after conversion
- No bottoms up circulation
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- **Complicated cement job**
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- No direct indicators of cementing success and no cement evaluation log



# Planned Cement Job at Macondo




# Production Well Conversion



00:26 | Frame: 640



# Planned Cement Job at Macondo



# BP Understood This Was a Complex Cement Job

April 1, 2010

Brian Morel emphasizes importance of cement:



From: Morel, Brian P  
Sent: Thu Apr 01 12:10:42 2010  
To: Jesse Gagliano; Hafle, Mark E; Cocales, Brett W  
Cc: Quang Nguyen  
Subject: RE: Out of Office  
Importance: Normal  
Jesse/Quang,

Can you start running some tests on the nitrogen job? This is an **important** job and we need to have the data well in advance to make the correct decisions on this job.

Thanks  
Brian

September 8, 2010

## 2.1 Cement Design



Considering the narrow pore pressure and fracture gradient conditions in the Macondo well, **planning the cement job to achieve effective cement placement and zonal isolation was a challenge** for the BP and Halliburton personnel involved.

BP Deepwater Horizon Accident Investigation Report, Pg. 55

September 8, 2010

## Cement Slurry Design



Due to the narrow margin between pore pressure and fracture gradient, the **accuracy of cement placement was critical**. Several design iterations were conducted by Haliburton using the OptiCem™ wellbore simulation application to establish an acceptable slurry design and placement plan. **A complex design for the cement job** with base oil spacer, cementing spacer, lead (cap) cement, foam cement and tail cement, was recommended and implemented.

The Halliburton and BP Macondo well team's **technical reviews of the cement slurry design appear to be focused primarily on achieving an acceptable equivalent circulating density during cement placement to prevent loss returns**. Other important aspects of the foam cement design, such as foam stability, possible contamination effects and fluid loss potential did not appear to have been critically assessed in the pre-job reviews

BP Deepwater Horizon Accident Investigation Report, Pg. 34

September 8, 2010



Several key factors (such as **small cement slurry volume [approximately 62 bbls], narrow pore pressure/fracture gradient window** and upper technical range for using nitrified foam cement) **highlight the difficulties in designing a reliable cement slurry**.


The BP Macondo well team and the Halliburton in-house cementing engineer were aware of the narrow pore pressure/fracture gradient window. This was evident by the number of OptiCem™ model runs and meetings held to discuss ECD and channeling potential.

BP Deepwater Horizon Accident Investigation Report, Pg. 67



# Situation at Time of Cement Job – April 19, 2010

- ❑ Difficult drilling conditions
- ❑ Serious lost returns in the zone to be cemented
- ❑ Forced to stop drilling earlier than planned
- ❑ Difficulty converting float equipment
- ❑ Low circulating pressure after conversion
- ❑ No bottoms up circulation
- ❑ Cement jobs are known to occasionally need further work
- ❑ Cement modeling perceived as unreliable by BP
- ❑ Complicated cement job
- ❑ **Low rate of cement flow**
- ❑ Low cement volume
- ❑ Uncertain centralization
- ❑ No direct indicators of cementing success and no cement evaluation log





# Low Cement Flow Rate



Multiple Pay Sands  
18,104' – 18,175'

Formation



**Cementing design called for low cement flow rate to limit circulating pressure**

**High cement flow rate would aid in removing mud and cuttings from the shoe track and annulus**


**Low cement flow rate increased the risk of leaving these materials in the shoe track and annulus and increased risk of channeling**






## Situation at Time of Cement Job – April 19, 2010

- ❑ Difficult drilling conditions
- ❑ Serious lost returns in the zone to be cemented
- ❑ Forced to stop drilling earlier than planned
- ❑ Difficulty converting float equipment
- ❑ Low circulating pressure after conversion
- ❑ No bottoms up circulation
- ❑ Cement jobs are known to occasionally need further work
- ❑ Cement modeling perceived as unreliable by BP
- ❑ Complicated cement job
- ❑ Low rate of cement flow
- ❑ **Low cement volume**
- ❑ Uncertain centralization
- ❑ No direct indicators of cementing success and no cement evaluation log



# Low Top of Cement



01:09 |Frame: 1666



# Long String Compared to Liner




**After 13,000 feet of travel**


**Multiple Pay Sands**  
18,104' – 18,175'

**Formation**

**Mud scraped by top plug contaminates shoe track cement. Shoe track is designed in part to capture this contaminated cement, keep it out of annulus, where drillers want uncontaminated cement.**




# Long String vs. Liner Debate Focused on Cementing Concerns



- Original design called for long string
- Engineering personnel briefly decided to use liner because of ECD concerns
- Consulted internal BP cement expert and concluded that long string could be cemented

## Situation at Time of Cement Job – April 19, 2010



- ❑ Difficult drilling conditions
- ❑ Serious lost returns in the zone to be cemented
- ❑ Forced to stop drilling earlier than planned
- ❑ Difficulty converting float equipment
- ❑ Low circulating pressure after conversion
- ❑ No bottoms up circulation
- ❑ Cement jobs are known to occasionally need further work
- ❑ Cement modeling perceived as unreliable by BP
- ❑ Complicated cement job
- ❑ Low rate of cement flow
- ❑ Low cement volume
- ❑ **Uncertain centralization**
- ❑ No direct indicators of cementing success and no cement evaluation log



# Centralizers



# Original Design Called for Many Centralizers



- 750 ton equipment should be used for this section, ensure inspected and ready to use prior to running casing.
- Centralizers will be run every joint for the first 5 joints, followed by every other joint from the shoe to 500' above productive interval. Check system which is supplied to ensure it's in proper working fashion.
- Rig up Allamon Top Drive Surface Cement Equipment as follows and place on riser skate or stand back in derrick:

- Centralizers will be run every joint for the first 5 joints, followed by every other joint from the shoe to 500' above productive interval. Check system which is supplied to ensure it's in proper working fashion.
- Rig up Allamon Top Drive Surface Cement Equipment as follows and place on riser skate or stand back in derrick:

**But...not enough centralizer "subs" available**



# Bow Spring Centralizers vs. Centralizer Subs



## Centralizer Sub

---

**Advantage:**  
Threaded onto casing, less chance of “hanging up” in wellhead or BOP




## Centralizer and Stop Collars

---

**Advantage:**  
Performs centralization functions and is available

# OptiCem™ Models and Halliburton Personnel Recommend 21 Centralizers


April 15, 2010



BP-HZN-IIT-0004255  
BP-HZN-MB100137309


BB-HCM-WB100121309  
BB-HCM-ILL-0004252

HALLIBURTON



I was actually in the office working on it, and when I noticed the problem, I printed it out, and I got up to go show BP, and when I came around the corner, I ran into Brett Cocales and Mark Hafle, and I pointed out to them, said, "Hey, I think we have a potential problem here. There's a potential for flow due to the six centralizers on joint channeling."

Testimony of Jesse Gagliano, Halliburton Sales Representative, USCG 8/24 Tr. 20



5 (Pages 17 to 20)

PROFESSIONAL SHORTHAND REPORTERS, INC(800) 536-5255 (504) 529-5255  
New Orleans \* Baton Rouge \* Shreveport



# To 'Honor the Modeling,' BP Sends Additional Centralizers to Rig

April 16, 2010

From: Guide, John  
Sent: Fri Apr 16 19:27:43 2010  
To: SPM, David C  
Subject: FW: Additional Centralizers  
Importance: Normal

See below. I left a message on your cell phone.

From: Walz, Gregory S  
Sent: Friday, April 16, 2010 12:53 PM  
To: Guide, John  
Subject: Re: Additional Centralizers

I agree. This is not what I was encountering. I will call you directly.

Gregg Walz  
See down my BlackBerry

From: Guide, John  
To: Walz, Gregory S  
Sent: Fri Apr 16 12:48:11 2010  
Subject: Re: Additional Centralizers

I am based out of my office and am not part of the centralizer as you stated. Also it will take 10 hrs to install them. We are adding 47 pieces that are cost off to a new remote address. I do not like this and as David approved in my absence I did not question but now I very concerned about using them

From: Walz, Gregory S  
To: Guide, John  
Sent: Fri Apr 16 00:50:27 2010  
Subject: Additional Centralizers

John,  
Halliburton came back to us this afternoon with additional modeling after they loaded the final directional surveys, caliper log information, and the planned 6 centralizers. What it showed, is that the ECD at the base of sand jumped up to 15.06 ppg. This is being driven by channeling of the cement higher than the planned TOC.  
Brett and I tried to reach you twice to discuss things. David was still here in the office and I discussed this with him and he agreed that we needed to be consistent with honoring the model.  
To be able to have this option we needed to kick things off at 6:00 pm tonight, so I went ahead and gave Brett the go ahead. We also lined up a Weatherford hand for installing them to go out on the same flight. I wanted to make sure that we did not have a repeat of the last Atlantis job with questionable centralizers going into the hole.  
John, I do not like or want to disrupt your operations and I am a full believer that the rig needs only one Team Leader. I know the planning has been lagging behind the operations and I have to turn that around. I apologize if I have over step my bounds.

Confidential

BP-HZN-CEC0224

**From:** Walz, Gregory S  
**To:** Guide, John  
**Sent:** Fri Apr 16 00:50:27 2010  
**Subject:** Additional Centralizers

John,

Halliburton came back to us this afternoon with additional modeling after they loaded the final directional surveys, caliper log information, and the planned 6 centralizers. What it showed, is that the ECD at the base of sand jumped up to 15.06 ppg. This is being driven by channeling of the cement higher than the planned TOC.

The model runs for 20 centralizers (6 on hand + 14 new ones) reduce the ECD to 14.65 ppg, which is back below the 14.7+ ECD we had when we lost circulation earlier.

There has been a lot of discussion about this and there are differing opinions on the model accuracy. However, the issue, is that **we need to honor the modeling to be consistent with our previous decisions to go with the long string.** Brett and I tried to reach you twice to discuss things. David was still here in the office and I discussed this with him and he agreed that we needed to be consistent with honoring the model.

To be able to have this option we needed to kick things off at 6:00 pm tonight, so I went ahead and gave Brett the go ahead. We also lined up a Weatherford hand for installing them to go out on the same flight. I wanted to make sure

that we did not have a repeat of the last Atlantis job with questionable centralizers going into the hole.

John, I do not like or want to disrupt your operations and I am a full believer that the rig needs only one Team Leader. I know the planning has been lagging behind the operations and I have to turn that around. I apologize if I have over step my bounds.


Confidential

BP-HZN-CEC022434



# Last-Minute Decision Not to Use Additional Six Centralizers


April 16, 2010



**From:** Guide, John  
**To:** Walz, Gregory S  
**Sent:** Fri Apr 16 12:48:11 2010  
**Subject:** Re: Additional Centralizers

I just found out the stop collars are not part of the centralizer as you stated. Also it will take 10 hrs to install them. We are adding 45 pieces that can come off as a last minute addition. I do not like this and as David approved in my absence I did not question but now I very concerned about using them

April 16, 2010




**From:** Cocales, Brett W  
**Sent:** Friday, April 16, 2010 4:15 PM  
**To:** Morel, Brian P  
**Subject:** RE: Macondo STK geodetic

\* \* \*

But, who cares, it's done, end of story, will probably be fine and we'll get a good cement job. I would rather have to squeeze than get stuck above the WH. So Guide is right on the risk/reward equation.

# No Clarity Even Now on Whether the Additional Centralizers Should Have Been Used

September 8, 2010




The BP Macondo well team erroneously believed that they had received the wrong centralizers.

BP Deepwater Horizon Accident Investigation Report, Pg. 35

**Weatherford man on rig not consulted**

# BP Never Performed Modeling to Check Whether Six Centralizers Were Enough

September 8, 2010



When the decision was made to proceed without the additional centralizers, the BP Macondo well team did not ask for the OptiCem™ model to be re-run.


BP Deepwater Horizon Accident Investigation Report, Pg. 64

## Situation at Time of Cement Job – April 19, 2010

- Difficult drilling conditions
- Serious lost returns in the zone to be cemented
- Forced to stop drilling earlier than planned
- Difficulty converting float equipment
- Low circulating pressure after conversion
- No bottoms up circulation
- Cement jobs are known to occasionally need further work
- Cement modeling perceived as unreliable by BP
- Complicated cement job
- Low rate of cement flow
- Low cement volume
- Uncertain centralization
- **No direct indicators of cementing success and no cement evaluation log**



# Indirect Cementing Indicators



# Halliburton's April 20, 2010 Post-Job Report

## HALLIBURTON

### Significant Points


- Cement job pumped as planned.
- Chemical straps determined that additives were pumped at planned volumes
- Rig completed displacement and both plugs were bumped.

## HALLIBURTON

### Significant Points

- Cement job pumped as planned.
- Chemical straps determined that additives were pumped at planned volumes
- Rig completed displacement and both plugs were bumped.
- Full returns seen throughout entire job.
- Estimated 100 psi of lift pressure (350 psi circulating to 450 psi circulating), before bumping top plug.
- Floats held after job.

# BP Internal Criteria for Determining Zonal Isolation



## 5.3. Determining zonal isolation

### 5.3.1. Cement evaluation logs

To accurately assess TOC and zonal isolation cement sonic and ultrasonic logs should be used.

*To get accurate information from the logs they have to be run under optimum conditions (impacts of microannuli and gas can compromise log quality) and may need specialist log evaluation and / or interpretation*

### 5.3.2. Cement column backpressure

The simplest way of estimating TOC is to determine the cement column hydrostatic by slowing the pumps down immediately prior to bumping the plug.

*This will only give a very coarse estimate and where cement and mud weights are very similar (within 0.2 SG) is unlikely to provide a sufficiently accurate estimate.*

### 5.3.3. Temperature logs

Temperature logs can give a simple estimate of the TOC when they are run soon after cementing.


*They identify a temperature anomaly usually associated with the heat evolved when the cement sets but give no indication of isolation.*

Highly Confidential  
Confidential

BP-HZN-MBI00192556



# Cement Evaluation



Formation

**Evaluated**

Multiple Pay Sands


**Not Evaluated**

00:28 | Frame: 675



# BP Didn't Conduct a Formal Risk Assessment of the Annulus Cement Barrier

September 8, 2010



But not conducting a formal risk assessment of the annulus cement barrier per the ETP recommendation, it is the investigation team's view that the BP Macondo well team did not fully conform to the intent of ETP GP 10-60. Such a risk assessment might have enabled the BP Macondo well team to identify further mitigation options to address risks such as the possibility of channeling; this may have included running a cement evaluation log.

BP Deepwater Horizon Accident Investigation Report, Pg. 66

The Deepwater Horizon

Drilling Offshore Wells

Macondo Time Line

Cementing the Macondo Well

**Questions About Cement**

Temporary Abandonment


Kick Detection

Blowout


# Questions About Cement



# Base vs. Foam Cement




# Advantages of Foam Cement



## Foam cement helps improve mud displacement, helps prevent gas migration and helps protect the formation:

- Foam cement under compression is a highenergy, high-viscosity system that is more efficient than conventional slurries in displacing mud. Preflushes and spacers can also be foamed to make them more efficient. Result: Cement-formation bonds that really hold up because all the mud has been removed.
- The compressed gas bubbles in foam cement shrink or expand, but they don't move around or coalesce. Instead, they maintain pressure while the cement hydrates. Result: Virtually no gas migration into the cement, ever – while cement is being placed or while it sets.
- The bubbles actually "plate out" against the formation and form a barrier. Result: lower water loss to the formation, which helps prevent formation swelling, washouts and other damage.
- Foam cement can be mixed at very light weights – as low as 4 lb./gal. Result: A good fix for extreme lost-circulation problems where nothing else will work.
- The density of foam cement can be varied at will using the same base slurry. Result: Hydrostatic pressure that can be tailored to protect fragile formations and help prevent high-pressure zones from coming in – all within the same job.




Halliburton has successfully used foam cement in over 1000 jobs, including 279 jobs at 15,000 ft. or deeper and 79 jobs at 18,000 ft or deeper.



# How Foam Cement Testing Is Done



To be stable, density of all sections should be close to each other and close to the density of the foam cement pour prior to curing



Artist's interpretation; for demonstrative purposes only





# Halliburton's Pre-Job Test Results

**April 12th 2010**

UCA Comp. Strength, Request Test ID:811522						
End Temp (°F)	Pressure (psi)	50 psi (hh:mm)	500 psi (hh:mm)	12 hr CS (psi)	24 hr CS (psi)	48 hr CS (psi)
210	14,459	08:12	08:40	2,301	2,966	3,050
Circulate before pouring C.S. for 3 Hrs						

Operation Test Results Request ID 73909/1						
Crush Compressive Strength, Request Test ID:806069						
Curing Temp (°F)	Time 1 (hrs)	Strength 1	Time 2 (hrs)	Strength 2	Time 3 (hrs)	Strength 3
180	12	0	24	0	48	1,550
Foam quality 0						
Condition for 1.5 hrs						

FYSA Viscosity Profile & Gel Strength, Request Test ID:806074	
Test Temp (°F)	80
80	

HALLIBURTON		LAB RESULTS - Primary	
Cementing Gulf of Mexico, Broussard			
<b>Job Information</b>			
Request/Job	05002	Rig Name	TRANSOCEAN HORIZON
Submitted By	Jesse DiGirola	Job Type	9 7/8" X 7" Prod Casing
Customer	BP	Location	Mexico Gulf City
<b>Well Information</b>		<b>Well</b>	
Casing/Liner Size (")	Depth (MD)	15,900 ft	BMST
			232.7

## Foam Mix and Stability, Request Test ID:813603

Time to Foam [Sec]	SG top	SG bot.	Conditioning time (hrs:min)
8	1.8	1.8	03:00

Temp (°F)	Pressure (psi)	Reached in (min)	Start BC	30 BC (hh:mm)	45 BC (hh:mm)	60 BC (hh:mm)
126	14,459	03	14	07:25	07:34	07:36

Bulk Balance Density, Request Test ID:811529	
Density (ppg)	15.7
From part 1	

Mixability (0 - 5) - 0 is not mixable, Request Test ID:811524  
 Mixability rating (0 - 5)  
 4

**PPG**  
**15.0**


**SG (specific gravity) top and bottom are the same as each other, but different than starting density**

**Note three-hour conditioning time**



# Results of Chevron Testing of Macondo Slurry

October 26, 2010



Many of the test results were in reasonable agreement with those reported by Halliburton. However, we were unable to generate stable foam with any of the tests described in Section 9 of this report.



# Results of Chevron Testing of Macondo Slurry

Test Number	Approach	Result
1, 2, 3	Used Chevron methods	Unstable
4	Used BP expert's methods	Unstable
5	With offset density correction	Unstable
6, 7, 9	Attempt to replicate Halliburton testing	Unstable
8	Used alternate cement	Unstable

# Halliburton Foam Stability Testing

Halliburton's test takes a minimum of 48 hours

Test ID #	Apparent Test Date	Target Foam Density	Tested Top Density	Tested Bottom Density	Conditioning Time	Analysis	Available Before Job?	Given to BP Before Job?
73909/1	Apr. 18	14.5 ppg	15.0	15.0	3:00	Stable?	Uncertain	No
73909/1	Apr. 13	14.5 ppg	15.7	15.1	1:30	Unstable	Yes	No
65112/3	Feb. 17	14.5 ppg	15.9	15.9	2:00	Unstable	Yes	Yes, listing 0:00 conditioning time
65112/1	Feb. 13	14.5 ppg	16.8	17.6	0:00	Unstable	Yes	No

# Commission Letter



National Commission on the  
BP DEEPWATER HORIZON OIL SPILL  
AND OFFSHORE DRILLING

Commissioners  
Bob Graham, Co-Chair  
William K. Reilly, Co-Chair  
Frances Beinecke  
Donald F. Boesch  
Terry D. Garcia  
Cherry A. Murray  
Fran Ulmer

Chevron agreed as a public service to test the cement slurry on behalf of the Commission. Chevron employs some of the industry's most respected cement experts, and it maintains a state-of-the-art cement testing facility in Houston, Texas. Halliburton agreed that the Chevron lab was highly



National Commission on the  
BP DEEPWATER HORIZON OIL SPILL  
AND OFFSHORE DRILLING

#### Commissioners

Bob Graham, Co-Chair  
William K. Reilly, Co-Chair  
Frances Beinecke  
Donald F. Boesch  
Terry D. Garcia  
Cherry A. Murray  
Fran Ulmer

Richard Lazzara  
Executive Director

October 28, 2010

To: Bob Graham, Co-Chair  
William K. Reilly, Co-Chair  
Frances Beinecke  
Donald F. Boesch  
Terry D. Garcia  
Cherry A. Murray  
Fran Ulmer

Dear Commissioners,

We write to report the results of cement testing that we have recently conducted and several conclusions we have reached based on that testing and documents subsequently provided to us by Halliburton. We wanted to report these results immediately to facilitate your consideration of their implications for offshore drilling safety.

We have known for some time that the cement used to secure the production casing and isolate the hydrocarbon zone at the bottom of the Macondo well must have failed in some manner. That cement should have prevented hydrocarbons from entering the well. For a variety of technical reasons that we will explain at the upcoming hearing, BP cemented the well with a nitrogen foam cement recommended and supplied by Halliburton. Halliburton generated the nitrogen foam cement by injecting high pressure nitrogen into a base cement slurry as it pumped that slurry into the well.

We asked Halliburton to supply us samples of materials like those actually used at the Macondo well so that we could investigate issues surrounding the cement failure. Halliburton provided us off-the-shelf cement and additive materials used at the Macondo well from their stock. Although these materials did not come from the specific batches used at the Macondo well, they are in all other ways identical in composition to the slurry used there.

Fourth Floor One Thomas Circle, NW Washington, D.C. 20005 • Tel (202) 254-2600 • Fax (202) 254-2617 • [www.OilSpillCommission.gov](http://www.OilSpillCommission.gov)

Fourth Floor One Thomas Circle, NW Washington, D.C. 20005 • Tel (202) 254-2600 • Fax (202) 254-2617 • [www.OilSpillCommission.gov](http://www.OilSpillCommission.gov)

Fourth Floor One Thomas Circle, NW Washington, D.C. 20005 • Tel (202) 254-2600 • Fax (202) 254-2617 • [www.OilSpillCommission.gov](http://www.OilSpillCommission.gov)

**Chevron's report states, among other things, that its lab personnel were unable to generate stable foam cement in the laboratory using the materials provided by Halliburton and available design information regarding the slurry used at the Macondo well. Although laboratory foam stability tests cannot replicate field conditions perfectly, these data strongly suggest that the foam cement used at Macondo was unstable. This may have contributed to the blowout.**

THE MACONDO CEMENT SLURRY. THE FIRST TWO TESTS WERE CONDUCTED IN February 2010 using different well design parameters and a slightly different slurry recipe than was finally used. Both tests indicated that this foam slurry design was unstable.


Halliburton provided data from one of the two February tests to BP in an email dated March 8, 2010. The data appeared in a technical report along with other information. There is no indication that Halliburton highlighted to BP the significance of the foam stability data or that BP personnel raised any questions about it. There is no indication that Halliburton provided the data from the other February test to BP.

Fourth Floor One Thomas Circle, NW Washington, D.C. 20005 • Tel (202) 254-2600 • Fax (202) 254-2617 • [www.OilSpillCommission.gov](http://www.OilSpillCommission.gov)



# Consequences of Unstable Foam Cement

September 8, 2010



All Agree That **Unstable Foam Cement Should Not Be Used**,  
But No Agreement on Specific Consequences

**BP Report: Unstable slurry caused:**

“nitrogen breakout, nitrogen migration and incorrect cement density. This would explain the failure to achieve zonal isolation of hydrocarbons. Nitrogen breakout and migration would have also contaminated the shoe track cement...”

## Results and Discussion


Parameters Affecting BSD. *Stability and Quality.* Good foam stability is required to maintain the initial foam structure until the cement sets. Unstable foams lead to a pore structure that is highly interconnected. This is caused by unstable nitrogen bubble walls that rupture upon contact with other nitrogen bubbles; the bubbles then coalesce and form larger gas pockets, resulting in a sponge-like structure with possible density inhomogeneity owing to gravity drainage of the base slurry.

## SLURRY DESIGN AND TESTING

The importance of slurry design in successful implementation of stable foamed cement systems cannot be overemphasized. Slurry density, neat-cement behavior, extender additives, foaming agents, etc., all exhibit a marked effect upon the integrity of the foam system and its ability to maintain a homogeneously dispersed gaseous phase. In an environment of continuously changing pressure, temperature and fluid shear, accurate foam slurry design as confirmed by laboratory testing is an indispensable prerequisite to effective placement design engineering.

## Situation at Time of Cement Job – April 19, 2010

- ❑ **Difficult drilling conditions**
- ❑ **Serious lost returns in the zone to be cemented**
- ❑ **Forced to stop drilling earlier than planned**
- ❑ **Difficulty converting float equipment**
- ❑ **Low circulating pressure after conversion**
- ❑ **No bottoms up circulation**
- ❑ **Cement jobs are known to occasionally need further work**
- ❑ **Cement modeling perceived as unreliable by BP**
- ❑ **Complicated cement job**
- ❑ **Low rate of cement flow**
- ❑ **Low cement volume**
- ❑ **Uncertain centralization**
- ❑ **No direct indicators of cementing success and no cement evaluation log**



The Deepwater Horizon

Drilling Offshore Wells

Macondo Time Line

Cementing the Macondo Well

Questions About Cement

**Temporary Abandonment**


Kick Detection

Blowout


# Temporary Abandonment



# Temporary Abandonment Procedure Begins After Cement Job




End of Cement Job



Temporarily Abandoned

# Cement is Perforated at Production Phase




00:53 | Frame: 1273




# Testing Integrity of Well – Three Tests

1. Seal Assembly Test
2. Positive-Pressure Test
3. Negative-Pressure Test




# Testing Integrity of Well – Three Tests

1. Seal Assembly Test
2. Positive-Pressure Test
3. Negative-Pressure Test



# Seal Assembly Test



Sea Floor

Formation

Casing Hanger Seal


Pack off and  
pressurize to  
test seal

00:26 | Frame: 644




# Testing Integrity of Well – Three Tests

1. Seal Assembly Test
2. Positive-Pressure Test
3. Negative-Pressure Test



# Positive-Pressure Test




00:40 | Frame: 971



# Testing Integrity of Well – Three Tests

1. Seal Assembly Test
2. Positive-Pressure Test
3. Negative-Pressure Test





# Negative-Pressure Test Is Very Important

Q. Please tell the Board how important or not important a negative test is to the final stage for completion of a well for T&Aing or P&Aing.

A. A negative test or putting the well into an equivalent or less than the seawater gradient is very important to understand that the tier barriers are in place and they work and they hold prior to displacing to seawater and removing the blowout preventers from the wellhead.

It's very important.

Testimony of Daou Winslow, Transocean General Manager of Gulf of Mexico, MBI Hearing 8/24 AM Tr. 234

PROFESSIONAL SHORTHAND REPORTERS, INC. Houston, Texas  
The Best Value for Your Investment in Court Reporting, Mediation & Arbitration

1 never seen a written, standardized type  
2 recommended test protocol for negative tests  
3 to your history with Transocean, correct?  
4 A. No, sir.  
5 Q. Have you ever seen such from any  
6 of the well operation associations or  
7 companies?  
8 A. No, sir.  
9 Q. What well certification company  
10 has Transocean used over the last five to  
11 seven years to educate and certify its  
12 personnel in the procedures for a negative  
13 test?  
14 A. I believe you are asking me what  
15 well control schools that were --  
16 Q. Yes, sir.  
17 A. Well, as an internal well control  
18 school, it's regulated through IADC and  
19 attended by the customers. We have also  
20 used WMI Well Control Services.  
21 Q. Who is that? I'm sorry.  
22 A. WMI Well Control, Randy Smith.  
23 And I can't remember the other names. I  
24 think there are a few other facilities.  
25 Q. I take it you no longer have to go  
26 to those four year or three year  
27 regimens --  
28 A. I do.  
29 Q. You still go to them?  
30 A. Yes, sir.  
31 Q. Do you recall if any of those  
32 entities publish a recommended negative test  
33 protocol?  
34 A. Not that I recall.  
35 Q. Please tell the Board how  
36 important or not important a negative test  
37 is to the final stage for completion of a  
38 well for T&Aing or P&Aing.  
39 A. A negative test or putting the  
40 well into an equivalent or less than the  
41 seawater gradient is very important to  
42 understand that the tier barriers are in  
43 place and they work and they hold prior to  
44 displacing to seawater and removing the  
45 blowout preventers from the wellhead. It's  
46 very important.  
47 Q. And you want a valid test protocol  
48 to be instituted so that the test can be  
49 the result can be valid, correct?  
50 A. If I understand what you are  
51 asking is you want me to get the protocols  
52 to get one done?  
53 Q. No, the sorry. Let me ask it this  
54 way. You discuss on your rigs for the  
55 negative test to have a valid result?  
56 Whether that result from the test failed or  
57 whether it passed, you want to know that  
58 category, correct?  
59 A. Yes.  
60 Q. Now, if it passes, tell us  
61 technically what that means.  
62 A. Technically that means that the  
63 barriers that were in place after  
64 substituting the effect of the hydrostatic  
65 of the mud it displaces on those barriers,  
66 it would be safe to proceed with  
67 displacement and the removal of the BOPs.  
68 Q. Thank you. And the barriers you  
69 are speaking of are cement, correct?  
70 A. Cement.  
71 Q. Cement, correct?  
72 A. Cement.  
73 Q. Hanger seals, plugs, correct?  
74 A. Cement.  
75 Q. Do those are the materials and  
76 mechanical barriers that you want to make  
77 sure contains the well so that the well  
78 could be left static, correct?  
79 A. Could be left with just the  
80 seawater gradient that you would have, yes.  
81 Q. Yes, sir. Can you tell us the  
82 types of pressures you would expect in a  
83 drift pipe. Once you have done a negative  
84 test and you are ready to understand the  
85 results, is there anything about the kill  
86 line, the choke line, or the anti-slope  
87 pressures that you could tell us which is a  
88 standard that you want to watch for?  
89 MR. CLARKE:  
90 Your Honor, let me object that  
91 it's an immaterial hypothetical. There are  
92 many different ways to set the alignment of  
93 valves and piping. There could be many  
94 circumstances under which the test could be  
95 performed. So to ask the general question  
96 is imprecise, and frankly, asking an  
97 opinion.  
98 MR. WINTON:  
99 Judge, he has a lawyer. This is a  
100 very experienced witness.  
101 Page 234

59 (Pages 233 to 236)

PROFESSIONAL SHORTHAND REPORTERS, INC. 800-525-5255 (540) 426-0255  
New Orleans • Baton Rouge • Shreveport

PROFESSIONAL SHORTHAND REPORTERS, INC. Houston, Texas  
The Best Value for Your Investment in Court Reporting, Mediation & Arbitration


101 never seen a written, standardized type  
102 recommended test protocol for negative tests  
103 to your history with Transocean, correct?  
104 A. No, sir.  
105 Q. Have you ever seen such from any  
106 of the well operation associations or  
107 companies?  
108 A. No, sir.  
109 Q. What well certification company  
110 has Transocean used over the last five to  
111 seven years to educate and certify its  
112 personnel in the procedures for a negative  
113 test?  
114 A. I believe you are asking me what  
115 well control schools that were --  
116 Q. Yes, sir.  
117 A. Well, as an internal well control  
118 school, it's regulated through IADC and  
119 attended by the customers. We have also  
120 used WMI Well Control Services.  
121 Q. Who is that? I'm sorry.  
122 A. WMI Well Control, Randy Smith.  
123 And I can't remember the other names. I  
124 think there are a few other facilities.  
125 Q. I take it you no longer have to go  
126 to those four year or three year  
127 regimens --  
128 A. I do.  
129 Q. You still go to them?  
130 A. Yes, sir.  
131 Q. Do you recall if any of those  
132 entities publish a recommended negative test  
133 protocol?  
134 A. Not that I recall.  
135 Q. Please tell the Board how  
136 important or not important a negative test  
137 is to the final stage for completion of a  
138 well for T&Aing or P&Aing.  
139 A. A negative test or putting the  
140 well into an equivalent or less than the  
141 seawater gradient is very important to  
142 understand that the tier barriers are in  
143 place and they work and they hold prior to  
144 displacing to seawater and removing the  
145 blowout preventers from the wellhead. It's  
146 very important.  
147 Q. And you want a valid test protocol  
148 to be instituted so that the test can be  
149 the result can be valid, correct?  
150 A. If I understand what you are  
151 asking is you want me to get the protocols  
152 to get one done?  
153 Q. No, the sorry. Let me ask it this  
154 way. You discuss on your rigs for the  
155 negative test to have a valid result?  
156 Whether that result from the test failed or  
157 whether it passed, you want to know that  
158 category, correct?  
159 A. Yes.  
160 Q. Now, if it passes, tell us  
161 technically what that means.  
162 A. Technically that means that the  
163 barriers that were in place after  
164 substituting the effect of the hydrostatic  
165 of the mud it displaces on those barriers,  
166 it would be safe to proceed with  
167 displacement and the removal of the BOPs.  
168 Q. Thank you. And the barriers you  
169 are speaking of are cement, correct?  
170 A. Cement.  
171 Q. Cement, correct?  
172 A. Cement.  
173 Q. Hanger seals, plugs, correct?  
174 A. Cement.  
175 Q. Do those are the materials and  
176 mechanical barriers that you want to make  
177 sure contains the well so that the well  
178 could be left static, correct?  
179 A. Could be left with just the  
180 seawater gradient that you would have, yes.  
181 Q. Yes, sir. Can you tell us the  
182 types of pressures you would expect in a  
183 drift pipe. Once you have done a negative  
184 test and you are ready to understand the  
185 results, is there anything about the kill  
186 line, the choke line, or the anti-slope  
187 pressures that you could tell us which is a  
188 standard that you want to watch for?  
189 MR. CLARKE:  
190 Your Honor, let me object that  
191 it's an immaterial hypothetical. There are  
192 many different ways to set the alignment of  
193 valves and piping. There could be many  
194 circumstances under which the test could be  
195 performed. So to ask the general question  
196 is imprecise, and frankly, asking an  
197 opinion.  
198 MR. WINTON:  
199 Judge, he has a lawyer. This is a  
200 very experienced witness.  
201 Page 234

59 (Pages 233 to 236)

PROFESSIONAL SHORTHAND REPORTERS, INC. 800-525-5255 (540) 426-0255  
New Orleans • Baton Rouge • Shreveport



# Negative-Pressure Test




00:52 | Frame: 1257



# Nobody Disputes it Was a Failed Negative-Pressure Test

September 8, 2010



Abnormal pressures observed during the negative-pressure test were indicative of a failed or inconclusive test; however, the test was deemed successful.

BP Deepwater Horizon Accident Investigation Report p. 79


\* \* \*

There was “1,400 psi on the drill pipe, an indication of communication with the reservoir.”

BP Deepwater Horizon Accident Investigation Report p. 88

**All parties agree**

# Negative-Pressure Test at Macondo



03:15 | Frame: 4703



# No Required Negative-Pressure Test Procedures



MMS



Yes

No

Yes	No
	✓
	✓
	✓

**MMS didn't require negative-pressure test at all**

**BP requires negative-pressure test but does not have set procedures; "could be different on every single rig depending on what the team agreed to"**

Testimony of John Guide, BP Well Team Leader, MBI Hearing 7/22 PM, Tr. 158-159

**Transocean requires negative-pressure test but does not have set procedures**

Testimony of Daun Winslow, Transocean General Manager of Gulf of Mexico, MBI Hearing 8/24 AM, Tr. 232-33



# Interpretations of Negative-Pressure Test

Page 17  
1 A. Yes, I did.  
2 Q. Who on the DEEPWATER HORIZON was  
3 interpreting the negative test data for the  
4 first and second tests?  
5 A. The man interpreting the data?  
6 The company man and the toolpusher up there.  
7 Q. Was there a third negative test  
8 conducted prior to the second test?  
9 A. There was no third negative test  
10 done by Mr. Harrell.  
11 Q. Let's talk about interpreting the mud  
12 pit, if you will.  
13 During a negative test, where is  
14 the mud generally circulated to?  
15 A. The shaker and onto the mud pit.  
16 Q. When circulating mud from the  
17 riser, where is it normally returned to?  
18 A. To the active mud pits, mud traps  
19 and all that.  
20 Q. Why is the mud normally returned  
21 to the mud pits during the course of a  
22 negative test?  
23 A. Why is it always --  
24 Q. Why is it normally returned to the  
25 mud pits as opposed to some other location?  
26

Q. Who on the DEEPWATER HORIZON was interpreting the negative test data for the first and second tests?

A. Who was interpreting the data? The company man and the toolpusher up there.

Testimony of Jimmy Harrell, Transocean Offshore Installation Manager, MBI Hearing 5/27 AM Tr. 85

Page 18  
1 How to conduct a negative test.  
2 Q. Was it Mr. Kaluza's and  
3 Mr. Vidrine's responsibility to determine  
4 whether the results of the negative test  
5 were satisfactory before moving on from that  
6 operation?  
7 A. They were -- whichever one was on  
8 tour at the time -- one of the people who  
9 were supposed to determine if the negative  
10 test was successful or not.  
11 Q. They were both one of the people?  
12 A. Yes, sure. That's right.  
13 Q. But in the Transocean that operation  
14 that you and Mr. Kaluza the decision as to  
15 whether or not certain operations are  
16 going to be performed and when they are  
17 performed is that correct?  
18 A. That is correct. So the way in  
19 which you and Mr. Kaluza the decision was  
20 made, especially when they're doing  
21 testing, that they look at the results and  
22 that's correct that the company man  
23 and especially if they're not an operator,  
24 that they're not responsible, they're not  
25 to justify the issue.  
26

Q. Was it Mr. Kaluza's and Mr. Vidrine's responsibility to determine whether the results of the negative test were satisfactory before moving on from that operation?

A. They were – whichever one was on tour at the time one of the people who were supposed to determine if the negative test was successful or not.

Testimony of John Guide, BP Wells Team Leader, 7/22 AM Tr. 167

Page 19  
1 INTERPRETATION OF THE RESULTS  
2 A. Yes, I did.  
3 Q. Who on the DEEPWATER HORIZON was  
4 interpreting the negative test data for the  
5 first and second tests?  
6 A. The man interpreting the data?  
7 The company man and the toolpusher up there.  
8 Q. Was there a third negative test  
9 conducted prior to the second test?  
10 A. There was no third negative test  
11 done by Mr. Harrell.  
12 Q. Let's talk about interpreting the mud  
13 pit, if you will.  
14 During a negative test, where is  
15 the mud generally circulated to?  
16 A. The shaker and onto the mud pit.  
17 Q. When circulating mud from the  
18 riser, where is it normally returned to?  
19 A. To the active mud pits, mud traps  
20 and all that.  
21 Q. Why is the mud normally returned  
22 to the mud pits during the course of a  
23 negative test?  
24 A. Why is it always --  
25 Q. Why is it normally returned to the  
26 mud pits as opposed to some other location?  
27

Q. Given your experience with Transocean, would you expect Transocean's toolpusher to be able to interpret the results of a negative test?


A. I would think so.

Q. Would you also expect Transocean's driller to be able to interpret the results of a negative test?

A. Yes.

Testimony of Pat O'Bryan, BP Vice President Drilling and Completions, MBI Hearing 8/26 PM Tr. 322-323


# Planned Temporary Abandonment Procedure Once Negative-Pressure Test Passed




00:34 | Frame: 823



# Displacing to 8,300 Feet Underbalanced Well More Than Necessary



# Irregularity of Setting Cement Plug So Low



Q. But it was somewhere around 8300, right?

A. Yes, yes.

Q. A lot deeper than you had probably seen before, right?

A. Yes.

Testimony of Ross Skidmore, BP Contract Vendor, MBI Hearing 7/20 PM Tr. 60

Q. You testified earlier that one of the unusual aspects of the displacement here was down to 83 –

A. 67, that's true. Usually it's 300 feet below the mud line, and 8367 is much further down than usual.


Testimony of Leo Lindner, MI-Swaco Mud Engineer, MBI Hearing 7/19 PM Tr. 86

Q. Well, the additional pressure, give the depth of this well, the displacement of mud with water in a volume much greater than is standard, is normal?

A. We were going to do a displacement at roughly 8,300 feet. It was a little bit – well, it was deeper than normal.

Testimony of John Guide, BP Wells Team Leader, MBI Hearing 7/22 PM Tr. 124

# Procedure Meant Only One Barrier Besides Open BOP During Displacement



00:26 | Frame: 626



# Evolution of Temporary Abandonment Procedure

## April 14 E-Mail From Morel to R. Sepulvado

From: Sepulvado, Ronald W  
 Sent: Wed Apr 14 10:15:15 2010  
 To: Morel, Brian P  
 Subject: RE: Forward Ops

Run RSWC #3  
 Make clean-out run to 18360' / short trip and CBU at 18,360'  
 POOH and retrieve wear bushing  
 Run tapered long string  
 POOH with landing string  
 RIH set wear bushing continue to 8367' set 300' cement plug  
 Wait on cement / tag TOC with 15k  
 Negative test with base oil in kill/choke line to the wellhead  
 POOH to 6000'  
 Displace to seawater  
 POOH and wash wellhead on the way out  
 Run lead impression  
 Run lockdown sleeve  
 Pull Riser

April 14 Morel E-Mail	April 16 MMS Permit	April 20 Ops Note
Run in hole to 8,367'		
Set 300' cement plug in mud <b>BARRIER</b>		
Negative test with base oil to wellhead		
Displace mud in well and riser from 6,000' with seawater		
Set lockdown sleeve		

# Evolution of Temporary Abandonment Procedure

## April 16 Application for Permit to Drill Sent to MMS

Temporary Abandonment Procedure: (estimated start time Sunday, April 18, 2010)

1. Negative test casing to seawater gradient equivalent for 30 min. with kill line.
2. TIH with a 3-1/2" stinger to 8367'.
3. Displace to seawater. Monitor well for 30 min.
4. Set a 300' cement plug (125 cu.ft. of Class H cement) from 8367' to 8067'.

The requested surface plug depth deviation is for minimizing the chance for damaging the LDS sealing area, for future completion operations.

This is a Temporary Abandonment only.


The cement plug length has been extended to compensate for added setting depth.

5. POOH.
6. Set 9-7/8" LDS (Lock Down Sleeve)

April 14 Morel E-Mail	April 16 MMS Permit	April 20 Ops Note
Trip in hole to 8,367'	Negative test to seawater gradient (with base oil to wellhead)	
Set 300' cement plug in seawater <b>BARRIER</b>		
Negative test with base oil to wellhead	Displace mud in well and riser from 8,367' with seawater	
Displace mud in well and riser from 6,000' with seawater	Monitor well for 30 minutes to ensure no flow	
Set lockdown sleeve		

# Evolution of Temporary Abandonment Procedure

## April 20 Operations Note From Morel to Rig



Quick ops note for the next few days:

1. Test casing per APD to 250 / 2500 psi
2. RIH to 8367'
3. Displace to seawater from there to above the wellhead
4. With seawater in the kill close annular and do a negative test ~2350 psi differential
5. Open annular and continue displacement
6. Set a 300' balanced cement plug w/ 5 bbls in DP
7. POOH ~100-200' above top of cement and drop neft ball / circulate DS volume
8. Spot corrosion inhibitor in the open hole
9. POOH to just below the wellhead or above with the 3-1/2" stinger (if desired wash with the 3-1/2" / do not rotate / a separate run will not be made to wash as the displacement will clean up the wellhead)
10. POOH and make LIT / LDS runs
11. Test casing to 1000 psi with seawater (non MMS test / BP DWOP) – surface plug
  - a. Confirm bbls to pressure up on original casing test vs bbls to test surface plug (should be less due to volume differences and fluid compressibility –seawater vs sobm)
  - b. Plot on chart / send to Houston for confirmation

April 14 Morel E-Mail	April 16 MMS Permit	April 20 Ops Note
Run in hole to 8,367'	Negative test to seawater gradient (with base oil to wellhead)	
Set 300' cement plug in mud <b>BARRIER</b>	Trip in hole to 8,367'	Displace mud with seawater from 8,367' to above wellhead (BOP)
Negative test with base oil to wellhead	Displace mud in well and riser from 8,367' with seawater	Negative test with seawater to depth 8,367' rather than with base oil to wellhead
Displace mud in well and riser from 6,000' with seawater	Monitor well for 30 minutes to ensure no flow	Displace mud in riser with seawater <b>Blowout</b>
	Set 300' cement plug in seawater <b>BARRIER</b>	
Set lockdown sleeve	Set lockdown sleeve	

# Evolution of Temporary Abandonment Procedure

## April 28 Interview of Robert Kaluza

We did not circulate bottoms up before the cement job. The program called for 1 1/2 times the drill pipe volume - it didn't call for bottoms up from the above to surface before the cement job.

Steve asked about the cement job differential - I would think it would be close to balance. Of course the cement will be slightly higher on the back side. Did not flow back much - there was a limit of 6 barrels.

I came on tour when we were getting ready to run in hole for the positive and negative tests.

From conversations it looked like everything went ok.

The permit was modified for the surface cement plug. **It was a different sequence.** While running in the hole I was in the office and Hafle called to ensure I had seen the modified APM. Brian was on the rig sleeping as he was on the cement job. Mark called to go through the ADP - said I should talk to Brian so I went to wake up Brian. **The team in town wanted to do something different - Mark was on vacation.** They decided we could do the displacement and negative test together - don't know why - maybe trying to save time. At the end of the well sometimes they think about speeding up.

Mark was out of the office and the team got together and discussed doing it as per the bullet points. The town team had decided to do it differently - Brian said he would talk to Mark. It occurred to me that the team including John had decided this. In this case we just went and did it this way.

I went to the rig floor. Did the positive test. Ran in hole to 8367ft.

Went through the mud engineer's displacement program in the rig floor. On Thunderhorse we've done many displacements - we went through this - I had a couple

and Requested

BP-1

April 14 Morel E-Mail	April 16 MMS Permit	April 20 Ops Note
Run in hole to 8,367'	Negative test to seawater gradient (with base oil to wellhead)	
Set 300' cement plug in mud <b>BARRIER</b>	Trip in hole to 8,367'	Displace mud with seawater from 8,367' to above wellhead (BOP)
Negative test with base oil to wellhead	Displace mud in well and riser from 8,367' with seawater	Negative test with seawater to depth 8,367' rather than with base oil to wellhead
Displace mud in well and riser from 6,000' with seawater	Monitor well for 30 minutes to ensure no flow	Displace mud in riser with seawater <b>Blowout</b>
	Set 300' cement plug in seawater <b>BARRIER</b>	
Set lockdown sleeve	Set lockdown sleeve	

The Deepwater Horizon

Drilling Offshore Wells

Macondo Time Line

Cementing the Macondo Well

Questions About Cement

Temporary Abandonment


**Kick Detection**

Blowout

# Kick Detection



# Driller Responsibilities

	DEEPWATER HORIZON EMERGENCY RESPONSE MANUAL DWH-HSE-PR-001	SECTION: 7
	WELL CONTROL/SHALLOW GAS BLOWOUT	SUBSECTION: N/A

## 2 DETECTION

Detection of a kick (intrusion of liquid or gas into the wellbore) is the responsibility of the Driller. The Driller and his crew will continuously monitor the surface system indicators (flow rate, pit level, etc.) and break downhole indications, such as mud pressure, rate of penetration (drilling break), etc., for signs of a kick. Upon detecting a kick, the Driller is trained to shut the well in quickly. In fact, the speed with which this is accomplished will determine the severity of the situation.

Title:  
DEEPWATER HORIZON  
EMERGENCY RESPONSE MANUAL  
VOL. 1

Revision Status:  
Level: L3  
Classification: RSP  
Manual Number: DWH-HSE-PR-001  
Issue Number: 02  
Revision Number: 04  
Effective Date: February 15, 2008

Hard copies are printed from an electronic system and are not controlled

Non Controlled

CONFIDENTIAL TREATMENT REQUESTED

BP-HZN-MB00000943

## 2 DETECTION

Detection of a kick (intrusion of liquid or gas into the wellbore) is the responsibility of the Driller. The Driller and his crew will continuously monitor the surface system indicators (flow rate, pit level, etc.) and break downhole indications, such as mud pressure, rate of penetration (drilling break), etc., for signs of a kick. Upon detecting a kick, the Driller is trained to shut the well in quickly. In fact, the speed with which this is accomplished will determine the severity of the situation.

Factors such as excessive shut in casing pressure, may lead the Operator's Senior Representative and the Offshore Installation Manager (OIM) to realize the treatment of a given kick will not be routine. In such a case, they will decide to declare a Level Two Alert.

Hard copies are printed from an electronic system and are not controlled


ISSUE NO: 02	REVISION NO: 01	PAGE	OF
REVISION DATE: March 31, 2008		1	11

CONFIDENTIAL TREATMENT REQUESTED

BP-HZN-MB00001006





# Anomalies in Data Indicate Kick



[Return to Graphs](#)

# Well Design – Long String Compared to Liner



# Evidence Inconsistent With Picking Up and Dropping

Casing hanger seal assembly was in expected position at Macondo


No apparent damage to the casing hanger seals



# New vs. Macondo Casing Hanger Seal Assembly

## Inside

Ridges and grooves on inside appear to have been eroded away




1/4-inch-deep slots on inside appear eroded away

# New vs. Macondo Casing Hanger Seal Assembly

## Outside




Flow from annulus would have come up through holes



No apparent erosion on outside

# Transocean's Time Line of Last Five Hours



# Crew Attempts to Divert Mud and Gas – Mud-Gas Separator



# Crew Attempts to Divert Mud and Gas – Diversers



# When to Divert Overboard

## 9.2 EQUIPMENT FOR HANDLING GAS IN THE RISER

The diverter system above the telescopic joint with two (2) overboard lines and a system to remove gas from large volumes of mud and return it to the mud system (such as a mud box on the overboard line) is preferred.

The diverter and overboard lines should be designed to handle high flow rates and be as straight as possible.

This system is not designed to choke or control high gas or liquid flow; rather, it is a system to keep combustible gases safely away from sources of ignition and to remove gas from the mud.

At any time, if there is a rapid expansion of gas in the riser, the diverter must be closed (if not already) and the flow diverted overboard.

be used while circulating and monitoring the riser. This could be the trip tank if available.

SPECIFIC ENVIRONMENTS  
 DEEPWATER

- The use of a second PVT system on the riser should be considered when circulating the riser. This provides a better indication of an approaching gas bubble and its associated liquid slug.
- However, if large volumes of gas have entered the riser, it will flow rapidly on its own and there will be no way to control it by adjusting the circulation rate. Then, the surface gas and liquid rates become very high, especially as the gas bubble reaches surface and the flow must be diverted overboard.

9.2 EQUIPMENT FOR HANDLING GAS IN THE RISER

The diverter system above the telescopic joint with two (2) overboard lines and a system to remove gas from large volumes of mud and return it to the mud system (such as a mud box on the overboard line) is preferred.

The diverter and overboard lines should be designed to handle high flow rates and be as straight as possible.

This system is not designed to choke or control high gas or liquid flow; rather, it is a system to keep combustible gases safely away from sources of ignition and to remove gas from the mud.

At any time, if there is a rapid expansion of gas in the riser, the diverter must be closed (if not already) and the flow diverted overboard.

This is true for water-based mud as well as for oil-based mud. An alternate system using the MGS to remove gas from the mud is shown in Figure 8-4.12.

Either the mud from the riser or from the well can be circulated through the MGS to remove the residual gas (but only one at a time). Automatic valve switching suggests such that the closing of the 12" valve and the opening of the 6" valve are coordinated.


An override switch should be available that will allow the manual opening of the 12" valve if the need arises. Also, automatic opening of the 12" valve should be tied to the separator pressure so that the separator rating is not exceeded or an automatic pressure relief bypass should be included.

A small volume circulating system should be isolated so that a volume totalizer can be used while circulating and monitoring the riser. This could be the trip tank available.

Hardcopies are printed from an electronic system and are not controlled



# Diverting Overboard Might Have Prevented or Delayed the Explosion



**Figure 7: 16 of 20 diverter uses were considered successful because the venting of gas was sustained until the well bridged.**

As indicated in Figure 7, the success rate for diverter systems was very high during the current period and improved significantly from the previous study. During the current period, diverters were used in 20 of the 39 blowouts. Sixteen of the 20 diverter uses were considered successful because the desired venting of gas was sustained until the well bridged, allowing all personnel to be safely evacuated. During the previous period, 22 of the 41 diverter uses were considered successful. Table 2 present information on diverter use and failures by rig type. A contributing factor to the improvement in diverter performance may be attributed to the revised diverter regulations that were published in 1988 and became effective two years later.

## WELL CONTROL



**Figure 6: Cementing problems increased significantly during this study period, being associated with 18 of the 39 blowouts.**

In the current study, 41% lasted between one and seven days, compared with 20% during the previous study. There were fewer blowouts that lasted more than seven days. The blowout with the longest duration during the current study period was 11 days, compared with more than 30 days in the previous period.

Just over 50% of the blowouts were controlled by pumping mud or cement or by actuating mechanical well control equipment during the current study (Figure 4). In 30% of the blowout events, the wells ceased flowing because sediments bridged or sealed the well. Thirteen of the wells ceased flowing when trapped gas or shallow gas pockets were depleted. Although relief wells were initiated in two of the blowouts, both wells were controlled by other means prior to completion of the relief well. Unlike the current study, almost three-fourths of the blowouts in the previous study were controlled when sediments bridged the well.

**The most important improvement identified during the current study is the significant decrease in fatalities and injuries—only one fatality and two injuries resulted from blowouts from 1992 to 2006.**


## SHALLOW GAS

During the current period, the blowout rate for exploration wells was one every 298 wells drilled, and the blowout rate for development wells was one every 120 wells drilled. Development drilling during the current period accounted for a slightly greater percentage (21%) of blowouts than did exploratory drilling (19%). In contrast, although the relative percentages of development and exploratory wells drilled were the same during both study periods (62% and 38%, respectively), exploratory drilling accounted for a greater percentage (29%) of blowouts than development drilling (47%) during the previous period.

Similar to the previous period, over half of the blowouts during the current period occurred before the well had been drilled to DSDR (70%) (Figure 5) and were not triggered by hydrocarbon inflow from productive horizons. During the current period, shallow gas was associated with 49% of the blowouts and was most frequently associated with development wells.

## CONTRIBUTING FACTORS

During the current period, more than one contributing factor was identified for just over half of the blowouts. The most significant factors included cementing problems resulting in gas migration during or after cementing of the well casing (15



**Figure 7: 16 of 20 diverter uses were considered successful because the venting of gas was sustained until the well bridged.**

blowouts, equipment failure (12 blowouts), and casing failure (10 blowouts). Figure 6 shows a break-out of these and other contributing factors to blowouts in the current study.

In the previous study, the primary contributing factors were resulting formation fracture equipment failure and cementing. Cementing problems increased significantly during the current period as these problems were associated with 18 of the 39 blowouts, compared with 19 of the 20 blowouts with identified contributing factors during the previous study. During the current period, all but one of the blowouts associated with cementing problems occurred in wells with water depths less than 800 ft.

During the current period, one incident involving an accidental flare disconnect on a floating drilling rig resulted in a blowout. As drilling activity is deeperwater increases, procedures for these operations should continue to be evaluated to identify flare disconnects and the potential for blowouts associated with them that are prevented.

## FLARE TYPES, DIVERTER SYSTEMS


Of the 19 blowouts during the current period, five occurred on platform rigs. Of the remaining 14 blowouts involving wells drilled with mobile units, 29 blowouts, or 65%, were drilled with jacking and six were drilled with nonobservable rigs. It is noted that each of the exploratory and development drilling in the EORR is conducted from jacking. In the previous study, no significant difference in the consequences of blowouts was found between jacking and other bottom-founded rigs. During the current study, blowouts on jacking and platform rigs were associated with the most significant consequences.

The only fatality that occurred during the current period was on a jacking rig when a crew member was fatally injured after an explosion associated with a blowout. In addition, the seven fire/injuries associated with blowouts during the current period occurred either on jacking or platform rigs. Four of these seven blowouts resulted in major property damage.

The stability of bottom-founded rigs can be affected by disturbances to the sea floor. Such disturbing structures can include a shallow gas influx fractures the unconsolidated portion of the hole and forms a crater around the wellhead. Many operators prefer



# Gas Expands Exponentially as it Rises



The Deepwater Horizon

Drilling Offshore Wells

Macondo Time Line

Cementing the Macondo Well

Questions About Cement

Temporary Abandonment


Kick Detection

**Blowout**

# Blowout



# Hydrocarbons Emerge on the Rig



April 21, 2010



Photos: *Times Picayune, Wall Street Journal*



# Lessons Learned From December 2009 Event

In December 2009, a Transocean rig in the North Sea experienced a well control event during completion operations

Transocean and the well's operator analyzed the event and reached a number of conclusions regarding handling of such events:

- **High vigilance** when reduced to one barrier underbalanced
- Recognize when underbalanced – **heightened vigilance**
- Highlight what the kick detectors are when not drilling



# Last Two Hours: Explosion at 21:49 (9:49 PM)

BOP  
open –  
cement  
is only  
barrier



Time	Event
20:02	Negative-pressure test over, begin to remove heavy mud and replace it with lighter seawater
20:52	BP report calculates well underbalanced
21:01 – 21:08	<b>Anomalous drill pipe pressure: subtle increase while displacing heavy fluid with lighter fluid</b>
21:08 – 21:14	<b>Anomalous drill pipe pressure: increase while pumps off</b>
21:38	BP report calculates hydrocarbons in riser
21:40	Mud begins to overflow on rig floor
21:41	Annular preventer activated, BP report calculates 1,000 bbl gain
21:42	Nearby ship told to move
21:46	Gas emerges onto drill floor
21:49	First explosion, power lost, BP report calculates 2,000 bbl gain



## Preliminary Conclusions – Technical

- Flow path was exclusively through shoe track and up through casing.
- Cement (potentially contaminated or displaced by other materials) in shoe track and in some portion of annular space failed to isolate hydrocarbons.
- Pre-job laboratory data should have prompted redesign of cement slurry.
- Cement evaluation tools might have identified cementing failure, but most operators would not have run tools at that time. They would have relied on the negative pressure test.
- Negative pressure test repeatedly showed that primary cement job had not isolated hydrocarbons.
- Despite those results, BP and TO personnel treated negative pressure test as a complete success.
- BP's temporary abandonment procedures introduced additional risk.

## Preliminary Conclusions – Technical

- Number of simultaneous activities and nature of flow monitoring equipment made kick detection more difficult during riser displacement.
- Nevertheless, kick indications were clear enough that if observed would have allowed the rig crew to have responded earlier.
- Once the rig crew recognized the influx, there were several options that might have prevented or delayed the explosion and/or shut in the well.
- Diverting overboard might have prevented or delayed the explosion. Triggering the EDS prior to the explosion might have shut in the well and limited the impact of any explosion and/or the blowout.
- Technical conclusions regarding BOP should await results of forensic BOP examination and testing.
- No evidence at this time to suggest that there was a conscious decision to sacrifice safety concerns to save money.



The National Commission on the

# BP DEEPWATER HORIZON OIL SPILL AND OFFSHORE DRILLING

