



Inspection / Investigation Report No. 11287051

U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Enforcement

Inspection Location:

St. Petersburg Fire Department
400 Dr Marting Luther King Jr. St
St. Petersburg, FL 33701

Contact: Bill Schorn, Detective-Fire
Investigator
Phone: (727) 892-5212
Fax: (727) 892-5011

Type of Inspection: ACCIDENT/FAILURE INVESTIGATION **Result:** NO FURTHER ACTION

Inspector: QUAIL, ERNEST
Code: PHH-287
Title: HAZARDOUS MATERIALS ENFORCEMENT SPECIALIST

Signature:

Supervisor Name:
Title:

Inspector #2:
Code:
Title:

Authorization Date:

Summary of Inspection

On September 11, 2011, a DOT-3AL-3000 aluminum cylinder manufactured by Hy-Mark Cylinders, Hapton, VA in 2007 ruptured in the residence of (b) (6), a certified dive instructor, who subsequently died because of the injuries received in the explosion. At the time of the accident, there were 11 scuba tanks within the residence because Mr (b) (6) and several friends were preparing to go on a scuba diving excursion.

PHMSA Hazardous Materials Investigator Ernest G. Quail arrived at the St. Petersburg Fire Department, 400 Martin Luther King Blvd, St. Petersburg FL on September 13, 2011 to photograph the cylinder and create a cylinder observation report (Exhibit 1, 2). The St. Petersburg police also supplied an Incident Investigation Report (Exhibit 3). The cylinder was a DOT-3AL 3000 and was in two pieces, split longitudinally. The resulting explosion melted part of the sidewall and around the inside neck area. The fire department attributed the force of the escaping gas, which they felt was pure oxygen, produced a severe heat event. The valve was separated and the threads were sheared indicating the valve was removed with significant force. Labels were attached to the cylinder which indicated "Oxygen" and "for Decompre...". The label further indicated "have been cleaned formix, Oxygen content 22 to 40%." Date punches on the label indicate the year as 2011, the

St. Petersburg Fire Department
Inspection / Investigation Report No. 11287051

month is not clear. The cylinder was manufactured in 10/07 and there were no RIN stamps indicating a hydro test of the cylinder.

The cylinder was secured by Investigator Quail for storage until a contract with a test lab was obtained to determine the cause of the explosion. A contract was made with RTI Group, LLC, 910 Bestgate Rd, Suite E, Annapolis, MD 21401 and a protocol was developed for the testing of the cylinder (Exhibit 4). The cylinder was mailed to RTI and arrived November 15, 2011.

The final report was issued by RTI Group on August 29, 2012. The testing revealed no defects in the cylinder or problems with the regulator, pressure lines or valve. There was no contamination present in the cylinder, regulator, valve or hose. The mechanism of ignition which resulted in the explosion was undetermined (Exhibit 5).

No further action is being taken on this incident by PHMSA at this time.

Additional Information Pertaining to the Inspection:

Exhibit Summary

Evidence		Obtained From		
No.	Description	Name, Title	Company	City, State
1	Cylinder Photos	Ernest G. Quail, Hazardous Materials Investigator	US DOT/PHMSA/OHMSFO/Southern Region	Atlanta, GA
2	Cylinder Observation Report	Ernest G. Quail, Hazardous Materials Investigator	US DOT/PHMSA/OHMSFO/Southern Region	Atlanta, GA
3	St Petersburg PD Incident Investigation Report	Bill Schorn, Detective	St. Petersburg Police Department	St. Petersburg, FL
4	Test Protocol		RTI Group	Annapolis, MD
5	Final Report With Attachment		RTI Group	Annapolis, MD

**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE


St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

<u>LOCATION</u> St. Petersburg Fire Department 400 Martin Luther King Blvd S <u>CITY, STATE</u> St. Petersburg, FL	<u>PHOTOGRAPH DATE</u> 09/13/2011 <u>PHOTOGRAPHER</u> Ernest G. Quail
--------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE


St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE


St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE


St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE


St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE


St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

<u>LOCATION</u> St. Petersburg Fire Department 400 Martin Luther King Blvd S <u>CITY, STATE</u> St. Petersburg, FL	<u>PHOTOGRAPH DATE</u> 09/13/2011
	<u>PHOTOGRAPHER</u> Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

<u>LOCATION</u> St. Petersburg Fire Department 400 Martin Luther King Blvd S <u>CITY, STATE</u> St. Petersburg, FL	<u>PHOTOGRAPH DATE</u> 09/13/2011 <u>PHOTOGRAPHER</u> Ernest G. Quail
--------------------------------------------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE


St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



**U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration
Office of Hazardous Materials Safety Field Operations
Photograph Summary**

LOCATION

St. Petersburg Fire Department
400 Martin Luther King Blvd S

CITY, STATE

St. Petersburg, FL

PHOTOGRAPH DATE

09/13/2011

PHOTOGRAPHER

Ernest G. Quail



CYLINDER OBSERVATION REPORT

Inspectors: _____

Location: St. Petersburg FL.

Phone: _____

Contact: _____

Date: 9-13-11



Time: 1150

Size: _____ Height _____

Diameter _____

Paint: yellow

Misc.: Oxygen.



U.S. DOT/PHMSA/OHME/SOUTHERN REGION

REPORT #: _____

EXHIBIT #: _____

PAGE: _____ OF _____

Incident/Investigation Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCYDate Printed: 09/13/2011 11:59:36
(42529) BELLITTERA, RYAN T

Incident Information

Date/Time Reported 09/11/2011 07:00	Date/Time From 09/11/2011 07:00	Date/Time To 09/11/2011 07:00	Officer (42529) BELLITTERA, RYAN T
Incident Location (b) (6) St Petersburg, FL 33710			
Case Status: FURTHER INVESTIGATION			Case Disposition:
Incident Report Dissemination <input type="checkbox"/> State Attorney <input type="checkbox"/> CASA <input type="checkbox"/> Other			

Charges

1	Charge Type	Description ASSIST OUTSIDE AGENCY	Statute 999	UCR 999	<input type="checkbox"/> Att <input checked="" type="checkbox"/> Com
Alcohol, Drugs or Computers Used <input type="checkbox"/> Alcohol <input type="checkbox"/> Drugs <input type="checkbox"/> Computers		Location Type RESIDENCE...	Premises Entered	Forced Entry <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Weapons 1. 2. 3.
Entry	Exit	Criminal Activity			
Bias Motivation	Bias Target	Bias Circumstances	Hate Group		

Victims

Seq. # 1	Type INDIVIDUAL	Injuries None	Residency Status Resident		Ethnicity Non-Hispanic	
Name (Last, First, M) (b) (6)			Race W	Sex M	DOB (b) (6)	Age 23
Address (b) (6) HOLIDAY, FL 34690				Cell Phone:		Home Phone
Employer Name/Address					Business Phone	
Victim of Crimes 1	Height 601	Weight 0	Hair BRO	Eyes	Place of Birth	Occupation
Missing Person/Runaway Notes						

Incident/Investigation Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCY

Date Printed: 09/13/2011 11:59:38
(42529) BELLITTERA, RYAN T

Witnesses

Seq. #	Name (Last, First, M)	Race	Sex	DOB	Age
1	(b) (6)	W	F	(b) (6)	26
Address		Cell Phone:		Home Phone	
(b) (6) ST PETERSBURG, FL 33710				(b) (6)	
Employer Name/Address		Occupation: TEACHER		Business Phone	
(b) (6)				(000) 000-0000	
Witness Type					

Witness Notes

Seq. #	Name (Last, First, M)	Race	Sex	DOB	Age
2	(b) (6)	W	M	(b) (6)	22
Address		Cell Phone:		Home Phone	
(b) (6) ST PETE BEACH, FL 33702				(b) (6)	
Employer Name/Address		Occupation: STUDENT		Business Phone	
				(000) 000-0000	
Witness Type					

Witness Notes

Seq. #	Name (Last, First, M)	Race	Sex	DOB	Age
3	(b) (6)	W	F		
Address		Cell Phone: (b) (6)		Home Phone	
(b) (6) CEDAR RAPIDS, IA 52402					
Employer Name/Address		Occupation:		Business Phone	
Witness Type					
OTHER					

Witness Notes

(b) (6) is the mother and the next of kin of the victim.

Property

Incident/Investigation Report

Agency: SPPD

Case Number: 2011-056076

Date Printed: 09/13/2011 11:59:38

Report Type: ASSIST OUTSIDE AGENCY

(42529) BELLITTERA, RYAN T

Description FL DL AND MILITARY ID		Serial Number		Make/Model	
Owner (b) (6)		License / State		Color	
Status SAFEKEEPING	Status Officer (42529) BELLITTERA, RYAN T		Quantity 1	Units of Measure	Value \$1.00
Gun Type	Caliber	Finish	Grip		Gun Stock
Condition	Gun Test <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Test Type	Sight Test <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Sight Type	
Property Notes					

Jewelry Type

Jewelry Type	Metal	Karat	Gender	Style	Size	Weight
Stone 1	Stone Type	Count 0	Shape	Weight	Color	
Stone 2	Stone Type	Count 0	Shape	Weight	Color	

Assisting Officers

(24351) MAUCH, DAVID D
(25316) MCTAVISH, ALLAN C
(25744) HERRIGAN, MICHAEL D
(33212) VAUGHAN, CHRISTOPHER S
(34188) CAPRA, JOHN P
(35954) CARTER, MICHAEL W
(43028) KIMES, DAVID M
(44076) FARRELL, AUBRIE P
(45128) ZOLLOTA, VLADIMIR P

Incident Report Narrative

This report was written by Ofc Zollota and reviewed by Ofc Bellittera

Synopsis:

=====
This report was written in reference to a call of an assist outside agency,SPFD, at (b) (6) A witness, (b) (6) had called the 911 operator, informing them of a scuba tank explosion inside the apartment. Upon my arrival, the victim (b) (6) had already been transported to St Pete General Hospital and pronounced dead at 0716 hours by Dr. Kurusz. (See Ofc Mauch Supplement) The scene had been secured by the initial units arriving to the crime scene. SPFD was present at the scene. A technician was notified to process the scene and photographs were taken. A/Sgt Vaughan and Detective Tower were present at the scene. The victim's family was notified by Cedar Rapids PD. The Medical examiner office was notified and all the necessary information was provided to the Medical examiner's office.

Scene Description:

Report: r_lw1ni.frx

Page 3 of 11

09/13/2011 11:59:39

Incident/Investigation Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCY

Date Printed: 09/13/2011 11:59:40
(42529) BELLITTERA, RYAN T

Incident Report Narrative

The incident occurred at (b) (6). The single story apartment complex is located on the north side of (b) (6). The front door faces west. The building is painted beige with burgundy roof top and burgundy brick corners. There are pieces of broken glass and broken drapes across the parking lot located west on the building. There are two vehicles parked in front of the apartment. One of the vehicles, FI tag (b) (6) has the drivers side window broken and pieces of broken glass from the apartments window all over the hood. The front door of the apartment had been blown apart as the result of the explosion. There are large amounts of blood inside and outside the front door. There were other scuba tanks on the hallway and living room floor. The hallway grants entry to a large living room. A closet is located on the south wall of the hallway. The scuba tank that exploded was located inside the closet. The bedroom is located to the north of the hallway and the kitchen to the south of the hallway. The south and east bedroom walls are demolished. The glass of the bedroom window which faces west is broken. The north kitchen wall is demolished as well. There are pieces of wood and dry wall debris all over the apartment. Half of the ceiling above the bedroom and the kitchen had fallen down. An exploded scuba tank was hanging from the kitchen ceiling. The explosion has caused the living room window to brake as well. There are pieces of broken glass on the grassed area in the back of the apartment. The back door of the apartment facing east is also damaged and hanging only by the top hinge. (b) (6) is located to the north of where the explosion occurred. The living room window of (b) (6) which faces east, had been broken as the result of the explosion.

As a result of the explosion the victim had lost his right thumb and had a laceration along his right wrist. The bottom of his left foot was shattered in pieces and his upper part of his right leg was cut open with the muscle showing.

Witness Statement- (b) (6)

(b) (6) resides at (b) (6). She advised the victim, herself, and (b) (6) were going to scuba dive today. She advised the victim was a scuba diving instructor. (b) (6) advised the victim, (b) (6) had filled the tanks sometime this week with regular air. As they had finished eating breakfast this morning at approximately 0645 hours, (b) (6) had gone to the bedroom and (b) (6) was in the bathroom. She advised the victim advised he wanted to check the tanks which were located inside the hallway closet. As she entered the bedroom door, she heard a loud explosion coming from the hallway. She asked (b) (6) to call the 911 operator and ran east towards the living room window. She climbed the window, walked around the building and saw the victim laying on the hallway floor. Shortly after SPFD had arrived and the victim was transferred to St Pete General.

Witness Statement- (b) (6)

(b) (6) was a friend of the victim. He advised he had gone scuba diving twice with the victim and that the victim was a scuba diving instructor. He advised after they had eaten breakfast, (b) (6) went in her bedroom and he went to the bathroom. At that time the victim stated he was going to check the scuba tanks which were located inside the hallway closet. As he entered the bathroom he heard a loud explosion coming from the hallway. (b) (6) advised the bathroom door opened as a result of the explosion. He then called the 911 operator. He advised (b) (6) ran towards the back of the apartment and exited through the window. He ran outside of the apartment as he was speaking to the 911 operator. He advised the victim was lying on the ground asking for help when SPFD arrived.

Officers Action and Observations:

On the above date and time I was dispatched to (b) (6) in reference to a call assisting SPFD. Upon arrival I met with other officers that had already responded and secured the scene. A scuba tank had exploded inside the apartment. The victim had been transported to the St Pete General Hospital and had been pronounced dead at 0716 hours by Dr. Kurusz. I spoke with the witnesses and obtained their above captioned statements. I then drove to St Pete General Hospital and verified the victim. A technician responded to the scene and to the hospital and photographs were taken. I located the victim's mother, (b) (6) who is the next of kin. Echo channel notified Cedar Rapids PD, where the mother lives, and two officers from the Cedar Rapids PD notified her. I contacted the Medical examiners office and informed him of the incident and provided him with all the information. I also received a phone call from the brother of the victim, (b) (6) and answered his questions. I spoke with the mother of the victim. She advised that the victim was a certified scuba diving instructor. I also received a phone call from the father of the victim, (b) (6) I answered his questions and he was advised about the outcome of the accident. A representative from FDLE arrived at and took control of the scene of the accident. All the other scuba tanks inside the apartment were emptied. I left the scene and took no further action at this time.

EOR

Incident/Investigation Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCY

Date Printed: 09/13/2011 11:59:45
(42529) BELLITTERA, RYAN T

Supplemental Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCY

Date Printed: 09/13/2011 11:59:45
(28191) BURCH, MICHAEL J

Supplement Information

Supplement Date 09/11/2011 07:30:00	Supplement Type FOLLOW UP	Supplement Officer (28191) BURCH, MICHAEL J
Contact Name		
Case Status: FURTHER INVESTIGATION	Case Disposition:	

Supplement Narrative

On today's date 09/11/2011, I was dispatched to (b) (6) to assist mid-night officers. Upon my arrival, I was advised to stand by the rear of apartment number (b) (6). I was assigned with rear security until the scene was cleared.

I took no further actions.

E.O.R.

UNAPPROVED**Supplemental Report**

Agency: SPPD

Case Number: 2011-056076

Date Printed: 09/13/2011 11:59:46

Report Type: ASSIST OUTSIDE AGENCY

(33584) NIKOLOV, EMIL

Supplement Information

Supplement Date 09/11/2011 14:27:26	Supplement Type FORENSIC TECHNICIAN REPORT	Supplement Officer (33584) NIKOLOV, EMIL
Contact Name		
Case Status: FURTHER INVESTIGATION	Case Disposition:	

Supplement Narrative

I RESPONDED TO A AOA AT (b) (6) WHERE I TOOK 158 PHOTOS OF THE SCENE.

CLOSE UPS WERE TAKEN OF ALL AIR TANKS.

MESUREMENTS WERE TAKEN OF DUBREE OUTSIDE OF RESIDENCE.

THE FRONT SCREEN DOOR WAS 116 FT. FROM THE RESIDENCE.

THE FRONT WINDOW SCREEN WAS 37 FT. FROM RESIDENCE

A METAL PANEL WAS 51 FT. FROM RESIDENCE.

THE REAR WINDOW SCREEN WAS 18 FT. FROM RESIDENCE

THE REAR WINDOW BLINDS WERE 37 FT. FROM RESIDENCE.

Supplemental Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCY

Date Printed: 09/13/2011 11:59:47
(24351) MAUCH, DAVID D

Supplement Information

Supplement Date 09/11/2011 14:30:07	Supplement Type FOLLOW UP	Supplement Officer (24351) MAUCH, DAVID D
Contact Name		
Case Status: FURTHER INVESTIGATION	Case Disposition:	

Supplement Narrative

WRITER RESPONDED TO "ST. PETE GENERAL HOSPITAL" ,AS RELIEF FOR OFFICER KIMES, AT 0810HRS.

THE VICTIM "(b) (6)" WAS PRONOUNCED BY DOCTOR KURUSZ, AT 0716 HRS THIS DATE, ON HIS ARRIVAL (CHART # (b) (6))

WRITER STAYED WITH THE VICTIM UNTIL TECHNICIAN NIKOLOV RESPONDED TO PHOTOGRAPH THE VICTIMS INJURIES.

THE EMERGENCY ROOM HAD CONTATED THE "ME'S" OFFICE AND NOTIFIED THEM OF THE VICTIMS DEATH. THEY WOULD BE SENDING THEIR REMOVAL UNIT AND NOT A INVESTIGATOR.

WRITER TOOK NO FURTHER ACTION. EOR-----

Supplemental Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCYDate Printed: 09/13/2011 11:59:48
(42529) BELLITTERA, RYAN T

Supplement Information

Supplement Date 09/12/2011 11:08:24	Supplement Type FOLLOW UP	Supplement Officer (42529) BELLITTERA, RYAN T
Contact Name		
Case Status: FURTHER INVESTIGATION		Case Disposition:

Vehicles

Seq. #	Year	Color	Style	Make	Model
1	2001	ALUMINUM /...	SEDAN, 4 DOOR	HONDA	
VIN (b) (6)	License Plate Type REGULAR...	License / State (b) (6)	License Year 2012	Owner (b) (6)	
Status	Status Date	Value			
Vehicle Notes damaged in explosion					

Supplement Narrative

NARRATIVE

This is a follow-up to an assist outside agency report 2011-056076.

On 9-11-2011, Myself and probationary officer V. Zollota responded to (b) (6) in reference to an assist fire department. Dispatch advised that Fire/Rescue was responding to a possible scuba tank explosion and needed assistance. Upon arrival, several officers had secured the scene and the victim had been transported to ST Pete General Hospital in critical condition.

I spoke with (b) (6) who was inside the apartment during the explosion. He stated that he arrived at approx. 0632 hours. They were planning on going scuba diving today. Himself, the victim, (b) (6) were all eating breakfast. At approx. 0645 hours they were finished eating. (b) (6) advised he went into the bathroom. As he was going into the bathroom he remember (b) (6) saying something about going over to check the tanks but he was not sure what he said. The next thing he knew there was a loud explosion and the bathroom door came flying open. He was struck in the left ankle with debris flying through the door and received a minor cut to his ankle. He ran out the front door and called 911. He stated that (b) (6) was screaming for help.

I also spoke with (b) (6) who was also inside the residence when the explosion happened. She stated that they had just finished breakfast and she had just walked into the bedroom when the explosion occurred. She was towards the east side of the bedroom near the closet and she was able to get to the back of the apartment and climbed out. She ran to the front to help (b) (6)

After I finished speaking with (b) (6) I noted the damage to the apartment. The explosion occurred at (b) (6) This is a single story concrete building containing several apartments that is built going north and south. The front of the apartments faces west and the rear of the apartments faces east. There is a grass lawn with sidewalks leading to other apartment building east of the apartment. To the west of the apartments is a parking lot that had several cars parked in the lot. Apartment (b) (6) is the apartment where the explosion occurred. This apartment is located approx in the center of building (b) (6) To the north of (b) (6) is apartment (b) (6) A few pictures fell from inside the apartment but it received no other visible damage. To the south of (b) (6) is a hallway and a laundry room with no visible damage.

Debris including glass and the front door were found to the west of the apartment in the grassy area between the building and the parking lot. There was also debris in the parking lot and the storm door was located approx 75 ft to the west of the apartment on sidewalk. There was also glass and debris approx 50 ft east of the apartment in the grassy area and sidewalks behind the apartment.

The inside of the apartment suffered severe damage. Inside the front door there was a large amount of debris. The scuba tanks were

Supplemental Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCY

Date Printed: 09/13/2011 11:59:51
(42529) BELLITTERA, RYAN T

Supplement Narrative

located just inside the front door to the south where a closet was located prior to the explosion. That closet was now missing along with the wall to the south and the ceiling had collapsed to the apartment over this area but not to the building. The roof to the building was still intact but there was a gap between the ceiling to the apartment and the roof of the building. To the north of the hallway inside the front door was the bedroom. The wall to the bedroom had collapsed. The victim was located just inside the front door. The southwest corner of the apartment contained the kitchen which was next to where the explosion occurred. The oven had been flipped on its side and there was severe damage and debris throughout the entire kitchen. There were two additional tanks located at the east end of the hallway. To the east of the hallway was a dining room then a living room. There was debris throughout this area but the damage was not as severe as the kitchen and front hallway/bedroom.

By this time, A/Sgt. Vaughn, Lt. Gatlin and Det. R. Tower had all arrived on scene and Det. Tower continued the investigation.

Myself and Ofc. Zollota the responded to St. Pete General to investigate the injuries received to (b) (6) (b) (6) received severe trauma to his left foot. Most of the foot was missing with several bones exposed. Both of his legs had abrasions and what appeared to be burns. The burns did not have any blackening from a fire but the skin appeared to be melted in some areas on the legs. His upper right leg and thigh had severe trauma. A severe laceration sliced through his leg muscle which was only attached to the upper portion of his leg. His right thumb was severed and he had a severe laceration to his right wrist just above the thumb that exposed his bone. There was no visible injury to his head chest and left arm.

We then responded back to the scene. Myself and several other officers established the perimeter around the apartment for safety reason because the condition of the remaining tanks were not known. The Tampa bomb squad arrived on scene and made the remaining tanks safe. (Tampa Report number 2011-511428.) Det Tower and the fire investigators continued their investigation. Myself and ofc. McTavish documented the tanks.

There were a total of 11 scuba tanks found within the apartment and 1 oxygen tank found in the vehicle. The Fire investigators removed 9 including the destroyed tank and placed them outside of the apartment. Two tanks were left inside the apartment and one tank was located inside the victim's vehicle. Those tanks were as follows:

Tank #1: Small Black tank bearing a 100% oxygen label. Decompression use only.

Certified by Scuba West sticker date 12/2010 727-863-6911

Yellow sticker tank and valve cleaned sticker Prerr.ix, oxygen 22%-40% 12/2010
stamped MOD 20 FSW MOD 6MSW

Tank #2: Medium size yellow tank bearing Aqua Lung

Certified by Scuba West 10/2010

Nitrox green label stamped 5/93

tank and valve cleaned sticker Prerr.ix oxygen 22% - 40% 10/2010

Tank #3 Medium sized Dk silver tank

Certified by Scuba West 4/2011

tank and valve cleaned sticker Prerr.ix oxygen 22%-40% 4/2011

Stamped TC-SU4957-230 BAR DOT # F14157-3442 TP 5250 10/06

Tank #4 Medium sized light silver tank stamped Japan

Certified by Scuba West 2/2011

tank and valve cleaned sticker Prerr.ix oxygen 22%-40% 3/2011

DOT-SP120793442 TP 5250 SPUN Japan 2/08

Tank #5 Small yellow tank Stamped AIR

Certified by Scuba West 4/2007 stamped VanHorn

DOT 3Al#000 CB 000 9036 M400215C14 Catalina

519TCBALM207

Tank #6 Medium gray tank Luxfer

Certified by Scuba West 12/2010

Seatasea sticker 3/2010

Cedar Rapids Iowa Hydrotested Marine Services Chylau Dista California 619-422-8918 07/2009

DOT-3AL3000 P343454 7/09 12A97580

Tank #7 Medium sized Dk gray tank

Certified by SCuba West 04/2011

TC SU4957-230BAR DOT-F14157-3443 TP 5250 10/06

unreadable stickers also

Supplemental Report

Agency: SPPD

Case Number: 2011-056076
Report Type: ASSIST OUTSIDE AGENCY

Date Printed: 09/13/2011 11:59:54
(42529) BELLITTERA, RYAN T

Supplement Narrative

Tank #8 Medium sized Dk Gray tank stamped VanHorn
Certified by Scuba West 4/2010
DOT-E9791-3442 unreadable
unreadable stickers also

Tank #9 Destroyed yellow tank
Smaller section read For Decompression
prerr.ix oxygen 22%-40% unreadable month/ 2011
unreadable sticker
DOT-3AL3000 unreadable

Tank #10 Inside of vehicle green oxygen tank inside green bag
Certified by Scuba West 3/2011
Prerr.ix oxygen 22%-40% sticker 3/2011
DOT-3AL2216 HH399 M4141 01A07 DAN sticker

Tank #11 Located inside apartment.
Full size yellow tank
Certified by Scuba West 04/2011
Prerr.ix oxygen sticker 22%-40% 04/2011
Luxfur tank samped 9/2010 P30 9 LUXFUR CTC-DOT3 stamped VanHorn

Tank #12 Located inside apartment
Full size yellow tank Stamped Enriched Air
Certified by Scuba West 04/2011 Luxfur
Prerr.ix oxygen 22%-40% sticker 04/2011
CTC-DOT-3L3000- S80 stamped 9/2010

All of the above tanks were fully intact with the valves in the top except for the destroyed tank. A search inside the apartment was conducted in an attempt to locate the missing valve from the exploded tank but we had negative results. A search outside of the apartment was also conducted for the valve with negative results.

A/Sgt Vaughn advised that we could release the outer perimeter and the fire investigator and FDLE would finish their investigation. I responded to Police Headquarters and placed (b) (6) Florida driver's license and Military I.D. card into property and evidence locker #99.

I took no further action

EOR

TEST PROTOCOL

November 29, 2011

RTI Matter Name: DOT – Ruptured SCUBA Cylinder

RTI Matter No.: 50151ME002

RTI Investigators:

Richard B. Loucks, Ph.D., P.E.

Matthew Wagenhofer, Ph.D.

Background:

RTI was tasked through Government Contract DTPH56-12-P-000004, dated November 9, 2011, issued by Office of Acquisition Services US DOT/PHMSA/PHA-30 to perform an investigation on a DOT 3AL-3000 cylinder involved in a fatal accident to determine if non-compliance with Hazardous Materials Regulations played a part in the cylinder failure and if modification of the regulatory standards is necessary.

Additionally, the purpose of this contract is to evaluate the ruptured DOT 3AL-3000 cylinder valve and determine the following:

- The degree of exposure to thermal energy; and
- Evidence of oxygen contamination which may have resulted in the explosion (fire) inside the ruptured DOT 3AL cylinder.

On November 15, 2011, RTI Group, LLC (RTI) received four items from the Department of Transportation, Pipeline and Hazardous Materials Safety Administration (PHMSA). These items are described as follows:

1) Yellow high pressure gas cylinder, Part 1

Smaller fragment from the cylinder, measures approximately 12 inches by 6 inches. Fragment displays the following marks near the neck: HY-MARK DOT-3AL 3000 OU

Cylinder has one decal and part of another:

Decal 1: “Tank & Valve Have Been Cleaned For Premix, Oxygen Content 22 to 40%” is not punched out. “Tank & Valve Have Been Cleaned In Accordance With O₂ Service” Is punched out at 2011. The month is uncertain.

Decal 2 (partial): for decompression use IANTD/IAND, Inc.

2) Yellow high pressure gas cylinder, Part 2

Larger section contains the bottom, neck and valve opening, measures approximately 24 inches by 14 inches. This item has the following markings near the neck: 0001 M5442 10 07 S40 TC-3AL 207

This part of the cylinder contains the remaining portion of Decal 2 stating:

Decal 2 (partial): OXYGEN for decompression use only – MOD 20 FSW MOD 6 MSW
WWW.IANTD.COM

3) High Pressure Tank Valve, DIN Valve,

Manufactured by Genesis containing a 5000 psi, 30 lb/hr CG-1 type rupture disk. A pressure regulator adaptor is present in the opening which has a fractured outlet. The metal particle filter is evident in the opening. The rubber hand closure knob is present, but separate from the valve.

4) Regulator

Manufactured by Dive Rite, serial number 12008135, fitted with regulator fitting. The opening is occupied by the fractured end of the pressure regulator adaptor.

Attached to the regulator:

1. Black pressure line with dial gage on high pressure side of regulator. Dial gage face is heat affected and the gage is illegible.
2. Length of green pressure line stating “WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury” no manufacturer identified. Distal end terminates unattached. Low pressure side

Objective:

Under the tasking directive of the contract, sub-section 3.02 “Advanced Analysis and Examination”, as part of the investigation the evidence is to be subjected to a series of invasive, therefore destructive, examinations in which sophisticated laboratory equipment will be employed, such as Fourier Transform Infrared Spectroscopy (FTIR), Scanning Electron Microscopy (SEM), Energy Dispersive Spectroscopy (EDS), metallography, alloy chemistry, hardness testing and tension and compression testing. This protocol addresses the schedule and procedures that will be performed to fulfill this task.

Date, Time and Location:

- Tuesday, December 6, 2011 at 10:00 am pacific coast time
- ANAMET, Inc.
26102 Eden Landing Road, Suite 3
Hayward, CA 94545-3811
- Local Contact: Kenneth Pytlewski, 800-377-7768 OR Ken@Anametinc.com

Procedure:

Phase I – Initial Examination.

Document the condition of the evidence through the use of field notes and still photography. The use of optical microscopy will be used where appropriate. This process is non-destructive and is intended to document the evidence prior to any alterations.

Phase II - Search for the presence of oxygen non-compatible substances.

An examination in search for materials typically found in SCUBA dive operations, such as silicone greases found in diving gear (dimethylsiloxane), hydrocarbon greases/oils used in diving gas compressors, perfluorinated lubricants found in Nitrox diving gear, and other lubricant materials such as Tribolube (ALI Aerospace Lubricants), Christo Lube (Lubrication Technologies, Inc.), IKV-Fluor & Zarox, etc. With the use of solvents, such as: Asahiklin AK 225 (Hydrochlorofluorocarbons); DuPont Vertrel XF, DuPont Vertrel MCA (Hydrofluorocarbon); or 3M HFE 7100, 3M HFE 71DE (Hydrofluoroether), obtain samples from within the valve gas passage area and subject the samples for FTIR analysis. The solvent will be decided upon at the time of the examination.

High Pressure Tank Valve

Subject valve and regulator will have to be disassembled to reveal any existing gasket/seal materials, provide access to components for solvent washing and sample collection. With each disassembly, each component will be documented, and then the areas upstream of the containment feature will be searched for the presence of non-oxygen compatible materials. The disassembly will proceed in the following order:

1. Test the valve closure mechanism to determine if the valve is open or closed. Mark alignment of the gland nut to the valve body prior to turning with sharpie.
2. Remove the pressure regulator adaptor.
3. Remove the CG-1 burst disk pressure relief device.
4. Remove the closure mechanism. The gland nut will be removed exposing a series of gaskets and back up rings. These will be removed to gain access to the stem and the high pressure

seat. The condition of the high pressure seat will be inspected by SEM/EDS followed by solvent wash for FTIR analysis. Components will be removed until the valve body is empty.

Samples of the valve body will be obtained for chemistry analysis to determine the alloy of the materials used.

Material from the threads of the valve will be removed and inspected under the SEM. They will be removed using a pick and collected onto carbon tape for mounting on a SEM stage. Alternately, a segment section of the threads will be cut from the valve, polished and mounted, then inspected using the SEM.

Items having been separated from the parent object will be secured within a plastic container and labeled using the scheme: Part xx followed by a lower case alpha character, e.g. "Part 3-a Gland Nut".

Pressure Regulator Adaptor

The fractured surface of the pressure regulator adaptor will be examined using the SEM to determine the mode of fracture and the presence of foreign materials. The air filter cup within the adaptor will be subjected to SEM analysis to identify both the discolored material on the filter surface and any particles that may be trapped in the filter. Subsequently, the filter will be subject to a solvent wash to determine by FTIR the presence of any contaminants.

Regulator

The high pressure hose attachment will be removed and the interior of the tubing will be inspected. The low pressure tubing will be removed and inspected. The interior of the regulator will be inspected to the extent possible from the open ports. If possible, a solvent swab will be taken through a high pressure port and subject to FTIR to determine the presence of contaminants. If contaminants are present, the regulator will be dismantled.

Tank Material

Internal surfaces of the tank will be examined for the presence of oxygen non-compatible substances. Solvent washing of the internal area will provide samples for FTIR analysis in four areas, indicated as areas “A”, “B”, “C”, and “D” and any other areas deemed of interest on the day of the examination.



Figure 1. Solvent was areas for FTIR sampling.

Phase 3 – Mechanical properties testing of Cylinder material.

Several sections of the cylinder will be subjected to hardness testing, alloy chemistry, metallographic analysis and tension and compression testing.

Hardness traverses following the inner circumference of the tank will be made at several elevations along the length of the tank. The approximate elevations are indicated in Figure 2. The method of testing will be as follows:

1. Four sections of cylinder material of approximately 2 inches wide by 1 inch deep will be excised from the main body with the use of a liquid cooled diamond blade saw.
2. After removing the section from the main body, a ½ inch axial wide circumferentially cut section will be removed for subsequent metallographic mounting, polish and etch. This creates two sub-sub sections for evidence labeling where a lower case Roman numeral will be added to the nomenclature, e.g. “Part 1-a-i Excised section from Cylinder, Metallographic” and “Part 1-a-ii Hardness Specimen from cylinder”. See Figure 3.
3. The fracture surface from the larger section will be examined using the SEM to determine from the fracture morphology the mode of fracture, direction of crack propagation, EDS, and any other information discovered in the examination. The section will then be subjected to a Rockwell hardness test on the internal surface, not directly on the fracture surface.
4. The smaller section will be cast into a resin material with the cut surface including the fracture surface for examination. The specimen will be polished, then etched to allow examination of the grain structure. A profile of Knoop micro hardness tests will be performed at 1mm intervals in two directions: circumferentially along the mid thickness from the fracture surface for 1.5 cm; and along the radial from the internal to the external surface.



Figure 2. Approximate test sites for hardness testing and metallographic examination.




Figure 3. Hardness testing and Metallographic sectioning. ⊗ illustrate Knoop micro hardness locations along the traverse. (not to scale)

Tension and compression testing will be performed to determine the mechanical properties of the alloy. Sample material will be collected from the machined samples for chemical analysis to determine the aluminum alloy.

The tension and compression tests will be performed as follows. A spherometer will be used to measure the radius of curvature of the tank in its as-received condition. Baseline inner surface curvature measurements will be made on the intact bottom region of the tank. Further inner surface curvature measurements will be made along the length of the tank over all of the regions to determine the least

deformed section of the tank. Visual inspection of the as-received tank indicates that this section is likely to correspond to that indicated in Figure 3. At least one (1) tension test specimen and two (2) compression test specimens will be machined from this region. The tension test specimen will be oriented such that the tensile axis of the specimen is parallel to the longitudinal axis of the tank. One of the compression specimens will be oriented such that the compression axis is parallel to the radial axis of the tank. The other compression specimen will be oriented such that the compression axis is parallel to the transverse axis of the tank. The transverse axis is defined by a line tangent to a circumference around the tank located at the midpoint of the tank wall. Any additional specimens for which there is sufficiently un-deformed material will duplicate these three orientations.

Dental mold compound will be used to make highly accurate replicas of the threads inside the neck of the tank prior to sectioning and mounting of the threads for metallographic and microscopic analysis. It is anticipated that the entire circumference of the threads will be replicated in two to four sections to ease removal of the molds from the inner threaded surface of the neck. Sufficient overlap will be included at both ends of each section so as to retain all details available. Measurements such as pitch, thread root depth, etc. will be made from the molds, if possible. The process will start by subjecting a portion of the threaded area to a solvent wash, the samples then subjected to FTIR analysis. Then the molding compound will be applied in quadrants with greater than 90 ° coverage. The boundaries will be indicated on the opening rim with a Sharpie and the molds labeled following the stated nomenclature.

Once the thread mold profiles are completed, the opening will be sectioned to allow SEM/EDS examination of the threaded section and subsequent metallographic mounting. A section, comprising of no more than 30 ° of radial opening on the section opposite that material still attached to the cylinder body will be sectioned. The section will be subject to SEM/EDS examination to resolve the thread/root regions for contaminants and other information. The section will then be mounted with the cut surface exposed for examination, polished and etched to reveal the grain structure, and examine for contaminants trapped beneath smeared or swaged aluminum.

Phase 4 – Collection of Evidence, logging and

retrograde. Each item will be double checked to ensure it has been catalogued, logged, and properly packaged for storage. All graphs, apparatus created images, and measurements will be compiled for use in the final report.

About RTI Group, LLC

The RTI Group, LLC is a pioneering, global accident and failure investigation and safety management consultancy serving the legal and insurance markets. With origins dating back to 1975, RTI's forensic engineering services span comprehensive high-risk industries and transportation operations disciplines, including aviation, marine, rail, utilities, nuclear, explosion, and construction.

Headquartered in Annapolis, Maryland, RTI Group, LLC was founded in 2003 as a forensic engineering services company, with its origins dating back to 1975, by the founder of FTI Consulting, Inc. Anamet Inc., a forensic materials testing laboratory in San Francisco, California became a vital asset to RTI in 2003. In 2004, RTI founded its London office, RTI Ltd., as a wholly owned UK subsidiary that is the home office of the Aviation and Marine Departments. RTI Latin America was established in 2008 in Panama City, Panama as an extension of the London office to serve Latin America and, in particular, the Panamanian Flag State and Canal Operations. RTI opened its Bahrain branch office in April of 2011 to provide security and safety services, as well as access to other RTI disciplines in the Gulf and Middle East region. RTI continues to expand its worldwide range of analytical capabilities and services to other parts of the globe.



RTI Group, LLC
910 Bestgate Road, Suite E
Annapolis, MD 21401
ofc: +1 410 571 0712 | fax: +1 410 571 0713
www.rtiForensics.com

DOT Requested Analysis
of
Failed SCUBA Cylinder/Valve Assembly

Report Date
August 29, 2012

DOT Contract
No. DTPH56-12-P-000004

RTI Matter
No. 50151.ME002

Prepared and Submitted By:

Richard B. Loucks, PhD, PE
Senior Mechanical Engineer

Matthew Wagenhofer, PhD
Mechanical Engineer

Reviewed By:

Thomas W. Butler, PhD
Senior Materials Engineer

Joseph R. Reynolds, PE, MEWI, MAE
Principal Forensic Engineer

Table of Contents

	<u>Page No.</u>
1.0 INTRODUCTION/BACKGROUND	4
2.0 PURPOSE	5
3.0 INVESTIGATION	6
3.1 Standards, Codes, and Open Literature	6
3.2 Evidence Description	8
3.3 Evidence Inspection Observations	9
4.0 LABORATORY TESTING.	16
4.1 Unpacking Evidence	16
4.2 Disassembly and Visual Inspection	17
4.3 SEM Examination	31
4.4 Mechanical Testing and Metallography	35
4.5 Chemical Analysis	41
5.0 DISCUSSION	44
5.1 Origin of the Explosion	44
5.2 Ignition Mechanism	50
5.3 Cylinder Compliance with the Federal Regulations	51
6.0 CONCLUSIONS	55

Table of Contents continued

ATTACHMENTS

1. Test Protocol
2. Evidence Receipt Photos
3. Exemplar Valve Photos
4. Exemplar Regulator Photos
5. Testing Sign-in Sheet
6. Photographs from Anamet Testing
7. EDS Spectra and Tables
8. FTIR Spectra and Tables
9. Micrographs HF and Kellers Etch
10. Microhardness Testing
11. Tensile and Compression Testing
12. SEM Images
13. Inspection Photos of June 8, 2012
14. Surface Curvature Measurements
15. Cylinder Valve Markings
16. Chain of Custody

1.0 INTRODUCTION/BACKGROUND

It was reported to RTI Group, LLC (RTI) that an Open Circuit Self-Contained-Underwater-Breathing-Apparatus (SCUBA) cylinder, valve assembly, and regulator were involved in an explosion. It was reported that the source of the explosion was the high pressure gas cylinder failing. The incident cylinder had been filled with high purity oxygen, and the explosion had resulted in a fatality and extensive property damage, both from blast effects and a fire. Since the SCUBA cylinder had been certified under regulations promulgated by the U.S. Government, the evidence recovered by the St. Petersburg Police was transferred to the United States Department of Transportation (DOT), Pipeline and Hazardous Materials Safety Administration (PHMSA), Office of Hazardous Materials Safety. Reference is made to the Code of Federal Regulations (CFR), Title 49, Parts 173 and 178.

2.0 PURPOSE

RTI was tasked through Government Contract DTPH56-12-P-000004, dated November 9, 2011, issued by Office of Acquisition Services US DOT/PHMSA/PHA-30, to perform an investigation of the evidence recovered from the subject incident to determine if non-compliance with Hazardous Materials Regulations played a part in the cylinder failure and if modification of the regulatory standards would be necessary.

Additionally, the purpose of this contract is to evaluate the ruptured DOT 3AL-3000 cylinder valve and determine the following:

1. the degree of exposure to thermal energy; and
2. evidence of oxygen contamination which may have resulted in the explosion (fire) inside the ruptured DOT 3AL cylinder.

Under the tasking directive of the contract, sub-section 3.02 “Advanced Analysis and Examination”, as part of the investigation the evidence was to be subjected to a series of invasive, therefore destructive, examinations in which specific laboratory equipment would be employed, such as Fourier Transform Infrared Spectroscopy (FTIR), Scanning Electron Microscopy (SEM), Energy Dispersive Spectroscopy (EDS), metallography, alloy chemistry, hardness testing, and tension and compression testing.

Once completed, the evidence from physical examination and the results of the laboratory tests were subjected to an engineering evaluation to, if possible, determine the degree of exposure to thermal energy, and determine if there was evidence of contaminants or materials incompatible with oxygen that may have resulted in the incident.

3.0 INVESTIGATION

RTI performed the following: evidence inspection upon receipt on November 15, 2011; laboratory inspection of the evidence March 12-14, 2012, documented in field notes and with photographs; inspection of exemplar cylinder valves and regulator; review of the literature sources listed below; and engineering analysis.

3.1 Standards, Codes, and Open Literature

3.1.1 Standards and Codes:

- a) ASTM E 8M Test Method for Tension Testing of Metallic Materials.
- b) ASTM E9 Standard Test Method of Compression Testing of Metallic Materials at Room Temperature.
- c) ASTM G 88 Standard Guide for Designing Systems for Oxygen Service.
- d) ASTM G 93 Standard Practice for Cleaning Methods and Cleanliness Levels for Material and Equipment Used in Oxygen-Enriched Environments.
- e) ASTM G 94 Standard Guide for Evaluating Metals for Oxygen Service.
- f) Code of Federal Regulations, Title 49, Part 173 (Subpart G: Preparation and Packaging) and Part 178 (Subpart C: Specifications for Cylinders).

3.1.2 Open Literature

- a) "Guide for Oxygen Compatibility Assessment on Oxygen Components and Systems," K. Rosales, M. Shoffstall, J. Soltzfus, NASA/TM-2007-213740, March 2007.
- b) "U.S. Navy Diving Manual," SS521-AG-PRO-010 Revision 6, 0910-LP-106-0957, April 15, 2008.
- c) Handbook of Compressed Gases, Third Edition, Compressed Gas Association, Inc., Chapman & Hall, 1990.
- d) "Introduction to Aluminum Alloys and Tempers", Kaufman, G.J., ASM International, Materials Park, 2000.
- e) "Copper-Aluminum Interaction in Fire Environments", B. Beland, C. Roy, and M. Tremblay, Fire Technology, Vol. 19, Number 1, 1983, pages 22-30.

3.2 Evidence Description

On November 15, 2011, RTI Group, LLC (RTI) received four items from the Department of Transportation (DOT), Pipeline and Hazardous Materials Safety Administration (PHMSA). These items are described as follows:

3.2.1 Yellow high pressure gas cylinder fragment, Part 1

Smaller fragment from the incident cylinder; measures approximately 30 cm by 15 cm and weighs 760 gm.

3.2.2 Yellow high pressure gas cylinder fragment, Part 2

Larger section contains the bottom, neck, and valve opening; measures approximately 60 cm by 35 cm and weighs 6,137 gm.

3.2.3 High Pressure Cylinder Valve, DIN Valve

A chrome coated metal cylinder valve with the brand “Genesis” present on the front. A pressure regulator adaptor was present in the cylinder valve outlet opening with a fractured outlet. The rubber hand closure knob was present, but separate from the valve.

3.2.4 Pressure Regulator

A cylindrical metal device having a length of 6 cm and a diameter of 4.5 cm. Attached to the regulator were:

1. Black pressure line with dial gage on high pressure side of regulator.
2. Length of green pressure line. Distal end terminates unattached.

3.3 Evidence Inspection Observations

The received evidence was inspected and photographed to document the condition in which it was received. A receipt form was executed to preserve the Chain of Custody.

3.3.1 Yellow high pressure gas cylinder, Part 1

The smaller fragment from the cylinder measured approximately 30 cm by 15 cm, and is seen in **Figure 1**. This fragment contained a portion of the upper part of the cylinder proximate to the threaded opening. The fragment was clearly fractured by a catastrophic overload failure. In the portion near the cylinder opening, the fracture transitioned into a melted/eroded area where the material appeared to have eroded or “flowed” from the interior surface of the cylinder. The erosion was most extensive at the fracture where the cylinder wall was very thin, almost terminating into a sharp edge, with increasing thickness towards the non-eroded area. The flow patterns suggest that the eroded material flowed out of the crack formed in the cylinder wall, as well as out of the valve opening. The remaining cylinder interior surface was otherwise unremarkable. The curvature of the fragment was measured using a spherometer, and resulted in a reading of up to 200 mm near a portion of the interior fracture surface, compared to the original radius of curvature of 57 mm.



Figure 1. Smaller portion of high pressure gas cylinder

Along the base of the hemispherical connection were displayed the following marks near the neck:

HY-MARK

DOT-3AL 3000 OU

This is an incomplete DOT cylinder marking scheme. The remainder of the markings was found on the larger portion of the cylinder.

The cylinder fragment had on its exterior surface a full decal and part of another. The first decal, seen in **Figure 2**, appears like that used by the International Association of Nitrox and Technical Divers (IANTD), as seen in **Figure 3**, which states if the decaled cylinder has been cleaned for use with Nitrox¹ or Oxygen.

The remaining legible content of the label indicated the “Tank & Valve Have Been Cleaned For Premix, Oxygen Content 22 to 40%” was not punched out, while the “Tank & Valve Have Been Cleaned In Accordance With O₂ Service” was punched out at 2011. The month is obscured. There is no indication as to who may have stamped and applied the decal, or as to what procedure was followed to certify the cylinder was properly cleaned.

¹ Nitrogen-oxygen (NITROX) diving is a unique type of diving using nitrogen-oxygen breathing gas mixtures ranging from 75 percent nitrogen/25 percent oxygen to 60 percent nitrogen/40 percent oxygen. *U.S. Navy Diving Manual*, Chapter 10.




Figure 2. Label on smaller fragment.



Figure 3. Decal label from International Association Nitrox and Technical Divers²

² <http://www.iantd.com/decals.html> , D-3207. The web page does state that “These decals are available ONLY to Blenders or Facilities with Certified Blenders on staff.”

Only a small portion of the second decal was visible, and stated “for decompression use IANTD/IAND, Inc.”

3.3.2 Yellow high pressure gas cylinder, Part 2

The larger fragment of the high pressure gas cylinder, seen in **Figure 4**, contained the bottom, neck, and valve opening portions.



Figure 4. Larger portion of high pressure gas cylinder

A similar erosion pattern to that found on the smaller fragment was seen near the opening at the top. Facing the interior surface with the opening up, the inside surface to the left of the opening had significant erosion extending about 20 cm below the top before transitioning to a fracture. The threads in the opening were clearly stripped with only part of the thread root visible. The pattern of erosion within the opening was uneven in depth and texture, and was different around the opening compared to along the cylinder side towards the fractures. The opening had a stippled texture whereas the areas away from the opening had distinct flow lines with perpendicular waves.

The exterior surface exhibited evidence of heat effects and darkened coloration near the cylinder top. The normally yellow paint is discolored to brown, with black material (soot) found on some of the fracture surface.

This item had the following markings near the hemispherical connection to the cylindrical body:

0001 M5422 10 07 S40 TC-3AL 207

These, together with the stamped markings found on the other fragment, create the complete DOT marking scheme as follows:

DOT-3AL 3000 OU0001 M5422 10 07 S40 TC-3AL 207 HY-MARK

These complete markings indicate as follows³:

DOT-3AL – This is a Department of Transportation regulated seamless cylinder made from definitely prescribed aluminum alloy requiring a minimum service pressure of 150 psig, and a maximum water capacity of 1000 lb.⁴

3000 – is the maximum service pressure in psi.

OU0001 – is the manufacturer’s serial number.

M5422 – is the DOT PHMSA “M” or manufacturer’s identification number. This number indicates the manufacturer was Hy-Mark Cylinders, Inc. of 305 E. Street, Hampton, VA 23661, approved June 5, 2000.

10 07 – is the originating hydrostatic test date, October 2007

S40 – indicates the cylinder is intended for SCUBA use, and can hold compressed gas that has a volume of 40 ft³ of air at standard pressure and temperature conditions.

TC-3AL 207 – indicates the cylinder is also compliant with the Transportation Canada, identified as a 3AL container with service pressure to 207 Bar.

HY-MARK – is the manufacturer’s symbol, again consistent with Hy-Mark Cylinders. Hy-Mark Cylinders, Inc. was purchased by Worthington Industries, Inc. (NYSE WOR) on June 21, 2010.⁵

This part of the cylinder contained the remaining portion of the second decal stating “OXYGEN for decompression use only – MOD 20 FSW MOD 6 MSW⁶ WWW.IANTD.COM”. The label

³ *Handbook of Compressed Gases*, Chapter 4.

⁴ 49 CFR 178.46(a).

⁵ <http://www.worthingtonindustries.com/>

⁶ Maximum Oxygen Depth-MOD, Feet Submerged Water-FSW, Meters Submerged Water-MSD.

indicated that the purpose of this cylinder was for oxygen use during the latter stage decompression from extremely deep diving.

3.3.3 High Pressure Cylinder Valve, DIN Valve

A label stamped into the body indicated the incident cylinder valve was manufactured by Genesis and contained a 32.6 MPa (5000 psi, 30 lb/hr) CG-1 type rupture disk. A pressure regulator adaptor was present in the opening containing a fractured outlet. A metal particle filter was evident in the opening. The rubber hand valve closure knob was present, but separated from the valve, as seen in **Figure 5**.




Figure 5. View of cylinder valve, a) front, b) back

3.3.4 Pressure Regulator

The incident pressure regulator was manufactured by Dive Rite, serial number 12008135. The high pressure inlet opening was occupied by the fractured end of the pressure regulator adaptor, see **Figure 6**. Attached to the regulator were:

- A black pressure line with dial gage on high pressure side of regulator; dial gage face is heat affected and the gage is illegible.
- A length of green pressure line stating “WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury”; no manufacturer was identified.



Figure 6. Cylinder valve, cylinder valve adapter, regulator and regulator assembly.

The green line was discolored (lightened to yellow white) proximate to the regulator, indicating possible exposure to high heat. There were no indications of melting or combustion. The distal portion of the outlet line was bright green and terminated without the anticipated second stage regulator.

4.0 LABORATORY TESTING

On March 12, 2012, RTI traveled to the laboratories of Anamet, Inc., an affiliated RTI company, for the purpose of conducting a laboratory examination of the incident scuba cylinder fragments, cylinder valve, and regulator, as well as an exemplar cylinder valve. RTI prepared a protocol, dated November 29, 2011, as found in **Attachment 1**, which served as the guide for all investigative activities conducted over the three day examination. The examination, which included both nondestructive and destructive procedures, was also documented by way of both still photography and videography.

4.1 Unpacking Evidence

The container of evidence, shipped from RTI's Annapolis, MD offices, remained sealed until commencement of the examination on March 12, 2012 when all attending parties were present. Items were packaged individually as seen in **Figure 7**.



Figure 7. View of the individually packaged evidence items at Anamet after removal from the shipping container.

4.2 Disassembly and Visual Inspection

The incident cylinder valve, an exemplar cylinder valve, and the incident regulator were disassembled and photographed prior to further inspection and examination of the constituent components of each.

4.2.1 Exemplar Valve

The exemplar cylinder valve, shown in **Figure 8**, has four distinct sections. Proceeding from the left side of the valve in a clockwise direction they were: the valve stem assembly and housing, the high pressure regulator fitting, the pressure burst disk assembly, and the threaded cylinder attachment with a pick-up tube.



Figure 8. Front view of the exemplar cylinder valve. The valve stem assembly and housing is concealed by the black valve handle.

RTI first loosened and removed the locking nut securing the hard rubber valve handle grip in place. With the nut removed, the grip slid off of the 7.34 mm long threaded portion of the valve

stem. Between the threaded rod and the main portion of the valve stem, a square cross section was present that provided the rubber valve handle a means for turning the valve stem. A gland nut with a smooth center bore secured the valve stem inside the valve body. The smooth bore provides for free rotation of the valve stem. An O-ring, 1.28 cm in diameter, served to seal the connection between the gland nut and the valve body, see **Figure 9**. RTI removed this nut to expose the valve stem. As it is not secured by any part other than the nut, it could be removed from the valve body simply by pulling it straight out.



Figure 9. Rear view of the partial exemplar valve stem assembly showing the gland nut, O-ring, and valve stem.

Upon removal, RTI observed the stem to be covered in a white grease-like substance, and that it incorporated two polymer bushings and two O-rings, see **Figure 10**. The stem ended in a square mandrel approximately 8.53 mm long. RTI observed the inner wall of the portion of the valve body, within which the valve stem resides, to be threaded. A threaded, square bored valve seat

body resided at the inner end of this portion of the valve body. RTI removed it by reinserting the valve stem and rotating counter clockwise to unthread the valve seat body. Once removed, the valve seat body appeared to be made of bronze with a black colored coating over most of the surface area. **Figure 10** shows the valve seat body and provides orientation. The interior end incorporated a plastic valve seat.



Figure 10. Rear view of the fully disassembled exemplar valve stem assembly showing the valve seat body and its orientation in the assembly.

Referring to **Figure 11**, RTI next removed the pressure burst disk assembly, which consists of a hollow threaded plug, a 34.1 MPa (5000 psi) burst disk, and retaining rings. Threads on the plug stop short of the head by approximately 2.411 mm. The head of the plug is bored through, presumably to allow a dispersed release of excess high pressure gas should the burst disk fail. **Figure 12** shows the burst disk and retaining ring as installed in the plug. Markings on the outer surface of the assembly head indicate that the assembly is to be installed with 40.7 N-m (30 ft-lb) of torque.



Figure 11. Rear view of the exemplar pressure burst disk assembly as removed from the valve body.



Figure 12. View of the exemplar pressure burst disk assembly showing the burst disk and retaining ring.

Finally, RTI removed the threaded protective insert into the high pressure regulator port. Removal of the insert revealed a shallow threaded bore leading to a gas supply rectangular opening proceeding down into the center of the cylinder valve body, indicated by the in **Figure 13**. Additionally, RTI observed a 1.9 mm diameter vent hole on the right side of the high pressure regulator port, indicated in **Figure 13**. This vent is approximately 7.42 mm forward of the rear inner surface of the port such that it is closed off when a fitting is fully threaded into the port.



Figure 13. Front view of the exemplar cylinder valve showing the high pressure regulator port.

The cylinder attachment consists of a straight threaded insert with an 8.05 mm diameter, 4.01 cm long dip tube fit into a center bore, see **Figure 8**. The nominal thread diameter and pitch measured as approximately 25 mm with a 2 mm pitch (1.035 inches and 13 tpi), respectively. An O-ring is provided at the cylinder mating surface.

Further detailed examination of the disassembled cylinder valve body revealed information about the path of high pressure gas from the cylinder through the valve. With the valve handle in the fully closed (inserted) position, high pressure gas flowing from the cylinder proceeds up through the pick-up tube and is directed against the valve seat to the left and the pressure burst disk to the right. As the valve is opened, the gas is allowed to flow past the valve seat and makes its way to the regulator port. This is accomplished by way of an angled bore connecting the valve stem bore to the regulator port. The rectangular cutout visible inside the regulator port is the outlet of

the angled bore. The external housing of the angled bore is indicated in **Figure 14** showing the rear view of the exemplar valve.




Figure 14. Rear view of the assembled exemplar cylinder valve showing the angled bore housing that connects the high pressure regulator port to the valve system assembly chamber.

4.2.2 Incident Valve

As shown in **Figure 5**, the incident valve was received with several parts missing from the valve including the locking nut; the rubber valve handle (present but damaged and no longer attached); the threaded and square segment of the valve stem to which the handle attaches (this appeared to have separated from the main body of the valve stem leaving a square fracture surface); the dip tube; and a significant portion of the cylinder neck opening threads. The entire exterior of the incident valve and its installed components appeared charred and roughened compared to the exemplar valve.

RTI began the disassembly process of the incident valve by removing the gland nut, shown in **Figure 15**, with a torque wrench fitted with an appropriately sized socket in order to measure the installation torque. The gland nut was found to be threaded into the valve body approximately finger tight as measurements showed zero installation torque. The nut made four and one sixth turns before clearing the valve body. An intact O-ring similar to that found in the exemplar remained in its intended position on the gland nut.



Figure 15. View of the incident cylinder valve gland nut showing the presence of the intact O-ring.

Removal of the gland nut allowed access to the valve stem and the valve seat body. As shown in **Figure 16**, the incident valve stem was very similar in appearance to the exemplar although one of the bushings was different in color. Compared to the exemplar valve seat body in **Figure 17**, the incident valve seat body displayed a different color coating. The incident valve seat was also coated with some material, but with a green color. All portions of the incident gland nut, the

stem, the valve seat body, the plastic valve seat, and the interior of the valve stem portion of the valve body were further notable in that they were free of any apparent damage, heat effects, or discoloration as might be expected to result from fire or explosion.



Figure 16. View of the incident valve stem (top) as compared to the exemplar valve stem.




Figure 17. View of the incident valve seat body (green with white valve seat, upper) as compared to the exemplar valve seat body (black with yellow valve seat, lower).

RTI next removed the burst disk assembly of the incident valve. Compared to the gland nut, the burst disk assembly appeared tightly fit into the valve body. The installation torque was measured to be 10.17 N-m (90 in-lb). It took 5 $\frac{3}{4}$ turns to remove the assembly. While the exterior exposed surfaces of the plug had the same charred and damaged appearance as the rest of the incident valve, the interior surfaces were clean and bright and the burst disk was intact, see **Figure 18**. Correspondingly, the interior surfaces of the valve body in the area of the burst disk also proved to be clean and bright.



Figure 18. View of the incident burst disk assembly (upper) as compared to the exemplar burst disk assembly (lower).

During the explosion, the regulator, which attaches to the valve at the regulator port by way of a threaded adapter, broke away from the valve leaving a portion of the adapter still threaded into

the valve regulator port. This adapter included a plastic handle used for tightening into the regulator port, which remained intact. As seen in **Figure 5**, the adapter broke such that the handle remained attached to the valve but the portion that threads into the regulator remained with the regulator. Simply turning the handle allowed the adapter fragment to be removed from the valve. Some soot was observed on the interior surfaces of the regulator port and the adapter fragment. Inside the regulator port, charring was seen extensively around the vent and along the bottom thread. Soot-like discoloration was observed extending into the port from the charring near the center. Otherwise, the interior of the regulator port was clean and bright, see **Figure 19**.



Figure 19. View of the incident valve high pressure regulator port showing discoloration sooting around the vent.

The valve side of the adapter fragment contained an intact O-ring and a fitting suitable for inserting a hex key. Visible on the handle was the raised text “300 BAR”, see **Figure 20**. Internal to the adapter is a metal air cup that serves as a filter between the cylinder valve and the

regulator. RTI disassembled the adapter fragment and removed the air cup for further examination.



Figure 20. View of the incident valve and underside of the regulator adapter handle.

4.2.3 Incident Regulator

RTI received the incident regulator, shown in **Figure 6**, with approximately 1 m length of green hose attached to one of the low pressure ports. Attached to one of the high pressure ports was a pressure gauge at the end of a 13 cm length of black hose. Soot coated the exterior surfaces of the regulator body, pressure gauge, and black hose; and the first 53 cm of the green hose appear heat affected by discoloration.

RTI first removed the two hoses, revealing the interiors of the two ports to be clean and bright with very little evidence of soot. Next, the remaining portion of the adapter was removed. While soot covered the adaptor's exterior surface and inner bore surface, the interior of the

exposed high pressure port was again clean and bright. However, the bore between the port and the regulator barrel was covered in dark soot.

Next, the cap/spring/plunger assembly, that serves in conjunction with a diaphragm to meter the high pressure gas to the low pressure side of the regulator, was removed. An O-ring and a flat plastic washer were seated in the low pressure regulator barrel and subsequently removed. Minor sooting and particulate matter were visible inside the incident regulator, on the washer and O-ring, and at the interior plunger end. As much as possible of these particulates was captured for later chemical analysis. As is seen in **Figure 21** and **Figure 22**, these components appeared to be in an overall undamaged condition.



Figure 21. View of the incident regulator with the cap/spring/plunger assembly being removed.



Figure 22. View into the low pressure portion of the incident regulator showing the O-ring and washer.

The high pressure diaphragm was revealed by removing a large set screw/fitting from the bottom of the regulator barrel using a hex key. This fitting held a spring in place that easily slipped out once the fitting was removed. Inside the chamber, a minor but noticeable amount of particulate was observed. This chamber is separated from the high pressure gas by the diaphragm and sealed to the outside by the fitting. The diaphragm chamber was separated from the regulator barrel using a strap wrench and the particulate matter found was subsequently saved for chemical analysis.

4.3 SEM Examination

A scanning electron microscope (SEM) provided high magnification imaging of metallic components selected by RTI for more detailed examination. The SEM also features the capability of analyzing small areas of the components to determine the constituent elements present. This is accomplished through energy dispersive x-ray spectroscopy (EDS) built into the microscope and provides an approximate indication of the relative concentrations of the elements present. The EDS produces a spectra plot showing the results of the analysis. The spectra plots for all EDS analysis conducted are included in **Attachment 7**.

4.3.1 Incident valve stem fracture surface.

Figure 23 is a composite view of the four corners of the fracture surface on the incident valve stem. It is notable that the majority of the fracture surface from the left edge proceeding to the right has the appearance of a ductile tensile fracture. A small remaining area along the right edge, conversely, has the appearance of a shear failure. Otherwise there is nothing remarkable about the fracture surface. EDS of the fracture surface measured high levels of copper and zinc, indicating that the valve stem was manufactured from a brass alloy.




Figure 23. Composite SEM micrograph of incident valve stem fracture surface.

4.3.2 Incident pressure regulator adapter fracture surfaces

Figure 24 shows the fracture surface present on the pressure regulator adapter. As the exposed surfaces of the adapter, including the fracture surface, were covered in soot, the exact fracture morphology is not immediately apparent. Further compounding the characterization are areas that have the appearance of being mashed, or damaged, post fracture. These areas are also heavily sooted. Although there was a layer of soot on the adapter, EDS was able to measure high levels of copper and zinc which indicated that it was manufactured from a brass alloy.




Figure 24. SEM micrograph of pressure regulator adapter fracture surface.

4.3.3 Incident pressure regulator adapter air cup

Figure 25 shows the structure of the pressure regulator adapter air cup. It is composed of numerous metallic spheres approximately 250 μm , or 0.250 mm, in size, bonded together in a process known as sintering. The random spacing between the spheres varies in size from a few microns to as much as 300 or 400 microns and acts as a filter for most particulates that might be present in the gas flow upstream of the regulator by creating a tortuous path. EDS of the air cup revealed metallic peaks of aluminum, nickel, copper, and zinc which are consistent with brass alloys.




Figure 25. SEM micrograph of incident air cup structure.

4.3.4 Cylinder inside surface

A small piece of the cylinder from the larger fragment was examined in the SEM, primarily for the purpose of performing EDS on the interior surface of the cylinder. Metallic peaks were measured for aluminum and titanium.

4.3.5 Exemplar and incident valve seat bodies

Figure 26 and **Figure 27** show side by side comparison images of the exemplar and incident valve seat bodies in the threads and the smooth shaft, respectively. In **Figure 27** the extent of the coating is clearly visible on both bodies. EDS of both valve seat bodies in an uncoated area produced copper and zinc peaks indicative of brass alloys.




Figure 26. SEM micrographs comparing threaded portions of exemplar (left) and incident (right) valve seat bodies.




Figure 27. SEM micrographs comparing smooth portions of exemplar (left) and incident (right) valve seat bodies.

4.4 Mechanical Testing and Metallography

RTI conducted basic mechanical property testing of the cylinder material including tensile, compressive, and microhardness tests. Specimens of the cylinder material were also taken for metallographic examination.

4.4.1 Sectioning

Sectioning of the cylinder proceeded according to the established protocol, with specimens for hardness and metallography cut from the fracture edge and specimens for the tensile and compressive tests cut from a non-deformed area near the cylinder bottom. **Figure 28** shows the location of the billet cut for machining into tensile and compressive specimens. This location was chosen based on the results of spherometer measurements made of the cylinder inner curvature. It was necessary to locate an area of the cylinder, large enough to machine a full sized ASTM E-8M dog-bone specimen that had not been deformed significantly from the original curvature. Taking the specimen from such an area ensured that the cylinder material would be as close as possible to as-manufactured condition without any altering of strength properties due to deformation from the incident. **Figure 29** shows the locations of the specimens cut for hardness and metallography.



Figure 28. View of the incident cylinder showing the location of the billet removed for machining into tensile and compressive test specimens.



Figure 29. View of the incident cylinder showing the locations of the four metallography/microhardness specimens.

4.4.2 Machining

Specimens were machined according to ASTM E-8M and ASTM E-9 for tensile and compressive testing, respectively. Both specimens were machined such that tensile and compressive loading axes were parallel to the longitudinal axis of the cylinder. See **Figure 30** for the tensile specimen.



Figure 30. View of the tensile specimen machined from the incident tank.

4.4.3 Tensile and Compressive Testing

Both the tensile and compressive tests were conducted under quasi-static conditions. This resulted in a measured tensile yield strength of 318 MPa (46.1ksi) and a measured compressive yield strength of 347 MPa (50.3ksi). Additionally, an ultimate tensile strength of 354 MPa (51.4ksi) and tensile elongation of 15% were measured. Alcoa specifies minimum values of 290 MPa (42ksi), 345 MPa (50ksi), and 13% for the yield strength, tensile strength, and tensile elongation, respectively, for 6061-T6 aluminum.

4.4.4 Metallographic Examination

Samples A through D, as seen in **Figure 31**, were mounted and polished for metallographic examination. A weak hydrofluoric solution was used as an etchant to reveal the grain structure. The specimens were examined optically using a metallograph and images captured from various regions of all four samples. **Figure 32** and **Figure 33** show representative micrographs of samples A and D. Micrographs from all the samples were compared to a representative micrograph of 6061-T6 published in “Introduction to Aluminum Alloys and Tempers”.⁷ The microstructures compare favorably, confirming that the incident cylinder was manufactured from 6061-T6.




Figure 31. View of the four metallography/microhardness specimens prior to hardness testing. The “i” and “o” notations indicate the inner and outer surfaces, respectively.

⁷ *Introduction to Aluminum Alloys and Tempers*, Kaufman, G.J., ASM International, Materials Park, 2000.




Figure 32. Sample A center 200x



Figure 33. Sample D center 200x

4.4.5 Hardness Results

Upon completion of the metallographic examination, samples A through D were subjected to microhardness testing. Two microhardness traverses were made on each sample. One proceeded from the fracture edge across the circumference of the sample and the other proceeded from the inner to outer surfaces of the sample. A Knoop microhardness value of 120 is generally expected for 6061-T6. The microhardness measurements from sample A measured noticeably lower than the expected values. The measured values ranging from 82.7 to 110 with average values for the two traverses of 97.7 and 101.3. Sample A was taken from a section of cylinder that had undergone combustion, so the reduction in hardness is attributed to exposure heat causing over aging. Samples B through D showed measured values that were more consistent with the expected with averages of 123.8 and 126.0 for B, 119.3 and 125.8 for C, and 124.4 and 129.6 for D. The full set of results is included in **Attachment 10**.

4.5 Chemical Analysis

The level of purity of the oxygen that was allegedly contained in the incident cylinder dictates that a specific environment within the gas passages would be maintained at all times. If a contaminant is present in an oxygen rich environment, the potential for ignition increases dramatically. Wash samples using DuPont Vertrel MCA solvent were taken from: (1) the inner surface of the incident cylinder, (2) the surfaces of the incident valve and its components that are part of the gas passage, (3) the inner surface of the incident regulator green hose, (4) the interior surfaces of the incident regulator, and (5) surfaces of the exemplar valve and its components that are part of the gas passage. These samples were analyzed using Fourier Transform Infrared Spectroscopy (FTIR) for chemical composition. The samples taken from the exemplar valve were used as a control for those taken from the incident valve.

Additionally, Optical Emission Spectroscopy (OES) was performed on samples of the incident cylinder and the exemplar valve in order to specifically identify the aluminum and brass alloys, respectively, used to manufacture each.

4.5.1 FTIR Analysis

Full FTIR results are included in this report as **Attachment 8**. Other than the lubricant observed on the exemplar valve components, no substances were identified that could not be attributed to post incident sources. In other words, no unknown surface contaminants were found.

4.5.2 OES

Tables 1 and 2 contain the results of OES conducted on the cylinder and exemplar valve as compared to 6061 aluminum alloy and forging brass. The tested samples match well with the standard specifications for each alloy.

Table 1. Cylinder Valve Chemistry

Element	Cylinder Valve (wt%)	Requirements for Forging Brass UNS C37700	
		min	max
Copper (Cu)	Remainder	58.0	61.0
Iron (Fe)	0.26	-	0.30
Lead (Pb)	2.57	1.50	2.50
Nickel (Ni)	0.06	Information Only	
Phosphorus (P)	< 0.005	Information Only	
Tin (Sn)	0.21	Information Only	
Zinc (Zn)	38.47	Remainder	

Table 2. Cylinder Chemistry

Element	Tensile Specimen (wt%)	Requirements for Aluminum Alloy 6061 UNS A96061	
		min	max
Aluminum (Al)	Remainder	Remainder	
Chromium (Cr)	0.08	0.04	0.35
Copper (Cu)	0.33	0.15	0.40
Iron (Fe)	0.18	-	0.70
Lead (Pb)	< 0.005	Information Only	
Magnesium (Mg)	1.06	0.80	1.2
Manganese (Mn)	< 0.005	-	0.15
Nickel (Ni)	< 0.005	Information Only	
Silicon (Si)	0.70	0.40	0.80
Titanium (Ti)	0.01	-	0.15
Zinc (Zn)	< 0.005	-	0.25

5.0 DISCUSSION

5.1 Origin of the Explosion

The explosion has been determined to have been caused by the ignition of aluminum cylinder material and originated between the threads of the cylinder valve and the cylinder neck opening. Analysis of the cylinder dimensions and materials revealed that the cylinder was made from a material consistent with aluminum 6061-T6, and the wall thickness was appropriate. Laboratory testing failed to reveal the presence of contaminants or oxygen incompatible materials that may have auto-ignited. The resulting ignition promoted the growth and spread of further combustion of cylinder wall material. The combustion of aluminum occurred and was restricted to the inside surface of the cylinder. The heat generated was sufficient to locally soften the cylinder wall, as demonstrated by the over-aged condition of metallographic specimen “A”. The combustion also reduced the wall thickness. Additionally, the heat of combustion was released into the compressed gas, causing the gas pressure to rise. The combination of weakening the cylinder wall from heat of combustion, thinning due to the combustion of the cylinder material, and the increase in gas pressure from the release of heat from combustion, caused the cylinder to rupture and explosively release its contents.

The magnitude of aluminum material eroded from the event is greatest in the threaded neck opening region, indicative of the region of most intense and/or the longest burning. The initial fracture of the cylinder occurred along the base of the threaded opening, or “neck,” proximate to the ignition origin and began to grow along the perimeter of the opening base, until realigning along the cylinder axis and growing down towards the cylinder base, as indicated in **Figure 34**. Some of the fracture surfaces were either melted or covered by melted aluminum that re-solidified, but this could also be the result of the cylinder striking a hard surface which caused the cylinder to break up.




Figure 34. View showing the threaded neck opening region of the incident cylinder from the interior.

To evaluate the pattern of erosion about the cylinder opening, the depth of the threaded neck opening was measured at 30° intervals from the flat exterior top to the point where erosion seemed to stop along the threaded wall. The resulting measurements are shown in **Figure 35** in the radial diagram. The deepest erosion was set as the 0° point. The least erosion appears to have occurred at the 120°. The 120° region happened to be the area where the combustion deviated away from the opening and began to travel down the side of the cylinder interior, also being the direction where the hoop stress dominates the pattern of crack growth.




Figure 35. Depth measurements of the threaded neck cylinder opening, in mm.

The cylinder valve base also exhibits a matching pattern of erosion consistent with combustion from ignited aluminum, and alloying⁸ from flowing molten aluminum, all originating from the threaded region within the threaded neck cylinder opening, as seen in **Figure 36**. There is a region along the perimeter that exhibits fracture as well as melting and reaction. The gross erosion was angled to the axial normal, indicating that once ignited, the products of combustion were expelled downward into the cylinder. The damage pattern suggests the initial ignition and resultant kindling to promoted ignition occurred within the threads closest to the edge of where the threaded neck cylinder opening bottom and cylinder valve threads meet.

The depth of the existing material below the gasket lip was also measured to evaluate the pattern of erosion. The depths were measured at 30° intervals with the 0° set coincident with the valve

⁸ “Copper-Aluminum Interaction in Fire Environments”, B. Beland, C. Roy, and M. Tremblay, Fire Technology, Vol. 19, Number 1, 1983, page 20.

outlet centerline. As seen in **Figure 37**, the region with the greatest erosion was at 30°, with the least erosion at between 180° and 240°. Superimposing the radial plot with **Figure 35** and rotating the data -60° results in a near perfect overlay as seen in **Figure 38**. The closeness of fit supports the notion that the ignition point did occur within the threaded region. The exemplar cylinder valve threads extend 25 mm from the gasket lip to the flat bottom. The smallest depth of the valve threads measured 15 mm, indicating that perhaps 10 mm of material had eroded from the threads at that point.




Figure 36. View of cylinder valve threaded area.




Figure 37. Depth measurements of the valve threaded area, in mm.




Figure 38. Comparison of measured depths, in mm. Valve depth is rotated -60° to match.

The burn pattern within the cylinder had two distinct burn zones as seen in **Figure 39**. Zone 1 matched the hemispherical geometry of the domed cylinder top with a demarcation line of between 4 cm and 5 cm from the opening center. Zone 2 extended vertically down the cylinder wall about 20 cm from the opening, and having a width of about 11 cm. A fracture divided the second burn zone, indicating this region was the area from which the crack propagated after initiating at the base of the “neck.” The area in Zone 1 was due to a circumferential combustion progressing from the origin point. The burn pattern in Zone 2 is a directional effect due to gravity as the cylinder may have been on its side. Despite the fracture starting at the base of the “neck,” the weakened area of Zone 2 influenced the crack to propagate in that direction as the hoop stress from internal pressure was greater in this area.




Figure 39. View of interior surface showing the two distinct burn zones.

As the aluminum was consumed, the local wall thickness was reduced; the heat weakened the aluminum; and the internal gas pressure increased from the heat energy produced by the combustion. The reaction was likely to have been more of a burning rather than explosive process. Due to this combustion process the cylinder failed at a pressure less than 38 MPa (5,500 psi)⁹ as the pressure relieving burst disk in the cylinder valve was still intact after the explosion.

⁹ The CG-1 burst disk is rated at 32.6 MPa \pm 10% (5000 psi \pm 10%), 38 MPa is the upper range of possible activation of the relief.

5.2 Ignition Mechanism

There are several ignition mechanisms that are possible within the incident cylinder. Some ignition mechanisms are: **promoted ignition**, where a source of heat acts to start the metal burning; **friction ignition**, where the rubbing of two surfaces together generates heat; **particle impact**, where the kinetic energy of a particle striking the surface is converted to heat; **mechanical impact**, much like the particle impact, heat is generated from the transfer of kinetic energy from an object having significantly more mass and less velocity than a particle; **exposure of base metal**, where the protective oxide layer is removed to expose the base metal, which in turn, oxidizes in the oxygen enriched atmosphere generating heat; **auto ignition of contaminants or incompatible materials**, where a material, such as a hydrocarbon based lubricant, is incompatible with use in an oxygen rich environment and self-ignites to promote ignition of the metal; **heat of compression**, where the rapid filling of a low pressure vessel from a high pressure line can cause the existing gas in the low pressure chamber to be driven into a compact region and compress to an increased temperature; **charging rigid vessels**, where the kinetic energy of the gas entering a low pressure vessel is converted to heat; **electric arc**, where the discharge across gaps between conventionally powered, electrically energized objects are heated from the very high temperature arc; **static electric discharge**, like an electric arc where a competent electric discharge occurs across a gap, but the electrical potential was created by a charge difference between the objects, not by electrical energizing; and **acoustic resonance**, where the oscillations of acoustic pressure waves from flowing gas create a temperature rise within the resonant cavity.¹⁰

The incident cylinder valve was found closed. The extents of heat and combustion effects were limited to the entrance of the cylinder valve at the point where the pick-up tube entered the valve body. At that point in the cylinder valve and beyond, there was no evidence of heat or combustion as the valve interior wall surfaces appeared clean and without heat effects. Plastic components within the cylinder valve were spared heating as they did not suffer any melting,

¹⁰ ASTM G 94 – 92, and Advanced Thermodynamics for Engineers, §1-7-1 Charging and Discharging Rigid Vessels.

warping, combustion, or exhibit soot. Additionally, the valve seat was at the most forward position, indicating that the valve was shut at the time of the incident. The laboratory testing also failed to reveal the presence of any identifiable materials that are non-compatible with high purity oxygen systems. It would be expected that if such a substance existed prior to the fire, remnants of the substance or its by-products would still exist.

As a result, the following ignition mechanisms can be ruled out: particle impact; incompatible materials within the cylinder valve; charging a rigid vessel; heat of compression; static electric discharge; and acoustic resonance. This leaves electric arcing, mechanical impact, exposure of base metal, promoted ignition, and friction ignition. Electric arcing and promoted ignition are ruled out as improbable, thus leaving mechanical impact, exposure of base metal and friction ignition as the most likely causes. The actual mechanism of ignition could not be determined.

5.3 Cylinder Compliance with the Federal Regulations

5.3.1 Compliance with Labeling

Compressed oxygen gas is considered a hazardous material, and is regulated under Title 49 of the Code of Federal Regulation, Part 172, Sub Chapter B. As found in the “Hazardous Materials Table,” §172.101, oxygen, as a compressed gas: has a Hazard Classification or Division of 2.2 (non-flammable gas); has an Identification number of UN1072; must be label coded as 2.2 or 5.1 (oxidizer); is subject to the special provisions of §172.102 A14 and A52; and must be packaged as per §172.302 for bulk packaging, or §172.314 and 315 for non-bulk packaging, with exceptions found in §172.306. Of the exceptions provided, none provided an exception to the labeling requirements for the incident cylinder. In summary, the incident cylinder should have been minimally labeled with a diamond shaped, durable label clearly marking the contents as “oxygen” followed by a “2.2”.¹¹ However, the Code is silent with regards to identification of the degree of cleanliness, as indicated in ASTM G 93.

¹¹ 49 CFR 172.407 provides the specifications for the label, §172.426 demands that an oxidizer have specific wording and Division for an oxidizer, and §172.405 modifies the oxidizer label to configure specifically to compressed oxygen gas.

In accordance with the federal regulations, the incident cylinder should have possessed a label indicating that the contents of the cylinder were compressed gas oxygen. The incident cylinder possessed two decals or labels. The first, shown in **Figure 2**, indicated that the cylinder had been cleaned in accordance with O₂ service. There is no indication as to who may have stamped and applied the decal, or as to what procedure was followed to certify the cylinder was properly cleaned. The failure to provide this information is counter to the suggestions of the Compressed Gas Association,¹² and a violation of the ASTM G 93 which states as follows:

12.2 Package Marking:

12.2.1 Each oxygen cleaned and packaged article shall be clearly labeled to include the following information:

12.2.1.1 The manufacturer, component identification, date cleaned, responsible department or agent,

12.2.1.2 Notification that it has been specially cleaned for oxygen service, such as oxygen cleaned, cleaned for oxygen service or specially cleaned,

12.2.1.3 Identification of cleaning method used, such as “Cleaned in accordance with ASTM G 93, Verification Type I, Test 1 through 4, Type II, Test 1, Level A, and Test 2, Level 175” or “Cleaned in accordance with ASTM G-XXX” (the manufacturer’s or purchaser’s specification).

The statement on the decal “Tank & Valve Have Been Cleaned In Accordance With O₂ Service” is not appropriate as it fails to indicate to what standard and level the cylinder has been cleaned, and who performed the cleaning. The decal does not provide the necessary information needed to ensure that the cylinder is appropriate for use with oxygen enriched gases. Additionally, the incident cylinder lacked the labeling as required by Federal statute. Should the incident tank have been used for Nitrox at 40% oxygen concentration or less, the IANDT label would have been sufficient and appropriate.

¹² Handbook of Compressed Gases, page 205 under section “Pressurization”.

Had the requirements of proper labeling been adhered to, there would not have been a need to produce an inadequate label indicating the incident cylinder had been cleaned for oxygen use. Use of the incident cylinder prior to being labeled is unknown. The entity that allegedly cleaned the incident cylinder for oxygen use should have affixed the federally mandated label prior to allowing the incident cylinder to be used with compressed oxygen. Without further information regarding the events preceding the incident, it is impossible to determine if the inappropriate labeling played a part in the incident.

5.3.2 Compliance with Regulations for 3AL Cylinder

The requirements for a 3AL cylinder are found in Title 49 of the Code of Federal Regulations, part 178.46. The regulation dictates the cylinder material is to be similar to aluminum alloy 6061 with a T6 heat treatment with the mechanical properties having a minimum yield strength of 241 MPa (35,000 psi), a minimum tensile strength of 262 MPa (38,000 psi), and a minimum elongation of 14%. A sample of the cylinder was removed for tensile testing and compression testing. The sample was machined from the wall section having as much of the original curvature as possible to minimize the effects of work hardening from the accident. The specimen, seen in **Figure 40**, measured 12.93 mm (0.509 in) wide by 9.68 mm (0.381 in) thick by 131.75 mm (5.187 in) long. The testing performed in this investigation revealed that the cylinder material had a yield strength of 318 MPa (46,100 psi), a tensile strength of 354 MPa (51,400 psi), and an elongation of 15% – exceeding the minimum requirements of the regulation.




Figure 40. Tensile test specimen and tensile test.

Section 178.46(d) of the CFR provides for a minimum wall thickness. The regulation states that “The minimum wall thickness must be such that the wall stress at the minimum specified test pressure will not exceed 80 percent of the minimum yield strength nor exceed 67 percent of the minimum ultimate tensile strength as verified by physical tests in paragraph (i) of this section.” The wall thickness was measured to be 9.78 mm. The prescribed minimum test pressure was 34.5 MPa (5,000 psi)¹³. Using the measured mechanical properties, the results were that the wall stress measured 63.7% of the yield stress and 57.1% of the ultimate stress, which were below the regulation maximums. The resulting analysis indicates the wall thickness of the incident cylinder exceeded the minimum required by the regulation.

A sample of the material from the tension specimen was subjected to an alloy composition analysis. The incident cylinder material was found to be consistent with aluminum 6061 with T6 temper.

¹³ 49 CFR 178.46(g)(3)(iii) Five-thirds times the service pressure for cylinders having a service pressure of at least 500 psig. The incident cylinder was rated for 3,000 psi service pressure.

6.0 CONCLUSIONS

The opinions expressed in this report are based on RTI's inspection and evaluation of the evidence; and engineering analysis using generally accepted scientific and engineering methodologies. These opinions are also based on RTI's education, background, knowledge, and experience in the fields of mechanical engineering, material science, chemistry, fluid dynamics, thermodynamics, and physics.

RTI concludes, to within a reasonable degree of engineering certainty that:

1. There is no evidence to suggest that non-compliance with the hazardous materials regulations played a part in the incident cylinder failure; however, modifications to the regulatory standards may be necessary.
2. The incident cylinder was not labeled as required by the hazardous materials regulations. However, it is uncertain if the failure to properly label the incident cylinder played a part in the incident.
3. The incident cylinder failure was not due to excess thermal exposure from an external source.
4. Laboratory testing failed to reveal any evidence of contamination from an oxygen incompatible substance on the incident cylinder, cylinder valve, hoses, and regulator.
5. There were no problems evident with the incident cylinder, except for the way it was labeled.
6. There were no problems evident with the incident cylinder valve.

7. There were no problems evident with the incident regulator and pressure lines.
8. The ignition of the fire that led to an explosion originated within the threaded section of the cylinder neck opening. The actual mechanism of ignition could not be determined.

RTI reserves the right to amend or supplement this report and its conclusions or recommendations should additional information become available.

Respectfully submitted,



Richard B. Loucks, Ph.D., P.E.
Senior Mechanical Engineer



Matthew Wagenhofer, Ph.D.
Mechanical Engineer

ATTACHMENT 1

Test Protocol

TEST PROTOCOL

November 29, 2011

RTI Matter Name: DOT – Ruptured SCUBA Cylinder

RTI Matter No.: 50151ME002

RTI Investigators:

Richard B. Loucks, Ph.D., P.E.

Matthew Wagenhofer, Ph.D.

Background:

RTI was tasked through Government Contract DTPH56-12-P-000004, dated November 9, 2011, issued by Office of Acquisition Services US DOT/PHMSA/PHA-30 to perform an investigation on a DOT 3AL-3000 cylinder involved in a fatal accident to determine if non-compliance with Hazardous Materials Regulations played a part in the cylinder failure and if modification of the regulatory standards is necessary.

Additionally, the purpose of this contract is to evaluate the ruptured DOT 3AL-3000 cylinder valve and determine the following:

- The degree of exposure to thermal energy; and
- Evidence of oxygen contamination which may have resulted in the explosion (fire) inside the ruptured DOT 3AL cylinder.

On November 15, 2011, RTI Group, LLC (RTI) received four items from the Department of Transportation, Pipeline and Hazardous Materials Safety Administration (PHMSA). These items are described as follows:

1) Yellow high pressure gas cylinder, Part 1

Smaller fragment from the cylinder, measures approximately 12 inches by 6 inches. Fragment displays the following marks near the neck: HY-MARK DOT-3AL 3000 OU

Cylinder has one decal and part of another:

Decal 1: “Tank & Valve Have Been Cleaned For Premix, Oxygen Content 22 to 40%” is not punched out. “Tank & Valve Have Been Cleaned In Accordance With O₂ Service” Is punched out at 2011. The month is uncertain.

Decal 2 (partial): for decompression use IANTD/IAND, Inc.

2) Yellow high pressure gas cylinder, Part 2

Larger section contains the bottom, neck and valve opening, measures approximately 24 inches by 14 inches. This item has the following markings near the neck: 0001 M5442 10 07 S40 TC-3AL 207

This part of the cylinder contains the remaining portion of Decal 2 stating:

Decal 2 (partial): OXYGEN for decompression use only – MOD 20 FSW MOD 6 MSW
WWW.IANTD.COM

3) High Pressure Tank Valve, DIN Valve,

Manufactured by Genesis containing a 5000 psi, 30 lb/hr CG-1 type rupture disk. A pressure regulator adaptor is present in the opening which has a fractured outlet. The metal particle filter is evident in the opening. The rubber hand closure knob is present, but separate from the valve.

4) Regulator

Manufactured by Dive Rite, serial number 12008135, fitted with regulator fitting. The opening is occupied by the fractured end of the pressure regulator adaptor.

Attached to the regulator:

1. Black pressure line with dial gage on high pressure side of regulator. Dial gage face is heat affected and the gage is illegible.
2. Length of green pressure line stating “WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury” no manufacturer identified. Distal end terminates unattached. Low pressure side

Objective:

Under the tasking directive of the contract, sub-section 3.02 “Advanced Analysis and Examination”, as part of the investigation the evidence is to be subjected to a series of invasive, therefore destructive, examinations in which sophisticated laboratory equipment will be employed, such as Fourier Transform Infrared Spectroscopy (FTIR), Scanning Electron Microscopy (SEM), Energy Dispersive Spectroscopy (EDS), metallography, alloy chemistry, hardness testing and tension and compression testing. This protocol addresses the schedule and procedures that will be performed to fulfill this task.

Date, Time and Location:

- Tuesday, December 6, 2011 at 10:00 am pacific coast time
- ANAMET, Inc.
26102 Eden Landing Road, Suite 3
Hayward, CA 94545-3811
- Local Contact: Kenneth Pytlewski, 800-377-7768 OR Ken@Anametinc.com

Procedure:

Phase I – Initial Examination.

Document the condition of the evidence through the use of field notes and still photography. The use of optical microscopy will be used where appropriate. This process is non-destructive and is intended to document the evidence prior to any alterations.

Phase II - Search for the presence of oxygen non-compatible substances.

An examination in search for materials typically found in SCUBA dive operations, such as silicone greases found in diving gear (dimethylsiloxane), hydrocarbon greases/oils used in diving gas compressors, perfluorinated lubricants found in Nitrox diving gear, and other lubricant materials such as Tribolube (ALI Aerospace Lubricants), Christo Lube (Lubrication Technologies, Inc.), IKV-Fluor & Zarox, etc. With the use of solvents, such as: Asahiklin AK 225 (Hydrochlorofluorocarbons); DuPont Vertrel XF, DuPont Vertrel MCA (Hydrofluorocarbon); or 3M HFE 7100, 3M HFE 71DE (Hydrofluoroether), obtain samples from within the valve gas passage area and subject the samples for FTIR analysis. The solvent will be decided upon at the time of the examination.

High Pressure Tank Valve

Subject valve and regulator will have to be disassembled to reveal any existing gasket/seal materials, provide access to components for solvent washing and sample collection. With each disassembly, each component will be documented, and then the areas upstream of the containment feature will be searched for the presence of non-oxygen compatible materials. The disassembly will proceed in the following order:

1. Test the valve closure mechanism to determine if the valve is open or closed. Mark alignment of the gland nut to the valve body prior to turning with sharpie.
2. Remove the pressure regulator adaptor.
3. Remove the CG-1 burst disk pressure relief device.
4. Remove the closure mechanism. The gland nut will be removed exposing a series of gaskets and back up rings. These will be removed to gain access to the stem and the high pressure

seat. The condition of the high pressure seat will be inspected by SEM/EDS followed by solvent wash for FTIR analysis. Components will be removed until the valve body is empty.

Samples of the valve body will be obtained for chemistry analysis to determine the alloy of the materials used.

Material from the threads of the valve will be removed and inspected under the SEM. They will be removed using a pick and collected onto carbon tape for mounting on a SEM stage. Alternately, a segment section of the threads will be cut from the valve, polished and mounted, then inspected using the SEM.

Items having been separated from the parent object will be secured within a plastic container and labeled using the scheme: Part xx followed by a lower case alpha character, e.g. "Part 3-a Gland Nut".

Pressure Regulator Adaptor

The fractured surface of the pressure regulator adaptor will be examined using the SEM to determine the mode of fracture and the presence of foreign materials. The air filter cup within the adaptor will be subjected to SEM analysis to identify both the discolored material on the filter surface and any particles that may be trapped in the filter. Subsequently, the filter will be subject to a solvent wash to determine by FTIR the presence of any contaminants.

Regulator

The high pressure hose attachment will be removed and the interior of the tubing will be inspected. The low pressure tubing will be removed and inspected. The interior of the regulator will be inspected to the extent possible from the open ports. If possible, a solvent swab will be taken through a high pressure port and subject to FTIR to determine the presence of contaminants. If contaminants are present, the regulator will be dismantled.

Tank Material

Internal surfaces of the tank will be examined for the presence of oxygen non-compatible substances. Solvent washing of the internal area will provide samples for FTIR analysis in four areas, indicated as areas “A”, “B”, “C”, and “D” and any other areas deemed of interest on the day of the examination.



Figure 1. Solvent was areas for FTIR sampling.

Phase 3 – Mechanical properties testing of Cylinder material.

Several sections of the cylinder will be subjected to hardness testing, alloy chemistry, metallographic analysis and tension and compression testing.

Hardness traverses following the inner circumference of the tank will be made at several elevations along the length of the tank. The approximate elevations are indicated in Figure 2. The method of testing will be as follows:

1. Four sections of cylinder material of approximately 2 inches wide by 1 inch deep will be excised from the main body with the use of a liquid cooled diamond blade saw.
2. After removing the section from the main body, a ½ inch axial wide circumferentially cut section will be removed for subsequent metallographic mounting, polish and etch. This creates two sub-sub sections for evidence labeling where a lower case Roman numeral will be added to the nomenclature, e.g. “Part 1-a-i Excised section from Cylinder, Metallographic” and “Part 1-a-ii Hardness Specimen from cylinder”. See Figure 3.
3. The fracture surface from the larger section will be examined using the SEM to determine from the fracture morphology the mode of fracture, direction of crack propagation, EDS, and any other information discovered in the examination. The section will then be subjected to a Rockwell hardness test on the internal surface, not directly on the fracture surface.
4. The smaller section will be cast into a resin material with the cut surface including the fracture surface for examination. The specimen will be polished, then etched to allow examination of the grain structure. A profile of Knoop micro hardness tests will be performed at 1mm intervals in two directions: circumferentially along the mid thickness from the fracture surface for 1.5 cm; and along the radial from the internal to the external surface.




Figure 2. Approximate test sites for hardness testing and metallographic examination.




Figure 3. Hardness testing and Metallographic sectioning. ⊗ illustrate Knoop micro hardness locations along the traverse. (not to scale)

Tension and compression testing will be performed to determine the mechanical properties of the alloy. Sample material will be collected from the machined samples for chemical analysis to determine the aluminum alloy.

The tension and compression tests will be performed as follows. A spherometer will be used to measure the radius of curvature of the tank in its as-received condition. Baseline inner surface curvature measurements will be made on the intact bottom region of the tank. Further inner surface curvature measurements will be made along the length of the tank over all of the regions to determine the least

deformed section of the tank. Visual inspection of the as-received tank indicates that this section is likely to correspond to that indicated in Figure 3. At least one (1) tension test specimen and two (2) compression test specimens will be machined from this region. The tension test specimen will be oriented such that the tensile axis of the specimen is parallel to the longitudinal axis of the tank. One of the compression specimens will be oriented such that the compression axis is parallel to the radial axis of the tank. The other compression specimen will be oriented such that the compression axis is parallel to the transverse axis of the tank. The transverse axis is defined by a line tangent to a circumference around the tank located at the midpoint of the tank wall. Any additional specimens for which there is sufficiently un-deformed material will duplicate these three orientations.

Dental mold compound will be used to make highly accurate replicas of the threads inside the neck of the tank prior to sectioning and mounting of the threads for metallographic and microscopic analysis. It is anticipated that the entire circumference of the threads will be replicated in two to four sections to ease removal of the molds from the inner threaded surface of the neck. Sufficient overlap will be included at both ends of each section so as to retain all details available. Measurements such as pitch, thread root depth, etc. will be made from the molds, if possible. The process will start by subjecting a portion of the threaded area to a solvent wash, the samples then subjected to FTIR analysis. Then the molding compound will be applied in quadrants with greater than 90 ° coverage. The boundaries will be indicated on the opening rim with a Sharpie and the molds labeled following the stated nomenclature.

Once the thread mold profiles are completed, the opening will be sectioned to allow SEM/EDS examination of the threaded section and subsequent metallographic mounting. A section, comprising of no more than 30 ° of radial opening on the section opposite that material still attached to the cylinder body will be sectioned. The section will be subject to SEM/EDS examination to resolve the thread/root regions for contaminants and other information. The section will then be mounted with the cut surface exposed for examination, polished and etched to reveal the grain structure, and examine for contaminants trapped beneath smeared or swaged aluminum.

Phase 4 – Collection of Evidence, logging and

retrograde. Each item will be double checked to ensure it has been catalogued, logged, and properly packaged for storage. All graphs, apparatus created images, and measurements will be compiled for use in the final report.

About RTI Group, LLC

The RTI Group, LLC is a pioneering, global accident and failure investigation and safety management consultancy serving the legal and insurance markets. With origins dating back to 1975, RTI's forensic engineering services span comprehensive high-risk industries and transportation operations disciplines, including aviation, marine, rail, utilities, nuclear, explosion, and construction.

Headquartered in Annapolis, Maryland, RTI Group, LLC was founded in 2003 as a forensic engineering services company, with its origins dating back to 1975, by the founder of FTI Consulting, Inc. Anamet Inc., a forensic materials testing laboratory in San Francisco, California became a vital asset to RTI in 2003. In 2004, RTI founded its London office, RTI Ltd., as a wholly owned UK subsidiary that is the home office of the Aviation and Marine Departments. RTI Latin America was established in 2008 in Panama City, Panama as an extension of the London office to serve Latin America and, in particular, the Panamanian Flag State and Canal Operations. RTI opened its Bahrain branch office in April of 2011 to provide security and safety services, as well as access to other RTI disciplines in the Gulf and Middle East region. RTI continues to expand its worldwide range of analytical capabilities and services to other parts of the globe.

February 23, 2012 Amendment to

TEST PROTOCOL

November 29, 2011

RTI Matter Name: DOT – Ruptured SCUBA Cylinder

RTI Matter No.: 50151ME002

RTI Investigators:

Richard B. Loucks, Ph.D., P.E.

Matthew Wagenhofer, Ph.D.


Under Procedure, Phase II, High Pressure Tank Valve, change item 4 and add the following items of the disassembly procedure to read as follows:


4. Remove the closure mechanism. The gland nut will be removed exposing a series of gaskets and back up rings. These will be removed to gain access to the stem and the high pressure seat.
5. Perform an electrical continuity test and measure the electrical resistance between several points on the outer and inner surfaces of the valve seat body using a multimeter.
6. The condition of the high pressure seat will be inspected by SEM/EDS followed by solvent wash for FTIR analysis. Components will be removed until the valve body is empty.

ATTACHMENT 2

Evidence Receipt Photos







The enclosed items comprise all the pieces of the ruptured scuba cylinder. The testing is contracted for the value assembly. Please hold the two pieces of the cylinder in case PHMSA HQ decides on further testing. The value assembly is on top and the smaller piece of the cylinder is under the larger piece.

Please sign the enclosed DOT property inventory report in the signature receiving block on the bottom part of the form. If you can, scan the document and send it to:

Ernest.quail@dot.gov
 Or mail a copy to: US DOT/PHMSA
 233 Peachtree St, Suite 602
 Atlanta, GA 30303



assembly is on top and the smaller piece of the under the larger piece.

Please sign the enclosed DOT property inventory the signature receiving block on the bottom part form. If you can, scan the document and send a

SA
 Suite 602

U.S. DEPARTMENT OF TRANSPORTATION PROPERTY INVENTORY REPORT Page 1 of 1

DATE: 11/9/11	TIME:	LOCATION:	DESCRIPTION:	DATE OF PROPERTY RECEIVED:		
COMPLAINT NUMBER: Vanhorn, Russell (deceased)	REGISTRATION NUMBER: 5877-37	REGISTRATION STATE: N. Ark	REGISTRATION CITY: St. Petersburg	REGISTRATION COUNTY: Pinellas		
REGISTRATION TYPE: Ruptured scuba cylinder	REGISTRATION CLASSIFICATION: 2	REGISTRATION STATUS: 2	REGISTRATION EXPIRES: 11/9/11	REGISTRATION EXPIRES MONTH: 11		
CONTACT NAME & PHONE NO: 53770	CONTACT TITLE: 53770	CONTACT ADDRESS: 53770	CONTACT CITY: 53770	CONTACT STATE: 53770		
ITEM #	QUANTITY	DESCRIPTION OF PROPERTY	DATE AND TIME RELEASED	DATE AND TIME RETURNED	SIGNATURE AUTHORIZING	SIGNATURE RECEIVING
1	1	Scuba cylinder				
2	1	Separated piece of scuba cylinder				
3	1	Valve, regulator and hose				
Nothing Returned						
1			11/10/11			
2			11/10/11			
3			11/10/11			



KEEP WITH PROPERTY



















































ATTACHMENT 3


Exemplar Valve Photos



















ATTACHMENT 4

Exemplar Regulator Photos





































ATTACHMENT 5

Testing Sign-in Sheet



Anamet, inc

Materials Engineering & Laboratory Testing

26102 Eden Landing Road, suite 3 · HAYWARD, CALIFORNIA 94545 · (510) 887-8811 · Fax (510) 887-8427

Date: March 12, 2012

Matter: Ruptured SCUBA Cylinder

Anamet Job Number: 5004.7109

RIT Matter No: 50151ME002

Name

Matthew Wagenhofer

Company Name

RTI

Representing

DOT-PHMSA

Business Card or Contact Information

Address 910-E Bestgate Rd
Annapolis, MD 21401

Phone 410-571-0712

Email matthew.wagenhofer@rtiforensics.com

Name

Adam Horsley

Company Name

PHMSA

Representing

DOT-PHMSA



U.S. Department of Transportation
Pipeline and Hazardous Materials Safety Administration

ADAM HORSLEY

Attorney-Advisor
Office of the Chief Counsel

East Building, E26-202
1200 New Jersey Avenue, SE
Washington, DC 20590

Tel: 202-366-8000
Fax: 202-366-7041
adam.horsley@dot.gov

Name

BILL OLIVER

Company Name

SHERWOOD SCUBA LLC

Representing

SAME

SHERWOOD SCUBA, LLC.

1611 East Saint Andrew Place, Santa Ana, California 92705

Bill Oliver

bill@sherwoodscuba.com

Director of Product Development

TL: 714.259.4780 ext 7000

FX: 714.259.4709



Name

NORMAN YUEN

Company Name

ANAMET

Representing

ANAMET
(THIRD PARTY)

Norman Yuen

Materials Engineer
510-887-8811



Anamet, inc

Materials Engineering & Laboratory Testing, Since 1958

26102 Eden Landing Rd., Suite 3
Hayward, CA 94545-3811
800-377-7768 • Fax: 510-887-8427
www.anametinc.com
norman@anametinc.com

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 117 of 574

ATTACHMENT 6

Photographs from Anamet Testing




910-E Beegate Road
 Annapolis, MD 21401
 410.571.0712 tele
 866.327.1165 toll free



rti
REGISTRATION AND TRAINING INSTITUTE

Date 11/15/11 File/Lab No. 5D151ME002
 File Caption DOT-Ruptured SCUBA Cylinder
 Obtained From DOT-PHMSA
 Tagged By R. Louder
 Condition/Testing One (1) SCUBA cylinder fragment approx 6"x12" containing two (2) decals.
 Serial No./Markings _____
 Log Entry _____ Item 1 of 4

EVIDENCE














Online Merchant Administration Tool <https://www.diverightinscuba.com/catalog/admin/packingslip.php?o...>

Dive Right in Scuba
24222 W. Lockport St.
Plainfield, IL, 60544
815-267-8400



ORDER ID: 5611

SOLD TO:
 Richard Loucks
 29 Shadow Point Ct
 Edgewater, Maryland 21037
 United States

SHIP TO:
 Richard Loucks
 29 Shadow Point Ct
 Edgewater, Maryland 21037
 United States

410-571-0712
 rick_loucks@hotmail.com
IP Address: 70.90.83.177
ISP: cbrcoffee.com

Payment Method: PayPal Express (including Credit)

Products **Model**
 Convertible 200-BAR DIN Valve KA70
 Service Pressure: 3042 PSI

Date Added	Who Commented	Comment
No order comments		

Open the box and make sure that the plastic bags are safely closed: if not all the content could have been abused and must be replaced. Storage the Valve in an appropriate place. An inappropriate storage can expose the Valve to dust and impurities, that can compromise the working of the Valve and gas cleanliness. Handle with clean hands or gloves. The assembly area and all the instruments, tools, and machine used must be properly cleaned to prevent contamination. The valve must be installed in a cylinder which has been cleaned and tested for breathing air gases conforming to EN 12021 requirements. Manufacturer will not respond for any malfunctions due to inappropriate storage or handling.

Before installation on the cylinder, check if the marking of the Valve correspond with the cylinder diameter and the mounting angle of the coupling or 4-hole plate. Check if the Valve thread corresponds with the thread of cylinder's coupling.

DO NOT LUBRICATE.
 Make sure that the coupling is free of soiling like grease, painting colours, etc. The Valve must be free from oil especially the inlet and outlet connections. The presence of oil, lubricant and other substances containing hydrocarbons can be dangerous in case of contact with oxidizing gases. they are potential causes for fire and explosion, as well as fast opening of the handwheel.

Usage and maintenance
 Maintenance and repair of the Valve is under the responsibility of the user or the operator. Anyone attempting to maintain or repair the Valve must be thoroughly familiar with EN 250 and all other standards and regulations reference therein.

ALWAYS OPEN VALVE SLOWLY UNTIL PRESSURE BUILDS UP THROUGHOUT THE REGULATOR
 At the end of usage, close the Valve by hand without forcing. Maximum torque for opening and closing should be 5 Nm.

Chromium plated external part can be cleaned with disinfecting solutions not containing ammonia, using a clean cloth. Dry the device before using. Do not introduce any substance or foreign particles into the valve or into its inlet or outlet connections. Before using verify that the valve has no damaged parts and/or components. Damaged parts/components not subjected to pressure have to be substituted with original spare parts. If trained authorized personnel. When outlet connections or other parts under pressure are damaged, or when periodical cylinder maintenance is performed, device substitution is recommended.

MANUFACTURER IS NOT RESPONSIBLE OF DAMAGES COMING FROM ALTERATIONS, TAMPERING, AND INAPPROPRIATE USE OF THE VALVE.

Chromium plated external part can be cleaned with disinfecting solutions not containing ammonia, using a clean cloth. Dry the device before using. Do not introduce any substance or foreign particles into the valve or into its inlet or outlet connections. Before using verify that the valve has no damaged parts and/or components. Damaged parts/components not subjected to pressure have to be substituted with original spare parts. If trained authorized personnel. When outlet connections or other parts under pressure are damaged, or when periodical cylinder maintenance is performed, device substitution is recommended.

This warning paper is part of the sales contract. Manufacturer preserves the right to change design and materials as well as specifications and product information without prior notice.

Instructions for use VSBI 23 7 044 6362 INDEX A0 del 20 11 2008 ACTIVITY 06290



pergola
 Pergola s.r.l. Via Statale 11, 11713
 23010 Ponte S. Marco di Calcinato-BS- ITALY Tel +39 030/9663111 - Fax +39 030/9680884

INSTRUCTION FOR 232 bar SCUBA BREATHING AIR GASES READY VALVE
THIS LABEL IS TO BE REMOVED BY THE CUSTOMER ONLY AND RETAINED FOR FUTURE REFERENCE

Manufacturer general warranty conditions do not apply to Valve not installed, used and maintained accordingly to the instructions contained in these Warning Paper. Furthermore, Manufacturer general warranty conditions do not apply in the following:

- repair or replacement due to normal wear or damage during routine maintenance
- damage to components whose fragility is for technical reasons unavoidable and determined by product design
- damage arising from modifications not included in the procedures in this warning paper
- damage resulting from the use of unauthorised part, supplied, manufactured or modified by procedures not included in this warning paper.

Only those persons who have read these technical instructions thoroughly and understand them completely shall be authorized to use this Valve. Failure to follow any instruction or warning within this instruction manual or on any Valve label may result in a serious accident involving either personal injury, property damage or both.

Since the Valve is being purchased and used for incorporation into an other product Pergola reminds the end-product manufacturer that any and all product user warning, instructions and labels are the responsibility of such end-product manufacturer. This Valve is to be operated, maintained and installed only by individuals who have been trained by a recognized agency in Scuba Diving. You can disassembly the Valve only if you are properly trained to by specific training sessions organised by Manufacturer; furthermore you must follow the relevant instructions attached to the spare parts kit.

This high pressure cylinder valve is designed, intended and approved for scuba diving and must be used for Breathing Air Gases (EAN, Nitrox and Trimix G.M.); it should not be used for any other purposes. If the Valve user has any questions regarding the proper application or use of the Valve he must call Pergola. Any non-approved use or application and/or any non-approved modification of the Valve may result in a serious accident or personal injury for which the manufacturer will not be responsible.

Attention the Breathing Air Gases must be conform to EN 12021 requirements.

The valve is designed and manufactured according to: CE 97/23, EN ISO 10297 and UNI EN250

Technical data	Materials	Closure Torque
Working pressure: 232 bar	Body: Chromium plated Brass	Closure torque of the gland nut 45-55 Nm
Test pressure: 280 bar	O-rings: EPDM	Valving torque: 100-130 Nm
Temperature Range -20 +65 °C	Seat pad: PA 6.6	Steel cylinders without welding 95-130 Nm
	Burning Disc: Nickel	Aluminium cylinder

The Valve is to be used for oxygen enriched air, the Valve is to be operated, maintained and installed only by individuals who have been trained by a recognized agency in the use of oxygen enriched breathing air.



910-E Bestgate Road
Annapolis, MD 21401
410.571.0712 tele
866.327.1185 toll free




rti
R
Manufacturer of RTI Equipment, Inc.

Date 12/30/11 File/Lab No. 50151.ME002
File Caption DOT-Ruptured SCUBA cylinder
Obtained From Dive Right In Scuba
Tagged By M. Wagenhofer
Condition/Testing Exemplar Valve #1
(Convertible 200 Bar Dia Valve)
Serial No./Markings 60004328 11-10
Log Entry _____ Item 1 of 2

EVIDENCE







910-E Bestgate Road
Annapolis, MD 21401
410.571.0712 tele
866.327.1165 toll free

rti
REGULATOR OF PFI ENGINEERING, INC.

Date 12/30/11 File/Lab No. 5D151.ME002

File Caption DOT-Ruptured SCUBA cylinder

Obtained From Dive Right In Scuba

Tagged By M. Wagenhofer

Condition/Testing Exemplar Valve #2
(Convertible 200 Bar Pin Valve)

Serial No./Markings 60004328 11-10

Log Entry Item 2 of 2

EVIDENCE



Open the box and make sure that the plastic bags are safely closed. If run all the contents could have been altered and must be replaced. Storage the Valve in an appropriate place. An inappropriate storage can expose the Valve to dust and impurities, that can compromise the working of the Valve and gas cleanliness. Handle with clean hands or gloves. The assembly uses and all the instruments, tools, and machine used must be properly cleaned to prevent contamination. The valve must be installed in a cylinder which has been cleaned and tested for breathing air gases conforming to EN 12031 requirements. Manufacturer will not respond for any malfunctioning due to inappropriate storage or handling. Before installation on the cylinder, check if the marking of the Valve corresponds with the cylinder diameter and the mounting sight of the coupling or a hole plate. Check if the Valve thread corresponds with the thread of cylinder's coupling.

DO NOT LUBRICATE.
Make sure that the coupling is free of soiling like grease, painting colours, etc. The Valve must be free from oil especially the inlet and outlet connections. The presence of oil, lubricant and other substances containing hydrocarbons can be dangerous in case of contact with oxidizing gases, they are potential causes for fire and explosion, as well as fast opening of the handwheel.

Use a special tool corresponding to the Valve's screw to fit the Valve onto the cylinder to avoid any deformation. Fitting torque to be applied must be in accordance with the BS 1334 (see the table the valving torque value) and must not be exceed. If a leakage occurs after the correct assembly of the Valve onto the cylinder check the thread of the cylinder coupling.

Usage and maintenance
Maintenance and repair of the Valve is under the responsibility of the user or the operator. Anyone attempting to maintain or repair the Valve must be thoroughly familiar with EN 250 and all other standards and regulations reference therein.

After each filling operation close the Valve handwheel and check if there is any leak from the inlet connection and from the outlet of the Valve. Do not use leak detectors or solutions containing ammonia, phosphates, or other chemicals which are harmful to copper.

corrosion of the material and consequently increases the risk of leaks and explosion. Before insert the regulator onto the Valve open it slightly for an instance in order to clean the opening of particles of dust, dirt and to remove the moisture.

ALWAYS OPEN VALVE SLOWLY UNTIL PRESSURE BUILDS UP THROUGHOUT THE REGULATOR

At the end of usage, close the Valve by hand without forcing. Maximum torque for opening and closing should be 5 Nm.

If safety devices are present, pay the maximum attention during filling, soaking, and usage. For a correct use, make sure that cylinders are properly secured and usage and do not expose the cylinder to heat sources or directly to sun rays, that could increase the internal pressure of the container, and consequently cause the intervention of the safety device. In case this occurred, keep far from the gas containers until it's completely empty, air the room in order to prevent asphyxia and substitute the cylinder with one efficient.

MANUFACTURER IS NOT RESPONSIBLE OF DAMAGES COMING FROM ALTERATIONS, TAMPERING, AND INAPPROPRIATE USE OF THE VALVE.

Chromium plated external parts can be cleaned with disinfecting solutions not containing ammonia, using a clean cloth. Dry the device before using. Do not introduce any substance or foreign particles into the valve or into its inlet or outlet connections. Before using verify that the valve has no damaged parts and/or components. Damaged parts/components not subjected to pressure have to be substituted with original spare parts, by trained authorized personnel. When outlet connections or other parts under pressure are damaged, or when periodical cylinder maintenance is performed, device substitution is recommended.




This warning paper is part of the sales contract. Manufacturer preserved the right to change designs and materials as well as specifications and product information without prior notice.




Instructions for use VSB1 23 7 944 6362 INDEX A0 del 20-11-2008 ACTIVITY : 06290
















Motion: 001346000
 Motion Name: DOT - Registered SCUBA Cylinder
 Evidence Inventory
 1) Yellow high pressure gas cylinder, Part 1
 Regulator removed from the cylinder, approximately 22 inch by 8 inch, has the following marks as seen
 on the neck
 DOT-342 3000 HY 3444
 Cylinder has two decals
 Decal 1: DIFFUSEN for decompression use only - MOG (Maximum Operating Depth) 20 FSW (20 feet submerged water), MOG & MSW (30 meters submerged water), International Association of Nitrox & Technical Divers, Inc.
 Decal 2: "Tank & Valve Have Been Cleaned For Breathing, Oxygen Content 22 to 40%" is not punched out. "Tank & Valve Have Been Cleaned in Accordance with O₂ Service" is punched out at 2011. The month is uncertain.
 2) Yellow high pressure gas cylinder, Part 2
 Large section, measure the bottom, neck and valve opening, measure about 24 inches by 14 inches. Has the following markings near the neck
 (Hy 0001 463442 10 07 540 TC-34) 2107
 3) High Pressure Tank Valve, DIN Valve, manufactured by General, 5000 psi, 80 Bar, G.C. 1 type High Pressure Tank Oxygen (for Toxicity Tests and Corrosiveness FTSC Code 4150, 4, highly oxidizing, 1 non-toxic, 6 non-liquefied gas between 500 and 8000 psig, 0 non-corrosive, Class 2 Division 2.2 gas) use permits CG-1 (required in one end of the cylinder, regardless of length). A pressure regulator adaptor is present in the opening which has a fractured outlet. The metal particle filter is evident in the opening.
 3) Regulator by Dive Rite, serial number 12008135, fitted with regulator fitting. The opening is occupied by the fractured end of the pressure regulator adaptor.
 Attached:
 1. Black pressure line with dial gage on high pressure side of regulator. Dial gage face is heat affected and the gage is illegible.
 2. Length of green pressure line starting "WARNING Do not exceed 150 psi (17 bar) high pressure may cause damage or personal injury" no manufacturer identified. Distal end terminates unattached. Low pressure side



rti RTH Group, LLC
 10000 RTH Drive, Suite 100
 Dallas, Texas 75243
 (972) 412-1000
 www.rti-group.com

CHANGE OF EVIDENCE CUSTODY RECORD
 DATE: November 22, 2011
 RTI File Name: DOT - Registered Scuba Cylinder
 RTI File No.: 001346000
 The evidence herein described has been transferred on this date --
 To: Richard Loucks, PhD, PE From: U.S. Dept of Transportation Property Inventory Report
 Company: RTH Group, LLC Company:
 Description of Evidence (Note all markings):
 1. SEE ATTACHED LIST.
 Authorization of Sending Party: Authorization of Receiving Party:
 (Signature & Date) (Signature & Date)
 (Printed) (Printed)
 Richard B. Loucks, PhD, PE

U.S. DEPARTMENT OF TRANSPORTATION PROPERTY INVENTORY REPORT Page 1 of 1

Date: 11/9/11
 Location: (blank)
 Investigator: (blank)
 Case No.: (blank)

Case Name: (blank)
 Case Description: (blank)
 Case Number: (blank)

Date of Incident: 11/9/11
 Date of Report: 11/9/11



ITEM #	DESCRIPTION	QUANTITY	REMARKS
1	Scuba cylinder	1	
2	Separated piece of scuba cylinder	1	
3	valve, regulator and hose	1	

Nothing to report


ITEM #	DATE AND TIME RELEASED	DATE AND TIME RECEIVED	INITIALS AUTHORIZED	INITIALS RECEIVED
1	11/10/11	11/10/11	Richard	Richard
2	11/10/11	11/10/11	Richard	Richard
3	11/10/11	11/10/11	Richard	Richard

KEEP WITH PROPERTY


































































































































































































































































































































































































































































































































































































ATTACHMENT 7


EDS Spectra and Tables





























Air Cup

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
O	K_series	5.20	0.01749	26.49	0.23	SiO2	Yes	
F	K_series	1.06	0.00208	4.44	0.17	CaF2	Yes	
Mg	K_series	0.10	0.00063	1.00	0.06	MgO	Yes	
Al	K_series	3.65	0.02623	31.48	0.19	Al2O3	Yes	
Si	K_series	0.05	0.00038	0.49	0.04	SiO2	Yes	
S	K_series	0.05	0.00046	0.39	0.04	FeS2	Yes	
Ca	K_series	0.08	0.00069	0.42	0.04	Wollastonite	Yes	
Fe	K_series	0.06	0.00064	0.36	0.06	Fe	Yes	
Ni	K_series	2.69	0.02688	15.99	0.18	Ni	Yes	
Cu	K_series	1.94	0.01937	12.33	0.20	Cu	Yes	
Zn	K_series	0.90	0.00901	5.85	0.18	Zn	Yes	
Sn	L_series	0.11	0.00106	0.75	0.09	Sn	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 363 of 574

Pressure Regulator Adapter Debris

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
C				88.47				
O	K_series	2.37	0.00797	7.56	0.07	SiO2	Yes	
Mg	K_series	0.03	0.00021	0.04	0.00	MgO	Yes	
Al	K_series	1.75	0.01260	1.86	0.01	Al2O3	Yes	
Si	K_series	0.03	0.00025	0.03	0.00	SiO2	Yes	
S	K_series	0.02	0.00015	0.02	0.00	FeS2	Yes	
Cl	K_series	0.01	0.00010	0.01	0.00	NaCl	Yes	
Ca	K_series	0.11	0.00101	0.12	0.00	Wollastonite	Yes	
Fe	K_series	0.02	0.00019	0.02	0.00	Fe	Yes	
Cu	K_series	0.58	0.00579	0.79	0.02	Cu	Yes	
Zn	K_series	0.73	0.00730	1.00	0.02	Zn	Yes	
Pb	M_series	0.07	0.00067	0.08	0.01	PbTe	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 364 of 574

Pressure Regulator Adapter Base Metal

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	4.63	0.04633	60.35	0.37	Cu	Yes	
Zn	K_series	3.05	0.03054	39.65	0.37	Zn	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 365 of 574

Tank Inside Surface A

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
O	K_series	1.94	0.00654	48.57	0.47	SiO2	Yes	
Mg	K_series	0.05	0.00032	0.98	0.09	MgO	Yes	
Al	K_series	1.54	0.01103	27.92	0.30	Al2O3	Yes	
Si	K_series	0.14	0.00111	3.30	0.12	SiO2	Yes	
S	K_series	0.07	0.00064	1.42	0.08	FeS2	Yes	
Ca	K_series	0.33	0.00294	5.13	0.12	Wollastonite	Yes	
Ti	K_series	0.65	0.00647	12.37	0.21	Ti	Yes	
Fe	K_series	0.02	0.00016	0.30	0.10	Fe	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 366 of 574

Valve Body Thread Deposit

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
C				86.25				
O	K_series	1.54	0.00519	4.77	0.08	SiO2	Yes	
F	K_series	0.83	0.00164	0.90	0.03	CaF2	Yes	
Mg	K_series	0.07	0.00049	0.09	0.00	MgO	Yes	
Al	K_series	2.14	0.01535	2.38	0.01	Al2O3	Yes	
Si	K_series	0.03	0.00021	0.03	0.00	SiO2	Yes	
Fe	K_series	0.03	0.00025	0.03	0.01	Fe	Yes	
Ni	K_series	0.04	0.00036	0.04	0.01	Ni	Yes	
Cu	K_series	1.80	0.01795	2.42	0.03	Cu	Yes	
Zn	K_series	2.20	0.02201	2.98	0.04	Zn	Yes	
Pb	M_series	0.09	0.00079	0.10	0.01	PbTe	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 367 of 574

Valve Seat Body Exemplar 1

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	7.32	0.07318	62.01	0.36	Cu	Yes	
Zn	K_series	4.50	0.04498	37.99	0.36	Zn	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 368 of 574

Valve Seat Body Exemplar 2

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	4.45	0.04453	62.57	0.42	Cu	Yes	
Zn	K_series	2.67	0.02672	37.43	0.42	Zn	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 369 of 574

Valve Seat Body

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	8.82	0.08822	66.03	0.36	Cu	Yes	
Zn	K_series	4.55	0.04553	33.97	0.36	Zn	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 370 of 574

Valve Stem Fracture

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cu	K_series	3.93	0.03926	59.43	0.40	Cu	Yes	
Zn	K_series	2.69	0.02688	40.57	0.40	Zn	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 371 of 574

Valve Stem Coating

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
Cr	K_series	6.39	0.06390	54.35	0.24	Cr	Yes	
Ni	K_series	4.98	0.04982	45.65	0.24	Ni	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051

Exhibit Number: 5 Page Number: 372 of 574

Valve Stem Coating Debris

Element	Line Type	Apparent Concentration	k Ratio	Wt%	Wt% Sigma	Standard Label	Default Standard	Standard Calibration Date
O	K_series	3.66	0.01233	16.22	0.17	SiO2	Yes	
F	K_series	9.72	0.01908	53.47	0.24	CaF2	Yes	
Mg	K_series	0.27	0.00180	4.22	0.08	MgO	Yes	
Si	K_series	0.48	0.00377	5.15	0.07	SiO2	Yes	
Cr	K_series	1.23	0.01235	10.83	0.11	Cr	Yes	
Ni	K_series	0.46	0.00457	3.97	0.10	Ni	Yes	
Zn	K_series	0.65	0.00653	6.15	0.16	Zn	Yes	
Total:				100.00				



The Business of Science®

US DOT/PHMSA/OHMSFO/Southern Region

Report Number: 11287051


Exhibit Number: 5 Page Number: 373 of 574

ATTACHMENT 8

FTIR Spectra and Tables




rt113: Sample 1A, Valve Seat Body, Vertrel Solvent Wash, Nonvolatile on KBr window



rt13: Sample 1A, Valve Seat Body, Vertrel Solvent Wash, Nonvolatile on KBr Window


Peak	Pick	Intensity
682.1	847	97.145
758.0	443	98.588
810.6	154	97.588
1143.5	941	88.611
1179.9	196	88.518
1436.0	221	95.009
1551.1	171	95.249
1739.9	102	98.367
2925.4	87	99.538
2925.4	280	99.713

rt113: Sample 1A, Valve Seat Body, Vertrel Solvent Wash, Nonvolatile on KBr Window



Aramet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545


rti16: Sample 1B, Valve Stem, Vertrel Solvent wash, Nonvolatile on KBr window



rt16: Sample 1B, Valve Stem, Vertrel Solvent Wash, Nonvolatile on KBr Window


Peak cm-1	Pick	Intensity
543	960	98.684
814	844	96.021
1057	230	95.959
1149	578	77.497
1177	647	72.277
1360	262	93.322
266	502	99.411
294	278	94.390
299	85	90.3
33	8	98

rt118: Sample 1C, Relief Valve, Vertel Solvent Wash of Burst Disc Face, NV on KBr Win.




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545


rti18: Sample 1C, Relief Valve, Verrel Solvent Wash of Burst Disc Face, NV on KBr Win.




rt119: Sample 1D, Gland Nut, Vertrel Solvent Wash, Inside Bore, Nonvolatile, KBr Win.



rt119: Sample ID, Gland Nut, Vertrel Solvent Wash, Inside Bore, Nonvolatile, KBr Win.




rti20: Sample 1E, Valve Body, Deposits in 22mm Orifice, KBr 7mm Dia. Pressed Pellet




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti20: Sample 1E, Valve Body, Deposits in 22mm Orifice, KBr 7mm Dia. Pressed Pellet



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti21: Sample 1B, Valve Body, Deposits in 18mm Orifice, KBr 7mm Dia. Pressed Pellet



Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545


rti21: Sample 1E, Valve Body, Deposits in 18mm Orifice, KBr 7mm Dia. Pressed Pellet

Peak Pick

CM-1	Intensity
422.2	943.3
507.1	311.0
675.8	441.5
779.8	561.7
1114.0	420.0
1141.9	527.8
1145.8	332.2
1150.0	228.0
1153.9	208.8
1163.3	451.0
1164.3	884.0
1165.3	884.0
1166.3	884.0
1167.3	884.0
1168.3	884.0
1169.3	884.0
1170.3	884.0
1171.3	884.0
1172.3	884.0
1173.3	884.0
1174.3	884.0
1175.3	884.0
1176.3	884.0
1177.3	884.0
1178.3	884.0
1179.3	884.0
1180.3	884.0
1181.3	884.0
1182.3	884.0
1183.3	884.0
1184.3	884.0
1185.3	884.0
1186.3	884.0
1187.3	884.0
1188.3	884.0
1189.3	884.0
1190.3	884.0
1191.3	884.0
1192.3	884.0
1193.3	884.0
1194.3	884.0
1195.3	884.0
1196.3	884.0
1197.3	884.0
1198.3	884.0
1199.3	884.0
1200.3	884.0


Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti21: Sample 1E, Valve Body, Deposits in 18mm Orifice, KBr 7mm Dia. Pressed Pellet



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti22: Sample 1E, Valve Body, Deposits in 12mm Orifice, KBr 7mm Dia. Pressed Pellet




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti22: Sample 1E, Valve Body, Deposits in 12mm Orifice, KBr 7mm Dia. Pressed Pellet

Peak Pick


CM-1	Intensity
653.3311	89.666
653.3311	87.711
653.3311	85.411
653.3311	83.211
653.3311	81.011
653.3311	78.811
653.3311	76.611
653.3311	74.411
653.3311	72.211
653.3311	70.011
653.3311	67.811
653.3311	65.611
653.3311	63.411
653.3311	61.211
653.3311	59.011
653.3311	56.811
653.3311	54.611
653.3311	52.411
653.3311	50.211
653.3311	48.011
653.3311	45.811
653.3311	43.611
653.3311	41.411
653.3311	39.211
653.3311	37.011
653.3311	34.811
653.3311	32.611
653.3311	30.411
653.3311	28.211
653.3311	26.011
653.3311	23.811
653.3311	21.611
653.3311	19.411
653.3311	17.211
653.3311	15.011
653.3311	12.811
653.3311	10.611
653.3311	8.411
653.3311	6.211
653.3311	4.011
653.3311	1.811
653.3311	0.611

rti122: Sample 1E, Valve Body, Deposits in 12mm Orifice, KBr 7mm Dia. Pressed Pellet



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti23: Sample 1E, Valve Body, Deposits in 5mm Orifice, KBr 7mm Dia. Pressed Pellet




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545


rti23: Sample IE, Valve Body, Deposits in 5mm Orifice, KBr 7mm Dia. Pressed Pellet

Peak Pick
Cm-1
555:534
673:915
814:012
1092:341
2928:078
3419:093


Intensity
56:381
48:593
55:413
93:706
97:746
83:340
85:836



Anatnet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545




rti24: Sample 1F, Regulator Adapter Air Cup, Vertrel Solvent Wash, Nonvol. KBr Window




Transmittance

rti25: Sample 2aa, Regulator Body Diaphragm, Print Side, Vertrel SOL. Wash, NV KBr Win.




rti25: Sample 2aa, Regulator Body Diaphragm, Print Side, Vertrel Sol. Wash, NV KBr Win.



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti26: Sample 2aa Regulator Body Diaphragm, NonPrint Side, Vertrel Sol. Wash, NV KBr. W.




rt126: Sample 2aa, Regulator Body Diaphragm, NonPrint Side, Vertrel Sol. Wash, NV. KBr W.

Peak Pick


cm-1	Intensity
6211.1118	97.9689
6881.4225	94.6891
7721.5750	93.8849
7868.5308	93.6630
91067.8218	90.6657
11107.5330	89.0923
11145.7984	88.2580
11179.0891	87.7771
11235.9045	88.4255
11489.4445	88.2580
11589.9784	88.9957
11735.0440	88.2580
11851.2854	88.9957
11955.2854	88.2580
12034.6	88.9957

rti28: Sample 2aa Regulator Body, Deposits Already Extracted, KBr 7mm Dia. Pellet




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti28: Sample 2aa Regulator Body, Deposits Already Extracted, KBr 7mm Dia. Pellet



rti29: Sample 2ab, Retaining Ring, Vertrel Solvent Wash, Nonvolatile on KBr Window




rti29: Sample 2ab, Retaining Ring, Vertrel Solvent Wash, Nonvolatile on KBr Window

Peak Pick


Intensity	cm-1
99.4	882.5
99.5	845.2
99.5	817.4
99.5	783.0
99.5	750.0
99.5	710.0
99.5	677.7
99.5	645.5
99.5	612.8
99.5	580.3
99.5	547.5
99.5	515.0
99.5	482.5
99.5	450.0
99.5	417.5
99.5	385.0
99.5	352.5
99.5	320.0
99.5	287.5
99.5	255.0
99.5	222.5
99.5	190.0
99.5	157.5
99.5	125.0
99.5	92.5
99.5	60.0
99.5	27.5

rti29: Sample 2ab, Retaining Ring, Vertrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rt130: Sample 2ac, Spring Carrier, Vertrel Solvent Wash, Nonvolatile on KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

Rti30: Sample 2ac, Spring Carrier, Vertrel Solvent Wash, Nonvolatile on KBr Window

Peak Pick


Intensity	cm-1
97.660	884.7773
98.556	816.8012
97.2014	1109.3633
97.6214	1140.1723
97.5030	1173.9704
97.4970	1288.5401
97.7503	1448.5928
97.0756	1525.928
97.088	1633.508
97.978	1716.472
97.978	1849.541
97.978	2016.060
97.978	2297.040
97.978	2491.040
97.978	2693.508
97.978	2916.472
97.978	3168.012
97.978	3433.508
97.978	3716.472
97.978	4016.472
97.978	4333.508
97.978	4666.472
97.978	5016.472
97.978	5383.508
97.978	5766.472
97.978	6166.472
97.978	6583.508
97.978	7016.472
97.978	7466.472
97.978	7933.508
97.978	8416.472
97.978	8916.472
97.978	9433.508
97.978	9966.472

rti30: Sample 2ac, Spring Carrier, Vertrel Solvent Wash, Nonvolatile on KBr Window




Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti34: Sample 2ad, Metal Diaphragm Retainer Interior, Vertrel Sol. Wash, NV KBr Win.




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti35: Sample 2ad, Metal Diaphragm Retainer, Already Extracted Residue, KBr 7mm Pellet




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti35: Sample 2ad, Metal Diaphragm Retainer, Already Extracted Residue, KBr 7mm Pellet



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti36: Sample 2ae Main Regulator Body, + 2ef, 2ag, & 2ah, Vertrel SOL. Wash NV KBr Win



Aramet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545


ri36: Sample 2ae, Main Regulator Body, + 2ef, 2ag, & 2ah, Vertrel Sol. Wash NV KBr Win

Peak Pick


CM-1	Intensity
545	881
808	227
109	115
115	77
120	57
145	133
173	97
221	33
292	29
340	17

Intensity
97
82
79
73
74
69
67
63
53
46
39
28
27
21

rti36: Sample 2ae Main Regulator Body, + 2ef, 2ag, & 2ah, Vertrel Sol. Wash NV KBr Win




rti38: Sample 2aj, HP Diaphragm, Spring & Sleeve, Verrel Sol. Wash, Nonvol. KBr Wln.




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti39: Sample 2ak, Mating Half Reg. Adj. Adapter, Vertrel Sol. Wash, Nonvol. KBr Win.




rti39: Sample 2ak, Mating Half Reg. Adj. Adapter, Vertrel Sol. Wash, Nonvol. KBr Win.



Transmittance

rti40: Sample 2b, Green Hose, Interior, Vertrel Solvent Wash, Nonvolatile KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rt40: Sample 2b, Green House, Vertrel Solvent Wash, Nonvolatile KBr Window

Peak Pick


Intensity	cm-1
85.523	729.138
82.517	744.570
80.582	933.563
77.327	1033.396
70.397	1107.293
61.887	1124.559
46.880	1155.891
35.323	1157.329
33.394	1178.491
25.424	1289.749
22.318	1381.578
18.122	1449.181
15.333	1501.018
13.555	1579.048
11.333	1654.800
9.588	1738.115
8.227	1819.815
7.007	1915.488
5.880	2015.080
4.880	2119.404
3.880	2229.800
3.333	2335.018
2.880	2449.181
2.318	2579.048
1.815	2715.488
1.315	2857.329
0.815	2999.749
0.315	3149.181
0.215	3299.578
0.115	3449.969
0.015	3599.361
0.015	3749.753
0.015	3899.145
0.015	4049.537
0.015	4199.929
0.015	4349.321
0.015	4499.713
0.015	4649.105
0.015	4799.497
0.015	4949.889
0.015	5099.281
0.015	5249.673
0.015	5399.065
0.015	5549.457
0.015	5699.849
0.015	5849.241
0.015	5999.633
0.015	6149.025
0.015	6299.417
0.015	6449.809
0.015	6599.201
0.015	6749.593
0.015	6899.985
0.015	7049.377
0.015	7199.769
0.015	7349.161
0.015	7499.553
0.015	7649.945
0.015	7799.337
0.015	7949.729
0.015	8099.121
0.015	8249.513
0.015	8399.905
0.015	8549.297
0.015	8699.689
0.015	8849.081
0.015	8999.473
0.015	9149.865
0.015	9299.257
0.015	9449.649
0.015	9599.041
0.015	9749.433
0.015	9899.825
0.015	10049.217
0.015	10199.609
0.015	10349.001
0.015	10499.393
0.015	10649.785
0.015	10799.177
0.015	10949.569
0.015	11099.961
0.015	11249.353
0.015	11399.745
0.015	11549.137
0.015	11699.529
0.015	11849.921
0.015	11999.313
0.015	12149.705
0.015	12299.097
0.015	12449.489
0.015	12599.881
0.015	12749.273
0.015	12899.665
0.015	13049.057
0.015	13199.449
0.015	13349.841
0.015	13499.233
0.015	13649.625
0.015	13799.017
0.015	13949.409
0.015	14099.801
0.015	14249.193
0.015	14399.585
0.015	14549.977
0.015	14699.369
0.015	14849.761
0.015	14999.153
0.015	15149.545
0.015	15299.937
0.015	15449.329
0.015	15599.721
0.015	15749.113
0.015	15899.505
0.015	16049.897
0.015	16199.289
0.015	16349.681
0.015	16499.073
0.015	16649.465
0.015	16799.857
0.015	16949.249
0.015	17099.641
0.015	17249.033
0.015	17399.425
0.015	17549.817
0.015	17699.209
0.015	17849.601
0.015	17999.993
0.015	18149.385
0.015	18299.777
0.015	18449.169
0.015	18599.561
0.015	18749.953
0.015	18899.345
0.015	19049.737
0.015	19199.129
0.015	19349.521
0.015	19499.913
0.015	19649.305
0.015	19799.697
0.015	19949.089
0.015	20099.481
0.015	20249.873
0.015	20399.265
0.015	20549.657
0.015	20699.049
0.015	20849.441
0.015	20999.833
0.015	21149.225
0.015	21299.617
0.015	21449.009
0.015	21599.401
0.015	21749.793
0.015	21899.185
0.015	22049.577
0.015	22199.969
0.015	22349.361
0.015	22499.753
0.015	22649.145
0.015	22799.537
0.015	22949.929
0.015	23099.321
0.015	23249.713
0.015	23399.105
0.015	23549.497
0.015	23699.889
0.015	23849.281
0.015	23999.673
0.015	24149.065
0.015	24299.457
0.015	24449.849
0.015	24599.241
0.015	24749.633
0.015	24899.025
0.015	25049.417
0.015	25199.809
0.015	25349.201
0.015	25499.593
0.015	25649.985
0.015	25799.377
0.015	25949.769
0.015	26099.161
0.015	26249.553
0.015	26399.945
0.015	26549.337
0.015	26699.729
0.015	26849.121
0.015	26999.513
0.015	27149.905
0.015	27299.297
0.015	27449.689
0.015	27599.081
0.015	27749.473
0.015	27899.865
0.015	28049.257
0.015	28199.649
0.015	28349.041
0.015	28499.433
0.015	28649.825
0.015	28799.217
0.015	28949.609
0.015	29099.001
0.015	29249.393
0.015	29399.785
0.015	29549.177
0.015	29699.569
0.015	29849.961
0.015	29999.353
0.015	30149.745
0.015	30299.137
0.015	30449.529
0.015	30599.921
0.015	30749.313
0.015	30899.705
0.015	31049.097
0.015	31199.489
0.015	31349.881
0.015	31499.273
0.015	31649.665
0.015	31799.057
0.015	31949.449
0.015	32099.841
0.015	32249.233
0.015	32399.625
0.015	32549.017
0.015	32699.409
0.015	32849.801
0.015	32999.193
0.015	33149.585
0.015	33299.977
0.015	33449.369
0.015	33599.761
0.015	33749.153
0.015	33899.545
0.015	34049.937
0.015	34199.329
0.015	34349.721
0.015	34499.113
0.015	34649.505
0.015	34799.897
0.015	34949.289
0.015	35099.681
0.015	35249.073
0.015	35399.465
0.015	35549.857
0.015	35699.249
0.015	35849.641
0.015	35999.033
0.015	36149.425
0.015	36299.817
0.015	36449.209
0.015	36599.601
0.015	36749.993
0.015	36899.385
0.015	37049.777
0.015	37199.169
0.015	37349.561
0.015	37499.953
0.015	37649.345
0.015	37799.737
0.015	37949.129
0.015	38099.521
0.015	38249.913
0.015	38399.305
0.015	38549.697
0.015	38699.089
0.015	38849.481
0.015	38999.873
0.015	39149.265
0.015	39299.657
0.015	39449.049
0.015	39599.441
0.015	39749.833
0.015	39899.225
0.015	40049.617
0.015	40199.009
0.015	40349.401
0.015	40499.793
0.015	40649.185
0.015	40799.577
0.015	40949.969
0.015	41099.361
0.015	41249.753
0.015	41399.145
0.015	41549.537
0.015	41699.929
0.015	41849.321
0.015	41999.713
0.015	42149.105
0.015	42299.497
0.015	42449.889
0.015	42599.281
0.015	42749.673
0.015	42899.065
0.015	43049.457
0.015	43199.849
0.015	43349.241
0.015	43499.633
0.015	43649.025
0.015	43799.417
0.015	43949.809
0.015	44099.201
0.015	44249.593
0.015	44399.985
0.015	44549.377
0.015	44699.769
0.015	44849.161
0.015	44999.553
0.015	45149.945
0.015	45299.337
0.015	45449.729
0.015	45599.121
0.015	45749.513
0.015	45899.905
0.015	46049.297
0.015	46199.689
0.015	46349.081
0.015	46499.473
0.015	46649.865
0.015	46799.257
0.015	46949.649
0.015	47099.041
0.015	47249.433
0.015	47399.825
0.015	47549.217
0.015	47699.609
0.015	47849.001
0.015	47999.393
0.015	48149.785
0.015	48299.177
0.015	48449.569
0.015	48599.961
0.015	48749.353
0.015	48899.745
0.015	49049.137
0.015	49199.529
0.015	49349.921
0.015	49499.313
0.015	49649.705
0.015	49799.097
0.015	49949.489
0.015	50099.881
0.015	50249.273
0.015	50399.665
0.015	50549.057
0.015	50699.449
0.015	50849.841
0.015	50999.233
0.015	51149.625
0.015	51299.017
0.015	51449.409
0.015	51599.801
0.015	51749.193
0.015	51899.585
0.015	52049.977
0.015	52199.369
0.015	52349.761
0.015	52499.153
0.015	52649.545
0.015	52799.937
0.015	52949.329
0.015	53099.721
0.015	53249.113
0.015	53399.505
0.015	53549.897
0.015	53699.289
0.015	53849.681
0.015	53999.073
0.015	54149.465
0.015	54299.857
0.015	54449.249
0.015	54599.641
0.015	54749.033
0.015	54899.425
0.015	55049.817
0.015	55199.209
0.015	55349.601
0.015	55499.993
0.015	55649.385
0.015	55799.777
0.015	55949.169
0.015	56099.561
0.015	56249.953
0.015	56399.345
0.015	56549.737
0.015	56699.129
0.015	56849.521
0.015	56999.913
0.015	57149.305
0.015	57299.697
0.015	57449.089
0.015	57599.481
0.015	57749.873
0.015	57899.265
0.015	58049.657
0.015	58199.049
0.015	58349.441
0.015	58499.833
0.015	58649.225
0.015	58799.617
0.015	58949.009
0.015	59099.401
0.015	59249.793
0.015	59399.185
0.015	59549.577
0.015	59699.969
0.015	59849.361
0.015	59999.753
0.015	60149.145
0.015	60299.537
0.015	60449.929
0.015	60599.321
0.015	60749.713
0.015	60899.105
0.015	61049.497
0.015	61199.889
0.015	61349.281
0.015	61499.673
0.015	61649.065
0.015	61799.457
0.015	61949.849
0.015	62099.241
0.015	62249.633
0.015	62399.025
0.015	62

rti40: Sample 2b, Green Hose, Interior, Vertrel Solvent Wash, Nonvolatile KBr Window



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti31: Sample 3A, Valve Stem Exemplar, Vertrel Solvent Wash, Nonvolatile on KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545


rti31: Sample 3A, Valve Stem Exemplar, Vertrel Solvent Wash, Nonvolatile on KBr Window

Peak Pick

cm-1	Intensity
451.377	97.659
466.103	97.327
540.103	98.577
582.844	93.309
758.012	93.469
833.301	93.542
1067.791	77.018
1147.871	71.184
1381.143	63.183
1622.834	59.473
2920.71	39.7




rt131: Sample 3A, Valve Stem Exemplar, Vertrel Solvent wash, Nonvolatile on KBr window



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rt132: Sample 3B, Gland Nut Bore Exemplar, Vertrel Sol, Wash, NV KBr W.




Anamet, Inc.
26702 Eden Landing Road
Suite 3
Hayward, CA 94545

rti32: Sample 3B, Gland Nut Bore Exemplar, Vertrel Sol. Wash, NV KBr W.

Peak Pick

Intensity	cm-1
99.6339	543.9760
99.1422	624.5760
97.9559	758.0733
96.2466	814.0122
92.2222	1097.7712
91.5839	1146.2173
88.8396	1254.8228
81.2972	1457.9717
97.44	2957.7

rti33: Sample 3C, Valve Seat Body Exemplar, Vertrel Solvent Wash, Nonvol. KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti33 Sample 3C, Valve Seat Body Exemplar, Vertrel Solvent Wash, Nonvol. KBr Window


Peak Pick

Intensity	Retention Time
998.88813	0.322
997.53333	0.702
997.34894	0.833
884.31584	1.509
883.33043	1.937
883.14759	2.147
995.64291	2.595
992.34212	2.729
992.34212	3.421
992.34212	4.212
992.34212	5.000
992.34212	5.788
992.34212	6.576
992.34212	7.364
992.34212	8.152
992.34212	8.940
992.34212	9.728
992.34212	10.516
992.34212	11.304
992.34212	12.092
992.34212	12.880
992.34212	13.668
992.34212	14.456
992.34212	15.244
992.34212	16.032
992.34212	16.820
992.34212	17.608
992.34212	18.396
992.34212	19.184
992.34212	19.972
992.34212	20.760
992.34212	21.548
992.34212	22.336
992.34212	23.124
992.34212	23.912
992.34212	24.700
992.34212	25.488
992.34212	26.276
992.34212	27.064
992.34212	27.852
992.34212	28.640
992.34212	29.428
992.34212	30.216
992.34212	31.004
992.34212	31.792
992.34212	32.580
992.34212	33.368
992.34212	34.156
992.34212	34.944
992.34212	35.732
992.34212	36.520
992.34212	37.308
992.34212	38.096
992.34212	38.884
992.34212	39.672
992.34212	40.460
992.34212	41.248
992.34212	42.036
992.34212	42.824
992.34212	43.612
992.34212	44.400
992.34212	45.188
992.34212	45.976
992.34212	46.764
992.34212	47.552
992.34212	48.340
992.34212	49.128
992.34212	49.916
992.34212	50.704
992.34212	51.492
992.34212	52.280
992.34212	53.068
992.34212	53.856
992.34212	54.644
992.34212	55.432
992.34212	56.220
992.34212	57.008
992.34212	57.796
992.34212	58.584
992.34212	59.372
992.34212	60.160
992.34212	60.948
992.34212	61.736
992.34212	62.524
992.34212	63.312
992.34212	64.100
992.34212	64.888
992.34212	65.676
992.34212	66.464
992.34212	67.252
992.34212	68.040
992.34212	68.828
992.34212	69.616
992.34212	70.404
992.34212	71.192
992.34212	71.980
992.34212	72.768
992.34212	73.556
992.34212	74.344
992.34212	75.132
992.34212	75.920
992.34212	76.708
992.34212	77.496
992.34212	78.284
992.34212	79.072
992.34212	79.860
992.34212	80.648
992.34212	81.436
992.34212	82.224
992.34212	83.012
992.34212	83.800
992.34212	84.588
992.34212	85.376
992.34212	86.164
992.34212	86.952
992.34212	87.740
992.34212	88.528
992.34212	89.316
992.34212	90.104
992.34212	90.892
992.34212	91.680
992.34212	92.468
992.34212	93.256
992.34212	94.044
992.34212	94.832
992.34212	95.620
992.34212	96.408
992.34212	97.196
992.34212	97.984
992.34212	98.772
992.34212	99.560
992.34212	100.348
992.34212	101.136
992.34212	101.924
992.34212	102.712
992.34212	103.500
992.34212	104.288
992.34212	105.076
992.34212	105.864
992.34212	106.652
992.34212	107.440
992.34212	108.228
992.34212	109.016
992.34212	109.804
992.34212	110.592
992.34212	111.380
992.34212	112.168
992.34212	112.956
992.34212	113.744
992.34212	114.532
992.34212	115.320
992.34212	116.108
992.34212	116.896
992.34212	117.684
992.34212	118.472
992.34212	119.260
992.34212	120.048
992.34212	120.836
992.34212	121.624
992.34212	122.412
992.34212	123.200
992.34212	123.988
992.34212	124.776
992.34212	125.564
992.34212	126.352
992.34212	127.140
992.34212	127.928
992.34212	128.716
992.34212	129.504
992.34212	130.292
992.34212	131.080
992.34212	131.868
992.34212	132.656
992.34212	133.444
992.34212	134.232
992.34212	135.020
992.34212	135.808
992.34212	136.596
992.34212	137.384
992.34212	138.172
992.34212	138.960
992.34212	139.748
992.34212	140.536
992.34212	141.324
992.34212	142.112
992.34212	142.900
992.34212	143.688
992.34212	144.476
992.34212	145.264
992.34212	146.052
992.34212	146.840
992.34212	147.628
992.34212	148.416
992.34212	149.204
992.34212	150.000

rti33: Sample 3C, Valve Seat Body Exemplar, Vertrel Solvent Wash, Nonvol. KBr Window




Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti3: Tank Interior, Location A #1, Vertrel Solvent Wash, NV KBr Win.



Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti4: Tank Interior, Location A #2, Vertrel Solvent Wash, NV KBr Win.




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rt14: Tank Interior, Location A #2, Vertrel Solvent Wash, NV KBr Win.

Peak Pick


CM-1	Intensity
5991.341	955.361
6693.680	955.361
7022.680	897.809
7143.360	897.809
7277.580	897.809
7436.020	897.809
7545.200	897.809
7622.550	897.809
7733.600	897.809
7801.400	897.809
7855.080	897.809
7933.440	897.809
8011.440	897.809
8089.440	897.809
8167.440	897.809
8245.440	897.809
8323.440	897.809
8401.440	897.809
8479.440	897.809
8557.440	897.809
8635.440	897.809
8713.440	897.809
8791.440	897.809
8869.440	897.809
8947.440	897.809
9025.440	897.809
9103.440	897.809
9181.440	897.809
9259.440	897.809
9337.440	897.809
9415.440	897.809
9493.440	897.809
9571.440	897.809
9649.440	897.809
9727.440	897.809
9805.440	897.809
9883.440	897.809
9961.440	897.809
10039.440	897.809
10117.440	897.809
10195.440	897.809
10273.440	897.809
10351.440	897.809
10429.440	897.809
10507.440	897.809
10585.440	897.809
10663.440	897.809
10741.440	897.809
10819.440	897.809
10897.440	897.809
10975.440	897.809
11053.440	897.809
11131.440	897.809
11209.440	897.809
11287.440	897.809
11365.440	897.809
11443.440	897.809
11521.440	897.809
11599.440	897.809
11677.440	897.809
11755.440	897.809
11833.440	897.809
11911.440	897.809
11989.440	897.809
12067.440	897.809
12145.440	897.809
12223.440	897.809
12301.440	897.809
12379.440	897.809
12457.440	897.809
12535.440	897.809
12613.440	897.809
12691.440	897.809
12769.440	897.809
12847.440	897.809
12925.440	897.809
13003.440	897.809
13081.440	897.809
13159.440	897.809
13237.440	897.809
13315.440	897.809
13393.440	897.809
13471.440	897.809
13549.440	897.809
13627.440	897.809
13705.440	897.809
13783.440	897.809
13861.440	897.809
13939.440	897.809
14017.440	897.809
14095.440	897.809
14173.440	897.809
14251.440	897.809
14329.440	897.809
14407.440	897.809
14485.440	897.809
14563.440	897.809
14641.440	897.809
14719.440	897.809
14797.440	897.809
14875.440	897.809
14953.440	897.809
15031.440	897.809
15109.440	897.809
15187.440	897.809
15265.440	897.809
15343.440	897.809
15421.440	897.809
15499.440	897.809
15577.440	897.809
15655.440	897.809
15733.440	897.809
15811.440	897.809
15889.440	897.809
15967.440	897.809
16045.440	897.809
16123.440	897.809
16201.440	897.809
16279.440	897.809
16357.440	897.809
16435.440	897.809
16513.440	897.809
16591.440	897.809
16669.440	897.809
16747.440	897.809
16825.440	897.809
16903.440	897.809
16981.440	897.809
17059.440	897.809
17137.440	897.809
17215.440	897.809
17293.440	897.809
17371.440	897.809
17449.440	897.809
17527.440	897.809
17605.440	897.809
17683.440	897.809
17761.440	897.809
17839.440	897.809
17917.440	897.809
17995.440	897.809
18073.440	897.809
18151.440	897.809
18229.440	897.809
18307.440	897.809
18385.440	897.809
18463.440	897.809
18541.440	897.809
18619.440	897.809
18697.440	897.809
18775.440	897.809
18853.440	897.809
18931.440	897.809
19009.440	897.809
19087.440	897.809
19165.440	897.809
19243.440	897.809
19321.440	897.809
19399.440	897.809
19477.440	897.809
19555.440	897.809
19633.440	897.809
19711.440	897.809
19789.440	897.809
19867.440	897.809
19945.440	897.809
20023.440	897.809
20101.440	897.809
20179.440	897.809
20257.440	897.809
20335.440	897.809
20413.440	897.809
20491.440	897.809
20569.440	897.809
20647.440	897.809
20725.440	897.809
20803.440	897.809
20881.440	897.809
20959.440	897.809
21037.440	897.809
21115.440	897.809
21193.440	897.809
21271.440	897.809
21349.440	897.809
21427.440	897.809
21505.440	897.809
21583.440	897.809
21661.440	897.809
21739.440	897.809
21817.440	897.809
21895.440	897.809
21973.440	897.809
22051.440	897.809
22129.440	897.809
22207.440	897.809
22285.440	897.809
22363.440	897.809
22441.440	897.809
22519.440	897.809
22597.440	897.809
22675.440	897.809
22753.440	897.809
22831.440	897.809
22909.440	897.809
22987.440	897.809
23065.440	897.809
23143.440	897.809
23221.440	897.809
23299.440	897.809
23377.440	897.809
23455.440	897.809
23533.440	897.809
23611.440	897.809
23689.440	897.809
23767.440	897.809
23845.440	897.809
23923.440	897.809
24001.440	897.809
24079.440	897.809
24157.440	897.809
24235.440	897.809
24313.440	897.809
24391.440	897.809
24469.440	897.809
24547.440	897.809
24625.440	897.809
24703.440	897.809
24781.440	897.809
24859.440	897.809
24937.440	897.809
25015.440	897.809
25093.440	897.809
25171.440	897.809
25249.440	897.809
25327.440	897.809
25405.440	897.809
25483.440	897.809
25561.440	897.809
25639.440	897.809
25717.440	897.809
25795.440	897.809
25873.440	897.809
25951.440	897.809
26029.440	897.809
26107.440	897.809
26185.440	897.809
26263.440	897.809
26341.440	897.809
26419.440	897.809
26497.440	897.809
26575.440	897.809
26653.440	897.809
26731.440	897.809
26809.440	897.809
26887.440	897.809
26965.440	897.809
27043.440	897.809
27121.440	897.809
27199.440	897.809
27277.440	897.809
27355.440	897.809
27433.440	897.809
27511.440	897.809
27589.440	897.809
27667.440	897.809
27745.440	897.809
27823.440	897.809
27901.440	897.809
27979.440	897.809
28057.440	897.809
28135.440	897.809
28213.440	897.809
28291.440	897.809
28369.440	897.809
28447.440	897.809
28525.440	897.809
28603.440	897.809
28681.440	897.809
28759.440	897.809
28837.440	897.809
28915.440	897.809
28993.440	897.809
29071.440	897.809
29149.440	897.809
29227.440	897.809
29305.440	897.809
29383.440	897.809
29461.440	897.809
29539.440	897.809
29617.440	897.809
29695.440	897.809
29773.440	897.809
29851.440	897.809
29929.440	897.809
30007.440	897.809
30085.440	897.809
30163.440	897.809
30241.440	897.809
30319.440	897.809
30397.440	897.809
30475.440	897.809
30553.440	897.809
30631.440	897.809
30709.440	897.809
30787.440	897.809
30865.440	897.809
30943.440	897.809
31021.440	897.809
31099.440	897.809
31177.440	897.809
31255.440	897.809
31333.440	897.809
31411.440	897.809
31489.440	897.809
31567.440	897.809
31645.440	897.809
31723.440	897.809
31801.440	897.809
31879.440	897.809
31957.440	897.809
32035.440	897.809
32113.440	897.809
32191.440	897.809
32269.440	897.809
32347.440	897.809
32425.440	897.809
32503.440	897.809
32581.440	897.809
32659.440	897.809
32737.440	897.809
32815.440	897.809
32893.440	897.809
32971.440	897.809
33049.440	897.809
33127.440	897.809
33205.440	897.809
33283.440	897.809
33361.440	897.809
33439.440	897.809
33517.440	897.809
33595.440	897.809
33673.440	897.809
33751.440	897.809
33829.440	897.809
33907.440	897.809
33985.440	897.809
34063.440	897.809
34141.440	897.809
34219.440	897.809
34297.440	897.809
34375.440	897.809
34453.440	897.809
34531.440	897.809
34609.440	897.809
34687.440	897.809
34765.440	897.809
34843.440	897.809
34921.440	897.809
35000.440	897.809
35078.440	897.809
35156.440	897.809
35234.440	897.809
35312.440	897.809
35390.440	897.809
35468.440	897.809
35546.440	897.809
35624.440	897.809
35702.440	897.809
35780.440	897.809
35858.440	897.809
35936.440	897.809
36014.440	897.809
36092.440	897.809
36170.440	897.809
36248.440	897.809
36326.440	897.809
36404.440	897.809
36482.440	897.809
36560.440	897.809
36638.440	897.809
36716.440	897.809
36794.440	897.809
36872.440	897.809
36950.440	897.809
37028.440	897.809
37106.440	897.809
37184.440	897.809
37262.440	897.809
37340.440	897.809
37418.440	897.809
37496.440	897.809
37574.440	897.809
37652.440	897.809
37730.440	897.809
37808.440	897.809
37886.440	

rti4: Tank Interior, Location A #2, Vertrel Solvent Wash, NV KBr Win.




Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti5: Tank Interior, Location B, Verrel Solvent Wash, Nonvolatile on KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rt15: Tank Interior, Location B, Vertrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rtt16: Tank Interior, Location C, Vertrel Solvent Wash, Nonvolatile on KBr Window



Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545


rt6: Tank Interior, Location C, Vertrel Solvent Wash, Nonvolatile on KBr Window

Peak Pick

Intensity	cm-1
93.755	1900
91.825	1774
87.645	1523
87.395	1516
77.654	1483
76.510	1468
68.488	1449
67.555	1414
67.435	1388
65.625	1366
65.426	1350
65.015	1303
65.015	1299
65.015	1297
65.015	1296
65.015	1295
65.015	1294
65.015	1293
65.015	1292
65.015	1291
65.015	1290
65.015	1289
65.015	1288
65.015	1287
65.015	1286
65.015	1285
65.015	1284
65.015	1283
65.015	1282
65.015	1281
65.015	1280
65.015	1279
65.015	1278
65.015	1277
65.015	1276
65.015	1275
65.015	1274
65.015	1273
65.015	1272
65.015	1271
65.015	1270
65.015	1269
65.015	1268
65.015	1267
65.015	1266
65.015	1265
65.015	1264
65.015	1263
65.015	1262
65.015	1261
65.015	1260
65.015	1259
65.015	1258
65.015	1257
65.015	1256
65.015	1255
65.015	1254
65.015	1253
65.015	1252
65.015	1251
65.015	1250
65.015	1249
65.015	1248
65.015	1247
65.015	1246
65.015	1245
65.015	1244
65.015	1243
65.015	1242
65.015	1241
65.015	1240
65.015	1239
65.015	1238
65.015	1237
65.015	1236
65.015	1235
65.015	1234
65.015	1233
65.015	1232
65.015	1231
65.015	1230
65.015	1229
65.015	1228
65.015	1227
65.015	1226
65.015	1225
65.015	1224
65.015	1223
65.015	1222
65.015	1221
65.015	1220
65.015	1219
65.015	1218
65.015	1217
65.015	1216
65.015	1215
65.015	1214
65.015	1213
65.015	1212
65.015	1211
65.015	1210
65.015	1209
65.015	1208
65.015	1207
65.015	1206
65.015	1205
65.015	1204
65.015	1203
65.015	1202
65.015	1201
65.015	1200
65.015	1199
65.015	1198
65.015	1197
65.015	1196
65.015	1195
65.015	1194
65.015	1193
65.015	1192
65.015	1191
65.015	1190
65.015	1189
65.015	1188
65.015	1187
65.015	1186
65.015	1185
65.015	1184
65.015	1183
65.015	1182
65.015	1181
65.015	1180
65.015	1179
65.015	1178
65.015	1177
65.015	1176
65.015	1175
65.015	1174
65.015	1173
65.015	1172
65.015	1171
65.015	1170
65.015	1169
65.015	1168
65.015	1167
65.015	1166
65.015	1165
65.015	1164
65.015	1163
65.015	1162
65.015	1161
65.015	1160
65.015	1159
65.015	1158
65.015	1157
65.015	1156
65.015	1155
65.015	1154
65.015	1153
65.015	1152
65.015	1151
65.015	1150
65.015	1149
65.015	1148
65.015	1147
65.015	1146
65.015	1145
65.015	1144
65.015	1143
65.015	1142
65.015	1141
65.015	1140
65.015	1139
65.015	1138
65.015	1137
65.015	1136
65.015	1135
65.015	1134
65.015	1133
65.015	1132
65.015	1131
65.015	1130
65.015	1129
65.015	1128
65.015	1127
65.015	1126
65.015	1125
65.015	1124
65.015	1123
65.015	1122
65.015	1121
65.015	1120
65.015	1119
65.015	1118
65.015	1117
65.015	1116
65.015	1115
65.015	1114
65.015	1113
65.015	1112
65.015	1111
65.015	1110
65.015	1109
65.015	1108
65.015	1107
65.015	1106
65.015	1105
65.015	1104
65.015	1103
65.015	1102
65.015	1101
65.015	1100
65.015	1099
65.015	1098
65.015	1097
65.015	1096
65.015	1095
65.015	1094
65.015	1093
65.015	1092
65.015	1091
65.015	1090
65.015	1089
65.015	1088
65.015	1087
65.015	1086
65.015	1085
65.015	1084
65.015	1083
65.015	1082
65.015	1081
65.015	1080
65.015	1079
65.015	1078
65.015	1077
65.015	1076
65.015	1075
65.015	1074
65.015	1073
65.015	1072
65.015	1071
65.015	1070
65.015	1069
65.015	1068
65.015	1067
65.015	1066
65.015	1065
65.015	1064
65.015	1063
65.015	1062
65.015	1061
65.015	1060
65.015	1059
65.015	1058
65.015	1057
65.015	1056
65.015	1055
65.015	1054
65.015	1053
65.015	1052
65.015	1051
65.015	1050
65.015	1049
65.015	1048
65.015	1047
65.015	1046
65.015	1045
65.015	1044
65.015	1043
65.015	1042
65.015	1041
65.015	1040
65.015	1039
65.015	1038
65.015	1037
65.015	1036
65.015	1035
65.015	1034
65.015	1033
65.015	1032
65.015	1031
65.015	1030
65.015	1029
65.015	1028
65.015	1027
65.015	1026
65.015	1025
65.015	1024
65.015	1023
65.015	1022
65.015	1021
65.015	1020
65.015	1019
65.015	1018
65.015	1017
65.015	1016
65.015	1015
65.015	1014
65.015	1013
65.015	1012
65.015	1011
65.015	1010
65.015	1009
65.015	1008
65.015	1007
65.015	1006
65.015	1005
65.015	1004
65.015	1003
65.015	1002
65.015	1001
65.015	1000


Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rti6: Tank Interior, Location C, Vertrel Solvent Wash, Nonvolatile on KBr window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti7: Tank Interior, Location C', Vertrel Solvent Wash, Nonvolatile on KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti7: Tank Interior, Location C', Vertrel Solvent Wash, Nonvolatile on KBr Window



rti8: Tank Interior, Location D, Vertrel Solvent Wash, Nonvolatile on KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rti8: Tank Interior, Location D, Vertrel Solvent Wash, Nonvolatile on KBr Window

Peak Pick


Intensity
 133561
 32903
 36730
 42081
 43290
 43590
 43690
 43790
 43890
 43990
 44090
 44190
 44290
 44390
 44490
 44590
 44690
 44790
 44890
 44990
 45090
 45190
 45290
 45390
 45490
 45590
 45690
 45790
 45890
 45990
 46090
 46190
 46290
 46390
 46490
 46590
 46690
 46790
 46890
 46990
 47090
 47190
 47290
 47390
 47490
 47590
 47690
 47790
 47890
 47990
 48090
 48190
 48290
 48390
 48490
 48590
 48690
 48790
 48890
 48990
 49090
 49190
 49290
 49390
 49490
 49590
 49690
 49790
 49890
 49990
 50090

rtt18: Tank Interior, Location D, Vertrel Solvent Wash, Nonvolatile on KBr window



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

rt19: Tank Exterior, Yellow Paint, Vertrel Solvent Extracted, Nonvolatile, KBr Window




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

rt19: Tank Exterior, Yellow Paint, Vertrel Solvent Extracted, Nonvolatile, KBr Window

Peak Pick


Intensity	CM-1
90.829	929.1
97.788	729.3
77.470	800.0
53.422	877.1
28.652	101.8
22.814	110.3
22.477	111.6
22.477	119.2
22.477	126.5
22.477	137.5
22.477	145.1
22.477	151.3
22.477	158.9
22.477	165.3
22.477	174.3
22.477	182.0
22.477	192.4
22.477	204.4
22.477	220.4
22.477	235.4
22.477	240.4
22.477	245.4
22.477	255.4
22.477	265.4
22.477	275.4
22.477	285.4
22.477	295.4
22.477	305.4
22.477	315.4
22.477	325.4
22.477	335.4
22.477	345.4
22.477	355.4
22.477	365.4
22.477	375.4
22.477	385.4
22.477	395.4
22.477	405.4
22.477	415.4
22.477	425.4
22.477	435.4
22.477	445.4
22.477	455.4
22.477	465.4
22.477	475.4
22.477	485.4
22.477	495.4
22.477	505.4
22.477	515.4
22.477	525.4
22.477	535.4
22.477	545.4
22.477	555.4
22.477	565.4
22.477	575.4
22.477	585.4
22.477	595.4
22.477	605.4
22.477	615.4
22.477	625.4
22.477	635.4
22.477	645.4
22.477	655.4
22.477	665.4
22.477	675.4
22.477	685.4
22.477	695.4
22.477	705.4
22.477	715.4
22.477	725.4
22.477	735.4
22.477	745.4
22.477	755.4
22.477	765.4
22.477	775.4
22.477	785.4
22.477	795.4
22.477	805.4
22.477	815.4
22.477	825.4
22.477	835.4
22.477	845.4
22.477	855.4
22.477	865.4
22.477	875.4
22.477	885.4
22.477	895.4
22.477	905.4
22.477	915.4
22.477	925.4
22.477	935.4
22.477	945.4
22.477	955.4
22.477	965.4
22.477	975.4
22.477	985.4
22.477	995.4
22.477	1005.4

rti9: Tank Exterior, Yellow Paint, Vertrel Solvent Extracted, Nonvolatile, KBr Window



Anamet, Inc.
 26102 Eden Landing Road
 Suite 3
 Hayward, CA 94545

RT111: Tank Interior, White Material, Six Inches to Right of Location A, KBr Pellet




Anamet, Inc.
26102 Eden Landing Road
Suite 3
Hayward, CA 94545

RT111: Tank Interior, White Material, Six Inches to Right of Location A, KBr Pellet

Peak Pick

Intensity	cm-1
93.197	468
75.997	601
32.882	669
29.859	677
28.219	714
27.591	720
26.519	732
25.457	740
24.597	755
23.911	772
22.657	814
21.997	832
21.341	857
20.597	885
19.911	907
19.246	922
18.589	940
17.911	955
17.246	972
16.589	987
15.911	1000

RT111: Tank Interior, White Material, Six Inches to Right of Location A, KBr Pellet





Anamet, inc. *MATERIALS ENGINEERING & LABORATORY TESTING*

26102 Eden Landing Road Suite 3-Hayward CA 94545(510)887-8811-Fax (510)887-8427

March 22, 2012

Lab. No. 5004.7109 RTI Group

FTIR Spectra Characterization

Sample	Part No.	Spectrum No.	Characterization
Tank Interior	Loc. A, #1	rti3	vinyl acetate and ester type polymers + calcium sulfate
Tank Interior	Location A, #2	rti4	calcium sulfate + ester type polymer
Tank Interior	Location B	rti5	calcium sulfate + ester type polymers
Tank Interior	Location C	rti6	calcium sulfate
Tank Interior	Location C'	rti7	terephthalate type polyester
Tank Interior	Location D	rti8	calcium sulfate
Tank Exterior	Yellow Paint	rti9	terephthalate type polyester
Tank Interior	White material 6" to right of Location A	rti11	calcium sulfate
Valve Seat Body	1A	rti13	fluoro-polymer
Valve Stem	1B	rti16	fluoro-polymer (fluorine confirmed by EDS)
Relief Valve	1C	rti18	fluoro-polymer
Gland Nut	1D	rti19	fluoro-polymer
Valve Body	1E, 22mm orifice	rti20	silicate(s) + ammonium salt + oxides
Valve Body	1E, 18mm orifice	rti21	silicate(s) + ammonium salt + oxides
Valve Body	1E, 12mm orifice	rti22	silicate(s) + ammonium salt + oxides
Valve Body	1E, 5mm orifice	rti23	oxides
Regulator Adapter Air Cup	1F	rti24	fluoro-polymer
Regulator Body Diaphragm	2aa, Print Side	rti25	aromatic ester
Regulator Body Diaphragm	2aa, Non-Print Side	rti26	aromatic ester
Regulator Body	2aa, Non-Print Side	rti28	calcium sulfate + calcium carbonate



FTIR Spectra Characterization

Sample	Part No.	Spectrum No.	Characterization
Retaining Ring	2ab	rti29	fluoro-polymer + ester
Spring Carrier	2ac	rti30	fluoro-polymer
Metal Diaphragm Retainer, Interior	2ad	rti34	fluoro-polymer + ester
Metal Diaphragm Retainer	2ad	rti35	fluoro-polymer + silicate(s) + oxides
Main Regulator Body	2ae, 2ef, 2ag, & 2ah	rti36	fluoro-polymer + ester
High Pressure Diaphragm & Adjustment Sleeve	2aj'	rti38	fluoro-polymer + ester
Mating Half regulator Adjuster Adapter	2ak	rti39	fluoro-polymer
Green Hose, Interior	2b	rti40	phthalate type ester
Valve Stem Exemplar	3A	rti31	fluoro-polymer
Gland Nut Bore Exemplar	3B	rti32	fluoro-polymer
Valve Seat Body Exemplar	3C	rti33	fluoro-polymer + ester

Submitted by:

Harold R. Harlan,
Director, Organic Chemistry Laboratories

ATTACHMENT 9

Micrographs with HF Etch and Kellers Etch
Micrograph images, in order of appearance

HF Etch

Sample A Center 50x
Sample A Center 200x
Sample A Fracture 50x
Sample A Fracture 200x
Sample A Inside Surface 50x
Sample A Inside Surface 200x

Sample B Center 50x
Sample B Center 200x
Sample B Fracture 50x
Sample B Fracture 200x

Sample C Center 50x
Sample C Center 200x
Sample C Fracture 50x
Sample C Fracture 200x

Sample D Center 50x
Sample D Center 200x
Sample D Fracture 50x
Sample D Fracture 200x
Sample D Outside Surface 50x
Sample D Outside Surface 200x

Attachment 9, continued


Kellers Etch

Sample A Center 50x
Sample A Center 200x
Sample A Fracture 50x
Sample A Fracture 200x
Sample A Inside Surface 50x
Sample A Inside Surface 200x


Sample B Center 50x
Sample B Center 200x
Sample B Fracture 50x
Sample B Fracture 200x

Sample C Center 50x
Sample C Center 200x
Sample C Fracture 50x
Sample C Fracture 200x


Sample D Center 50x
Sample D Center 200x
Sample D Fracture 50x
Sample D Fracture 200x
Sample D Outside Surface 50x
Sample D Outside Surface 200x




0.05 mm




0.25 mm




0.05 mm




0.05 mm




0.25 mm




0.05 mm




0.05 mm




0.25 mm




0.05 mm




0.25 mm




0.05 mm




0.25 mm



0.05 mm




0.25 mm



0.05 mm



0.25 mm





0.05 mm



0.25 mm









25 mm





0.05 mm
































0.5 mm







0.25 mm



0.05 mm

ATTACHMENT 10

Microhardness Testing



Table 1
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample A** from
 Tank Outside Surface to Tank Inside Surface

Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	93.7	25
0.030	99.9	33
0.050	99.2	32
0.070	101.9	36
0.090	99.6	33
0.110	104.0	38
0.130	106.2	41
0.150	101.0	35
0.170	89.0	18
0.177	82.7	8
0.184	Inside Surface	

Table 2
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample A** from
 Tank Fracture Edge towards Tank Center

Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	102.4	36
0.020	102.2	36
0.070	92.2	23
0.170	98.3	31
0.270	101.3	35
0.370	95.9	28
0.470	100.9	34
0.570	103.6	38
0.620	110.0	45
0.670	106.6	41



Table 3
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample B** from
 Tank Outside Surface to Tank Inside Surface

Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	122.3	59
0.020	123.7	61
0.030	121.7	59
0.060	117.9	53
0.100	116.8	53
0.130	122.6	60
0.160	118.3	53
0.200	125.8	63
0.230	133.6	67
0.260	124.7	62
0.290	128.0	64
0.320	122.9	60
0.350	125.9	63
0.358	128.3	64
0.363	Inside Surface	

Table 4
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample B** from
 Tank Fracture Edge towards Tank Center

Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	128.5	64
0.020	131.7	66
0.030	133.0	66
0.080	130.7	65
0.130	121.0	58
0.180	127.5	64
0.230	128.0	64
0.280	128.8	64
0.330	125.3	62
0.380	120.8	58
0.430	129.8	65
0.480	119.3	56
0.530	117.3	53
0.580	122.7	60



Anamet, inc *Materials Engineering & Laboratory Testing*
 26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

Table 5
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample C** from
 Tank Outside Surface to Tank Inside Surface

Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	116.5	52
0.020	119.6	57
0.030	117.9	55
0.060	117.5	55
0.100	116.2	52
0.130	115.5	51
0.160	115.0	51
0.200	117.0	53
0.230	120.3	57
0.260	125.3	62
0.290	122.0	59
0.320	123.0	60
0.350	122.8	60
0.358	121.3	58
0.364	Inside Surface	

Table 6
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample C** from
 Tank Fracture Edge towards Tank Center

Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	128.6	64
0.020	135.0	67
0.030	131.3	65
0.080	128.3	64
0.130	133.9	67
0.180	127.5	63
0.230	126.3	63
0.280	123.8	61
0.330	122.5	59
0.380	122.1	59
0.430	121.4	58
0.480	118.0	55
0.530	124.9	62
0.580	117.2	53



Table 7
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample D** from
 Tank Outside Surface to Tank Inside Surface


Distance (inch)	HK500	Converted HRB
0.000	Outside Surface	
0.010	121.3	58
0.020	130.3	65
0.030	123.4	60
0.060	126.4	63
0.100	126.0	63
0.130	120.1	57
0.160	122.8	60
0.200	125.7	63
0.230	121.0	58
0.260	126.1	63
0.290	121.1	58
0.320	125.4	62
0.350	128.2	64
0.357	Inside Surface	

Table 8
 Knoop Microhardness Traverse and Converted Rockwell Hardness of **Sample D** from
 Tank Fracture Edge towards Tank Center

Distance (inch)	HK500	Converted HRB
0.000	Fracture Edge	
0.010	121.6	59
0.020	127.3	63
0.030	132.9	66
0.080	142.8	71
0.114	141.9	71
0.164	133.9	67
0.214	132.0	66
0.264	124.8	62
0.314	125.9	63
0.364	125.2	62
0.414	126.1	63
0.464	129.0	64
0.514	126.7	63
0.564	127.5	64
0.614	130.9	65
0.654	125.6	63

ATTACHMENT 11

Tensile and Compression Testing



Test Summary

Test Results

Counter: 13137
 Elapsed Time: 00:01:05
 Anamet Job Number: 5004.7104
 Specimen Identification: 1
 Operator: eaf/bck
 Comments: Compression Lenght 1.503"
 Procedure Name: Compression Load
 Start Date: 3/14/2012
 Start Time: 10:37:20 AM
 End Date: 3/14/2012
 End Time: 10:38:25 AM
 Workstation: MECH
 Tested By: Brian
 Customer: RTI


Load at Peak Load: 10010.1900 lbf
 Position at Peak Load: 0.2137 in
 Halt of Force Yield: 10010.1900 lbf
 Width: 0.5000 in
 Length: *(Thickness)* 0.3480 in
 Area: 0.1740 in²



Anamet, inc *Materials Engineering & Laboratory Testing*
 26102 EDEN LANDING ROAD, SUITE 3 • HAYWARD, CALIFORNIA 94545 • (510) 887-8811 • FAX (510) 887-8427

Table 1
 Results of Tensile Test on a Specimen from the SCUBA Tank

Property		Tank	
Dimensions of Specimen	Width	0.509	inch
	Thickness	0.381	inch
Area		0.194	inch ²
Tensile Load		9965	lbs
Tensile Strength		51400	psi
Yield Load 0.2% Offset		8937	lbs
Yield Strength 0.2% Offset		46100	psi
Specimen Length	After		inch
	Before	5.187	inch
Elongation		0.30	inch
Elongation in 2.0" Gage		15	%



Test Summary

Counter: 13136
 Elapsed Time: 00:03:15
 Anamet Job Number: 5004.7109
 Specimen Identification: 1
 Operator: eaf/bck
 Procedure Name: Tensile 2in. Ext.
 Start Date: 3/14/2012
 Start Time: 10:16:20 AM
 End Date: 3/14/2012
 End Time: 10:19:35 AM
 Workstation: MECH
 Tested By: Brian
 Customer: RTI
 Comments:

Test Results

Tensile Strength: 51392.4700 psi
 Peak Load: 9965.0000 lbf
 Young's Modulus: 8.07e+006 psi
 Area: 0.1939 in²
 Stress at Break: 2764.3120 psi
 Load at Break: 536.0000 lbf
 Halt of Force Yield: 9486.0000 lbf
 Load at Offset: 8937.8910 lbf
 Stress at Offset: 46095.3700 psi
 Width: 0.5090 in
 Thickness: 0.3810 in

ATTACHMENT 12


Scanning Electron Microscope Images *SEM images, in order of appearance*

Pressure Regulator Adaptor 1 – 150x
Pressure Regulator Adaptor Air Cup 2 - 100x
Pressure Regulator Adaptor 1 – 25x
Pressure Regulator Adaptor 2 – 500x
Pressure Regulator Adaptor 3 – 27x
Pressure Regulator Adaptor 4 – 500x
Pressure Regulator Adaptor 5 – 27x
Pressure Regulator Adaptor 6 – 500x
Pressure Regulator Adaptor 7 – 27x
Pressure Regulator Adaptor 8 – 500x

Cylinder Inside Surface A 1 – 40x

Valve Seat Body Exemplar 1 – 14x
Valve Seat Body Exemplar 2 – 14x
Valve Seat Body Subject 1 – 14x
Valve Seat Body Subject 2 – 14x


Valve Stem 1 – 40x
Valve Stem 2 – 40x
Valve Stem 3 – 40x
Valve Stem 4 – 40x
Valve Stem 5 – 40x
Valve Stem 6 – 500x
Valve Stem 7 – 1000x
Valve Stem 8 – 500x



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 18.1mm x150 SE


300um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 22.4mm x100 SE


500um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 18.8mm x25 SE


2.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 18.6mm x500 SE


100um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 16.2mm x27 SE


2.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 16.1mm x500 SE


100um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 16.1mm x27 SE

2.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 15.5mm x500 SE


100um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 16.1mm x27 SE


2.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 16.1mm x500 SE

100um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.8mm x40 SE






US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 38.4mm x14 SE


4.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 38.1mm x14 SE


4.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 37.3mm x14 SE


4.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 36.8mm x14 SE


4.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.4mm x40 SE


1.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.4mm x40 SE


1.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.4mm x40 SE


1.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.4mm x40 SE


1.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.4mm x40 SE


1.00mm



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.4mm x500 SE


100um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.5mm x1.00k SE

50.0um



US DOT/PHMSA/OHMSFO/Southern Region
Report Number: 11287051

20.0kV 10.1mm x500 SE




100um



ATTACHMENT 13

Inspection Photos of Jun. 8, 2012

Images of interior surface combustion area





























ATTACHMENT 14

Surface Curvature Measurements




ATTACHMENT 15

Cylinder Valve Markings













ATTACHMENT 16

Chain of Custody

CHANGE OF EVIDENCE CUSTODY RECORD

DATE: November 22, 2011

RTI File Name: DOT – Ruptured Scuba Cylinder

RTI File No.: 50151.ME002

The evidence herein described has been transferred on this date - -

To: Richard Loucks, PhD, PE

From: U.S. Dept of Transportation
Property Inventory Report

Company: RTI Group, LLC

Company:

Description of Evidence (Note all markings):

1. SEE ATTACHED LIST.

Authorization of **Sending** Party:

Authorization of **Receiving** Party:

(Signature & Date)

(Signature & Date)



(Printed)

(Printed)

Richard B. Loucks, PhD, PE

Matter: 50151ME002

Matter Name: DOT – Ruptured SCUBA Cylinder

Evidence Inventory

1) Yellow high pressure gas cylinder, Part 1

Smaller fragment from the cylinder, approximately 12 inch by 6 inch. Has the following marks at near the neck:

DOT-3AL 3000 HY-MARK

Cylinder has two decals

Decal 1: OXYGEN for decompression use only – MOD (Maximum Operating Depth) 20 FSW (20 feet submerged water), MOD 6 MSW (6 meters submerged water), International Association of Nitrox & Technical Divers, Inc.

Decal 2: “Tank & Valve Have Been Cleaned For Premix, Oxygen Content 22 to 40%” is not punched out. “Tank & Valve Have Been Cleaned In Accordance With O₂ Service” Is punched out at 2011. The month is uncertain.

2) Yellow high pressure gas cylinder, Part 2

Larger section, contains the bottom, neck and valve opening, measures about 24 inches by 14 inches. Has the following markings near the neck:

OU 0001 M5442 10 07 S40 TC-3AL 207

3) High Pressure Tank Valve, DIN Valve, manufactured by Genesis. 5000 psi, 30 lb/hr CG-1 type rupture disk. Oxygen (Fire Toxicity State and Corrosiveness FTSC Code 4160: 4 -highly oxidizing, 1-nontoxic, 6-nonliquified gas between 500 and 3000 psig, 0-noncorrosive, Class 2 Division 2.2 gas) use permits CG-1 (required in one end of the cylinder, regardless of length). A pressure regulator adaptor is present in the opening which has a fractured outlet. The metal particle filter is evident in the opening.

3) Regulator by Dive Rite, serial number 12008135, fitted with regulator fitting. The opening is occupied by the fractured end of the pressure regulator adaptor

Attached:

1. Black pressure line with dial gage on high pressure side of regulator. Dial gage face is heat affected and the gage is illegible.
2. Length of green pressure line stating “WARNING Do not exceed 250 psi (17 bar) high pressure may cause damage or personal injury” no manufacturer identified. Distal end terminates unattached. Low pressure side

U.S. DEPARTMENT OF TRANSPORTATION PROPERTY INVENTORY REPORT

DATE: <u>11/9/11</u>	TIME:	LOCATION:	INSPECTION TYPE:	CASE NO.:
COMPLAINANT'S NAME: <u>Vanhorn, Russell (deceased)</u>		REASON FOR TAKING INTO D.O.T. CUSTODY: <u>Ruptured cylinder</u>		
COMPLAINANT'S ADDRESS: <u>5875 37th N. Apt 6 St. Petersburg FL</u>		SIGNATURE OF PROPERTY CUSTODIAN:		
CONTACT NAME & PHONE NO.: <u>33710</u>		DATE TAKEN INTO D.O.T. POSSESSION: <u>11/9/11</u>		
ITEM #	QUANTITY	DESCRIPTION OF PROPERTY		
<u>1</u>	<u>1</u>	<u>Scuba cylinder</u>		
<u>2</u>	<u>1</u>	<u>Separated piece of scuba cylinder</u>		
<u>3</u>	<u>1</u>	<u>valve, regulator and hose</u>		
		<u>Not in following</u>		
		<u>RECEIVED</u>		
ITEM #	DATE AND TIME RELEASED	DATE AND TIME RETURNED	SIGNATURE AUTHORIZING	SIGNATURE RECEIVING
<u>1</u>	<u>11/10/11</u>	<u>11/15/11</u>	<u>[Signature]</u>	<u>[Signature]</u>
<u>2</u>	<u>11/10/11</u>	<u>11/15/11</u>	<u>[Signature]</u>	<u>[Signature]</u>
<u>3</u>	<u>11/10/11</u>	<u>11/15/11</u>	<u>[Signature]</u>	<u>[Signature]</u>

KEEP WITH PROPERTY



Anamet, inc

Materials Engineering & Laboratory Testing, Since 1958

EVIDENCE CHANGE OF CUSTODY RECORD

Date Received/Shipped/Transferred: July 2, 2012

Anamet, Inc. File No: 5004.7532

Anamet, Inc. File Name: RTI Group RTI File 50151.ME002
RTI File Name: DOT Ruptured
Scuba Cylinder

The evidence herein described has been transferred on this date to:

Matthew Wagmhofer
Name (Please Print)

Representing: RTI Group
Company Name (Please Print)

From: Norman Yuen
Name (Please Print)

Name Representing: Anamet
Company Name (Please Print)


Description of Evidence:

Two halves tensile specimen
One tank valve body

Signatures:
To: [Signature]
From: [Signature]

Date: 7/9/12

CHANGE OF CUSTODY RECORD

DATE:	TBD			
RTI File Name:	DOT – Ruptured Scuba Cylinder			
RTI File No.:	50151.ME002			
<i>The evidence herein described has been transferred on this date - -</i>				
To:	TBD		From:	Richard B. Loucks, PhD, PE
Company:	U.S. Department of Transportation Pipeline and Hazardous Materials Safety Admin. 1200 New Jersey Ave., SE Room E21-338 Washington, DC 20590		Company:	RTI Group, LLC 910 Bestgate Rd., Suite E Annapolis, MD 21401
<i>Description of Evidence (Note all markings):</i>				
1. See attached description of evidence listing.				
2.				
3.				
4.				
5.				
6.				
<i>Authorization:</i>				
Authorization of Sending Party:		Authorization of Receiving Party:		
(Signature)		(Signature)		
(Printed: name, company, address)		(Printed: name, company, address)		
Richard B. Loucks, PhD, PE RTI Group, LLC 910 Bestgate Rd., Suite E Annapolis, MD 21401				

CHANGE OF EVIDENCE CUSTODY RECORD

RTI File Name: DOT-Ruptured Scuba Cylinder
 RTI File No.: 50151.ME002

Description of Evidence Listing
 Date _____

Contained in	Further contained in	Further contained in	Item	Part No.	Description
Bag "Tank Mounts A,B,C,D"			Sample A	1-a-i	Hardness tested sample
			Sample B	1-b-i	Hardness tested sample
			Sample C	1-c-i	Hardness tested sample
			Sample D	1-d-i	Hardness tested sample
Tupperware container 1			Fragment of the Scuba Tank	2	Approx. 6"x12". Two Decals.
Bag 2	Bag "Subject Valve - Relief Valve"		Relief Valve	3-a	Intact 5000psi burst disk in a hollow threaded bolt
	Bag "Subject Valve - Vave Seat Body"		Valve Seat Body	3-b	Threads coated green. Rectangular hollow.
	Bag "Subject Valve - Gand Nut"		Gland Nut	3-c	Threaded, hex head.
			O Ring	3-c-i	Black polymer, approx 1/2" diameter
	Bag "Subject Valve - Valve Stem"		Valve Stem	3-d	Steel stem, approx 1 1/8" in length
			O Ring	3-d-i	Brown Polymer, approx 3/8" diameter
			O Ring	3-d-ii	Brown Polymer, approx 3/8" diameter
			Washer	3-d-iii	White Polymer, approx 3/8" diameter
			Washer	3-d-iv	Brown Polymer, approx 1/2" diameter
	Bag "Subject Valve - Regulator Adapter"		Air Cup	3-f	Brass cup, approx 3/8" diameter 1/2" tall
			Handle	3-e-viii	Matte black, approx 1 3/4" diameter
			Adjuster	3-e	Black. Hollow. Threaded inside. Hex head.
			Adjuster Adapter	3-e-iv	Black. Hollow. Threaded outside. Hex opening. Fractured
			O Ring	3-e-v	Black polymer, approx 3/4" diameter
			O Ring	3-e-vi	Black polymer, approx 1/2" diameter
		O Ring	3-e-vii	Black polymer, approx 3/8" diameter	
Tupperware container 3	Bag 3-A		Pressure line	4-i	Green. Some yellow discoloration
	Bag 3-B		Regulator Handle	4-j	Black polymer, fire damaged
	Bag 3-C		Pressure Gauge	4-k	Attached to an approx 6" black hose
	Bag "Regulator Body"	Bag "O Ring, Thrust Washer"	O Ring	4-g	Black polymer, approx 1" diameter
			Thrust Washer	4-h	White Polymer, approx 1" diameter
		Bag "Metal Diaphragm Retainer, Main Regulator Body, Valve Lifter"	Diaphragm Retainer	4-c-v	Metal, 1 5/8" diameter approx 3/4" tall
			Regulator Body	4	Metal, 1 5/8" diameter approx 1 1/2" tall
			Valve Lifter	4-a	Resembes a large thumbtack
		Bag "Turret"	Turret	4-b	Metal, 1 5/8" diameter approx 1" tall
			Gasket	4-b-i	Brown Polymer, approx 1 5/8" diameter
			O Ring	4-b-ii	Black polymer, approx 1 1/4" diameter
		Bag "High Pressure Diaphragm Spring, Adjustment Sleeve"	Diaphragm Spring	4-c-iii	approx 1/2" diameter, 3/4" tall, 5 turns
			Adjustment Sleeve	4-c-iv	approx 3/4" diameter, 3/8" tall, outside threaded
		Bag "Diaphragm, Retaining Ring, Spring Carrier"	Diaphragm	4-c	Grey Polymer approx 1 1/2" diameter
			Retaining Ring	4-c-i	Clear Polymer Ring approx 1 1/2" diameter
			Spring Carrier	4-c-ii	Metallic button, approx 3/4" diameter. Center portion raised
		Bag "Mating Half Regulator Adjuster Adapter"	Adjuster	3-e-i	Remaining part of the adjuster
			O Ring	3-e-ii	Black Polyer approx 3/8" diameter
	Bag "Regulator Insert Low Pressure"	Regulator Insert	4-f	Piston Body with compression spring	
		O Ring	4-f-i	Black Polymer approx 1/2" diameter	
Bag 4	Bag 4-1		Tank Section	1-e	approx 2" in engh and 1/4" width
			Tank Section	1-f	approx 1 1/2" in length triangular section
	Bag 4-2		Tank Section	1-g	Main body approx 1" length and 1/2" width
	Bag 4-3		Tank Section	1-h	Triangular section approx 3/4" height
	Bag 4-4		Tank Section	1-c-ii	Approx 1 1/2" length and 3/4" width. Marked C
			Tank Section	1-c-iii	Approx 1 1/2" length and 1/4" width. Marked C
	Bag 4-5		Tank Section	1-i	Approx 3" length, 1" at one end and 1 1/2" at another
	Bag "Compression Specimen"		Tank Section	1-j	Approx 1 1/4" length and 5/8" width
	Bag 4-6		Tank Section	1-d-ii	Curved section of the tank. Marked D
Bag 4-7		Tank Section	1-c-iv	Main body approx 4 1/2" x 6". Marked C	
Bag 4-8		Tank Section	1-k	Main body approx 8" length	
Tupperware container 5			Tank Valve	3	Tank valve body. Fractured
Not Bagged			Scuba Cylinder	1	Ruptured. Specimens taken.
Bag 6			Tank Bottom	1-l	Bottom of the ruptured tank.
Bag "Tensile Specimens"	Envelope "Tensile Specimen A Fracture Surface"		Tank Section	1-m-ii	Part of the fractured specimen No. 1-m-i
	Envelope "Tensile"		Tank Section	1-m-i	Tensile testing specimen half
			Tank Section	1-m-iii	Tensile testing specimen half. Marked B.



RTI Group, LLC
910 Bestgate Road, Suite E
Annapolis, MD 21401
ofc: +1 410 571 0712 | fax: +1 410 571 0713
www.rtiForensics.com

CHANGE OF CUSTODY RECORD

DATE: June 12, 2012
RTI File Name: DOT-Ruptured Scuba Cylinder
RTI File No.: 50151.ME002

The evidence herein described has been transferred on this date - -

To: Norman Yuen
Company: Anamet, Inc.

From: Matthew Wagenhofer
Company: RTI

Description of Evidence (Note all markings):

1. Two (2) halves tensile specimen

2. One (1) tank valve body

3.

4.

5.

6.

7.

8.

Authorization of **Sending Party:**

Authorization of **Receiving Party:**

(Signature)

(Signature)

(Printed) Matthew Wagenhofer

(Printed) NORMAN YUEN