

004

MGDR WAS

IP812 OCTOBER 20, 1970 REC'D WAS OCT 20 1970

SUBJ UDORN REPORTS UH34D SUCCESSFUL

REF FORCED LANDING

UDORN REPORTS UH34D H57 MADE A FORCED LANDING AT QC0198 AT 0410Z 19 OCTOBER AFTER EXPERIENCING ENGINE TROUBLE INVOLVING DROPPING OIL PRESSURE, RISING OIL TEMPERATURE AND ENGINE CUTTING OUT. NO DAMAGE OR INJURIES INVOLVED AND AREA CONSIDERED SECURE. POST LANDING CHECKS REVEALED METAL CHUNKS ON OIL SCREEN. ENGINE CHARGE ON SITE PLANNED. PIC D. E. KAWALEK, SIC M. L. MORRIS, FLTMECH A. J. ALOR. NO PASSENGERS REPORTED, AIRCREW RECOVERED TO UDORN AFTERNOON 19TH.

PRES TPE

=

4- 10/20/70

APPROVED FOR RELEASE DATE:
13-Mar-2009

NNNN