BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
FC 115					

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
1079	12-14-84	657	Install anchors in concrete deck Holdbus for Parachutes
3077	11-16-87	3915	Repl Compressor for A/C Syst
3164	10-11-95	128	Remove Abandoned 3$^{\phi}$ Line to G.P. Area
4371	3-5-93	830	Repair Valve.
3054	9-3a94	1752	Replace Water Heater SEP 08 1998 Purged SA
3453	3-8-96	004	Repair Lites & Double SEP 08 1998 Purged SA
13682	4-6-01	12.470	Repl Lighting in parking area

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION