# RESEARCH TRIANGLE INSTITUTE




National Laboratory Certification Program

April 22, 1999

0323
Dr. Lawrence Bond
Quest Diagnostics of Missouri LLC
2320 Schuetz Road
St. Louis, MO 63146

Dear Dr. Bond:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the tenth maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the outcome of the laboratory's performance in this inspection is unacceptable. Before RTI will recommend continued certification of your laboratory, the laboratory must successfully complete the following remedial actions:



Dr. Bond Page 2 of 5 04/22/99

Dr. Bond Page 3 of 5 04/22/99 Dr. Bond Page 4 of 5 04/22/99



The laboratory must submit, within 5 calendar days of receipt of this letter, a plan to complete all remedial actions. Once this plan is approved, the laboratory will have a maximum of 30 calendar days to implement the plan and to complete all necessary remedial actions. If the laboratory fails to provide and execute an approved plan, RTI will recommend to the Department of Health and Human Services (HHS) that your laboratory's certification be suspended and/or revoked. The laboratory should also review the enclosed critique and take all necessary corrective actions.

The NLCP reserves the right to conduct an inspection to determine full compliance with the requirements of this letter. The laboratory is hereby notified that failure to sustain acceptable performance in the inspection phase of this program may result in our recommendation to HHS that your laboratory's certification be suspended and/or revoked, consistent with sections 3.13 and 3.14 of the Mandatory Guidelines.

In responding to the issues raised, please organize the material in accordance with the item numbers listed in the text of this letter. If we can be of assistance or answer any questions, please call me at (919) 541-6176 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Susan Crumpton

**NLCP Inspection Analyst** 

**Enclosure** 

CC:

Project Files/M10

#### NATIONAL LABORATORY CERTIFICATION PROGRAM

#### **Document Review and Critique**

Laboratory I.D. Number: 0323

Document No. Final

Laboratory:

Quest Diagnostics of Missouri LLC

Location:

St. Louis, MO

**Document Reviewed:** 

[ ] Application Form

[XX] Inspection Report #M10

Date: 25 February 1999

Status:

] Highly Acceptable

] Acceptable

[XX] Unacceptable

] Other

] Failure

A review of the National Laboratory Certification Program (NLCP) inspection reports has reen completed. It is the judgment of the reviewers that the laboratory has not met the standards required for the inspection phase of the Program. Evidence that appropriate remedial action has been taken is required for continued certification.


There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

NLCP + Research Triangle Institute


Page 1

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:


Section E. Standard Operating Procedures - Procedures Manual








Section F. Chain-of-Custody. Accessioning, and Security




Section G. Quality Control




Section H. Initial Tests



Section I. Confirmatory Tests




Section J. Records Audit
Section K. Reporting
Section L. Computers, Software, and LIMS
Section M. Equipment and Maintenance
Coction Al Domensol
Section N. Personnel



Quest Diagnostics 11.0

A Partner with Unity Health

2320 Schuetz Road St. Louis, Missouri 63146 314.991.1311 800.288.7293 314.997.7112 Fax





April 29, 1999


Susan Crumpton NLCP Inspection Analyst National Laboratory Certification Program 3040 Cornwallis Road Research Triangle Park, NC 27709-2194

Dear Ms. Crumpton:

The following is our plan of action to correct the deficiencies cited during the tenth maintenance inspection of our laboratory.

: Page 7 of 5

G. Quality Control Section:



•

J. Records section:

Sincerety

Lawrence W. Bond, Ph.D. Responsible Person

Quest Diagnostics LLC

A Partner with Unity Health

2320 Schuetz Road St. Louis, Missouri 63146 314.991.1311 800.288.7293 314.997.7112 Fax







June 3, 1999


Susan Crumpton NLCP Inspection Analyst National Laboratory Certification Program 3040 Cornwallis Road Research Triangle Park, NC 27709-2194


Dear Ms. Crumpton:

The following is our response to the plan you approved to correct the deficiencies cited during the tenth maintenance inspection of our laboratory. The following document is an expanded version of the approved plan which addresses each item mentioned by the inspection report.









4 Sincerely, Lawrence W. Bond, Ph.D. Responsible Person

Page Sof's




National Laboratory Certification Program


June 9, 1999

0323
Dr. Lawrence Bond
Quest Diagnostics of Missouri LLC
2320 Schuetz Road
St. Louis, MO 63146

Dear Dr. Bond:

We have reviewed the material provided in your correspondence of June 3, 1999, submitted in response to deficiencies cited during the tenth maintenance inspection of your laboratory as outlined in our correspondence of April 22, 1999. The information submitted by the laboratory appears to demonstrate that appropriate remedial actions have been completed to address most issues. However, the following issues remain or were raised during our review of the submitted material:







Dr. Bond Page 2 of 3 06/09/99

The laboratory must submit, within 10 working days of receipt of this letter, a final report addressing the unresolved issues described above. RTI will recommend to the Department of Health and Human Services (HHS) that the laboratory continue to be certified under the National Laboratory Certification Program (NLCP) upon receipt of documentation to demonstrate that the unresolved issues have been addressed. If, however, the laboratory fails to address these unresolved issues within this time, the issues will be discussed with the staff at HHS. The laboratory is reminded that the implementation and completion of all remedial actions are subject to review by the next inspection team.

Dr. Bond Page 3 of 3 06/09/99

The NLCP reserves the right to conduct an inspection to determine full compliance with the requirements of this letter. The laboratory is hereby notified that failure to correct deficiencies may result in our recommendation to HHS that your laboratory's certification be suspended and/or revoked, consistent with sections 3.13 and 3.14 of the HHS Guidelines.

If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Michael Baylor, Ph.D. at (919) 541-7043.

Sincerely,

Susan Crumpton **NLCP Inspection Analyst** 

CC: Dr. Michael Baylor

Project Files/M14

June 24, 1999

Susan Crumpton NLCP Inspection Analyst National Laboratory Certification Program 3040 Cornwallis Road Research Triangle Park, NC 27709-2194

#### Dear Ms. Crumpton:

The following is our response to your review of our corrections to the deficiencies cited during the tenth maintenance inspection of our laboratory. The following document directly reviews the issues cited in your letter of June 9, 1999 and received by me on June 14, 1999.

I greatly appreciate the suggestions provided in your review, they reflected obvious thoroughness on your part in helping us achieve greater clarity in our SOP and general operations.

Cinnanda

Lawrence W Bond, Ph.D. Responsible Person Quest Diagnostics 14.0

13:00

2320 Schnerz Rosal St. Louis, Missouri 63146 314.991.1311 800.288.7293 314.997.7112 Fax





July 1, 1999

Susan Crumpton
NLCP Inspection Analyst
National Laboratory Certification Program
3040 Cornwallis Road
Research Triangle Park, NC 27709-2194

Dear Ms. Crumpton:

The following is our response to your phone call today. Attached you will find our updated SOP for performing new or modified initial screening procedures. This procedure was written based upon the recommended guidelines by NLCP.

I hope this is satisfactory based upon our conversation of this morning

Respectfully.

Lawrence W. Bond, Ph.D. Responsible Person Quest Diagnostics, (J.C.

St Louis, MO 63146




National Laboratory Certification Program

July 8, 1999

0323
Dr. Lawrence Bond
Quest Diagnostics of Missouri LLC
2320 Schuetz Road
St. Louis, MO 63146

Dear Dr. Bond:

We have reviewed the material provided in your correspondence of June 24, 1999, and your faxed correspondence of July 1, 1999, submitted in response to deficiencies cited during the tenth maintenance inspection of your laboratory as outlined in our correspondence of June 9, 1999, and our telephone conversation of July 1, 1999. The information submitted by the laboratory appears to demonstrate that appropriate remedial actions have been completed to address the deficiencies cited. The following is a review of the material submitted:



Based upon our review of the material submitted, RTI is recommending to the Department of Health and Human Services (HHS) that your laboratory continue to be certified under the National Laboratory Certification Program. All corrective actions must be implemented within 30 days of the receipt of this correspondence and will be reviewed during the next inspection. If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Michael Baylor, Ph.D. (919) 541-7043.

Sincerely,


Susan Crumpton

**NLCP Inspection Analyst** 

Swan Crupton

cc: l

Dr. Michael Baylor Project Files/M10






National Laboratory Certification Program

October 7, 1999

0323
Dr. Lawrence Bond
Quest Diagnostics of Missouri LLC
2320 Schuetz Road
St. Louis, MO 63146


Dear Dr. Bond:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the eleventh maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is acceptable. Before RTI will recommend continued certification of your laboratory, the laboratory must clarify/correct the following issues raised:





Dr. Bond Page 2 of 2 10/07/99



The laboratory must submit, within 30 calendar days of receipt of this letter, documentation to demonstrate that corrective actions have been implemented to address the issues raised in section E. Once these issues have been successfully addressed, RTI will recommend to the Department of Health and Human Services (HHS) that the laboratory's certification be continued. The laboratory must also review the enclosed critique and take all necessary corrective actions. All corrective actions must be implemented within 30 days receipt of this correspondence and will be reviewed at the next inspection.

If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Susan Crumpton

NLCP Inspection Analyst

Enclosure

cc: Project Files/323

## NATIONAL LABORATORY CERTIFICATION PROGRAM

### **Document Review and Critique**

Laboratory I.D. Number: <u>0323</u> Document No. Final

Laboratory:

Quest Diagnostics of Missouri LLC

Location:

St. Louis, MO

Document Reviewed:

[ ] Application Form

[XX] Inspection Report #M11

Date: 26 August 1999

[ ] Other \_

Status:

] Highly Acceptable

[XX] Acceptable


] Unacceptable [ ] Failure


Inspection reports, from the inspectors who conducted the National Laboratory Certification Program (NLCP) inspection, have been carefully reviewed and found to provide sufficient information to judge that the laboratory has met the standards required for the inspection phase of the Program, pending the submission of evidence that appropriate corrective action has been taken.

There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual





Section G. Quality Control

Section H. Initial Tests

Section I. Confirmatory Tests

Section J. Records Audit

Ver. Final Lab ID# 323

Section K. Reporting

Section L. Computers, Software, and LIMS

Section M. Equipment and Maintenance

Section N. Personnel

## Quest Diagnostics LLC

A Partner with Unity Health

2320 Schuetz Road St. Louis, Missouri 63146 314.991.1311 800.288.7293 314.997.7112 FAX







November 4, 1999


Susan Crumpton NLCP Inspection Analyst National Laboratory Certification Program 3040 Cornwallis Road Research Triangle Park, NC 27709-2194

Dear Ms. Crumpton:



Section E. Standard Operating Procedures – Procedures Manual





Respectfully,

Lawrence W. Bond, Ph.D. Responsible Person

Quest Diagnostics, LLC St. Louis, MO 63146




National Laboratory Certification Program

November 11, 1999

0323
Dr. Lawrence Bond
Quest Diagnostics of Missouri LLC
2320 Schuetz Road
St. Louis, MO 63146


Dear Dr. Bond:

We have reviewed the material provided in your correspondence of November 4, 1999, submitted in response to issues raised during the eleventh maintenance inspection of your laboratory as outlined in our correspondence of October 7, 1999. The information submitted by the laboratory appears to demonstrate that the laboratory is taking appropriate corrective actions to address the issues raised. However, the following items were noted during our review of submitted standard operating procedure (SOP) revisions:





Dr. Bond Page 2 of 2 11/11/99



Based upon our review of the material submitted, RTI is recommending to the Department of Health and Human Services (HHS) that your laboratory continue to be certified under the National Laboratory Certification Program. The revised SOP manual and its implementation will be reviewed at the next inspection. If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Michael Baylor, Ph.D. (919) 541-7043.

Sincerely,

Susan Crumpton

**NLCP Inspection Analyst** 

cc: Dr. Michael Baylor Project Files/323

## RESEARCH TRIANGLE INSTITUTE



National Laboratory Certification Program

March 31, 2000

0323
Dr. Lawrence Bond
Quest Diagnostics of Missouri LLC
2320 Schuetz Road
St. Louis, MO 63146

Dear Dr. Bond:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the twelfth maintenance inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is highly acceptable. The inspection team had some areas of concern, which are detailed in the attached critique.

RTI is recommending to the Department of Health and Human Services (HHS) that the laboratory's certification be continued based upon its acceptable performance in the inspection phase of the program.

If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Susan Crumpton

**NLCP Inspection Analyst** 

**Enclosure** 

cc: Project Files/M12

## NATIONAL LABORATORY CERTIFICATION PROGRAM

## **Document Review and Critique**

Laboratory I.D. Number: 0323

Document No. Final

Laboratory:

Quest Diagnostics of Missouri LLC

Location:

St. Louis, MO

**Document Reviewed:** 

[ ] Application Form

[XX] Inspection Report #M12 Other Date: 17 February 2000

Status:

[XX] Highly Acceptable

] Acceptable ] Failure


[ ] Unacceptable [ ] Failu

A review of the National Laboratory Certification Program (NLCP) inspection reports has been completed. It is the judgment of the reviewers that the laboratory has met the standards required for the inspection phase of the Program.

There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual



Section F. Chain-of-Custody, Accessioning, and Security

Section G. Quality Control

Ver. Final	Lab ID# 0323
Section H. Initial Tests	-
Section I. Confirmatory Tests	
Section J. Records Audit	
Section K. Reporting	
Section L. Computers, Software, and LIMS	
Section M. Equipment and Maintenance	

Section N. Personnel