



UNDER SECRETARY OF DEFENSE
1100 DEFENSE PENTAGON
WASHINGTON, DC 20301-1100

COMPTROLLER

APR 28 2009

The Honorable Ike Skelton
Chairman, Committee on Armed Services
U.S. House of Representatives
Washington, DC 20515

Dear Mr. Chairman:

The American Recovery and Reinvestment Act of 2009, Public Law 111-5 (the Recovery Act), was designed to stimulate economic growth by creating millions of jobs through investments in infrastructure improvements and expanding energy research in an effort to lead the way toward energy independence for our country.

To implement the Recovery Act, the Department of Defense has identified specific investments in construction, facility improvements, and energy efficiency projects. In its March 20, 2009 report, the Department provided a list of over 3,300 projects with an estimated cost of \$3.4 billion for Facilities Sustainment, Restoration, and Modernization (FSRM) funded under Division A, Title III of the Recovery Act—representing about 80 percent of the total FSRM funds appropriated to the Department of Defense. Enclosure 1 provides a list of 856 projects associated with the remaining 20 percent (\$835 million) of FSRM funds provided by the Act.

The projects in the report will be executed on installations located in 37 states and the District of Columbia, and will perform needed repairs and upgrades in a variety of facilities, increase energy efficiency, upgrade utilities systems and improve quality of life, especially for our single service members living in barracks. The following table provides a summary of the costs and numbers of projects by category:

| Project Category (Code) | Cost Estimate (\$000) | Number of Projects |
|--------------------------------|-----------------------|--------------------|
| Energy-related (E) | \$345,929 | 338 |
| Roof repair/replacement (R) | \$37,324 | 92 |
| Utilities (U) | \$50,289 | 53 |
| Pavement, roads or grounds (P) | \$152,819 | 91 |
| Barracks (B) | \$69,849 | 74 |
| Quality of Life (Q) | \$18,836 | 28 |
| Operations (O) | \$160,427 | 180 |
| Total | \$835,473 | 856 |

As with the initial report, this letter further provides the Congress, pursuant to section 2811 of Title 10, United States Code, with notification that the Department will be conducting repair projects greater than \$7.5 million for nine projects (Enclosure 2). The Department will ensure any statutory notice and wait periods are followed before obligating funds provided under the Recovery Act.

In addition to the final projects submitted herein, this report also provides notification of project changes in Hawaii, Tennessee and New York. Enclosure 3 provides project-level detail for these actions.

This notification and the initial March 20, 2009 report represent the Department's current plan, subject to amendment if significant changes occur during implementation. The Department of Defense appreciates the continued support of the Congress for Defense facility and infrastructure programs. Similar letters have been sent to the chairmen and ranking members of the House and Senate Armed Services Committee and the Committees on Appropriations of the House and Senate.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert F. Hale". The signature is written in a cursive style with some capital letters.

Robert F. Hale

Enclosures:

As stated

cc:

The Honorable John M. McHugh
Ranking Member



UNDER SECRETARY OF DEFENSE
1100 DEFENSE PENTAGON
WASHINGTON, DC 20301-1100

COMPTROLLER

APR 28 2009

The Honorable Carl Levin
Chairman, Committee on Armed Services
United States Senate
Washington, DC 20510

Dear Mr. Chairman:

The American Recovery and Reinvestment Act of 2009, Public Law 111-5 (the Recovery Act), was designed to stimulate economic growth by creating millions of jobs through investments in infrastructure improvements and expanding energy research in an effort to lead the way toward energy independence for our country.

To implement the Recovery Act, the Department of Defense has identified specific investments in construction, facility improvements, and energy efficiency projects. In its March 20, 2009 report, the Department provided a list of over 3,300 projects with an estimated cost of \$3.4 billion for Facilities Sustainment, Restoration, and Modernization (FSRM) funded under Division A, Title III of the Recovery Act—representing about 80 percent of the total FSRM funds appropriated to the Department of Defense. Enclosure 1 provides a list of 856 projects associated with the remaining 20 percent (\$835 million) of FSRM funds provided by the Act.

The projects in the report will be executed on installations located in 37 states and the District of Columbia, and will perform needed repairs and upgrades in a variety of facilities, increase energy efficiency, upgrade utilities systems and improve quality of life, especially for our single service members living in barracks. The following table provides a summary of the costs and numbers of projects by category:

| Project Category (Code) | Cost Estimate (\$000) | Number of Projects |
|--------------------------------|-----------------------|--------------------|
| Energy-related (E) | \$345,929 | 338 |
| Roof repair/replacement (R) | \$37,324 | 92 |
| Utilities (U) | \$50,289 | 53 |
| Pavement, roads or grounds (P) | \$152,819 | 91 |
| Barracks (B) | \$69,849 | 74 |
| Quality of Life (Q) | \$18,836 | 28 |
| Operations (O) | \$160,427 | 180 |
| Total | \$835,473 | 856 |

As with the initial report, this letter further provides the Congress, pursuant to section 2811 of Title 10, United States Code, with notification that the Department will be conducting repair projects greater than \$7.5 million for nine projects (Enclosure 2). The Department will ensure any statutory notice and wait periods are followed before obligating funds provided under the Recovery Act.

In addition to the final projects submitted herein, this report also provides notification of project changes in Hawaii, Tennessee and New York. Enclosure 3 provides project-level detail for these actions.

This notification and the initial March 20, 2009 report represent the Department's current plan, subject to amendment if significant changes occur during implementation. The Department of Defense appreciates the continued support of the Congress for Defense facility and infrastructure programs. Similar letters have been sent to the chairmen and ranking members of the House and Senate Armed Services Committee and the Committees on Appropriations of the House and Senate.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert F. Hale". The signature is written in a cursive, flowing style.

Robert F. Hale

Enclosures:
As stated

cc:
The Honorable John McCain
Ranking Member



UNDER SECRETARY OF DEFENSE
1100 DEFENSE PENTAGON
WASHINGTON, DC 20301-1100

COMPTROLLER

APR 28 2009

The Honorable David R. Obey
Chairman, Committee on Appropriations
U.S. House of Representatives
Washington, DC 20515

Dear Mr. Chairman:

The American Recovery and Reinvestment Act of 2009, Public Law 111-5 (the Recovery Act), was designed to stimulate economic growth by creating millions of jobs through investments in infrastructure improvements and expanding energy research in an effort to lead the way toward energy independence for our country.

To implement the Recovery Act, the Department of Defense has identified specific investments in construction, facility improvements, and energy efficiency projects. In its March 20, 2009 report, the Department provided a list of over 3,300 projects with an estimated cost of \$3.4 billion for Facilities Sustainment, Restoration, and Modernization (FSRM) funded under Division A, Title III of the Recovery Act—representing about 80 percent of the total FSRM funds appropriated to the Department of Defense. Enclosure 1 provides a list of 856 projects associated with the remaining 20 percent (\$835 million) of FSRM funds provided by the Act.

The projects in the report will be executed on installations located in 37 states and the District of Columbia, and will perform needed repairs and upgrades in a variety of facilities, increase energy efficiency, upgrade utilities systems and improve quality of life, especially for our single service members living in barracks. The following table provides a summary of the costs and numbers of projects by category:

| Project Category (Code) | Cost Estimate (\$000) | Number of Projects |
|--------------------------------|-----------------------|--------------------|
| Energy-related (E) | \$345,929 | 338 |
| Roof repair/replacement (R) | \$37,324 | 92 |
| Utilities (U) | \$50,289 | 53 |
| Pavement, roads or grounds (P) | \$152,819 | 91 |
| Barracks (B) | \$69,849 | 74 |
| Quality of Life (Q) | \$18,836 | 28 |
| Operations (O) | \$160,427 | 180 |
| Total | \$835,473 | 856 |

As with the initial report, this letter further provides the Congress, pursuant to section 2811 of Title 10, United States Code, with notification that the Department will be conducting repair projects greater than \$7.5 million for nine projects (Enclosure 2). The Department will ensure any statutory notice and wait periods are followed before obligating funds provided under the Recovery Act.

In addition to the final projects submitted herein, this report also provides notification of project changes in Hawaii, Tennessee and New York. Enclosure 3 provides project-level detail for these actions.

This notification and the initial March 20, 2009 report represent the Department's current plan, subject to amendment if significant changes occur during implementation. The Department of Defense appreciates the continued support of the Congress for Defense facility and infrastructure programs. Similar letters have been sent to the chairmen and ranking members of the House and Senate Armed Services Committee and the Committees on Appropriations of the House and Senate.

Sincerely,

A handwritten signature in cursive script that reads "Robert F. Hale".

Robert F. Hale

Enclosures:
As stated

cc:
The Honorable Jerry Lewis
Ranking Member



UNDER SECRETARY OF DEFENSE
1100 DEFENSE PENTAGON
WASHINGTON, DC 20301-1100

COMPTROLLER

APR 28 2009

The Honorable Daniel K. Inouye
Chairman, Committee on Appropriations
United States Senate
Washington, DC 20510

Dear Mr. Chairman:

The American Recovery and Reinvestment Act of 2009, Public Law 111-5 (the Recovery Act), was designed to stimulate economic growth by creating millions of jobs through investments in infrastructure improvements and expanding energy research in an effort to lead the way toward energy independence for our country.

To implement the Recovery Act, the Department of Defense has identified specific investments in construction, facility improvements, and energy efficiency projects. In its March 20, 2009 report, the Department provided a list of over 3,300 projects with an estimated cost of \$3.4 billion for Facilities Sustainment, Restoration, and Modernization (FSRM) funded under Division A, Title III of the Recovery Act—representing about 80 percent of the total FSRM funds appropriated to the Department of Defense. Enclosure 1 provides a list of 856 projects associated with the remaining 20 percent (\$835 million) of FSRM funds provided by the Act.

The projects in the report will be executed on installations located in 37 states and the District of Columbia, and will perform needed repairs and upgrades in a variety of facilities, increase energy efficiency, upgrade utilities systems and improve quality of life, especially for our single service members living in barracks. The following table provides a summary of the costs and numbers of projects by category:

| Project Category (Code) | Cost Estimate (\$000) | Number of Projects |
|--------------------------------|------------------------------|---------------------------|
| Energy-related (E) | \$345,929 | 338 |
| Roof repair/replacement (R) | \$37,324 | 92 |
| Utilities (U) | \$50,289 | 53 |
| Pavement, roads or grounds (P) | \$152,819 | 91 |
| Barracks (B) | \$69,849 | 74 |
| Quality of Life (Q) | \$18,836 | 28 |
| Operations (O) | \$160,427 | 180 |
| Total | \$835,473 | 856 |

As with the initial report, this letter further provides the Congress, pursuant to section 2811 of Title 10, United States Code, with notification that the Department will be conducting repair projects greater than \$7.5 million for nine projects (Enclosure 2). The Department will ensure any statutory notice and wait periods are followed before obligating funds provided under the Recovery Act.

In addition to the final projects submitted herein, this report also provides notification of project changes in Hawaii, Tennessee and New York. Enclosure 3 provides project-level detail for these actions.

This notification and the initial March 20, 2009 report represent the Department's current plan, subject to amendment if significant changes occur during implementation. The Department of Defense appreciates the continued support of the Congress for Defense facility and infrastructure programs. Similar letters have been sent to the chairmen and ranking members of the House and Senate Armed Services Committee and the Committees on Appropriations of the House and Senate.

Sincerely,

A handwritten signature in cursive script that reads "Robert F. Hale".

Robert F. Hale

Enclosures:
As stated

cc:
The Honorable Thad Cochran
Vice Chairman

**American Recovery and Reinvestment Act of 2009
Sustainment, Restoration and Modernization Projects by State**

| | Active Army | | Army National Guard | | Total | |
|----------------------|--------------------|----------------|----------------------------|---------------|--------------------|----------------|
| | Number of Projects | Cost (\$000s) | Number of Projects | Cost (\$000s) | Number of Projects | Cost (\$000s) |
| Alaska | 69 | 48,807 | 3 | 540 | 72 | 49,347 |
| Alabama | 15 | 8,602 | | | 15 | 8,602 |
| Arkansas | 1 | 355 | | | 1 | 355 |
| Arizona | 10 | 5,166 | | | 10 | 5,166 |
| California | 19 | 9,473 | | | 19 | 9,473 |
| Colorado | 24 | 36,949 | | | 24 | 36,949 |
| District of Columbia | 4 | 4,188 | | | 4 | 4,188 |
| Georgia | 22 | 47,628 | 5 | 3,270 | 27 | 50,898 |
| Hawaii | 51 | 59,179 | | | 51 | 59,179 |
| Iowa | | | 1 | 505 | 1 | 505 |
| Idaho | | | 2 | 788 | 2 | 788 |
| Illinois | 3 | 3,276 | | | 3 | 3,276 |
| Indiana | 4 | 424 | 3 | 2,761 | 7 | 3,185 |
| Kansas | 17 | 18,751 | | | 17 | 18,751 |
| Kentucky | 57 | 83,038 | | | 57 | 83,038 |
| Louisiana | 4 | 4,311 | 56 | 7,730 | 60 | 12,041 |
| Massachusetts | 8 | 1,868 | 7 | 8,701 | 15 | 10,569 |
| Maryland | 107 | 45,667 | | | 107 | 45,667 |
| Michigan | 9 | 3,672 | 1 | 800 | 10 | 4,472 |
| Minnesota | | | 7 | 3,109 | 7 | 3,109 |
| Missouri | 1 | 1,958 | 14 | 2,440 | 15 | 4,398 |
| Montana | | | 4 | 580 | 4 | 580 |
| North Carolina | 52 | 82,912 | | | 52 | 82,912 |
| New Jersey | 6 | 2,935 | | | 6 | 2,935 |
| New Mexico | 12 | 9,693 | 1 | 1,000 | 13 | 10,693 |
| Nevada | 7 | 6,332 | | | 7 | 6,332 |
| New York | 18 | 10,944 | | | 18 | 10,944 |
| Oklahoma | 37 | 65,892 | | | 37 | 65,892 |
| Pennsylvania | 13 | 4,549 | 25 | 6,687 | 38 | 11,236 |
| South Carolina | 12 | 4,208 | 1 | 750 | 13 | 4,958 |
| Texas | 65 | 153,747 | 9 | 1,239 | 74 | 154,986 |
| Utah | 12 | 10,706 | | | 12 | 10,706 |
| Virginia | 34 | 28,483 | | | 34 | 28,483 |
| Vermont | | | 3 | 2,022 | 3 | 2,022 |
| Washington | 13 | 27,562 | | | 13 | 27,562 |
| Wisconsin | | | 3 | 501 | 3 | 501 |
| West Virginia | | | 2 | 100 | 2 | 100 |
| Wyoming | | | 3 | 676 | 3 | 676 |
| Total: | 706 | 791,274 | 150 | 44,199 | 856 | 835,473 |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------|-------|---|-----------------------|------------------|
| Active Army | | | | 791,274 | |
| 1474 | Fort Greely | AK | Construct 2nd Traffic Lane | 100 | P |
| 1475 | Fort Greely | AK | Renovate Physical Fitness Center--Finishes, Plumbing, Electrical, HVAC, Doors, Windows. | 2,000 | E |
| 1476 | Fort Greely | AK | Replace Windows In Bldg 702 | 276 | E |
| 1477 | Fort Greely | AK | Install exterior insulation finishing system on Exterior of Admin Bldg 663 | 923 | E |
| 1478 | Fort Greely | AK | Install Installation Identification Signs | 213 | O |
| 1479 | Fort Greely | AK | Install Ice Dams and Gutters on Child Development Center | 80 | Q |
| 1480 | Fort Greely | AK | Install Main Gate and Sidewalks at BLDG 671 | 19 | O |
| 1481 | Fort Greely | AK | Install an Up-To-Date Vehicle Exhaust System BLDG 615 Motor Pool | 50 | O |
| 1482 | Fort Greely | AK | Prepare and Install Directional Signs On-Post | 30 | O |
| 1483 | Fort Richardson | AK | Bldg 624, Barracks, Repair Interior For 4/25 ABCT, Paint, Lighting, Dayroom Repair | 394 | B |
| 1484 | Fort Richardson | AK | Bldg 628, Barracks, Repair Interior For 4/25 ABCT, Paint, Lighting, Dayroom Repair | 394 | B |
| 1485 | Fort Richardson | AK | Bldg 630, Barracks, Repair Interior For 4/25 ABCT, Paint, Lighting, Dayroom Repair | 279 | B |
| 1486 | Fort Richardson | AK | Bldg 798, Veh Maint, Repair Vent & Exhaust Sys For the 98 Maint | 1,712 | O |
| 1487 | Fort Richardson | AK | Repair Wall and Windows Bldg 724 | 150 | O |
| 1488 | Fort Richardson | AK | Repair Water and Electrical Systems | 650 | E |
| 1489 | Fort Richardson | AK | Bldg 622, Barracks--Repair Interior For 4/25 ABCT, Paint, Lighting, Dayroom Repair | 279 | B |
| 1490 | Fort Richardson | AK | Bldg 632, Barracks--Repair Interior For 4/25 ABCT, Paint, Lighting, Dayroom Repair | 394 | B |
| 1491 | Fort Richardson | AK | Bldg 626, Barracks, Repair Interior For 4/25 ABCT, Paint, Lighting, Dayroom Repair | 279 | B |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------|-------|---|-----------------------|------------------|
| 1492 | Fort Richardson | AK | Bldg 750, Motor Pool, Repair Vent & Exhaust Sys For 4/25 ABCT | 394 | O |
| 1493 | Fort Richardson | AK | Bldg 976, Motor Pool, Repair Vent & Exhaust Sys For the 4/25 ABCT | 1,471 | O |
| 1494 | Fort Richardson | AK | Bldg 664, UPH, Repair Interior for 62 Truck Company | 2,546 | O |
| 1495 | Fort Richardson | AK | Construct addition to motor pool bldg B47645 | 750 | O |
| 1496 | Fort Richardson | AK | Install Heat Controls Bldg 7 | 33 | E |
| 1497 | Fort Richardson | AK | Repair and Upgrade Rail Spur | 890 | P |
| 1498 | Fort Richardson | AK | Install Heat Controls For Side Walk System Bldg 1 | 85 | E |
| 1499 | Fort Richardson | AK | Install Heat Controls For Sidewalks Bld 690 | 50 | E |
| 1500 | Fort Richardson | AK | Install Lighting Controls Bld 806 | 66 | E |
| 1501 | Fort Richardson | AK | Install Lighting Controls Bldg 804 | 66 | E |
| 1502 | Fort Richardson | AK | Install Lighting Controls Bldg 802 | 55 | E |
| 1503 | Fort Richardson | AK | Install Lighting Controls Bldg 600 | 55 | E |
| 1504 | Fort Richardson | AK | Install Lighting Controls Bldg 800 | 50 | E |
| 1505 | Fort Richardson | AK | Install Lighting and Controls Bldg 802 | 72 | E |
| 1506 | Fort Richardson | AK | Install Lights and Controls Bldg 750 | 150 | E |
| 1507 | Fort Richardson | AK | Install Lights and Controls Bldg 756 | 150 | E |
| 1508 | Fort Richardson | AK | Install Lights and Controls Bldg 778 | 150 | E |
| 1509 | Fort Richardson | AK | Install Lighting and Controls Bldg 784 | 150 | E |
| 1510 | Fort Richardson | AK | Renovate Bldg 668 Basement-Finishes, Heat, Latrines | 600 | O |
| 1511 | Fort Richardson | AK | Repair and Upgrade Non-Commission Officers Academy Facilities | 950 | O |
| 1512 | Fort Richardson | AK | Convert Bldg 806 for parachute repair and storage | 500 | O |
| 1513 | Fort Richardson | AK | Construct Vehicle Inspection Facility at front gate | 749 | O |
| 1514 | Fort Richardson | AK | Upgrade Fire Suppression System Bldg 652 | 500 | O |
| 1515 | Fort Richardson | AK | Install Waterless Latrines In Range | 175 | E |
| 1516 | Fort Richardson | AK | Repair Water Sprinkler System Bld 656 | 360 | Q |
| 1517 | Fort Richardson | AK | Repair & Upgrade Vent System B806 | 1,000 | E |
| 1518 | Fort Richardson | AK | Renovate Assembly/Briefing Facility | 340 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------|-------|--|-----------------------|------------------|
| 1519 | Fort Wainwright | AK | Construct General Instruction Bldg at Known Distance Range | 700 | O |
| 1520 | Fort Wainwright | AK | Bldg 1051 - Repair 1st & 2nd Fl For Garrison Offices | 1,007 | O |
| 1521 | Fort Wainwright | AK | Bldg 1051 - Restoration of Basement Doors, Finishes, Elect, Heat | 1,377 | O |
| 1522 | Fort Wainwright | AK | Bldg 3401 - Repair Admin Space Finishes, Restrooms, Lighting | 500 | O |
| 1523 | Fort Wainwright | AK | Bldg 1046 - Repair Admin Space Painting, Floors, Lighting, Latrines | 2,500 | O |
| 1524 | Fort Wainwright | AK | Bldg 3487 SSA Warehouse - Repair/Renovate Interior | 2,025 | O |
| 1525 | Fort Wainwright | AK | Renovate and Expand Fire Station-Bldg 4390 | 1,400 | O |
| 1526 | Fort Wainwright | AK | 25ID 1BCT Vehicle Maintenance Shop Bldg 3485- Repair finishes, HVAC, elect | 865 | E |
| 1527 | Fort Wainwright | AK | 25ID 1BCT Company Ops Bldg 3450-Repair finishes, HVAC, elect | 313 | E |
| 1528 | Fort Wainwright | AK | 25ID 1BCT Battalion Hq Bldg 3409-Repair finishes, HVAC, elect | 125 | E |
| 1529 | Fort Wainwright | AK | 25ID 1BCT Battalion Hq Bldg 3407-Repair finishes, HVAC, elect | 322 | E |
| 1530 | Fort Wainwright | AK | 25ID 1BCT Org Storage Bldg 3496-Repair finishes, HVAC, elect | 206 | E |
| 1531 | Fort Wainwright | AK | 25ID 1BCT Org Storage Bldg 3494-Repair finishes, HVAC, elect | 414 | E |
| 1532 | Fort Wainwright | AK | 25ID 1BCT Org Storage Bldg 3492-Repair finishes, HVAC, elect | 414 | E |
| 1533 | Fort Wainwright | AK | 25ID 1BCT Battalion Ops Bldg 3717-Repair finishes, HVAC, elect | 947 | E |
| 1534 | Fort Wainwright | AK | 25ID 1BCT Vehicle Maintenance Shop Bldg 3425- Repair finishes, HVAC, elect | 1,515 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------|-------|--|-----------------------|------------------|
| 1535 | Fort Wainwright | AK | Replace Meridian/Neely Road Intersection With Improved Traffic Control Facility | 700 | P |
| 1536 | Fort Wainwright | AK | Replace Meridian/Montgomery Road Intersection With Improved Traffic Control Facility | 700 | P |
| 1537 | Fort Wainwright | AK | Repair North Section of Building 1054 Roof and Trusses | 1,400 | R |
| 1538 | Fort Wainwright | AK | Pave Fire Station Parking Area | 40 | P |
| 1539 | Fort Wainwright | AK | Building 1555, Garrison HQ: HVAC Repair & Upgrade For Energy Efficiency | 5,000 | E |
| 1540 | Fort Wainwright | AK | Building 3401, Welcome Center: HVAC Repair & Upgrade For Energy Efficiency | 5,000 | E |
| 1541 | Fort Wainwright | AK | Replace Roof Building 2019 | 409 | R |
| 1542 | Fort Wainwright | AK | Building 3490: Replace Ventilation System | 350 | E |
| 1543 | Anniston Army Depot | AL | Restricted Area Water System Repairs | 330 | U |
| 1544 | Fort Rucker | AL | Repair HVAC - Training Barracks | 2,000 | E |
| 1545 | Fort Rucker | AL | HVAC Conversion - Permanent Party Barracks | 500 | E |
| 1546 | Fort Rucker | AL | Replace All Exterior Windows at Barracks 5909 | 250 | E |
| 1547 | Fort Rucker | AL | Renovate Bathrooms and Kitchens Barracks B303 | 300 | B |
| 1548 | Fort Rucker | AL | Repair Bridge | 275 | P |
| 1549 | Fort Rucker | AL | Restore Pavement at Cantonment Intersections | 654 | P |
| 1550 | Fort Rucker | AL | Install Air Conditioning to Communication Rooms | 125 | O |
| 1551 | Fort Rucker | AL | Convert Electrical and Gas Meters to Advanced Metering Kits | 600 | E |
| 1552 | Fort Rucker | AL | Replace Digital Controls - B5102 | 200 | E |
| 1553 | Fort Rucker | AL | Replace Digital Controls - B9214 | 150 | E |
| 1554 | Fort Rucker | AL | Repair Restrooms and Septic System Building B24207 | 250 | U |
| 1555 | Fort Rucker | AL | Construct Mail Distribution Center | 716 | O |
| 1556 | Redstone Arsenal | AL | Replace Existing and Install New Potable Water Meters | 1,847 | E |
| 1557 | Redstone Arsenal | AL | Renovate Bldg. 5105, Gate 1 Visitors Center | 405 | O |
| 1558 | Pine Bluff Arsenal | AR | Upgrade Electrical Service to 63 Area Buildings | 355 | U |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------------------|-------|--|-----------------------|------------------|
| 1559 | Fort Huachuca | AZ | Admin Building 22526--Repair Finishes, Elect, HVAC, Latrines, Doors, Windows. | 1,225 | E |
| 1560 | Fort Huachuca | AZ | Repair Boiler and Insulate Admin Building 41420 | 50 | E |
| 1561 | Fort Huachuca | AZ | Replace Boiler With Wood Chip Boiler at Central Plant | 675 | E |
| 1562 | Fort Huachuca | AZ | Retrofit All Existing T-12 Lights to T-8 | 1,000 | E |
| 1563 | Fort Huachuca | AZ | Repair Basewide Energy management Control System | 725 | E |
| 1564 | Fort Huachuca | AZ | Repair Sewer Line From manhole 5-90 to 5-91 | 75 | U |
| 1565 | Fort Huachuca | AZ | Repair Sewer Line From manhole 8-70 to 7-125 | 125 | U |
| 1566 | Fort Huachuca | AZ | Improve Chilled Water Distribution Loop In Building | 700 | E |
| 1567 | Yuma Proving Ground | AZ | Paving Repairs Main Cantonment Areas | 252 | P |
| 1568 | Yuma Proving Ground | AZ | Misc Paving Admin Areas - Part 2 | 339 | P |
| 1569 | Concord Military Ocean Terminal | CA | Repair Fire Suppression Bldg 128 | 750 | O |
| 1570 | Concord Military Ocean Terminal | CA | Repair HVAC Admin Building 542 | 75 | E |
| 1571 | Fort Irwin | CA | Repair family Support bldg 1313--Finishes, roof, doors, windows, HVAC, electrical, restrooms | 300 | E |
| 1572 | Fort Irwin | CA | Repair Shoulders Truck-By-Pass Phase 4 | 975 | P |
| 1573 | Fort Irwin | CA | Repair HVAC Units - Augmentee Barracks | 490 | E |
| 1574 | Fort Irwin | CA | Repair Billets and Latrine/Shower Reserve Component | 526 | B |
| 1575 | Presidio Of Monterey | CA | Design & Construct Access Control Point at Bolio Gate | 747 | O |
| 1576 | Presidio Of Monterey | CA | Design & Construct Access Control Point at Franklin Gate | 747 | O |
| 1577 | Presidio Of Monterey | CA | Design & Construct Information Ctr at High Street | 745 | O |
| 1578 | Presidio Of Monterey | CA | Construct Information Center, Taylor Street Gate | 670 | O |
| 1579 | Presidio Of Monterey | CA | Replace Windows Barracks Bldg 622 | 550 | E |
| 1580 | Presidio Of Monterey | CA | Repair Corroded Ext Surfaces, Bldg 840 | 51 | B |
| 1581 | Presidio Of Monterey | CA | Replace Failing Water Laterals Supporting Classroom Buildings 209-218 | 98 | U |
| 1582 | Presidio Of Monterey | CA | Install Turnstile at Taylor Gate | 50 | O |
| 1583 | Sierra Army Depot | CA | Repair Roofs Buildings 671 & 672 | 500 | R |
| 1584 | Sierra Army Depot | CA | Repair Fencing at Various Locations | 500 | P |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------------|-------|---|-----------------------|------------------|
| 1585 | Sierra Army Depot | CA | Repair Paving at Various Warehouses | 1,000 | P |
| 1586 | Sierra Army Depot | CA | Various Repairs to Enlisted Barracks. Windows, Stucco, Paint | 200 | B |
| 1587 | Sierra Army Depot | CA | Minor Repairs to Warehouses | 500 | O |
| 1588 | Fort Carson | CO | Replacement of O/H Circuits 11 and 12 w/ underground electrical | 3,300 | U |
| 1589 | Fort Carson | CO | Repair/Replace Sanitary Sewers Phase 5 | 2,500 | U |
| 1590 | Fort Carson | CO | Bldg 1860 Replacement of Boiler #1-Phase 3 of 3 | 1,500 | E |
| 1591 | Fort Carson | CO | Repair/Replace Sanitary Sewers Phase 3 | 2,500 | U |
| 1592 | Fort Carson | CO | Repair Overhead Electric Lines, 5000 Area | 3,400 | U |
| 1593 | Fort Carson | CO | Repair Overhead Electric Lines, 7000 Area | 1,700 | U |
| 1594 | Fort Carson | CO | Remove/Replace Bridge No. T85115 | 500 | P |
| 1595 | Fort Carson | CO | Repair damaged concrete pavements at Tactical Vehicle Wash Facility | 300 | P |
| 1596 | Fort Carson | CO | Construct New Parking Lot Adjacent to Bldg 2360 (Meddac) | 136 | P |
| 1597 | Fort Carson | CO | Repair & Improve Gate 3 & expand queuing area | 1,241 | P |
| 1598 | Fort Carson | CO | Repair/Replace underground Electric Lines In the 4000 Area-Housing | 3,000 | U |
| 1599 | Fort Carson | CO | Replace Boilers and Furnaces in Multiple Buildings | 900 | E |
| 1600 | Fort Carson | CO | Upgrade Barracks 7480-Repair Finishes, Elect, HVAC, Latrines, Doors, Windows. | 2,708 | E |
| 1601 | Fort Carson | CO | Repair DFAC, 7481 For 10th Sfg | 1,090 | B |
| 1602 | Fort Carson | CO | Repair Parking Lots, 2356 | 114 | P |
| 1603 | Fort Carson | CO | Restore 4/4 Id Bn Hqtrs Bldg 1352 | 1,050 | O |
| 1604 | Fort Carson | CO | Repair & Modernize Existing Co Hq Bldg 1650 | 2,980 | O |
| 1605 | Fort Carson | CO | Repair and Modernize Existing Co Hq Bldg 1957 | 2,980 | O |
| 1606 | Fort Carson | CO | Design /Construct Headquarters Facility For 71st Explosive Ordnance Disposal Detachment | 750 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------|-------|--|-----------------------|------------------|
| 1607 | Fort Carson | CO | Design /Construct artifact storage facility for 4th Infantry Division | 750 | O |
| 1608 | Fort Carson | CO | Repair interior, bldg 8030 Floors, Finishes, Latrines, HVAC, Elect. | 2,000 | O |
| 1609 | Fort Carson | CO | Repair Intersection Nelson - Specker | 750 | P |
| 1610 | Fort Carson | CO | Repair Intersection Ellis - Specker | 750 | P |
| 1611 | Fort Carson | CO | Replace Flooring child development center | 50 | Q |
| 1612 | Fort McNair | DC | Restoration of B33 Hard Stand Parking Lot DPW Area | 500 | P |
| 1613 | Fort McNair | DC | Decentralize Steam Plant McNair Bldg 34 | 1,943 | E |
| 1614 | Fort McNair | DC | Relamp NDU Bldgs on Ft McNair | 800 | E |
| 2163 | Fort McNair | DC | Correct Road Deficiencies and Widen 5th Ave | 945 | P |
| 1615 | Fort Benning | GA | Decentralize Boiler Plant, Bldg 397 (8 Stand Alone Units) | 3,267 | E |
| 1616 | Fort Benning | GA | Repair Storm Sewer - Lumpkin to Yeager - DPW | 545 | U |
| 1617 | Fort Benning | GA | Repair & Upgrade Storm Sewer - Sigafos to Wold | 1,534 | U |
| 1618 | Fort Benning | GA | Repair & Upgrade Storm Sewer - Wold to Ingersoll | 2,900 | U |
| 1619 | Fort Benning | GA | Pavement repairs at various locations | 566 | P |
| 1620 | Fort Benning | GA | Interior Building Renovation - Bldg 72 - 199th Inf Bde | 1,145 | O |
| 1621 | Fort Benning | GA | Repairs to Garrison Admin Bldg 89. Repair finishes, doors, windows, latrines, HVAC, elect | 1,300 | O |
| 1622 | Fort Benning | GA | Repair Building Army Community Service bldg 7. Repair walls, windows, doors, HVAC, latrines, elect | 1,300 | Q |
| 1623 | Fort Benning | GA | Replace Roof Bldg 5081 | 40 | R |
| 1624 | Fort Benning | GA | Renovate Auditorium Bldg 328 | 554 | Q |
| 1625 | Fort Gillem (enclave) | GA | Replace/Remove Fire Hydrants | 173 | U |
| 1626 | Fort Gillem (enclave) | GA | Replace Fire Mains In Enclave | 856 | U |
| 1627 | Fort Gillem (enclave) | GA | Reroute Boiler Drains to Sanitary Sewer | 15 | U |
| 1628 | Fort Gordon | GA | Replace Range Control Bldg | 526 | O |
| 1629 | Fort Gordon | GA | Replace Forestry Bldg | 489 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|--------------------|-------|---|-----------------------|------------------|
| 1630 | Fort Gordon | GA | Renovate and Expand DPWL Offices, Repair Finishes, Plumbing, Electric, HVAC, Doors, Windows. | 924 | E |
| 1631 | Fort Gordon | GA | Roof Replacement, Chaplain Admin | 800 | R |
| 1632 | Fort Stewart | GA | Repair Chilled Water Distribution System | 24,000 | E |
| 1633 | Fort Stewart | GA | Renovate DFAC bldg 207 | 900 | B |
| 1634 | Fort Stewart | GA | Repair bldg 443 Admin and operational space, repair finishes, HVAC, elect, doors, windows, latrines | 3,000 | E |
| 1635 | Fort Stewart | GA | Renovate Lift Station - Hunter Army Air Field | 795 | E |
| 1636 | Fort Stewart | GA | Aviation Maintenance Hanger Fire Suppression System Repair | 2,000 | O |
| 1637 | Fort Shafter | HI | Repair Staff Judge Advocate Bldg 718 - repair finishes, doors, windows, elect, HVAC, latrines | 2,350 | O |
| 1638 | Fort Shafter | HI | Structural Termite Repairs, Palm Circle B102 | 2,750 | O |
| 1639 | Schofield Barracks | HI | Install Solar Heating Systems For Billeting | 83 | E |
| 1640 | Schofield Barracks | HI | Barracks Bdgs 130 and 131--Mold/Moisture/Vapor Remediation | 1,000 | B |
| 1641 | Schofield Barracks | HI | Renovate Motor Pool-Repair Finishes, Plumbing, Electric, HVAC, Doors, Windows. | 575 | E |
| 1642 | Schofield Barracks | HI | Building 1580 Replace Water Treatment Plant Generator Load Interruption | 4,650 | E |
| 1643 | Schofield Barracks | HI | Central Plant Tube Repair and Maintenance | 300 | E |
| 1644 | Schofield Barracks | HI | Building 2069 Replace Roof, Install Photovoltaic System (150 KW) | 2,400 | R |
| 1645 | Schofield Barracks | HI | Range Control Wind/Solar Power Generation System | 749 | E |
| 1646 | Schofield Barracks | HI | Install Photovoltaic system and generator set, Bradshaw Airfield | 683 | E |
| 1647 | Schofield Barracks | HI | Install Generator Set Ph 3 | 900 | E |
| 1648 | Schofield Barracks | HI | Install Generator Set Ph 4 | 900 | E |
| 1649 | Schofield Barracks | HI | Replace Roof For Troop Issue Subsistence Activity Facility and Install photovoltaic system | 3,150 | R |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|--------------------|-------|---|-----------------------|------------------|
| 1650 | Schofield Barracks | HI | Restore Showers and replace water heaters with solar heaters - admin bldg 520 | 1,400 | E |
| 1651 | Schofield Barracks | HI | Replace Latchsets With Keyless Lock | 1,000 | B |
| 1652 | Schofield Barracks | HI | Repair Non-Commissioned Officer Academy Barracks | 1,500 | B |
| 1653 | Schofield Barracks | HI | Renovate B2102/2105 25th ID Band | 500 | O |
| 1654 | Schofield Barracks | HI | Repair Exterior Damage, B692 | 1,150 | O |
| 1655 | Schofield Barracks | HI | Replace Perimeter Fence at Mendonca | 1,400 | P |
| 1656 | Schofield Barracks | HI | Install Perimeter Fence, Water Storage Tank Bldg 4 | 100 | P |
| 1657 | Schofield Barracks | HI | Street Light Renovation, Generals Loop | 1,000 | U |
| 1658 | Schofield Barracks | HI | Replace Roof and Install 32kv photovoltaic system | 1,162 | R |
| 1659 | Schofield Barracks | HI | Repair Fort Shafter Youth Center bldg 505 | 250 | Q |
| 1660 | Schofield Barracks | HI | Repair Child Development Center | 1,000 | Q |
| 1661 | Schofield Barracks | HI | Repair Fort Shafter Library | 350 | Q |
| 1662 | Schofield Barracks | HI | Repair Education Center | 450 | Q |
| 1663 | Schofield Barracks | HI | Repair Roof and Access Ramp to Wheeler Army Airfield Bldg 122 | 150 | R |
| 1664 | Schofield Barracks | HI | Replace Roof and Install 47 Kw photovoltaic system | 571 | R |
| 1665 | Schofield Barracks | HI | Install Motor Pool Crane (Bldg 2600) | 200 | O |
| 1666 | Schofield Barracks | HI | Building B780 Dining Facility--install pads, conduit, switchgear for backup Generator | 750 | E |
| 1667 | Schofield Barracks | HI | Repair Child Development Center (Bldg 9098) | 500 | Q |
| 1668 | Schofield Barracks | HI | Pohakuloa Training Area Building 238 photovoltaic system | 950 | E |
| 1669 | Schofield Barracks | HI | Pohakuloa Training Area Building 390 photovoltaic system | 950 | E |
| 1670 | Schofield Barracks | HI | Replace Roof and Install photovoltaic system to Various Bldgs | 2,201 | R |
| 1671 | Schofield Barracks | HI | Replace Roofing and Flashing Wheeler 1322 | 280 | R |
| 1672 | Schofield Barracks | HI | Replace Roofing and Daylighting For Building 2070 Central Issue Facility | 2,000 | R |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|--------------------------------|-------|---|-----------------------|------------------|
| 1673 | Schofield Barracks | HI | Room Lock Conversion For Barracks 1492 | 300 | B |
| 1674 | Schofield Barracks | HI | Install Solar Powered Security Light | 91 | E |
| 1675 | Schofield Barracks | HI | Repair Motor Pool - Finishes, Plumbing, Electric, HVAC, Doors, Windows. | 425 | E |
| 1676 | Schofield Barracks | HI | Improve Building Envelope motor pool bldg 990 | 560 | E |
| 1677 | Schofield Barracks | HI | Repair BAAF runway and Apron | 300 | P |
| 1678 | Wheeler Army Airfield | HI | Restore Failing Roof Admin bldg 547 & Install Photovoltaic System | 1,800 | R |
| 1679 | Wheeler Army Airfield | HI | Replace Parking Apron Concrete Sections | 2,000 | P |
| 1680 | Wheeler Army Airfield | HI | Replace Building 105 HVAC System | 600 | E |
| 1681 | Wheeler Army Airfield | HI | Building 1006 - Misc HVAC and Lighting Repair | 300 | E |
| 1682 | Wheeler Army Airfield | HI | Repair Solar Hot Water Systems | 300 | E |
| 1683 | Wheeler Army Airfield | HI | Combat Aviation Brigade Hanger Window Repairs | 3,000 | E |
| 1684 | Wheeler Army Airfield | HI | Repair Ammunition Supply Point Road Due to Storm Damage | 2,000 | P |
| 1685 | Wheeler Army Airfield | HI | Repair Electrical and Lighting Sys at combat aviation brigade Hangar 206 | 2,000 | E |
| 1686 | Wheeler Army Airfield | HI | Repair 3rd Floor B107 | 4,450 | O |
| 1687 | Wheeler Army Airfield | HI | Building B102 Dining Facility--install pads, conduit, switchgear for backup Generator | 750 | E |
| 1688 | Rock Island Arsenal | IL | Repair building exterior stonework, multiple historic bldgs | 2,531 | O |
| 1689 | Rock Island Arsenal | IL | Repair Railroad Bridge - Str 228 | 599 | P |
| 1690 | Rock Island Arsenal | IL | Perform carpentry, electrical, HVAC, plumbing repairs-- Multiple Buildings | 146 | O |
| 1691 | Crane Army Ammunition Activity | IN | Emergency Generator Replacement Bldg 2737 | 150 | E |
| 1692 | Crane Army Ammunition Activity | IN | Roof Replacement Bldg 2746 | 100 | R |
| 1693 | Crane Army Ammunition Activity | IN | Roof Replacement Bldg 2747 | 100 | R |
| 1694 | Crane Army Ammunition Activity | IN | Waterline Replacement Bldg 123 | 74 | E |
| 1695 | Fort Leavenworth | KS | Repair Harney Fitness Center HVAC, Building 664 | 3,000 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------|-------|---|-----------------------|------------------|
| 1696 | Fort Leavenworth | KS | Repair HVAC and Interior, Bldg 302, Gruber Fitness Center | 3,000 | E |
| 1697 | Fort Leavenworth | KS | Repair Electrical System In Bldg 136 | 3,000 | E |
| 1698 | Fort Leavenworth | KS | Repair Int/Ext, HVAC to Library, Eisenhower Hall, #120 | 4,000 | E |
| 1699 | Fort Leavenworth | KS | Repair the Central Tower On Grant Hall | 2,450 | O |
| 1700 | Fort Riley | KS | Bldg 8370 Install DDC Controls | 60 | E |
| 1701 | Fort Riley | KS | Bldg 8330 Install DDC Controls | 80 | E |
| 1702 | Fort Riley | KS | Bldg 8380 Motorpool Lighting Retrofit | 99 | E |
| 1703 | Fort Riley | KS | 7720 Motorpool Upgrade--Install Digital Controls | 100 | E |
| 1704 | Fort Riley | KS | Correct ADA Deficiencies in Dining Hall B | 300 | O |
| 1705 | Fort Riley | KS | Repair and Replace Failed Water Well | 750 | E |
| 1706 | Fort Riley | KS | Bldg 7515 Clean, Inspect and Paint | 50 | O |
| 1707 | Fort Riley | KS | Repair Bldg 7024 Parking Lot | 32 | P |
| 1708 | Fort Riley | KS | Bldg 8100 Design & Install Overhead Lighting | 750 | O |
| 1709 | Fort Riley | KS | Repair Bldg 8100 Bay Doors | 350 | E |
| 1710 | Fort Riley | KS | Repair Restorooms/Intall Handicap Lift to Access Auditorium Bldg | 605 | O |
| 1711 | Fort Riley | KS | Rebuild Gas Metering Station | 125 | E |
| 1712 | Blue Grass Army Depot | KY | Renovate Barracks 162-- Walls, HVAC, Electrical, Plumbing, Finishes | 995 | E |
| 1713 | Blue Grass Army Depot | KY | Repair and Upgrade Sewer Treatment Plant | 1,379 | U |
| 1714 | Blue Grass Army Depot | KY | Water Plant & Distribution Lines Repair and Upgrades | 702 | E |
| 1715 | Blue Grass Army Depot | KY | Repair Failed Building Exterior siding and roofs, multiple buildings. | 2,224 | R |
| 1716 | Blue Grass Army Depot | KY | Repair Ceiling Insulation (Bldgs 216,221 & 222) | 576 | E |
| 1717 | Fort Campbell | KY | Renovate Hanger #1, Bldg 6627 159th Combat Aviation Bde | 2,072 | O |
| 1718 | Fort Campbell | KY | Renovate Hangar #4, Bldg 7152 159th Combat Aviation Bde | 2,072 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------|-------|--|-----------------------|------------------|
| 1719 | Fort Campbell | KY | Renovate Hangar #2, Bldg 7156 159th Combat Aviation Bde | 2,072 | O |
| 1720 | Fort Campbell | KY | Renovate Hangar #5, Bldg 7206 159th Combat Aviation Bde | 2,072 | O |
| 1721 | Fort Campbell | KY | Renovation of Bldg 7523 - 52nd and 49th Eod. Repair Finishes, Plumbing, Elect, HVAC, Doors, Windows. | 1,202 | E |
| 1722 | Fort Campbell | KY | Renovate and Paint Bldg 7565, 7563 and 7562 | 750 | O |
| 1723 | Fort Campbell | KY | Renovate Barracks Bldg 7520-- Windows, HVAC, Roof | 500 | E |
| 1724 | Fort Campbell | KY | Repair Pavement at Campbell Army Airfield (Phase I) | 4,975 | P |
| 1725 | Fort Campbell | KY | Repair Pavement at Campbell Army Airfield (Phase II) | 4,925 | P |
| 1726 | Fort Campbell | KY | Refurbish 15 Hammerhead Barracks Bldg Exterior 3200 & 6700 Blocks | 640 | B |
| 1727 | Fort Campbell | KY | Recondition Hammerhead Barracks Stairwells 3200 & 6700 Block Paint and Recondition Floors | 1,110 | B |
| 1728 | Fort Campbell | KY | Repair Hammerhead Barracks 3200 (5th Sfg), Electric, & HVAC | 1,725 | E |
| 1729 | Fort Campbell | KY | Repair 159th Admin Facilities - 16 Bldgs, HVAC, Paint, door/window, latrines | 2,170 | E |
| 1730 | Fort Campbell | KY | Repair 159th Barracks (7110, 7112, 6936), HVAC, Paint, door/window, latrines | 1,340 | E |
| 1731 | Fort Campbell | KY | Repair Intersection at McAuliffe Way and 101st Airborne Road | 780 | P |
| 1732 | Fort Campbell | KY | Repair Bldg 5223 Motor Pool Finishes, Doors, Elect | 221 | O |
| 1733 | Fort Campbell | KY | Refurbish Finishes, Elect, HVAC, Barracks Bldg 6929 | 359 | E |
| 1734 | Fort Campbell | KY | Design/Construct Drivers Safety Course and Training Facility | 765 | O |
| 1735 | Fort Campbell | KY | Repair Barracks Bldgs 2994, 2995, 2997 & 6930 | 1,450 | B |
| 1736 | Fort Campbell | KY | Renovate & Refurbish HVAC, Plumbing, Roof, Windows, Paint, Floor Tile and Ceiling (NCO Academy) | 1,110 | R |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------|-------|--|-----------------------|------------------|
| 1737 | Fort Campbell | KY | Refurbish 14 Trainee Barracks / Admin - Camp Hinsch. HVAC, Plumbing, Finishes | 2,335 | E |
| 1738 | Fort Campbell | KY | Renovate Education Facility | 1,475 | Q |
| 1739 | Fort Campbell | KY | Repairs to barracks 6730, 6731, 6732, 6733 for 101st Sustainment Brigade | 1,455 | B |
| 1740 | Fort Campbell | KY | Repair exterior Fitness Facility | 1,829 | O |
| 1741 | Fort Campbell | KY | Renovate Community Support Facility - Ceiling, HVAC, sprinkler system | 425 | E |
| 1742 | Fort Campbell | KY | Repair Barracks Bldgs 3213, 3214 and 3217-- HVAC, Paint, door/window, latrines | 1,150 | E |
| 1743 | Fort Campbell | KY | Repair Barracks Bldgs 6921 and 6922--HVAC, Paint, door/window, latrines | 738 | E |
| 1744 | Fort Campbell | KY | Repair Barracks Bldg 6927-- HVAC, Paint, door/window, latrines | 290 | E |
| 1745 | Fort Campbell | KY | Repair Admin. Facilities Bldgs 6934 and 6935--HVAC, Paint, door/window, latrines | 75 | E |
| 1746 | Fort Campbell | KY | Repair Admin Bldgs 6747, 6748 6741--HVAC, Paint, door/window, latrines | 625 | E |
| 1747 | Fort Campbell | KY | Building 03730 -- Mold/Moisture/Vapor prevention and abatement improvements | 3,012 | B |
| 1748 | Fort Campbell | KY | Building 03731, Mold/Moisture/Vapor prevention and abatement improvements | 3,027 | B |
| 1749 | Fort Campbell | KY | Building 03748, Mold/Moisture/Vapor prevention and abatement improvements | 3,015 | B |
| 1750 | Fort Campbell | KY | Building 04067, Mold/Moisture/Vapor prevention and abatement improvements | 4,013 | B |
| 1751 | Fort Campbell | KY | Building 03713, Mold/Moisture/Vapor prevention and abatement improvements | 3,715 | B |
| 1752 | Fort Campbell | KY | Building 03725, Mold/Moisture/Vapor prevention and abatement improvements | 4,017 | B |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------|-------|---|-----------------------|------------------|
| 1753 | Fort Campbell | KY | Renovate Lazado Fitness Facility -restrooms and weight training area | 350 | O |
| 1754 | Fort Campbell | KY | Design and Construct Child & Youth Service Facility | 640 | Q |
| 1755 | Fort Knox | KY | Correct Structural Deficiencies on Installation Water Reservoir (Douglas Dam) | 450 | U |
| 1756 | Fort Knox | KY | Resurface Badly Deteriorated Ammo Route Pavement On Baker Road | 350 | P |
| 1757 | Fort Knox | KY | Repair Doors, Ceiling, Walls, Exterior, Landscaping to Barracks Bldgs #2376 & 2377 | 1,035 | B |
| 1758 | Fort Knox | KY | Renovate Natcher Physical Fitness Center--floors, lockers, showers | 773 | O |
| 1759 | Fort Knox | KY | Renovate Operational (Veh Maint) Facility B-2955 - Male/Female Latrines, Electric, HVAC, Windows, Doors, Exterior Walls | 570 | E |
| 1760 | Fort Knox | KY | Renovate Operational (Veh Maint) Facility B-2958- Male/Female Latrines, Electric, HVAC, Windows, Doors, Exterior Walls | 2,980 | E |
| 1761 | Fort Knox | KY | Repair Fayette Ave, Ballard Ave, and Audobon Street | 273 | P |
| 1762 | Fort Knox | KY | Repair HVAC System In 2341 With Renewable Geothermal System | 1,100 | E |
| 1763 | Fort Knox | KY | Repair HVAC System In 63 With Renewable Geothermal HVAC System | 900 | E |
| 1764 | Fort Knox | KY | Renovate B-298 Law Enforcement Command-Repair All Finishes, Doors, Windows, Mechanical Systems | 3,600 | O |
| 1765 | Fort Knox | KY | Maintain Water Well | 75 | U |
| 1766 | Fort Knox | KY | Replace Bridge # 26 | 100 | P |
| 1767 | Fort Knox | KY | Repair 9th Cavalry Regiment Avenue | 147 | P |
| 1768 | Fort Knox | KY | Renovate Interior B-1481-Rpr Latrines, Fire Alarm, and Mass Notification System | 313 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------------|-------|--|-----------------------|------------------|
| 1769 | Fort Polk | LA | Repair/Overlay North Fort Entrance Road and Repair Traffic Signals | 765 | P |
| 1770 | Fort Polk | LA | Repair and Clean 22 Tactical Equipment Maintenance and Administrative Facilities | 3,267 | O |
| 1771 | Fort Polk | LA | Main Post Chapel Renovations to Include Walls, Ceilings, Doors, Painting | 250 | Q |
| 1772 | Fort Polk | LA | Repair Parking Lot B 3350 | 29 | P |
| 1773 | Natick Soldier Systems Labs | MA | Improve Exterior Lighting | 30 | E |
| 1774 | Natick Soldier Systems Labs | MA | Replace Boilers Bldgs 1,2,3 & 4 | 1,300 | E |
| 1775 | Natick Soldier Systems Labs | MA | Repair Building 20 Exterior Surfaces | 250 | O |
| 1776 | Natick Soldier Systems Labs | MA | Maintain Climatic Chambers | 100 | O |
| 1777 | Natick Soldier Systems Labs | MA | Construct Stairs Between Boiler Plant and Rear Parking Lot | 30 | U |
| 1778 | Natick Soldier Systems Labs | MA | Repair Bldg 16 Front Wall | 65 | O |
| 1779 | Natick Soldier Systems Labs | MA | Repair Underground Sewer Line Between Bldg 14 & Bldg 15 | 20 | U |
| 1780 | Natick Soldier Systems Labs | MA | Repair/Upgrade HVAC Controls - Admin Bldg 1 | 73 | E |
| 1781 | Aberdeen Proving Ground | MD | Repair/Replace Defective Fan Coil Units, Bldg 3070 | 50 | E |
| 1782 | Aberdeen Proving Ground | MD | Replace Steam and Condensate Lines, 5200 Block | 100 | E |
| 1783 | Aberdeen Proving Ground | MD | Replace Roof On Bldg 4218 | 1,100 | R |
| 1784 | Aberdeen Proving Ground | MD | Replace Roof For Bldg 3148 | 484 | R |
| 1785 | Aberdeen Proving Ground | MD | Repairs to HVAC In Bldg 394 | 2,500 | E |
| 1786 | Aberdeen Proving Ground | MD | Repair Barracks 4307 HVAC, Finishes, Elect, Latrines | 250 | E |
| 1787 | Aberdeen Proving Ground | MD | Repair Spesuite Island Roads | 600 | P |
| 1788 | Aberdeen Proving Ground | MD | Repair Roof, E1454 | 75 | R |
| 1789 | Aberdeen Proving Ground | MD | Regrade Entrance to Bldg E5165 | 65 | O |
| 1790 | Aberdeen Proving Ground | MD | Repair Circuit Breaker, 333 | 250 | U |
| 1791 | Aberdeen Proving Ground | MD | Repair Emergency Lights, E4222 | 50 | B |
| 1792 | Aberdeen Proving Ground | MD | Repair Building 316 Electrical, HVAC, Plumbing, Finishes, Doors, Windows | 9,400 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------------------|-------|---|-----------------------|------------------|
| 1793 | Aberdeen Proving Ground | MD | Repair Walk-In Refrigerator Door at Dining Facility (Building 4503) | 40 | B |
| 1794 | Aberdeen Proving Ground | MD | Provide Disabled/Wheelchair Access to Bldg 1134 | 30 | O |
| 1795 | Aberdeen Proving Ground | MD | Structural Repairs to Bldg 700 | 50 | O |
| 1796 | Aberdeen Proving Ground | MD | Replace Air Handling Units, E5100 | 250 | E |
| 1797 | Aberdeen Proving Ground | MD | Repair Roof Section On bldg 450 | 120 | R |
| 1798 | Aberdeen Proving Ground | MD | Reposition Egress Doors, 392 | 50 | O |
| 1799 | Aberdeen Proving Ground | MD | Repair Hotwater Holding Tank, 2184 | 30 | O |
| 1800 | Aberdeen Proving Ground | MD | Repair HVAC, Admin Bldg E4585 | 75 | E |
| 1801 | Aberdeen Proving Ground | MD | Replace Carbon Filtration System, E1454 | 100 | O |
| 1802 | Aberdeen Proving Ground | MD | Repair Computer Room A/C, Admin Bldg 314 | 200 | E |
| 1803 | Aberdeen Proving Ground | MD | Repair Emergency Lighting and Magnetized Doors, Admin Bldg 314 | 50 | O |
| 1804 | Aberdeen Proving Ground | MD | Replace Air Conditioning Units, E2188 | 50 | E |
| 1805 | Aberdeen Proving Ground | MD | Repair Sidewalks, 314 | 50 | P |
| 1806 | Aberdeen Proving Ground | MD | Repair Door - Bldg E3330 | 20 | O |
| 1807 | Aberdeen Proving Ground | MD | Repair Parking Lot, E3516 | 20 | P |
| 1808 | Aberdeen Proving Ground | MD | Repair Ceiling Bldg E3510 | 10 | O |
| 1809 | Aberdeen Proving Ground | MD | Provide Concrete Berm, 507 | 50 | O |
| 1810 | Aberdeen Proving Ground | MD | Repair HVAC In Bldg 331 | 175 | E |
| 1811 | Aberdeen Proving Ground | MD | Repair Environmental Control Systems, E3100 | 350 | E |
| 1812 | Aberdeen Proving Ground | MD | Repair Roof Leak, Building 4600 | 100 | R |
| 1813 | Aberdeen Proving Ground | MD | Repair Roof, Building 642 | 195 | R |
| 1814 | Aberdeen Proving Ground | MD | Repair A/C and Heat Units, Admin Bldgs E4586/88 | 150 | E |
| 1815 | Aberdeen Proving Ground | MD | Repair A/C, Bldg 4401 | 50 | E |
| 1816 | Aberdeen Proving Ground | MD | Repair Boiler, Maintenance Bldg E1464 | 150 | E |
| 1817 | Aberdeen Proving Ground | MD | Repair Roof, E5102 | 50 | R |
| 1818 | Aberdeen Proving Ground | MD | Repair Restroom Facilities Bldg E2188 | 50 | O |
| 1819 | Aberdeen Proving Ground | MD | Repair Roof, E5141 | 60 | R |
| 1820 | Aberdeen Proving Ground | MD | Replace exterior steam lines serving several bldgs | 500 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------------------|-------|---|-----------------------|------------------|
| 1821 | Aberdeen Proving Ground | MD | Repair Roof, E5101 | 100 | R |
| 1822 | Aberdeen Proving Ground | MD | Replace Main Electric Switch Gear and Motor Control Center | 50 | E |
| 1823 | Aberdeen Proving Ground | MD | Repair Child Development Center Facility, 2485-Repair Roof, Sprinkler, Floor, Mechanical Systems | 1,800 | R |
| 1824 | Aberdeen Proving Ground | MD | Repair Family Support bldg 2522- Kitchen, Floors, Walls, Windows, Doors, Mechanical | 750 | Q |
| 1825 | Aberdeen Proving Ground | MD | Repair Fitness Facility, Bldg 3300- Roof, Interior Floors, Doors, and Finishes | 900 | R |
| 1826 | Aberdeen Proving Ground | MD | Repair Fitness Center, Bldg E4210--floors, HVAC, cardiac area | 346 | E |
| 1827 | Aberdeen Proving Ground | MD | Repairs to Operations Building E2433-Repair Roof, Doors, Parking | 100 | R |
| 1828 | Aberdeen Proving Ground | MD | Repair Modified Record Fire Range | 700 | O |
| 1829 | Aberdeen Proving Ground | MD | Repair Barracks Building 2503, Repair Finishes, Elect, HVAC, Latrines, Doors, Windows. | 1,500 | E |
| 1830 | Aberdeen Proving Ground | MD | Repair Road and Culvert, E3150 | 80 | P |
| 1831 | Aberdeen Proving Ground | MD | Repair Exterior Wall, E3330 | 30 | O |
| 1832 | Aberdeen Proving Ground | MD | Repair HVAC and Ceiling, E2188 | 75 | E |
| 1833 | Aberdeen Proving Ground | MD | Low Cost Energy Modifications-Replace Lighting and Install HVAC Sensors and Controls Various Buildings. | 179 | E |
| 1834 | Aberdeen Proving Ground | MD | Correct Steam Issues at E5103, E5106, E5100. | 750 | E |
| 1835 | Aberdeen Proving Ground | MD | Repair and Replace Windows Barracks Bldg 4218 | 700 | E |
| 1836 | Aberdeen Proving Ground | MD | Renovate Barracks 4401 Lounge Area-Repair Wall, Floor, Ceiling Finishes, Improve Electric, Repair Laundry Area. | 100 | B |
| 1837 | Aberdeen Proving Ground | MD | Renovate Barracks 4501 Lounge Area-Repair Wall, Floor, Ceiling Finishes, Improve Electric, Repair Laundry Area. | 100 | B |
| 1838 | Aberdeen Proving Ground | MD | Exterior Building Repairs Barracks E4222 | 100 | B |

American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------------------|-------|---|-----------------------|------------------|
| 1839 | Aberdeen Proving Ground | MD | Renovate Barracks 4504 Lobby Area-Repair Wall, Floor, Ceiling Finishes, Improve Electric. | 100 | B |
| 1840 | Aberdeen Proving Ground | MD | Repair and Replace Windows and Renovations In the Lobby Area-Barracks 4507 | 700 | B |
| 1841 | Aberdeen Proving Ground | MD | Replace Windows and Renovate Lounge Area Barracks 4509 | 700 | B |
| 1842 | Aberdeen Proving Ground | MD | Barracks E4222 Replace Chiller, Replace Windows Renovation Laundry Room and Lounge | 900 | B |
| 1843 | Aberdeen Proving Ground | MD | Barracks E4227 Replace Chiller, Replace Windows Renovation Laundry Room and Lounge | 750 | B |
| 1844 | Aberdeen Proving Ground | MD | Barracks E4229 Replace Chiller , Renovate Lobby and Laundry Room and Replace Windows | 1,100 | B |
| 1845 | Aberdeen Proving Ground | MD | Renovations In the Common Area, Barracks 4502 | 100 | B |
| 1846 | Aberdeen Proving Ground | MD | Repair Roof, 330 | 80 | R |
| 1847 | Aberdeen Proving Ground | MD | Repair Monitoring Wells | 10 | U |
| 1848 | Aberdeen Proving Ground | MD | Repair Warehouse Interior Bldg 2314 | 100 | O |
| 1849 | Aberdeen Proving Ground | MD | Repair North End of Admin Building 320 | 250 | O |
| 1850 | Aberdeen Proving Ground | MD | Repair Sidewalks and Paving | 1,250 | P |
| 1851 | Aberdeen Proving Ground | MD | Repair Aberdeen Blvd and Colleran Blvd | 500 | P |
| 1852 | Aberdeen Proving Ground | MD | Demolish Water Tower | 50 | U |
| 1853 | Adelphi Labs | MD | Replace Blossom Point Electrical Distribution System | 1,000 | U |
| 1854 | Adelphi Labs | MD | Install Elevator Bldg 103 | 306 | O |
| 1855 | Adelphi Labs | MD | Replace Deluge Fire Protection System Bldg 107 | 65 | U |
| 1856 | Adelphi Labs | MD | Replace Concrete Decking and Other Repairs - Floral Drive Bridge | 220 | P |
| 1857 | Adelphi Labs | MD | Replace HVAC Isolation Valves Bldg 204 3rd Floor | 200 | E |
| 1858 | Adelphi Labs | MD | Replace Hazardous & Toxic Waste Isolation Valves In 100/200 Series Bldgs | 245 | U |
| 1859 | Adelphi Labs | MD | Renovate Fitness Facility -showers and exercise area floors | 300 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|---|-----------------------|------------------|
| 1860 | Fort Meade | MD | Repair/Replace HVAC at Fitness Facility | 163 | E |
| 1861 | Fort Meade | MD | Pave Overflow Parking Lot at Bldg 909 | 57 | P |
| 1862 | Fort Meade | MD | Replace Roof 6500 | 1,505 | R |
| 1863 | Fort Meade | MD | Repair Admin Building 6530 finishes, doors, windows, HVAC, masonry | 786 | E |
| 1864 | Fort Meade | MD | Repair/Replace of HVAC and Controls 4550 | 95 | E |
| 1865 | Fort Meade | MD | Repair/Replace of HVAC and Controls 4551 | 85 | E |
| 1866 | Fort Meade | MD | Repair Heat and Air Units Barracks 4704 | 225 | E |
| 1867 | Fort Meade | MD | Replace HVAC Bldg 6330 | 586 | E |
| 1868 | Fort Meade | MD | Replace Controls For HVAC In Mechanical Room | 51 | E |
| 1869 | Fort Meade | MD | Repair/Replacement of HVAC System and Controls, Exterior Painting 8550 | 95 | E |
| 1870 | Fort Meade | MD | Repair Ernie Pyle/Reece Road Intersection | 809 | P |
| 1871 | Fort Meade | MD | Replace Slate Roof Bldg 4551 | 75 | R |
| 1872 | Fort Meade | MD | Repair Exterior Lighting various areas | 125 | U |
| 1873 | Fort Meade | MD | Replace Roof Bldg 4704 | 260 | R |
| 1874 | Fort Meade | MD | Replace Roof Bldg 4705 | 260 | R |
| 1875 | Fort Meade | MD | Replace Roof Bldg 4707 | 260 | R |
| 1876 | Fort Meade | MD | Replace HVAC System Bldg 03100 | 1,365 | E |
| 1877 | Fort Meade | MD | Replace HVAC System Bldg 4725 | 1,115 | E |
| 1878 | Fort Meade | MD | Replace Heat and Air Units Barracks Bldg 4703 | 225 | E |
| 1879 | Fort Meade | MD | Replace Heat and Air Units Barracks Bldg 4707 | 320 | E |
| 1880 | Fort Meade | MD | Replace Heat and Air Units Barracks Bldg 4709 | 320 | E |
| 1881 | Fort Meade | MD | Replace Broken Pneumatic Controls With Digital Controls | 97 | E |
| 1882 | Fort Meade | MD | Install 7 Variable Air Volume Boxes and Associated Ductwork and Piping; Replace Outdoor Condensing Unit and Coil. Repipe Boiler | 360 | E |
| 1883 | Fort Meade | MD | Replace HVAC With 4-Pipe System. Install Ventilation. Reuse Chiller and Boiler - Barracks Bldg 4415 | 299 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------------|-------|---|-----------------------|------------------|
| 1884 | Fort Meade | MD | Repair/Replace Sidewalks and Ramped Crosswalks | 250 | P |
| 1885 | Fort Meade | MD | Replace Air Cooled Chiller and Building Loop Circulation Pumps Bldg 8544 | 224 | E |
| 1886 | Fort Meade | MD | Bldg 8544 Repairs For Outside Air and Moisture Control | 380 | O |
| 1887 | Fort Meade | MD | Repair/Replacment of Roadway Markings and Striping - Post | 40 | P |
| 1888 | Detroit Arsenal | MI | Replace Electric Cables From Building 212 to Building 230 E | 842 | U |
| 1889 | Detroit Arsenal | MI | Repair Roads (\$787k) and Construct Organizational Parking (\$612k) | 1,399 | P |
| 1890 | Detroit Arsenal | MI | Mound Rd Improvements at Mound Rd Access Control Point | 380 | P |
| 1891 | Detroit Arsenal | MI | Reconfigure Office Space For Garrison Missions bldg 232 | 395 | O |
| 1892 | Detroit Arsenal | MI | Replace faulty capacitor banks at electrical substations | 60 | E |
| 1893 | Detroit Arsenal | MI | Renovate Conf Rooms Bldg 231 | 93 | O |
| 1894 | Detroit Arsenal | MI | Replace HVAC System In B212 Office Areas | 258 | E |
| 1895 | Detroit Arsenal | MI | B212 Replace Cooling Water and Condensate Pump Motors | 145 | E |
| 1896 | Detroit Arsenal | MI | B232, Install Fuel Cell Generator | 100 | E |
| 1897 | Fort Leonard Wood | MO | Repair Primary and Secondary Digestor at sewage treatment plant | 1,958 | O |
| 1898 | Fort Bragg | NC | Repair Admin Building 1-3571 finishes, electrical, HVAC, plumbing, doors and windows, flooring, roofing | 11,000 | E |
| 1899 | Fort Bragg | NC | Replace Failed and Failing Chillers at 82nd Chiller Plant, C-6039 | 2,320 | E |
| 1900 | Fort Bragg | NC | Repair Failing Chiller/Boiler Controls (plant-wide) | 200 | E |
| 1901 | Fort Bragg | NC | Repair Chiller/Boiler Controls (stand-alone systems) | 200 | E |
| 1902 | Fort Bragg | NC | Replace Failing Bridge T8520, Camp Mackall | 603 | P |
| 1903 | Fort Bragg | NC | Construct Parking Lot for Warrior in Transition facilities | 750 | P |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|---|-----------------------|------------------|
| 1904 | Fort Bragg | NC | Install Ground Source Heat Pump, Bldg 3-3327 | 150 | E |
| 1905 | Fort Bragg | NC | Replace Academic Facility Lighting, Bldg D-3915 | 300 | E |
| 1906 | Fort Bragg | NC | Repair and Upgrade Water System Post Wide | 753 | E |
| 1907 | Fort Bragg | NC | Hammond Hills Erosion Control | 1,000 | P |
| 1908 | Fort Bragg | NC | Replace and Relocate Existing Womack Army Medical Center Helipad For Placement of the Warrior Transition Barracks Complex | 750 | O |
| 1909 | Fort Bragg | NC | Repair/Renovate Building: A-3275 to Support Joint Mobilization/Redeployment Center | 2,500 | O |
| 1910 | Fort Bragg | NC | Repair Failed Existing Wooden Trestle Bridge East of Turkey Road Firebreak # 3. | 112 | P |
| 1911 | Fort Bragg | NC | Repair Failed Existing Wooden Trestle Bridge East of Turkey Road Firebreak # 5 | 112 | P |
| 1912 | Fort Bragg | NC | Install Ground Source Heat Pump For DPW Environmental Classroom, Building 3-2232 | 110 | E |
| 1913 | Fort Bragg | NC | Install Occupancy Sensors, Bldg 4-2843 Soldier Support Center | 113 | E |
| 1914 | Fort Bragg | NC | Replace Chiller, Bldg 4-1431 Soldier family support bldg | 300 | E |
| 1915 | Fort Bragg | NC | 4-2175 Post Office--Install ADA Ramps, Doors, Parking Sign | 250 | Q |
| 1916 | Fort Bragg | NC | Restore ARHOC Barracks M-3019--Walls, Ceilings, HVAC, Elect, Plumbing, Windows | 6,000 | E |
| 1917 | Fort Bragg | NC | Repair/Renovate Bldg. C-1244, 4th Bct Barracks, HVAC, Elect, Finishes, Roof | 5,800 | E |
| 1918 | Fort Bragg | NC | Repair/Renovate Bldg. C-1647, 4th Bct Barracks, HVAC, Elect, Finishes, Roof | 5,800 | E |
| 1919 | Fort Bragg | NC | Repair/Renovate Bldg. C-1943, 4th Bct Barracks,, HVAC, Elect, Finishes, Roof | 5,800 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|--|-----------------------|------------------|
| 1920 | Fort Bragg | NC | Repair/Renovate Bldg. C-1137, Company HQ For 4th BCT | 1,740 | O |
| 1921 | Fort Bragg | NC | Repair & Upgrade Soldier Support Center, 4-2843 | 2,210 | O |
| 1922 | Fort Bragg | NC | Repair/Renovate Bldg. C-8344, Barracks/COF For 4th Bct | 800 | B |
| 1923 | Fort Bragg | NC | Misc Repairs 4th Bct Bldg. C-8241, Barracks/COF/Battalion HQ | 800 | B |
| 1924 | Fort Bragg | NC | Repair Bldg. C-4329, Bde Hq For 1st Bct | 800 | O |
| 1925 | Fort Bragg | NC | Misc Repairs 1st Bct Bldg. C-8442, Barracks/COF/Bn Hq | 1,600 | B |
| 1926 | Fort Bragg | NC | Repair Bldg. P-3642, Maintenance Hanger for 82d CAB | 800 | O |
| 1927 | Fort Bragg | NC | Repair Bldg. P-3962, Maintenance Hanger for 82d CAB | 800 | O |
| 1928 | Fort Bragg | NC | Replace Failing CW/HW Distribution Piping Serving Faith Barracks Complex | 5,600 | E |
| 1929 | Fort Bragg | NC | Renovate Bldg 2-1246 | 925 | O |
| 1930 | Fort Bragg | NC | Renovate Bldg 2-1249 | 925 | O |
| 1931 | Fort Bragg | NC | Mold, Moisture, Vapor R&M Improvements barracks bldg H-5454 | 4,500 | B |
| 1932 | Fort Bragg | NC | Repair Bldg. C-6015 Vehicle Maintenance Facility For 82d-Finishes, Doors, HVAC, Elect, Plumbing. | 400 | O |
| 1933 | Fort Bragg | NC | Repair Bldg. C-6117 Vehicle Maintenance Facility For 82d-Finishes, Doors, HVAC, Elect, Plumbing. | 400 | O |
| 1934 | Fort Bragg | NC | Repair Bldg. C-6018 Vehicle Maintenance Facility For 82d-Finishes, Doors, HVAC, Elect, Plumbing. | 400 | O |
| 1935 | Fort Bragg | NC | Repair Bldg. C-5917 Vehicle Maintenance Facility For 82d-Finishes, Doors, HVAC, Elect, Plumbing. | 400 | O |
| 1936 | Fort Bragg | NC | Repair/Replace Failing Central Plant Equipment Serving Bldg. 4-2843, Soldier Support Center | 2,000 | E |
| 1937 | Fort Bragg | NC | Repair & replace Failed Equipment, Central heating plant bldg. 4-2472 | 1,000 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------------------------------|-------|---|-----------------------|------------------|
| 1938 | Fort Bragg | NC | Repair/Replace Undersized Central Plant Equipment Serving Smoke Bomb Hill | 2,000 | E |
| 1939 | Fort Bragg | NC | Repair/Replace Failing Steam Heating System, Bldg. C-5332, Memorial Chapel | 255 | E |
| 1940 | Fort Bragg | NC | Repair/Replace Failing Steam Heating System, Bldg. C-5535 | 240 | E |
| 1941 | Fort Bragg | NC | Repair/Replace Failing Steam Heating System, Bldg. C-5934 | 261 | E |
| 1942 | Fort Bragg | NC | Repair/Replace Failed and Failing Mechanical Piping/Equipment DFAC, Bldg. M-4234, | 820 | E |
| 1943 | Fort Bragg | NC | Replace Roof Building: 1-1460 | 210 | R |
| 1944 | Fort Bragg | NC | Demolish Portion of Building: 1-1460 | 350 | Q |
| 1945 | Fort Bragg | NC | Repair Roofs - Various Buildings | 924 | R |
| 1946 | Fort Bragg | NC | Renovate Fire Station No. 1 Building: 6-9572 | 900 | O |
| 1947 | Fort Bragg | NC | Renovate SAAF Fire Station: Building: P-4539 | 700 | O |
| 1948 | Fort Bragg | NC | Renovate Fredrick Physical Fitness Center Building H-5718 | 3,358 | O |
| 1949 | Military Ocean Terminal Sunny Point | NC | Repair Wharf | 1,870 | O |
| 1950 | Picatinny Arsenal | NJ | Repair Road (3rd Ave) | 450 | P |
| 1951 | Picatinny Arsenal | NJ | Fire Protection - Repair Sprinkler/Deluge Systems, Various Bldgs | 226 | O |
| 1952 | Picatinny Arsenal | NJ | B-119 Renovate Garrison Staff Offices | 933 | O |
| 1953 | Picatinny Arsenal | NJ | Repair Reilly Rd Pavement | 675 | P |
| 1954 | Picatinny Arsenal | NJ | Renovate Unit Ops Building 13 - Finishes, Doors, Windows, Elect, Plumbing, HVAC | 200 | O |
| 1955 | Picatinny Arsenal | NJ | Inspect and Design Water Distribution replacement system | 450 | U |
| 1956 | White Sands Missile Range | NM | Rehabilitate Water Well #2 | 150 | U |
| 1957 | White Sands Missile Range | NM | Repair sewer lines by slip lining pipes | 500 | U |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------------|-------|---|-----------------------|------------------|
| 1958 | White Sands Missile Range | NM | Install Exterior Lighting Area II | 150 | U |
| 1959 | White Sands Missile Range | NM | Install Fire Alarm System bldg 21235 | 100 | O |
| 1960 | White Sands Missile Range | NM | Install Air Conditioning Bldg 1506 | 100 | O |
| 1961 | White Sands Missile Range | NM | B-32292 Fire Suppression Sys | 183 | O |
| 1962 | White Sands Missile Range | NM | B-31590, Install Fire Supr Sys | 250 | O |
| 1963 | White Sands Missile Range | NM | B-29742, Install Fire Suppr/Escape | 250 | O |
| 1964 | White Sands Missile Range | NM | Repair the Roof On Fitness Center bldg 236 | 150 | R |
| 1965 | White Sands Missile Range | NM | Restore Flooring In Fitness Center Latrine area bldg 236 | 44 | O |
| 1966 | White Sands Missile Range | NM | Repair Tank Trails Construct Crossings | 5,720 | P |
| 1967 | White Sands Missile Range | NM | Repair Range Route 202 Facility # 85110 | 2,097 | P |
| 1968 | Hawthorne Army Depot | NV | Repair Building 4 Barracks to Include All Finishes, Doors, Windows, Mechanical Systems | 2,091 | B |
| 1969 | Hawthorne Army Depot | NV | Repair Maintenance Building 47 to Include Doors, Electrical, Mechanical Systems, Finishes | 580 | E |
| 1970 | Hawthorne Army Depot | NV | Install Solar Powered Lighting in ammo storage areas | 713 | E |
| 1971 | Hawthorne Army Depot | NV | Replace Main Potable Water Line | 950 | U |
| 1972 | Hawthorne Army Depot | NV | Construct Industrial Vehicle Wash Station | 383 | O |
| 1973 | Hawthorne Army Depot | NV | Upgrade Known Distance Range | 1,126 | O |
| 1974 | Hawthorne Army Depot | NV | Modernize Steam & Condensate Line 103-6 to 103-16 | 488 | E |
| 1975 | Fort Drum | NY | Repair Backflow Preventers (Water)/Cross-Connection Testing | 23 | E |
| 1976 | Fort Drum | NY | Replace Furnaces In 72 Buildings By Converting From Oil to Natural Gas Heat | 1,450 | E |
| 1977 | Fort Drum | NY | Repair Barracks Doors and Install Keyless Entry 2nd BCT | 1,100 | B |
| 1978 | Fort Drum | NY | Emergency Repairs to Runway 15-33 | 600 | P |
| 1979 | Fort Hamilton | NY | Repair Schum Ave, Lee to 1st Division | 261 | P |
| 1980 | Fort Hamilton | NY | Replace HVAC With Geothermal Energy For Bldg 209 | 1,540 | E |
| 1981 | Fort Hamilton | NY | Replace Elec/Water Meters Post-Wide | 250 | U |
| 1982 | Fort Hamilton | NY | Repair Schum Ave, 1st Div to Bldg 110 | 337 | P |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|----------------------------|-------|---|-----------------------|------------------|
| 1983 | Fort Hamilton | NY | Repair Elevator, Bldg 114 Admin | 210 | O |
| 1984 | Fort Hamilton | NY | Construct Geo-Thermal Plant Near Bldg 301 | 750 | E |
| 1985 | Fort Hamilton | NY | Construct Geo-Thermal Plant Near B302 | 700 | E |
| 1986 | Fort Hamilton | NY | Remodel Kitchen In Building 219, Chapel | 24 | Q |
| 1987 | Fort Hamilton | NY | Convert Oil-Fired Boilers to Gas and Remove Fuel storage tanks | 683 | E |
| 1988 | Watervliet Arsenal | NY | Replace Woodblock Floor, Bldg 135, Bays C18-C25 | 160 | O |
| 1989 | West Point Mil Reservation | NY | B601 Rehab Elevator Car #2 | 369 | O |
| 1990 | West Point Mil Reservation | NY | Repair Crandall Fitness Center--heat and fire suppression systems | 1,500 | O |
| 1991 | West Point Mil Reservation | NY | Demolish Dunover Court Buildings B134,136,139,142 | 750 | B |
| 1992 | West Point Mil Reservation | NY | B917 Replace Existing Security Fence | 238 | O |
| 1993 | Fort Sill | OK | Repair Ketch Lake Dam and Upper Canyon Dam | 1,000 | P |
| 1994 | Fort Sill | OK | Replace Runway Lighting at Henry Post Army Airfield | 5,296 | P |
| 1995 | Fort Sill | OK | Rpr Components of Electrical Substation - Bd 1888 (DPW) | 4,333 | U |
| 1996 | Fort Sill | OK | Bldg 3040 Central Plant Mechanical Equipment | 1,389 | E |
| 1997 | Fort Sill | OK | Repair/Replace Components Feeders 6&7 (DPW) | 4,333 | U |
| 1998 | Fort Sill | OK | Repair/Replace Electrical Distribution System Feeders, West Range | 2,002 | U |
| 1999 | Fort Sill | OK | Bd 730 Rpr Central Plant Mechanical Equipment (DPW) | 642 | E |
| 2000 | Fort Sill | OK | Repair/Replace Bleachers and Lights Bldg 3444 Fitness Center | 100 | O |
| 2001 | Fort Sill | OK | Construct Ph 1 Waste Water Recycling Distribution Network | 500 | E |
| 2002 | Fort Sill | OK | Building 730 Central Heating and Cooling Distribution System (FAS) | 6,664 | E |
| 2003 | Fort Sill | OK | Replace 2 Each Back-Up Generators, Electrical Distribution System (DPW) | 1,780 | E |
| 2004 | Fort Sill | OK | Bldg 900/912/913/914 Install Fire Rated Doors | 35 | B |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------------------|-------|--|-----------------------|------------------|
| 2005 | Fort Sill | OK | Bldg 2857 replace All Storm Windows | 25 | E |
| 2006 | Fort Sill | OK | Replace Energy Management Control System (DPW) | 1,108 | E |
| 2007 | Fort Sill | OK | Bldg 3281 Install Electrical Receptacles | 8 | E |
| 2008 | Fort Sill | OK | Repair Bathrooms and Building Components B700 Knox Hall | 6,600 | O |
| 2009 | Fort Sill | OK | Bldgs 59, 60, 700, 3164, 6011, 6036 repair/replace All Life Safety Systems (Postwide) | 2,100 | O |
| 2010 | Fort Sill | OK | Repair Tower Two Road | 2,040 | P |
| 2011 | Fort Sill | OK | Bldg 840-Replace Lighting | 508 | E |
| 2012 | Fort Sill | OK | Replace Chiller Bldg 1712 | 250 | E |
| 2013 | Fort Sill | OK | D6240-Repair Lake George Dam. | 6,070 | P |
| 2014 | Fort Sill | OK | Bldg 1605-Replace Tile Roof. | 160 | R |
| 2015 | Fort Sill | OK | Bldg 707-Install Bars On Supply Windows/Doors. | 15 | O |
| 2016 | Fort Sill | OK | Bldg 2414 & 2415-Rpr Exterior Doors. | 20 | O |
| 2017 | Fort Sill | OK | Bldg 4915-Renovate Hangar Doors. | 75 | O |
| 2018 | Fort Sill | OK | Bldg 5030-Repair Broken Windows. | 40 | E |
| 2019 | Fort Sill | OK | Bldg 700-Install Emergency Light. | 15 | O |
| 2020 | Fort Sill | OK | Bldg 463-Roof Replacement. | 100 | R |
| 2021 | Fort Sill | OK | Roof Replacement Bldg 1712 | 350 | R |
| 2022 | Fort Sill | OK | Repair B730 Snow Hall--HVAC, plumbing, electrical, fire protection, Latrines, classrooms, lighting, finishes | 11,200 | E |
| 2023 | Fort Sill | OK | Bldg 2281-Install Electrical Equipment | 110 | E |
| 2024 | Fort Sill | OK | Bldg 730 Paint Exterior | 150 | O |
| 2025 | Fort Sill | OK | Bldg 462-Replace All Over Head Electrical Service With Pad-Mounted Transformer Service. | 574 | U |
| 2026 | McAlester Army Ammunition Plant | OK | Replace Water Distribution Lines to Ammo Production Area | 800 | E |
| 2027 | McAlester Army Ammunition Plant | OK | Repair Bomb & Mine Buildings - replace Doors & Windows and Increase Energy Efficiency. | 2,000 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------------------|-------|--|-----------------------|------------------|
| 2028 | McAlester Army Ammunition Plant | OK | Repair Medium Caliber & Major Caliber Bldgs -Insulate, Replace Doors & Windows and Increase Energy Efficiency. | 2,000 | E |
| 2029 | McAlester Army Ammunition Plant | OK | Repair Admin/Indust Area Bldgs-Insulate, Replace Doors & Windows and Increase Energy Efficiency. | 1,500 | E |
| 2030 | Carlisle Barracks | PA | Replace the HVAC Air Handlers @ B-122 | 80 | E |
| 2031 | Carlisle Barracks | PA | Install Potable Water Distribution line to B-950 | 130 | U |
| 2032 | Carlisle Barracks | PA | Water Plant/Distribution Evaluation and Upgrades | 210 | E |
| 2033 | Carlisle Barracks | PA | Upgrade Lighting in B-632 | 25 | E |
| 2034 | Carlisle Barracks | PA | Replace All Lighting In B-122 | 154 | E |
| 2035 | Carlisle Barracks | PA | Re-Commission Building 950 For Energy Conservation | 50 | E |
| 2036 | Letterkenny Army Depot | PA | Alterations/Additions to Guided Missile Maintenance Shop | 750 | O |
| 2037 | Letterkenny Army Depot | PA | Production Support Area Addition, Building 350 | 750 | O |
| 2038 | Tobyhanna Army Depot | PA | Renovate First Floor Barracks 230 Bathrooms | 210 | B |
| 2039 | Tobyhanna Army Depot | PA | Repair Bathrooms(S) On Second Floor Bldg 230 | 120 | B |
| 2040 | Tobyhanna Army Depot | PA | Southwest Quadrant Depot Paving | 350 | P |
| 2041 | Tobyhanna Army Depot | PA | East Sector Pavement Replacement | 1,070 | P |
| 2042 | Tobyhanna Army Depot | PA | Central Region Paving Renovation | 650 | P |
| 2043 | Fort Jackson | SC | Construct Small Childcare Facility | 625 | Q |
| 2044 | Fort Jackson | SC | Central Energy Plant Distribution Repairs (B11000 Feeder) | 535 | E |
| 2045 | Fort Jackson | SC | Repair Ammunition Supply Point Access Road and Fence | 400 | P |
| 2046 | Fort Jackson | SC | Repair Failed Sewer Lift Station (Tank Hill Service Area) | 375 | U |
| 2047 | Fort Jackson | SC | Resurface Mcwhorter B6271 Building Drive and Parking Area B | 300 | P |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------------|-------|---|-----------------------|------------------|
| 2048 | Fort Jackson | SC | Renovate B9810 Training Bldg Finishes, Elect, Plumbing | 300 | O |
| 2049 | Fort Jackson | SC | Repair 2179 Admin Area Finishes, HVAC, Elect, Latrines | 150 | O |
| 2050 | Fort Jackson | SC | Repair B4325 Latrines and Finishes | 100 | O |
| 2051 | Fort Jackson | SC | Repair Leaks Within DFAC, B4210 | 100 | B |
| 2052 | Fort Jackson | SC | Renovate Child Development Center | 650 | Q |
| 2053 | Fort Jackson | SC | Renovate Daniel Circle Chapel, B 3350 | 356 | Q |
| 2054 | Fort Jackson | SC | Repair Starr Hall B3270 | 317 | O |
| 2055 | Corpus Christi Army Depot | TX | Repair HVAC, Elect, Plumbing, Finishes B1727 | 3,540 | E |
| 2056 | Fort Bliss | TX | Repair Vehicular Pavements, Combat Aviation Brigade | 3,819 | P |
| 2057 | Fort Bliss | TX | Repair Windows and Insulation Admin bldg 1 | 2,000 | E |
| 2058 | Fort Bliss | TX | Repair War Road | 10,000 | P |
| 2059 | Fort Bliss | TX | Repair Bn Hq Building 2911 , 3/2 Bn, 11 BDE-Finishes, Elect, Doors, Windows | 695 | O |
| 2060 | Fort Bliss | TX | Repair Bn Hq Building 2913-Finishes, Elect, Doors, Windows | 829 | O |
| 2061 | Fort Bliss | TX | Repair Bn Hq Building 2918, 1/43 Bn, 11 BDE-Finishes, Elect, Doors, Windows | 895 | O |
| 2062 | Fort Bliss | TX | Repair Bn Hq Building 2919 1/43 Bn, 11 BDE-Finishes, Elect, Doors, Windows | 768 | O |
| 2063 | Fort Bliss | TX | Repair Tac Equip Shop 1067, 93rd Mp Bn Elect, HVAC, Plumbing, Finishes | 810 | E |
| 2064 | Fort Bliss | TX | Repair Tac Equip Shop 2462, 3/43bn,11 Bde Elect, HVAC, Plumbing, Finishes | 915 | E |
| 2065 | Fort Bliss | TX | Repair Tac Equip Shop 2466, 3/43 Bn,11 Bde Elect, HVAC, Plumbing, Finishes | 825 | E |
| 2066 | Fort Bliss | TX | Repair Tac Equip Shop 2488,1/43 Bn,11 Bde Elect, HVAC, Plumbing, Finishes | 825 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|---|-----------------------|------------------|
| 2067 | Fort Bliss | TX | Repair Tac Equip Shop 2971 , Task Force Cram Elect, HVAC, Plumbing, Finishes | 985 | E |
| 2068 | Fort Bliss | TX | Install A Precooling System and Switch to the 20mw Backup Generator at Chaffee and Jeb Stuart | 500 | E |
| 2069 | Fort Bliss | TX | Repair Roof and add Solar Panels to admin bldg 777 | 900 | R |
| 2070 | Fort Bliss | TX | Electrical Lighting Conservation -Occupancy Sensors/Timers | 450 | E |
| 2071 | Fort Bliss | TX | Repair Bldg 4797 Fitness Center--HVAC & Resurface Floor | 2,200 | E |
| 2072 | Fort Bliss | TX | Repair Bldg 2930 Fitness Center--Floors, HVAC, Interior finishes, building envelope | 2,897 | E |
| 2073 | Fort Bliss | TX | Repair Bldg 1441, Chapel 3 | 1,500 | Q |
| 2074 | Fort Bliss | TX | Repair Bldg 1542, Chapel 2 | 1,500 | Q |
| 2075 | Fort Bliss | TX | Repair Int/Ext, Bldg 250, East End, Family Readiness Ctr | 3,200 | Q |
| 2076 | Fort Bliss | TX | Repair Int/Ext, Bldg 515, Processing Center | 2,400 | O |
| 2077 | Fort Bliss | TX | Repair Admin Bldg 241 | 900 | O |
| 2078 | Fort Bliss | TX | Replace Old HVAC and Provide Solar Daylighting - Buildings 1107 and 1108 | 2,250 | E |
| 2079 | Fort Bliss | TX | Replace Inadequate AC System With Energy Efficient Hybrid AC DFAC Bldg 9510 at Ranges | 520 | E |
| 2080 | Fort Bliss | TX | Replace Deteriorated AC System With Hybrid (Bldg 11251) | 850 | E |
| 2081 | Fort Bliss | TX | Repair Training Area Unpaved Tank Trails | 60,000 | P |
| 2082 | Fort Bliss | TX | Hanger 11108: Repair / Upgrade Fire Extinguisher System | 2,000 | O |
| 2083 | Fort Bliss | TX | Repair Airfield Pavement to Eliminate Hazards Phase I | 1,800 | P |
| 2084 | Fort Hood | TX | Repair Failed Low Water Crossing #8 | 225 | P |
| 2085 | Fort Hood | TX | Replace Failed Fire Protection System, Hangar 7027 | 700 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------------|-------|--|-----------------------|------------------|
| 2086 | Fort Hood | TX | Replace Failing Movable Divider Walls Ops Bldg 18000 | 100 | O |
| 2087 | Fort Hood | TX | Replace 180 Ton Chiller In Bldg 22028 | 500 | O |
| 2088 | Fort Hood | TX | Repair Failed Low Water Crossing #10 | 225 | P |
| 2089 | Fort Hood | TX | Perform carpentry, electrical, HVAC, plumbing, security system repairs--Multiple Buildings | 2,337 | O |
| 2090 | Fort Hood | TX | Remediate Mold In Bldg 49020 | 250 | Q |
| 2091 | Fort Hood | TX | Repair Building 422 Finishes, Electrical, Plumbing, HVAC, Fire Protection, Doors | 8,100 | E |
| 2092 | Fort Hood | TX | Replace and repair failed metering on electrical distribution system. | 1,000 | E |
| 2093 | Fort Hood | TX | Replace Traffic Controls at 30 Intersections | 2,000 | P |
| 2094 | Fort Hood | TX | Repair Roofs, Mechanical Systems, Electrical, Exterior Closures (Doors And Windows); Replace Steps and Ramps--14 buildings | 3,000 | E |
| 2095 | Fort Hood | TX | Repair Bldg 37005, BDE HQ Bldg -Restore All Finishes and Systems | 1,200 | O |
| 2096 | Fort Sam Houston | TX | Replace HVAC controls; connect bldg 4584 to Utility Management Control System (UMCS) | 1,428 | E |
| 2097 | Fort Sam Houston | TX | Connect bldg 1377 to Utility Management Control System (UMCS) | 488 | E |
| 2098 | Fort Sam Houston | TX | Repair Classroom, Bldg 1396 | 1,000 | O |
| 2099 | Fort Sam Houston | TX | Repair Heat Distribution Lines, Bldg 2248 | 100 | E |
| 2100 | Fort Sam Houston | TX | Barracks Bldg 904-- Replace HVAC, Plumbing, Electric, Finishes | 6,840 | E |
| 2101 | Fort Sam Houston | TX | Repair Stanley Road | 825 | P |
| 2102 | Fort Sam Houston | TX | Repair Bridges | 521 | P |
| 2103 | Fort Sam Houston | TX | Replace Traffic Signals | 800 | P |
| 2104 | Fort Sam Houston | TX | Repair Dickman Road | 825 | P |
| 2105 | Fort Sam Houston | TX | Improve Marne Road, Camp Bullis | 220 | P |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------|-------|---|-----------------------|------------------|
| 2106 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 904 | 770 | B |
| 2107 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 905 | 770 | B |
| 2108 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 907 | 770 | B |
| 2109 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 920 | 770 | B |
| 2110 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 915 | 770 | B |
| 2111 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 916 | 770 | B |
| 2112 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 929 | 770 | B |
| 2113 | Fort Sam Houston | TX | Design / Construct Laundry Room Addition to Barracks 930 | 770 | B |
| 2114 | Fort Sam Houston | TX | Repair Fire Alarm Systems, Various Buildings | 1,430 | Q |
| 2115 | Fort Sam Houston | TX | Repair Water System Controls | 725 | E |
| 2116 | Fort Sam Houston | TX | Design and Construct Fire Training Facility | 815 | O |
| 2117 | Fort Sam Houston | TX | Repair Culverts, Camp Bullis | 600 | P |
| 2118 | Fort Sam Houston | TX | Repair Latrines GIB Building 1396 | 310 | O |
| 2119 | Red River Army Depot | TX | Repair Truck Parking Lot South of 350 | 250 | P |
| 2120 | Dugway Proving Ground | UT | Install Stationary Generator, Dining Facility (Bldg 4545) | 38 | U |
| 2121 | Dugway Proving Ground | UT | Replace Generator, Ditto Communications Center | 120 | U |
| 2122 | Dugway Proving Ground | UT | Replace Roof, Provost Marshall Office | 200 | R |
| 2123 | Dugway Proving Ground | UT | Upgrade Electrical Service, Main Gate | 200 | U |
| 2124 | Dugway Proving Ground | UT | Upgrade Electrical Service, Post Office | 138 | U |
| 2125 | Dugway Proving Ground | UT | Install Additional Cooling Systems, Director of Information Management Area | 250 | U |
| 2126 | Dugway Proving Ground | UT | Repair Power Plant and Replace Failed Generators | 7,500 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------|-------|---|-----------------------|------------------|
| 2127 | Dugway Proving Ground | UT | Bldg 4531 Power Renovations | 500 | E |
| 2128 | Dugway Proving Ground | UT | Construct Mobile Command Post Garage | 745 | O |
| 2129 | Dugway Proving Ground | UT | Install Blast Resistant Windows Bldg 3236 | 500 | O |
| 2130 | Dugway Proving Ground | UT | Install Access Control Point Overhead Cover | 250 | O |
| 2131 | Tooele Army Depot | UT | Repair Roads | 265 | P |
| 2132 | Fort A P Hill | VA | Repair Bathrooms In 2nd Bn Area Barracks - Wilcox | 426 | B |
| 2133 | Fort Belvoir | VA | Repair Building 2116, Physical Fitness Facility-- Bathrooms, Showers, and Lockers, Heating, Ventilation, and Air Conditioning, Athletic Court Flooring, and Interior Finishes | 450 | O |
| 2134 | Fort Belvoir | VA | Repair Religious Education Center, Building 1028- Repair Doors, Windows, Finishes, Electric, HVAC Systems. | 500 | E |
| 2135 | Fort Belvoir | VA | Replace central steam heat with individual boilers--6 bldgs | 700 | E |
| 2136 | Fort Belvoir | VA | Replace central steam heat with individual boilers--2 bldgs | 425 | E |
| 2137 | Fort Eustis | VA | Major Repairs, Pier 17 at 3rd Port | 1,500 | P |
| 2138 | Fort Eustis | VA | Barracks Repair & Upgrade Bldg 698-Repaint, Repair Wall, Ceiling, Floor Finishes & Repair HVAC | 800 | B |
| 2139 | Fort Eustis | VA | Barracks Repair & Upgrade Bldg 699-Repaint, Repair Wall, Ceiling, Floor Finishes & Repair HVAC. | 800 | B |
| 2140 | Fort Eustis | VA | Alterations & Repairs to Main Fire Station, Bldg 648- Repair All Components of the Sleeping and Kitchen Area and Expand the Common Area | 911 | O |
| 2141 | Fort Eustis | VA | HVAC System Repairs For Energy Conservation, Bldg 805 | 753 | E |
| 2142 | Fort Eustis | VA | Repairs to Bldg 601-Repaint, Repair Wall, Ceiling, Floor Finishes & Repair HVAC | 250 | Q |
| 2143 | Fort Eustis | VA | Install Cooling Tower, Bldg 2715 | 188 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------|-------|---|-----------------------|------------------|
| 2144 | Fort Eustis | VA | Repair Sidewalks, Admin Bldg 300 | 12 | P |
| 2145 | Fort Eustis | VA | Replace Disabled Access/Wheelchair Ramp, Bldg 643 | 10 | Q |
| 2146 | Fort Eustis | VA | Install Left Turn Lanes & Repave Jefferson Blvd, Ph 1 | 154 | P |
| 2147 | Fort Lee | VA | Renovate Supply / Storage Building-- Finishes, Plumbing, Electric, HVAC, Doors, Windows | 650 | E |
| 2148 | Fort Lee | VA | Renovate HVAC at Child Development Center | 1,250 | E |
| 2149 | Fort Lee | VA | Garrison Hq Building--Repair Finishes, Plumbing, Electric, HVAC, Doors, Windows | 750 | E |
| 2150 | Fort Lee | VA | Construct small Fitness Center at Ordinance School | 743 | O |
| 2151 | Fort Lee | VA | Construct small Fitness Center at Logistics University | 730 | O |
| 2152 | Fort Lee | VA | Repair Bldg P-9302 Company Operations | 222 | O |
| 2153 | Fort Lee | VA | Repairs and Improvements to Youth Center bldg 10605 | 431 | Q |
| 2154 | Fort Lee | VA | Repair carpentry, electrical, plumbing, HVAC - Multiple Buildings | 315 | O |
| 2155 | Fort Lee | VA | Repair Bldg 12500 DFAC Dining Area & Canopy | 500 | O |
| 2156 | Fort Myer | VA | Replace Air Handling Unit (AHU) and Controls bldg P-73 | 98 | E |
| 2157 | Fort Myer | VA | Building MY447 Repair & Modify Boiler Control Panel | 67 | E |
| 2158 | Fort Myer | VA | Install HVAC, Server Rooms, Bldg 205 and Bldg 238 | 300 | E |
| 2159 | Fort Myer | VA | Renovate Bldg 249 Company Operations | 8,675 | O |
| 2160 | Fort Myer | VA | General Barracks Repair, Bldg. 247, 248 | 640 | B |
| 2161 | Fort Myer | VA | Replace Fire Alarm Transmitter System | 450 | O |
| 2162 | Fort Myer | VA | Bldg. 301 Repair Distribution Pump Station | 500 | E |
| 2164 | Fort Myer | VA | Repair & Upgrade C-1st Bn, 3rd US Inf Reg Bldg 251 | 870 | O |
| 2165 | Fort Myer | VA | Replace central steam heat with individual boilers-- multiple bldgs | 2,340 | E |
| 2166 | Fort Myer | VA | Replace Failing HVAC Equipment bldg 313 directorate of logistics maintenance facility | 1,072 | E |
| 2167 | Fort Lewis | WA | Repair Small Arms Range #111 | 500 | O |
| 2168 | Fort Lewis | WA | Repair Small Arms Range #112 | 500 | O |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------------------|-------|--|-----------------------|------------------|
| 2169 | Fort Lewis | WA | Repair Small Arms Range #113 | 500 | O |
| 2170 | Fort Lewis | WA | Major Range Road Repairs | 2,226 | P |
| 2171 | Fort Lewis | WA | Repair Heat Distribution Piping 3100 Block | 5,285 | E |
| 2172 | Fort Lewis | WA | Repair Heat Distribution Piping 3200 Block | 5,285 | E |
| 2173 | Fort Lewis | WA | Repair/replace Transformers and Vaults, Bldg 3746 | 2,000 | U |
| 2174 | Fort Lewis | WA | Repair/Upgrade Fire Suppression Systems Warehouse 9640 | 3,500 | O |
| 2175 | Fort Lewis | WA | Replace Stack On Boiler Plant 3292 | 1,700 | U |
| 2176 | Fort Lewis | WA | Replace Stack On Boiler Plant 9580 | 1,700 | U |
| 2177 | Yakima Training Center | WA | Repair Yakima Training Barracks B201-B219-Repair Walls, Floors, Ceilings, HVAC Systems | 1,358 | B |
| 2178 | Yakima Training Center | WA | Repair Yakima Barracks B222-B245-Repair Walls, Floors, Ceilings, HVAC Systems | 1,677 | B |
| 2179 | Yakima Training Center | WA | Repair Yakima Barracks B246-B269-Repair Walls, Floors, Ceilings, HVAC Systems | 1,331 | B |

| Army National Guard | | | | 44,199 | |
|----------------------------|---------------------------------|----|--|---------------|---|
| 2180 | Bethel | AK | Install Energy Efficient Lighting in Army Aviation Operating Facility | 170 | E |
| 2181 | NG Bryant Airfield | AK | Modernize all energy systems in Unit Training and Equipment Site | 250 | E |
| 2182 | NG Bryant Airfield | AK | Replace all non-energy building components in Unit Training and Equipment Site | 120 | E |
| 2183 | Volunteer Training Site Catoosa | GA | Repair Water and Water Sewer System | 270 | E |
| 2184 | Volunteer Training Site Catoosa | GA | Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-08) | 750 | E |
| 2185 | Volunteer Training Site Catoosa | GA | Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-09) | 750 | E |
| 2186 | Volunteer Training Site Catoosa | GA | Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-10) | 750 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------------------|-------|--|-----------------------|------------------|
| 2187 | Volunteer Training Site Catoosa | GA | Construct New Barracks to Replace Outdated, Energy Inefficient Barracks (Bldg TR-11) | 750 | E |
| 2188 | Camp Dodge Johnston Training Site | IA | Add Additional Space to Classroom Building | 505 | E |
| 2189 | Gowen Field Boise | ID | Install Energy Controls in Soldier Readiness Processing Bldg | 38 | E |
| 2190 | Orchard Range Training Site | ID | Extend Electrical Power to Ranges 5 and 6 | 750 | U |
| 2191 | Camp Atterbury | IN | Replace Bridge 20 damaged by June 2008 Tornadoes | 600 | E |
| 2192 | Camp Atterbury | IN | Reconstruct Barracks (Bldg 206) Totally Destroyed by June 2008 Tornadoes | 526 | B |
| 2193 | New Castle | IN | Repair Roof and Paint Exterior at Readiness Center | 1,635 | R |
| 2194 | Abbeville | LA | Repair/upgrade Entire Field Maintenance Shop to Current Electrical Standards | 35 | E |
| 2195 | Baton Rouge | LA | Repair/upgrade Field Maintenance Shop to Current Electrical Standards | 30 | E |
| 2196 | Bunkie | LA | Repair Roof and Interior of Readiness Center | 515 | R |
| 2197 | Camp Beauregard | LA | Repair Roof at Headquarters (Bldg 1017) | 15 | R |
| 2198 | Camp Beauregard | LA | Repair Roof at Headquarters (Bldg 823) | 20 | R |
| 2199 | Camp Beauregard | LA | Repair Roof at Storage Building (Bldg 905) | 20 | R |
| 2200 | Camp Beauregard | LA | Repair Roof at Unit Training and Equipment Site (Bldg 908) | 20 | R |
| 2201 | Camp Beauregard | LA | Repair Roof at Unit Training and Equipment Site (Bldg 910) | 20 | R |
| 2202 | Camp Beauregard | LA | Repair Roof at Headquarters (Bldg 951) | 20 | R |
| 2203 | Camp Beauregard | LA | Repair Roof at Unit Training and Equipment Site (Bldg 911) | 25 | R |
| 2204 | Camp Beauregard | LA | Repair Roof at Barracks (Bldg 1018) | 30 | R |
| 2205 | Camp Beauregard | LA | Repair Roof at Medical Clinic (Bldg 804) | 30 | R |
| 2206 | Camp Beauregard | LA | Repair Roof at Readiness Center (Bldg 805) | 30 | R |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------|-------|--|-----------------------|------------------|
| 2207 | Camp Beauregard | LA | Repair Roof at Unit Training and Equipment Site (Bldg 917) | 30 | R |
| 2208 | Camp Beauregard | LA | Repair Roof at Maintenance Facility (Bldg 822) | 35 | R |
| 2209 | Camp Beauregard | LA | Repair Roof at Barracks (Bldg 1010) | 40 | R |
| 2210 | Camp Beauregard | LA | Repair Roof at Readiness Center (Bldg 904) | 40 | R |
| 2211 | Camp Beauregard | LA | Repair Roof at Unit Training and Equipment Site (Bldg 909) | 40 | R |
| 2212 | Camp Beauregard | LA | Repair Roof at Readiness Center (Bldg 949) | 50 | R |
| 2213 | Camp Beauregard | LA | Repair Roof at Military Police Station (Bldg 301) | 60 | R |
| 2214 | Camp Beauregard | LA | Repair Roof at Storage Building (Bldg 468) | 60 | R |
| 2215 | Camp Beauregard | LA | Repair/upgrade Barracks to Current Electrical Standards | 70 | E |
| 2216 | Camp Beauregard | LA | Repair Roof at Barracks (Bldg 565) | 75 | R |
| 2217 | Camp Beauregard | LA | Repair Roof at Barracks (Bldg 209) | 120 | R |
| 2218 | Camp Beauregard | LA | Repair Roof at Readiness Center (Bldg 631) | 150 | R |
| 2219 | Camp Beauregard | LA | Repair/upgrade Barracks (Bldg 1004) to Current HVAC and Electrical Standards | 450 | E |
| 2220 | Camp Beauregard | LA | Repair/upgrade Barracks (Bldg 1005) to Current HVAC and Electrical Standards | 450 | E |
| 2221 | Camp Beauregard | LA | Repair/upgrade Barracks (Bldg 1008) to Current HVAC and Electrical Standards | 450 | E |
| 2222 | Camp Beauregard | LA | Repair/upgrade Barracks (Bldg 1012) to Current HVAC and Electrical Standards | 450 | E |
| 2223 | Camp Beauregard | LA | Repair/upgrade Barracks (Bldg 1014) to Current HVAC and Electrical Standards | 450 | E |
| 2224 | Camp Beauregard | LA | Construct Replacement Storage Building (Bldg 1122) Destroyed by Hurricane Gustav | 720 | O |
| 2225 | Camp Beauregard | LA | Repair Roof at Headquarters (Bldg 952) | 10 | R |
| 2226 | Camp Cook | LA | Repair Minor Roof Damage on all Buildings (Hurricane Gustav) | 170 | R |
| 2227 | Camp Minden | LA | Repair Roof at Unit Headquarters (Bldg 5087) | 19 | R |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|--------------------|-------|--|-----------------------|------------------|
| 2228 | Camp Minden | LA | Repair Roof at Unit Training and Equipment Site and Upgrade Electrical Systems | 487 | R |
| 2229 | Camp Villere | LA | Repair/upgrade Barracks (Bldg 0403) to Current HVAC and Electrical Standards | 450 | E |
| 2230 | Camp Villere | LA | Repair/upgrade Barracks (Bldg 0404) to Current HVAC and Electrical Standards | 450 | E |
| 2231 | Carville | LA | Repair Roof at Civil Support Team Storage Building | 340 | R |
| 2232 | Colfax | LA | Repair Roof at Readiness Center | 25 | R |
| 2233 | Crowley | LA | Repair Doors and Windows at Readiness Center | 10 | O |
| 2234 | Dequincy | LA | Repair Electrical Systems at Readiness Center | 45 | E |
| 2235 | Esler Field | LA | Repair Roof at Unit Training and Equipment Site (Bldg 6001) | 5 | R |
| 2236 | Esler Field | LA | Repair Roof at Unit Training and Equipment Site (Bldg 6065) | 54 | R |
| 2237 | Esler Field | LA | Repair Roof at Unit Training and Equipment Site Bldg (6002) | 100 | R |
| 2238 | Gillis Long Center | LA | Repair Roof at Civil Support Team Hq | 60 | R |
| 2239 | Jena | LA | Repair/upgrade Entire Field Maintenance Shop to Current Electrical Standards | 30 | E |
| 2240 | Jena | LA | Repair Roof at Field Maintenance Shop (FMS 6) | 75 | R |
| 2241 | Lafayette | LA | Repair Roof at Field Maintenance Shop (FMS 9) | 10 | R |
| 2242 | Lake Charles | LA | Repair Roof at Field Maintenance Shop (FMS 11) | 110 | R |
| 2243 | Monroe | LA | Repair/upgrade Entire Field Maintenance Shop to Current Electrical Standards | 30 | E |
| 2244 | Monroe | LA | Repair Roof at Field Maintenance Shop (FMS3) | 150 | R |
| 2245 | New Roads | LA | Repair Roof at Readiness Center | 235 | R |
| 2246 | Plaquemine | LA | Repair Roof at Field Maintenance Shop (FMS15) | 125 | R |
| 2247 | Plaquemine | LA | Repair Roof at Readiness Center | 130 | R |
| 2248 | Ruston | LA | Repair/upgrade Entire Field Maintenance Shop to Current Electrical Standards | 30 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------|-------|---|-----------------------|------------------|
| 2249 | Shreveport | LA | Repair/upgrade Entire Field Maintenance Shop to Current Electrical Standards | 30 | E |
| 2250 | Dorchester | MA | Repair/upgrade Electrical System and Building Envelope at Field Maintenance Shop to Current Energy Standards | 289 | E |
| 2251 | MTA Camp Edwards | MA | Repair/upgrade the Electrical, HVAC, Plumbing Systems, and Building Envelope for Barracks (Bldg 5244) to Current Building Standards | 1,402 | E |
| 2252 | MTA Camp Edwards | MA | Repair/upgrade the Electrical, HVAC, Plumbing Systems, and Building Envelope for Barracks (Bldg 5243) to Current Building Standards | 1,402 | E |
| 2253 | MTA Camp Edwards | MA | Repair/upgrade the Electrical, HVAC, Plumbing Systems, and Building Envelope for Barracks (Bldg 5242) to Current Building Standards | 1,402 | E |
| 2254 | MTA Camp Edwards | MA | Repair/upgrade the Electrical, HVAC, Plumbing Systems, and Building Envelope for Barracks (Bldg 5240) to Current Building Standards | 1,402 | E |
| 2255 | MTA Camp Edwards | MA | Repair/upgrade the Electrical, HVAC, Plumbing Systems, and Building Envelope for Barracks (Bldg 5232) to Current Building Standards | 1,402 | E |
| 2256 | MTA Camp Edwards | MA | Repair/upgrade the Electrical, HVAC, Plumbing Systems, and Building Envelope for Barracks (Bldg 5230) to Current Building Standards | 1,402 | E |
| 2257 | MTC-H Camp Grayling | MI | Repair/upgrade all Building Systems in BOQ(Bldg 418) to Current Building Standards | 800 | B |
| 2258 | Camp Ripley | MN | Construct Bachelor Officer Quarters to replace Bldgs 01301 and 01302 | 441 | B |
| 2259 | Camp Ripley | MN | Construct Bachelor Officer Quarters to replace Bldgs 01303 and 01304 | 441 | B |
| 2260 | Camp Ripley | MN | Construct Bachelor Officer Quarters to replace Bldgs 01305 and 01306 | 441 | B |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------|-------|---|-----------------------|------------------|
| 2261 | Camp Ripley | MN | Construct Bachelor Officer Quarters to replace Bldgs 01307 and 01308 | 441 | B |
| 2262 | Camp Ripley | MN | Construct Bachelor Officer Quarters to replace Bldgs 01309 and 01310 | 441 | B |
| 2263 | Camp Ripley | MN | Construct Bachelor Officer Quarters to replace Bldgs 01311 and 01312 | 452 | B |
| 2264 | Camp Ripley | MN | Construct Bachelor Officer Quarters to replace Bldgs 01313 and 01314 | 452 | B |
| 2265 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1232) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2266 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1240) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2267 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1241) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2268 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1244) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2269 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1259) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2270 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1260) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2271 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1274) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2272 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1275) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2273 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1276) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2274 | Fort Leonard Wood | MO | Repair/upgrade Barracks (Bldg 1278) to Current Fire Protection, Energy Controls, Restrooms Standards | 180 | E |
| 2275 | MTA Camp Clark Nevada | MO | Repair/upgrade Barracks (Bldg B468) to Current Fire Protection, Energy Controls, Restrooms Standards | 160 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-----------------------------|-------|--|-----------------------|------------------|
| 2276 | MTA Camp Clark Nevada | MO | Repair/upgrade Barracks (Bldg B469) to Current Fire Protection, Energy Controls, Restrooms Standards | 160 | E |
| 2277 | MTA Camp Clark Nevada | MO | Repair/upgrade Barracks (Bldg B470) to Current Fire Protection, Energy Controls, Restrooms Standards | 160 | E |
| 2278 | MTA Camp Clark Nevada | MO | Repair/upgrade Barracks (Bldg B471) to Current Fire Protection, Energy Controls, Restrooms Standards | 160 | E |
| 2279 | 16 Sites Statewide | MT | Install Energy Efficient Lighting Fixtures in All Cold Storage Buildings | 103 | E |
| 2280 | All Sites Statewide | MT | Install LED wall packs in all buildings Statewide | 25 | E |
| 2281 | Culbertson | MT | Repair/upgrade Readiness Center Female Latrines and Showers to Current Building Standards | 226 | O |
| 2282 | Malta Readiness Center | MT | Repair/upgrade Readiness Center Female Latrines and Showers to Current Building Standards | 226 | O |
| 2283 | Onate Complex Training Site | NM | Install Energy Management Systems in all Training Center Buildings | 1,000 | E |
| 2284 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-009) to Current Building Standards | 120 | E |
| 2285 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-010) to Current Building Standards | 120 | E |
| 2286 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-011) to Current Building Standards | 120 | E |
| 2287 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-015) to Current Building Standards | 120 | E |
| 2288 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-028) to Current Building Standards | 120 | E |
| 2289 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-029) to Current Building Standards | 120 | E |
| 2290 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-030) to Current Building Standards | 120 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------|-------|--|-----------------------|------------------|
| 2291 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-031) to Current Building Standards | 120 | E |
| 2292 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-042) to Current Building Standards | 120 | E |
| 2293 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-043) to Current Building Standards | 120 | E |
| 2294 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-044) to Current Building Standards | 120 | E |
| 2295 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-045) to Current Building Standards | 120 | E |
| 2296 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-046) to Current Building Standards | 120 | E |
| 2297 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-048) to Current Building Standards | 120 | E |
| 2298 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-049) to Current Building Standards | 120 | E |
| 2299 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-050) to Current Building Standards | 120 | E |
| 2300 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-051) to Current Building Standards | 120 | E |
| 2301 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-060) to Current Building Standards | 120 | E |
| 2302 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-061) to Current Building Standards | 120 | E |
| 2303 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-062) to Current Building Standards | 120 | E |
| 2304 | Fort Indiantown Gap | PA | Repair/upgrade Electrical and HVAC Systems in Barracks (Bldg 13-063) to Current Building Standards | 120 | E |
| 2305 | Fort Indiantown Gap | PA | Install Energy Efficient Lighting at Ammo Supply Point | 500 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------------------|-------|---|-----------------------|------------------|
| 2306 | Harrisburg Reserve Center | PA | Repair/upgrade all of Readiness Center (Bldg 2) to Current Building Code and Energy Standards | 1,181 | E |
| 2307 | Harrisburg Reserve Center | PA | Repair/upgrade all of Readiness Center (Bldg 1) to Current Building Code and Energy Standards | 2,411 | E |
| 2308 | Philadelphia Lancaster | PA | Upgrade All Readiness Center Windows to Current Energy Standards | 75 | E |
| 2309 | MTA McCrady Training Site | SC | Replace Roof on Classroom (Bldg S3800) | 750 | R |
| 2310 | Angleton | TX | Repair Roof at Readiness Center | 26 | R |
| 2311 | Baytown | TX | Repair Roof at Readiness Center | 11 | R |
| 2312 | Beaumont | TX | Repair Roof at Readiness Center | 29 | R |
| 2313 | Camp Swift | TX | Repair/upgrade 31 Barracks to Current HVAC and Electrical Standards | 745 | E |
| 2314 | Ellington Field | TX | Repair Roof at Army Aviation Support Facility | 26 | R |
| 2315 | La Marque | TX | Repair Roof at Readiness Center | 322 | R |
| 2316 | Pasadena | TX | Repair Roof at Readiness Center | 26 | R |
| 2317 | Port Arthur | TX | Repair Exterior Wall at Readiness Center | 18 | O |
| 2318 | Port Neches | TX | Repair Roof at Readiness Center | 36 | R |
| 2319 | Training Site Ethan Allen Range | VT | Repair/upgrade HVAC and Electrical Systems in Munda Area Barracks to Current Building Standards | 580 | E |
| 2320 | Training Site Ethan Allen Range | VT | Repair/upgrade HVAC and Electrical Systems in Argonne Area Barracks to Current Building Standards | 602 | E |
| 2321 | Training Site Ethan Allen Range | VT | Repair/upgrade HVAC and Electrical Systems in Wilderness Area Barracks to Current Building Standards | 840 | E |
| 2322 | Appleton | WI | Repair/upgrade Latrine Plumbing Systems, HVAC, and Kitchen Fire Suppression Systems in Readiness Center to Current Building Standards | 183 | E |
| 2323 | Black River Falls | WI | Repair/upgrade Latrine Plumbing Systems and Kitchen Fire Suppression Systems in Readiness Center to Current Building Standards | 183 | E |

**American Recovery and Reinvestment Act of 2009
Operation and Maintenance
Facilities Sustainment, Restoration and Modernization Project List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|---------------------|-------|---|-----------------------|------------------|
| 2324 | Tomah | WI | Repair/upgrade Kitchen Electrical and Fire Protection Systems in Readiness Center to Current Building Standards | 135 | E |
| 2325 | Wheeling | WV | Install Closed Circuit Television at Army Aviation Support Facility | 50 | O |
| 2326 | Wood County Armory | WV | Install Closed Circuit Television at Army Aviation Support Facility (AASF # 1) | 50 | O |
| 2327 | MTC-H Camp Guernsey | WY | Construct 2 12,000 Water Tanks in North Training Area | 136 | E |
| 2328 | MTC-H Camp Guernsey | WY | Repair/upgrade Electrical Wiring in Bldg 16 (Classroom) to Current Code | 60 | E |
| 2329 | MTC-H Camp Guernsey | WY | Repair/upgrade HVAC to Current Standards in All Area 500 Buildings | 480 | E |

**Congressional Notification under Title 10 U.S.C. 2811
Operation and Maintenance Funded Projects in Excess of \$7.5 Million**

Projects Requiring Notification

Pursuant to Section 2811 of Title 10, United States Code, the Department of Defense intends to proceed with the nine Army FSRM projects shown below funded with the Operation and Maintenance appropriation. These projects will be executed using a portion of the \$4.3 billion available for the facility repair and modernization and enhancing energy efficiency in the American Recovery and Reinvestment Act of 2009.

Chilled Water Distribution System, Fort Stewart, GA – Estimated cost of this project is \$24.0 million.

Description: This project will complete the repair, by replacement, of the existing chilled water distribution system with a combination of direct buried insulated piping and shallow trench piping. The project will install piping in the existing high temperature water shallow trench system in the 500 and 600 block and direct buried piping in the 200, 300 and 400 blocks. The project also includes the renovation of the mechanical rooms piping and associated equipment to current standards enhancing energy efficiency.

Repair Building 316 Electrical, HVAC, Plumbing, Finishes, Doors, Windows, Aberdeen Proving Ground, MD – Estimated cost of this project is \$9.4 million.

Description: This is a renovation of Building 316 which houses computer servers for units and organizations on the installation and provides space for Directorate of Information Management (DOIM) support personnel. This project will repair, by replacement, building systems to include the roof, interior finishes, heating, ventilation, air conditioning, electrical, fire protection, plumbing, generator, uninterruptible power supply (UPS), interior access and egress. The exterior work includes loading dock, entrance steps/ramp and fence.

Repair Admin Bldg I-3571 Finishes, Electrical, HVAC, Plumbing, Doors and Windows, Fort Bragg, NC – Estimated cost of this project is \$11.0 million.

Description: The project will repair, by replacement, facility components to ensure reliable operation for the remaining life of the facility. Work includes

repair and replacement of HVAC systems to maintain ambient temperatures of 75 degrees (cooling season) and 65 degrees (heating season); repair and replacement of mechanical systems (pumps, valves, controls) to ensure reliability and compatibility with replacement units; repair and replacement of major roofing systems to provide a leak-resistant facility; replacement of plumbing fixtures, piping, and support equipment to ensure dependable reliable and safe operation; replacement of all exterior doors and hardware and interior doors as required to provide for a secure environment; removal of mold and mildew on floors, walls, and ceilings that is beyond normal cleaning; repair and replacement of flooring and suspended ceiling systems; installation of energy efficient lighting; repair and replacement of windows to improve environmental conditions and save energy; and replacement of electrical and communication systems to support a modern office environment.

Repair B730 Snow Hall Latrines and Building Components, Fort Sill, OK – Estimated cost of this project is \$11.2 million.

Description: This project will repair, by replacement, building systems to include heating, ventilation, plumbing, electrical, and fire protection systems. The project will also include replacing latrines, chalkboards, white boards, lighting, and interior finishes. The work will include upgrading the building to current anti-terrorism and force protection standards.

Repair Training Area Unpaved Tank Trails, Fort Bliss, TX – Estimated cost of this project is \$60.0 million.

Description: This project will repair, by replacement, components of the unimproved tank trails located within Dona-Ana, South McGregor, and McGregor/Oro Grande Range compels on Fort Bliss. These repairs will critically support 4 heavy and 2 infantry brigade combat teams, a fires brigade, and several other units/organizations that have already arrived at Fort Bliss. The current tank trails have not had significant repair or maintenance for many years, and the drastic increase in troop population at Fort Bliss due to BRAC and Grow the Army decisions have made the timing of these repairs an immediate requirement. Units that are training to maintain combat readiness and prepare for imminent deployment to Operation Iraqi Freedom and are required to traverse these tank trails to access training areas and ranges. These repairs will redress safety and accessibility issues that have arisen due to deferred maintenance and repair.

Repair War Road, Fort Bliss, TX – Estimated cost of this project is \$10.0 million.

Description: This project will repair, by replacement, components of War Road. The War Road is the main connecting highway between Ft. Bliss and White Sands Missile Range (WSMR) cantonments. This road is used by approximately one-third of the WSMR civilian workforce with an average of one serious accident per month. In addition, approximately one-quarter of all commercial vehicles servicing WSMR use this road. With the arrival of the First Brigade combat teams, this road will become the major thoroughfare for the Heavy Equipment Tactical Transporters (HETTTS) transporting tanks to and from the training ranges. The work will consist of repairing paved road shoulders, milling the existing asphalt pavement, and applying an asphalt overlay to the existing pavement to improve its structural integrity.

Repair Building 422, Finishes, Electrical, Latrines, HVAC, Fort Hood, TX – Estimated cost of this project is \$8.1 million.

Description: This project will repair, by replacement, building systems to include the interior finishes, heating, ventilation, air conditioning, plumbing, electrical, fire protection systems, interior access and egress. The work will include bringing the building up to current anti-terrorism standards and removing hazardous materials.

Repair Power Plant & Replace Failed Generators, Dugway Proving Grounds, UT – Estimated cost of this project is \$7.5 million.

Description: This project will repair, by replacement, the WWII surplus submarine generators which have been out of service for several years with new large generators. The larger generators are capable of providing emergency power to the entire installation and reduce maintenance and repair cost. The current emergency power is provided by generators on long-term lease through the 279th Engineer Battalion (Prime Power).

Renovate Bldg 249 for Company Headquarters, Fort Myer, VA – Estimated cost of this project is \$8.7 million.

Description: This project is a renovation of Bldg 249. The project will repair, by replacement, building components to include exterior elements of the deteriorated and historic brick of the Unaccompanied Personnel Housing (UPH)/Company

Headquarters facility. Repair work will include roofing, windows, exterior doors, paving for road and sidewalks surrounding the building, landscaping, and lighting. Work will also include repair of chimneys, and repair/cleaning/re-pointing of exterior building facade and structures to closely resemble original construction. These items will be repaired to current standards. This project was developed to restore the exterior of the failing facility.

**American Recovery and Reinvestment Act of 2009
Facilities Sustainment, Restoration, and Modernization Project Replacement List**

Project Removed: The location of the Army Hangar Apron and Pavement Restoration is corrected.

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|--------------------|-------|-------------------------------------|-----------------------|------------------|
| 501 | Watervliet Arsenal | NY | Hangar Apron & Pavement Restoration | 1,400 | O |

Replacement Project:

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|-------------------------------------|-----------------------|------------------|
| 501 | West Point | NY | Hangar Apron & Pavement Restoration | 1,400 | O |

Project Removed: The following Air Force Fitness Center project is being replaced by the 14 replacement projects at the same location.

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|------------------------------|-----------------------|------------------|
| 684 | Hickam AFB | HI | Repair Fitness Center, B1120 | 9,681 | O |

Replacement Projects:

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|---|-----------------------|------------------|
| 684a | Hickam AFB | HI | Repair Pavement Access Road to Runway End (8L) | 98 | P |
| 684b | Hickam AFB | HI | Repair Fire Protection Systems (Lodging-Bldg #1168) | 825 | O |
| 684c | Hickam AFB | HI | Repair Sewer Lift Stations (Stations #1 and #1A) | 700 | E |
| 684d | Hickam AFB | HI | Repair Roof on Communications Bldg (Node 988, Ph 2) | 420 | R |
| 684e | Hickam AFB | HI | Repair Hangar Doors/Door Rails (Bldg #1055-Hangar 34 & 35) | 2,888 | O |
| 684f | Hickam AFB | HI | Repair Hangar Doors/Door Rails (Bldg #2030-Hangar 15 & 17) | 1,000 | O |
| 684g | Hickam AFB | HI | Install Traffic Signal, Vandenberg and Freedom Intersection | 600 | P |
| 684h | Hickam AFB | HI | Repair Interior Security Forces Building, Ph 2 (Bldg #1001) | 375 | O |

**American Recovery and Reinvestment Act of 2009
Facilities Sustainment, Restoration, and Modernization Project Replacement List**

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|------------|-------|---|-----------------------|------------------|
| 684i | Hickam AFB | HI | Repair Roof, Security Forces Building (Bldg #1001) | 225 | R |
| 684j | Hickam AFB | HI | Repair Aircraft Arresting Systems (Runways 4R and 8R) | 800 | O |
| 684k | Hickam AFB | HI | Repair Roof, Power Plant (Bldg #1109) | 150 | R |
| 684l | Hickam AFB | HI | Repair Child Development Center Roof (Bldg #1597) | 300 | R |
| 684m | Hickam AFB | HI | Paint Exterior Child Development Center (Bldg #1654) | 200 | Q |
| 684n | Hickam AFB | HI | Repair Pavement, O'Malley Ave between Apollo & Overpass | 1,100 | P |
| Total: | | | | 9,681 | |

Project Removed: The following Army National Guard Volunteer Training Site Catoosa project is being replaced by the Paris, TN

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------------|-------|-------------------------------|-----------------------|------------------|
| 1347 | VTS Catoosa | TN | Repair water and Sewer System | 514 | E |

Replacement Project:

| Installation/Location | | State | Project Title | Cost Estimate (\$000) | Project Category |
|-----------------------|-------|-------|---|-----------------------|------------------|
| 1347 | Paris | TN | Repair /upgrade Readiness Center HVAC to Current Building Standards | 514 | E |