

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
JB7 819 101 006	1/6/67	289	Remove deck and repair copper hot water heating line, repour deck and replace tile
JB7 819 101 117	8/26 67	1,574	Make repairs to HP 798 as per inspection sheets
HQ8 CM7 ONS 505	12/22/67	65	Misc. recurring maint follow-up replace lampholder in flourescent fixtures.
HQ8 CM ONS 512	1/26/68	259	Repair leak in steam line
XXXXXXXX-5XXX AA923** 15113			
AA923 ** 15113	1/9/69	440	Remove tack board anc coat racks in rooms one thru thirteen, deliver to storage in Midway Park school patch holes in floor and ceiling
AA923 ** 15116		1,839	Repair roofs on Brewster school bldgs 40, 797, 798 and 799
AA923 ** 15128	1/17/ 9	230	Perform interior repairs
AA923 ** 15134	2/21/69	146	Secure overhead concrete beams
AA923 ** 15138	3/14/69		Open-up built-up roof for engineers inspection, repair roof when inspection is complete
AA2 23 9237 23XXT	5/5/72	307	Install lights for school sign in from of bldg 40 and install wiremold recep in room 7 Bldg 798
<i>1751</i>	<i>9-20-74</i>		
<i>1751</i>	<i>9-20-74</i>	<i>886</i>	<i>Rep eniad lites in hallway with fl lites</i>
<i>1758</i>	<i>9-28-73</i>	<i>142</i>	<i>Inst receptacles</i>
<i>1819</i>	<i>11/16/72</i>		<i>Rpr oil line leak to water heater</i>
<i>7450</i>	<i>8-15-79</i>	<i>146 3</i>	<i>Support tree down + doddering eqvac traps</i>
<i>1765</i>	<i>6-29-78</i>	<i>94</i>	<i>Rpr drain lines in wall</i>
<i>1726</i>	<i>Comp</i>	<i>276</i>	<i>Exstale add. 115 VOLT outlets</i>
<i>1765</i>	<i>Comp</i>		<i>Repr drain line on wall</i>
<i>1714</i>	<i>2-29-80</i>	<i>597</i>	<i>Check out heating system</i>
<i>1710</i>	<i>Comp</i>	<i>97</i>	<i>Rpr termite damage</i>

