

ENGINEERING SERVICE REQUEST (ESR)
 NAVFAC 11000 7 (4-78)
 Supersedes NAVDOCKS 2038
 S/N 0105-2-110-0035

Instructions on Reverse

Copy No.

f gw L
Kip ESR
Key [unclear] [unclear]

SECTION A
 FOR USE BY REQUESTER

1 FROM (Agency and location) Base Maintenance Officer, Jacksonville, NC	
2 TO Public Works Officer	
3 REFERENCE(S)	4. ESR IDENTIFICATION NUMBER (if applicable) Project # 6C56
5. ENCLOSURE(S) (check) <input type="checkbox"/> NAVCOMPT 140 <input type="checkbox"/> OTHER (specify) <input type="checkbox"/> NAVCOMPT 2038 <input type="checkbox"/> NAVCOMPT 372	6. TYPE OF FUNDING (check) <input checked="" type="checkbox"/> O&MN <input type="checkbox"/> OTHER (specify) <input type="checkbox"/> NIF <u>M-1</u> <input type="checkbox"/> NAF
7. TYPE OF SERVICES REQUESTED Engineer study on exterior walls and windows. AS-710	8. DESIRED COMPLETION DATE 1st Qtr FY-86
9 DESCRIPTION OF WORK The exterior walls and windows of the officer's club allow water to penetrate to the interior damaging walls and carpet. Base Maintenance forces have on numerous occasions attempted to correct this problem without any success. Therefore, it is requested that an engineer study be done to correct this problem with a cost estimate. Jack Eagle, Club Manager, can locate areas of penetration. The most damage is in the bar area.	
10- FOR INFORMATION CONSULT (Name and phone) G. L. Shoemaker 5809	11. OFFICIAL REPRESENTATIVE (Signature) <i>[Signature]</i>
	12. DATE 24 SEP 1980

SECTION B
 FOR USE BY EFD

1. SCOPE OF SERVICES	2. DATE RECEIVED
	3. ESR NUMBER

SECTION C
 INTERIM ENDORSEMENT

1. REMARKS			
2. EST. COMPLETION DATE	3. AUTHORIZED REPRESENTATIVE (Signature)	4. DATE	

SECTION D
 FINAL ENDORSEMENT

1. ENCLOSURE(S) <input type="checkbox"/> DRAWINGS AND MAPS <input type="checkbox"/> SPECIFICATIONS <input type="checkbox"/> REPORT <input type="checkbox"/> OTHER (specify)			
2. EST. COST (if applicable) \$	3. AUTHORIZED REPRESENTATIVE (Signature)	4. DATE OF COMPLETION	

COPY TO

