

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA, SUITE 400 ARLINGTON, TEXAS 76011-4005

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

March 20, 2003

Garry L. Randolph, Senior Vice President and Chief Nuclear Officer Union Electric Company P.O. Box 620 Fulton, Missouri 65251

SUBJECT: CALLAWAY PLANT NRC SAFEGUARDS INSPECTION OF COMPLIANCE WITH ORDER INSPECTION REPORT 50-483/03-02

Dear Mr. Anderson:

On February 14, 2003, the NRC completed an inspection at your Callaway Plant. The enclosed report documents the inspection findings which were discussed on February 14, 2003, with Mr. W. Witt and other members of your staff. Additionally, on March 6, 2003, the inspectors conducted a final exit meeting with Mr. J. Laux, Manager, Operations Support, and other members of your staff.

This inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to security of your facility. The inspection utilized Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your responses dated March 18 and May 13, 2002. Within these areas, the inspection consisted of selected examination of procedures and representative records, observations of activities, and interviews with personnel.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will <u>not</u> be placed in the Public Document Room.

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

Union Electric Company

-2-

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response will be made available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

//RA//

Troy W. Pruett, Chief Plant Support Branch Division of Reactor Safety

Dockets: 50-483 License: NPF-30

Enclosure NRC Inspection Report 50-483/03-02

cc without safeguards enclosure:

Professional Nuclear Consulting, Inc. 19041 Raines Drive Derwood, Maryland 20855

John O'Neill, Esq. Shaw, Pittman, Potts & Trowbridge 2300 N. Street, N.W. Washington, D.C. 20037

Mark A. Reidmeyer, Regional Regulatory Affairs Supervisor Regulatory Affairs AmerenUE P.O. Box 620 Fulton, Missouri 65251

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

Manager - Electric Department Missouri Public Service Commission 301 W. High P.O. Box 360 Jefferson City, Missouri 65102

Ronald A. Kucera, Deputy Director for Public Policy Department of Natural Resources P.O. Box 176 Jefferson City, Missouri 65102

Rick A. Muench, President and Chief Executive Officer Wolf Creek Nuclear Operating Corporation P.O. Box 411 Burlington, Kansas 66839

Dan I. Bolef, President Kay Drey, Representative Board of Directors Coalition for the Environment 6267 Delmar Boulevard University City, Missouri 63130

Lee Fritz, Presiding Commissioner Callaway County Courthouse 10 East Fifth Street Fulton, Missouri 65251

J. V. Laux, Manager Quality Assurance AmerenUE P.O. Box 620 Fulton, Missouri 65251

Jerry Uhlmann, Director State Emergency Management Agency P.O. Box 116 Jefferson City, Missouri 65101

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

Union Electric Company

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

Scott Clardy, Director Section for Environmental Public Health P.O. Box 570 Jefferson City, Missouri 65102-0570

John D. Blosser, Manager Regulatory Affairs AmerenUE P.O. Box 620 Fulton, Missouri 65251

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

cc with safeguards enclosure:

Vonna Ordaz (NSIR/DNS/RSS) (MS T4D8) Juan Peralta (NSIR/DNS/SOS) (MS T4D8) Elaine McNeil (NSIR/DNS/RSS) (MS T4D8) RIV Docket File - File Room Custodian Security Inspector (Pick) Senior Resident Inspector (Peck)

Electronic distribution by RIV without safeguards enclosure: Regional Administrator (EWM) DRP Director (ATH) DRS Director (DDC) Branch Chief, DRP/B (DNG) Senior Project Engineer, DRP/B (RAK1) Staff Chief, DRP/TSS (PHH) RITS Coordinator (NBH) Ray Lorson (RKL) Site Secretary (DVY) Dale Thatcher (DFT) W. A. Maier, RSLO (WAM)

RIV:EMB	PSB	PBS	NSIR/DNS/SOS	DRP/D
LEEllershaw	PJElkmann	TLKlug	JDPeralta	DNGraves
via T	/RA/	/RA/	BHughes for	/RA/
3/ 10 /03	3/ 18 /03	3/ 10 /03	3/12 /03	3/ 13 /03
C:PSB				
TWPruett				
MPShannon for				
3/19/03				
OFFICIAL RECORD COPY		T=7	Telephone I	E=E-mail F=Fax

DOCUMENT: R:\CW2003-02tlkSGI.wpd

DOCUMENT CONTAINS

SAFEGUARDS INFORMATION

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION REGION IV

Dockets:	50-483	
Licenses:	NPF-30	
Report Nos.:	50-483/03-02	
Licensee:	Union Electric Company	
Facility:	Callaway Plant	
Location:	Junction Highway CC and Highway O Fulton, Missouri	
Dates:	February 10-14, 2003	
Inspectors:	L. E. Ellershaw, Senior Reactor Inspector Paul J. Elkmann, Emergency Preparedness Inspector Thomas L. Klug, Physical Security Inspector	
Approved By:	Troy W. Pruett, Chief, Plant Support Branch	
Attachment:	Supplemental Information	

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SUMMARY OF FINDINGS Callaway Plant NRC Inspection Report 50-483/03-02

IR 05000483-03-02, Union Electric Company; 02/10-14/03; Callaway Plant; TI 2515/148, Verification of Compliance With Interim Compensatory Measures Order.

The inspection was conducted by one senior reactor inspector, one emergency preparedness inspector, and one physical security inspector.

Cornerstone: Physical Security

- On February 25, 2002, the NRC imposed by Order, Interim Compensatory Measures to enhance physical security. The inspectors determined that, overall, the licensee appropriately incorporated the Interim Compensatory Measures into the site protective strategy and access authorization program; developed and implemented relevant procedures; ensured that the emergency plan could be implemented; and established and effectively coordinated interface agreements with offsite organizations.
- The inspectors identified an unresolved item related to the analysis developed to determine the survivability of armed responders from a bomb blast required by Item B.2.a.(1) of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section III.A).
- The inspectors identified an unresolved item related to the duties of the officer at the vehicle checkpoint required by Item B.2.a.(2) of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section III.B).
- The inspectors identified an unresolved item related to the evaluation of computer backup systems required by Item B.5.f of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section VI.F).
- The inspectors identified an unresolved item related to implementing physical and login controls on laptop computers required by Item B.5.f of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section VI.F).

DOCUMENT CONTAINS SAFEGUARDS INFORMATION