

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II

SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET SW SUITE 23T85 ATLANTA, GEORGIA 30303-8931

May 22, 2003 SAFEGUARDS INFORMATION

Carolina Power & Light Company

SAFEGUARDS INFORMATION REMOVED

ATTN: Mr. James Scarola

Vice President - Harris Plant Shearon Harris Nuclear Power Plant P. O. Box 165, Mail Code: Zone 1

New Hill, NC 27562-0165

SUBJECT: HARRIS NUCLEAR PLANT - NRC SAFEGUARDS INSPECTION

REPORT 50-400/03-06

Dear Mr. Scarola:

On April 10, 2003, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your Harris Nuclear Plant. The enclosed inspection report documents the inspection findings, which were discussed on April 10, 2003, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to security of your facility. The inspection used Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your responses dated March 18, 2002 and September 6, 2002. The inspection also reviewed other selected areas of the security program including performance indicators and behavioral observation/access authorization. Within these areas, the inspection consisted of selected examination of procedures and records, observation of activities, and interviews with personnel.

Based on the results of this inspection, the report documents an inspector-identified finding not related to the Interim Compensatory Measures, of very low safety significance (Green) which was determined to involve a violation of NRC requirements. However, because of the very low safety significance and because it has been entered into a corrective action process, the NRC is treating this finding as a non-cited violation (NCV) in accordance with Section VI.A of the NRC's Enforcement Policy. If you contest the NCV, you should provide a response within 30 days of the date of this inspection report, with a basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN.: Document Control Desk, Washington, DC 20555-0001; with

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

copies to the Regional Administrator, Region II; the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001; and the NRC Resident Inspector at the Harris Facility.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, without the enclosed Safeguards Information, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

Should you have any questions concerning this letter, please contact us.

Sincerely,

/RA/

Anne T. Boland, Chief Plant Support Branch Division of Reactor Safety

Docket No. 50-400 License Nos. NPF-63

Enclosure: NRC Inspection Report

50-400/03-06

cc w/encl: See Page 3

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

cc w/Safeguards Information:

James W. Holt, Manager Performance Evaluation and Regulatory Affairs CPB 9 Carolina Power & Light Company P. O. Box 1551 Raleigh, NC 27602-1551

cc w/o Safeguards Information:

Robert J. Duncan II
Director of Site Operations
Carolina Power & Light Company
Shearon Harris Nuclear Power Plant
P. O. Box 165 MC: Zone 1
New Hill, NC 27562-0165

Benjamin C. Waldrep Plant General Manager--Harris Plant Carolina Power & Light Company Shearon Harris Nuclear Power Plant P. O. Box 165 New Hill. NC 27562-0165

Terry C. Morton, Manager Support Services Carolina Power & Light Company Shearon Harris Nuclear Power Plant P. O. Box 165, Mail Zone 1 New Hill, NC 27562-0165

John R. Caves, Supervisor Licensing/Regulatory Programs Carolina Power & Light Company Shearon Harris Nuclear Power Plant P. O. Box 165, Mail Zone 1 New Hill, NC 27562-0165

(continued on page 4)

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

(cc w/o Safeguards Information - continued)

Steven R. Carr Associate General Counsel - Legal Department Progress Energy Service Company, LLC P. O. Box 1551 Raleigh, NC 27602-1551

John H. O'Neill, Jr. Shaw, Pittman, Potts & Trowbridge 2300 N. Street, NW Washington, DC 20037-1128

Beverly Hall, Acting Director
Division of Radiation Protection
N. C. Department of Environmental
Commerce & Natural Resources
3825 Barrett Drive
Raleigh, NC 27609-7721

Peggy Force Assistant Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

Public Service Commission State of South Carolina P. O. Box 11649 Columbia. SC 29211

Chairman of the North Carolina Utilities Commission P. O. Box 29510 Raleigh, NC 27626-0510

Robert P. Gruber, Executive Director Public Staff NCUC 4326 Mail Service Center Raleigh, NC 27699-4326

continued on Page 5

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

5

(cc w/o Safeguards Information - continued)

Herb Council, Chair Board of County Commissioners of Wake County 3309 Marblehead Lane Raleigh, NC 27612

Tommy Emerson, Chair Board of County Commissioners of Chatham County 186 Emerson Road Siler City, NC 27344

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

6

Distribution w/o Safeguards Information:

J. Peralta (encrypted copy)

C. Patel, NRR

C. Evans (Part 72 Only)

L. Slack, RII EICS

RIDSRIDSNRRDIPMLIPB

PUBLIC

OFFICE	RII:DRS		RII:DRS		RII:DRP		RII:DRS		RII:DRP		RII:DRS		NSIR	
SIGNATURE	ATB for		ATB via phone		JC via phone		LSM		PS		ATB		BH for	
NAME	ENNIS		FORBES		CANADY		MELLEN		FREDRICKSON		BOLAND		PERALTA	
DATE	05/ /03		05/ /03		05/ /03		05/ /03		05/ /03		05/ /03		05/ /03	
E-MAIL COPY?	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
PUBLIC DOCUMENT	YES	NO												

OFFICIAL RECORD COPY DOCUMENT NAME: C:\ORPCheckout\FileNET\ML031420553.wpd

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION

REGION II

Docket No.: 50-400

License No.: NPF-63

Report No.: 50-400/03-06

Licensee: Carolina Power and Light Company

Facility: Harris Nuclear Plant

Location: New Hill, NC

Dates: March 3-7 and April 7-10, 2003

Inspectors: Donald B. Forbes, Senior Physical Security Inspector

Jerry D. Ennis, Physical Security Inspector

Larry S. Mellen, Senior Emergency Preparedness Inspector

James A. Canady, Acting Senior Resident Inspector

Approved By: Anne T. Boland, Chief

Plant Support Branch Division of Reactor Safety

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SUMMARY OF FINDINGS

IR 05000400/2003-006: Carolina Power and Light Company; 3/3-7/2003 and 4/7-10/2003; Harris Nuclear Plant, Unit 1; Temporary Instruction (TI) 2515/148, Verification of Compliance with Interim Compensatory Measures Order and Access Authorization/Behavioral Observation.

The report covered an announced inspection by two regional physical security inspectors, an emergency preparedness inspector, and a resident inspector. One Green non-cited violation (NCV) was identified. The significance of most findings is indicated by their color (Green, White, Yellow, Red) using Inspection Manual Chapter 0609, "Significance Determination Process" (SDP). Findings for which the SDP does not apply may be Green or assigned a Severity level after NRC management review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000.

A. Inspector-Identified and Self-Revealing Finding

Cornerstone: Physical Security

Green. Failure to remove a worker, whose fitness may have been questionable, from activities within the scope of 10 CFR Part 26.

An inspector identified non-cited violation of 10 CFR 26.27(4)(b)(1) was identified. The finding is greater than minor, because if left uncorrected, the issue could have become a more significant safety concern in that the trustworthiness and reliability of employees is an critical attribute of the Physical Protection Cornerstone objective. It was determined to be of very low safety significance because it involved a failure to meet regulatory requirements involving the access control/behavioral observation program; however, there was no malevolent action and there have not been greater than two similar findings in the previous four quarters. (Section VII.B)

B. Licensee-Identified Violations

None

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION