

RESEARCH TRIANGLE INSTITUTE


National Laboratory Certification Program

August 11, 2000

0355
Dr. William R. Lynn
LabCorp Occupational Testing Services, Inc.
7207 North Gessner Road
Houston, TX 77040

Dear Dr. Lynn:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the initial inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the outcome of the laboratory's performance in this inspection is acceptable; however, the laboratory must clarify and/or correct the following issues before a recommendation for certification can be made:



Dr. Lynn Page 2 of 3 08/11/00

The laboratory must submit documentation to clarify and/or correct the items cited above. Once the laboratory has successfully completed these actions, RTI will recommend to the Department of Health and Human Services (HHS) that the laboratory be certified under the NLCP. The laboratory must also review the enclosed critique and take all necessary corrective actions.

Dr. Lynn Page 3 of 3 08/11/00

If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Michael Baylor, Ph.D. at (919) 541-7043.

Sincerely,

Susan Crumpton

NLCP Technical Analyst

Enclosure

CC:

Project Files/355

NATIONAL LABORATORY CERTIFICATION PROGRAM

Document Review and Critique

Laboratory I.D. Number: <u>0355</u> Document No. Final

Laboratory:

LabCorp Occupational Testing Services, Inc.

Location:

Houston, TX

Document Reviewed:

[XX] Inspection Report # I

Date: 15 June 2000

[] Other _____

Status:


[XX] Pass
[] Failure

Inspection reports, from the inspectors who conducted the National Laboratory Certification Program (NLCP) inspection, have been carefully reviewed and found to provide sufficient information to judge that the laboratory has met the standards required for the inspection phase of the Program, pending the submission of evidence that appropriate corrective action has been taken.


There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual



Section F. Chain-of-Custody, Accessioning, and Security



Section H. Initial Tests

Section I. Confirmatory Tests

Section J. Records Audit

Section K. Reporting

Section L. Computers, Software, and LIMS

Section M. Equipment and Maintenance

Section N. Personnel





Laboratory Corporation of America[®] 7207 North Gessner Road Houston, Texas 77040

Telephone: 713-856-8288


August 17, 2000

Susan Crumpton Research Triangle Institute 3040 Cornwallis Road Research Triangle Park, NC 27709-2194


Dear Ms Crumpton:

The following remedial actions have occurred to correct and/or clarify issues raised during the initial inspection:

Section E 2



Section E 5



Section F 16 Section I 1b Section I 4d Section I 18 Section J 10.a If you have any questions or need additional information please call me at 713-856-8288 x3653.

Sincerely,

William/R. Zynn, Ph.D. Director Toxicology



National Laboratory Certification Program

August 22, 2000

0355
Dr. William R. Lynn
LabCorp Occupational Testing Services, Inc.
7207 North Gessner Road
Houston, TX 77040

Dear Dr. Lynn:

We have reviewed the material provided in your correspondence of August 17, 2000, provided in response to issues raised during the initial inspection of your laboratory as outlined in our correspondence of August 11, 2000.

Based upon our review of the submitted material, the laboratory has successfully completed the requirements for initial certification. RTI is recommending to the Department of Health and Human Services (HHS) that your laboratory be certified under the National Laboratory Certification Program.

Details of the results of the laboratory's performance test samples have been provided under a separate correspondence. As indicated in the materials sent to you previously, a second inspection will be conducted at your laboratory as a follow-up to the initial certification process. This inspection will occur in about three months. After you have received your official certification letter from HHS, NLCP staff will contact you regarding inspection scheduling and payment.

We look forward to continuing to work with your laboratory as a participant in the program. If you have any questions or if we can be of further assistance, please call me at (919) 541-6176.

Sincerely,

Susan Crumpton

NLCP Technical Analyst

cc: Dr. Michael Baylor Dr. John Mitchell

Project Files/1






National Laboratory Certification Program

January 29, 2001


0355
Dr. William R. Lynn
LabCorp Occupational Testing Services, Inc.
7207 North Gessner Road
Houston, TX 77040

Dear Dr. Lynn:

The enclosed critique was developed from the inspection reports of the inspectors who conducted the second (three-month) inspection of your laboratory under the National Laboratory Certification Program (NLCP). Based upon our review of these reports, the laboratory's performance in this inspection is acceptable. Before RTI will recommend continued certification of your laboratory, the laboratory must clarify/correct the following issues raised:



Dr. Lynn Page 2 of 3 01/29/01



The laboratory must submit, within 30 calendar days of receipt of this letter, documentation to demonstrate that corrective actions have been implemented to address the issues raised. In responding to these issues, please organize the material in your document in accordance with the sections and item numbers as listed in this correspondence. Once these issues have been successfully addressed, RTI will recommend to the Department of Health and Human Services (HHS) that the laboratory's certification be continued. The laboratory must also review the enclosed critique and take all necessary corrective actions. All corrective actions must be implemented within 30 days receipt of this correspondence and will be reviewed at the next inspection.

If you have any questions or if we can be of further assistance, please call me at (919) 541-6176 or Dr. Michael Baylor at (919) 541-7043.

Sincerely,

Susan Crumpton

NLCP Technical Analyst

Enclosure

cc: Project Files/355

NATIONAL LABORATORY CERTIFICATION PROGRAM

Document Review and Critique

Laboratory I.D. Number: 0355

Document No. Final

Laboratory: <u>Laboratory Corporation of America Holdings</u>

Location: Houston, TX

Document Reviewed: Application Form

[XX] Inspection Report #2 Date: 16 November 2000

] Other _


Status:] Highly Acceptable [XX] Acceptable] Unacceptable [] Failure

Inspection reports, from the inspectors who conducted the National Laboratory Certification Program (NLCP) inspection, have been carefully reviewed and found to provide sufficient information to judge that the laboratory has met the standards required for the inspection phase of the Program, pending the submission of evidence that appropriate corrective action has been taken.


There were a number of comments and observations generated as a result of the inspection that are detailed on the following pages for the attention of the laboratory before its next inspection.

The following comments were noted, and appear in the same order as the corresponding questions in the Laboratory Inspection Report:

Section E. Standard Operating Procedures - Procedures Manual




Section F. Chain-of-Custody, Accessioning, and Security



NLCP ◆ Research Triangle Institute

Ver. Final

Section G. Quality Control and Quality Assurance



Ver. Final	Lab ID# 0355
Section H. Initial Tests	
Section I. Specimen Validity Tests	
the state of the s	
Section J. Confirmatory Tests	
Section K. Records Audit	

Section L. Certification and Reporting

Section M. Laboratory Information Management System (LIMS)

Section N. Personnel

Ver. Final Lab ID# 0355