



Massachusetts



American Recovery and Reinvestment Act

38 DoD Projects (\$ 24.2M) Completed or Under Way by August 31, 2009

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Roadway- Parking Lot - Sidewalks	Army	Natick Labs	1,900
Exterior Repairs to Navy R & D Building 7	Army	Natick Labs	175
Replace Heating Systems	Army Family Housing	Natick Soldier Systems Labs	100
Replace Windows	Army Family Housing	Natick Soldier Systems Labs	100
Repair Sewers	Army Family Housing	Natick Soldier Systems Labs	45
Repair/upgrade Electrical System and Building Envelope at Field Maintenance Shop to Current Energy Standards	Army National Guard	Dorchester	289
Upgrade HVAC/Lighting, Army National Guard Aviation Support Facility #1	Army National Guard	Otis AFB	715
Repair Steam & Condensate Lines Kirtland St Jb27 to Jb28	Air Force	Hanscom AFB	1,349
Repair Steam & Condensate Lines Kirtland St Jb28 to B1425	Air Force	Hanscom AFB	1,144
Repair Roof Building 1436 Jag	Air Force	Hanscom AFB	1,065
Repair Steam & Condensate Lines Chennault St Jb13 to Jb32	Air Force	Hanscom AFB	901
Paving IDIQ - Repair Pkg Lot Building 1521 Acquisition Facility	Air Force	Hanscom AFB	844

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Steam & Condensate Lines Chennault St B1614 to B1725	Air Force	Hanscom AFB	793
Paving IDIQ - Repair Grenier & Dow Streets	Air Force	Hanscom AFB	785
Repair Steam & Condensate Lines Chennault St Jb14 to Jb13	Air Force	Hanscom AFB	740
Repair Steam & Condensate Lines Along Grenier St Jb4 to Jb2	Air Force	Hanscom AFB	731
Repair Steam & Condensate Lines Chennault St Jb16 to Jb14	Air Force	Hanscom AFB	728
Paving IDIQ - Repair Pkg Lot Building 1240 Airmen Readiness Ctr	Air Force	Hanscom AFB	720
Repair Steam & Condensate Lines Grenier St Jb25 to Jb5	Air Force	Hanscom AFB	583
Paving IDIQ - Repair Pkg Lot Building 1305 Wing HQ	Air Force	Hanscom AFB	582
Paving IDIQ - Repair Pkg Lot Building 1103 Af Research Lab Library	Air Force	Hanscom AFB	571
Paving IDIQ - Repair Secondary Pkg Lot B1900 Clinic	Air Force	Hanscom AFB	494
Repair Roof Building Hangar 1722	Air Force	Hanscom AFB	494
Repair Roof Building 1128 Research Lab Research Labs	Air Force	Hanscom AFB	489
Repair Heating Piping Building 1520 Acquisition Facility	Air Force	Hanscom AFB	488
Repair Roof Building 1302d Research Facility for Lincoln Labs	Air Force	Hanscom AFB	430
Paving IDIQ - Repair Back Parking Lot Building 1642 Motor Pool	Air Force	Hanscom AFB	408

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Paving IDIQ - Repair Pkg Lot @ Eglin & Arnold	Air Force	Hanscom AFB	312
Repair Roof Building 1102d Research Lab Logistics-Mobility	Air Force	Hanscom AFB	269
Paving IDIQ - Bestic - Mit Pkg Lot to Tinker Loop	Air Force	Hanscom AFB	260
Paving IDIQ - Repair Pkg & Drive B1201 Heat Facility	Air Force	Hanscom AFB	260
Paving IDIQ - Repair Pkg Lot Building 1646 Communication Facility	Air Force	Hanscom AFB	248
Repair Skylight Main Entry Building 1305 - Wing HQ	Air Force	Hanscom AFB	247
Paving IDIQ - Repair Eglin St By B1900 Clinic	Air Force	Hanscom AFB	215
Paving IDIQ - Repair Vehicle Storage Lot	Air Force	Hanscom AFB	209
Paving IDIQ - Repair Pkg Lot Building 1813 Civil Engineering	Air Force	Hanscom AFB	183
Paving IDIQ - Repair Drainage at Pkg B1520 Acquisition Facility	Air Force	Hanscom AFB	170
Repair C-5 Ramp Perimeter Drainage	Air Force Reserve	Westover Air Reserve Base	4,160