



Kansas



American Recovery and Reinvestment Act

56 DoD Projects (\$ 67.4M) Completed or Under Way by August 31, 2009

| <i>Project Title</i> | <i>Component</i> | <i>Installation</i> | <i>Estimated Cost (\$000s)</i> |
|---|------------------|---------------------|--------------------------------|
| Repair Int/Ext, HVAC to Library, Eisenhower Hall, #120 | Army | Fort Leavenworth | 4,000 |
| Repair Electrical System in Building 136 | Army | Fort Leavenworth | 3,000 |
| Repair Harney Fitness Center HVAC, Building 664 | Army | Fort Leavenworth | 3,000 |
| Repair HVAC and Interior, Building 302, Gruber Fitness Center | Army | Fort Leavenworth | 3,000 |
| Repair HVAC in Community Activity Center | Army | Fort Leavenworth | 3,000 |
| Repair the Central Tower on Grant Hall | Army | Fort Leavenworth | 2,450 |
| Repair HVAC System in Building 45 for Combined Arms Center - Training | Army | Fort Leavenworth | 2,000 |
| Repair Roofs Postwide | Army | Fort Leavenworth | 1,050 |
| Repair Roads Postwide | Army | Fort Leavenworth | 750 |
| Road Repair - McPherson Ave. | Army | Fort Leavenworth | 700 |
| Repair Ceiling/Lights & Const Latrines, Building 56, Religious Ed, Chapel | Army | Fort Leavenworth | 579 |
| Repair and Improve Outdoor Recreational Facilities Postwide | Army | Fort Leavenworth | 512 |

| <i>Project Title</i> | <i>Component</i> | <i>Installation</i> | <i>Estimated Cost (\$000s)</i> |
|--|------------------|---------------------|--------------------------------|
| Exterior Painting and Repairs Postwide | Army | Fort Leavenworth | 250 |
| Repair Concrete Structures and Surfaces Postwide | Army | Fort Leavenworth | 250 |
| Repair Interior/Exterior Admin Building 216 | Army | Fort Riley | 8,000 |
| Replace Underground Cable | Army | Fort Riley | 4,000 |
| Volar Brks 8008 Barracks Remediation-Restore All Finishes and Systems. | Army | Fort Riley | 3,280 |
| Volar Building 8040 Barracks Remediation-Restore All Finishes and Systems. | Army | Fort Riley | 3,120 |
| Volar Building 8042 Barracks Remediation-Restore All Finishes and Systems. | Army | Fort Riley | 3,120 |
| Volar Building 8048 Barracks Remediation-Restore All Finishes and Systems. | Army | Fort Riley | 3,120 |
| Volar Building 8050 Barracks Remediation-Restore All Finishes and Systems. | Army | Fort Riley | 3,120 |
| Volar Building 8052 Barracks Remediation-Restore All Finishes and Systems. | Army | Fort Riley | 3,120 |
| Volar Building 8054 Barracks Remediation-Restore All Finishes and Systems. | Army | Fort Riley | 3,120 |
| Repair Building 219 Directorate of Emergency Services | Army | Fort Riley | 1,900 |
| Replace Existing Underground | Army | Fort Riley | 1,500 |
| Repair Dam Moon Lake | Army | Fort Riley | 850 |
| Gimfe Repair and Replace Failed Water Well | Army | Fort Riley | 750 |

| <i>Project Title</i> | <i>Component</i> | <i>Installation</i> | <i>Estimated Cost (\$000s)</i> |
|---|------------------|---------------------|--------------------------------|
| Rpr Restorerooms/Install Handicap Lift to Access Auditorium Buildingg | Army | Fort Riley | 605 |
| Repair Failing Ceiling, Building 7086, Chapel | Army | Fort Riley | 350 |
| Repair Grass and Irrigation, Building 84 Cmty Field | Army | Fort Riley | 350 |
| Repair Latrines, Building 221, Military Police Station | Army | Fort Riley | 250 |
| Repair Damaged Floor, Building 5315, Religious Ed | Army | Fort Riley | 150 |
| Repair ADA Deficiencies Type: 74028 Building 202 Community | Army | Fort Riley | 150 |
| Rebuild Gas Metering Station | Army | Fort Riley | 125 |
| Repair Deficiencies on Airfield Levee | Army | Fort Riley | 80 |
| Replace or Repair Pump at 393 | Army | Fort Riley | 57 |
| Repair Roof Normandy Chapel, Type: 73017, Building 7865, Religious | Army | Fort Riley | 50 |
| Repair Roof, Building 6 , Main Post Chapel Type: 73017 | Army | Fort Riley | 50 |
| Repair Building 7024 Parking Lot | Army | Fort Riley | 32 |
| Repair Roof, Building 3 | Army | Fort Riley | 30 |
| Repair Deteriorated Floors, Building 6620a, Child Development Center | Army | Fort Riley | 10 |
| Repair Deteriorated Floors, Building 6620b, Child Development Center | Army | Fort Riley | 10 |

| <i>Project Title</i> | <i>Component</i> | <i>Installation</i> | <i>Estimated Cost (\$000s)</i> |
|---|---------------------|------------------------------|--------------------------------|
| Upgrade Housing Services Office | Army Family Housing | Fort Leavenworth | 70 |
| Field Maintenance Site #1 Light Upgrade | Army National Guard | Hays Readiness Center | 18 |
| Field Maintenance Site #9 Light Upgrade | Army National Guard | JFHQ - Kansas | 28 |
| Kansas City Light Upgrade | Army National Guard | Kansas City Readiness Center | 18 |
| Assembly Hall Light Upgrade | Army National Guard | Manhattan Readiness Center | 73 |
| Building 680 Remodel Latrine | Army National Guard | Topeka Forbes Field | 130 |
| Hangar 680 Flooring Coating | Army National Guard | Topeka Forbes Field | 100 |
| Hangar 681 Lighting Upgrade | Army National Guard | Topeka Forbes Field | 84 |
| Hangar 682 Lighting Upgrade | Army National Guard | Topeka Forbes Field | 84 |
| Hanger 680 Lighting Upgrade | Army National Guard | Topeka Forbes Field | 84 |
| Hangar 682 Flooring Coating | Army National Guard | Topeka Forbes Field | 75 |
| Install HVAC, Office & Latrine | Army National Guard | Topeka Forbes Field | 44 |
| Alter Building 1127 for Soar | Air Force | McConnell AFB | 753 |
| Repair Roof Security Forces Building 1115 | Air Force | McConnell AFB | 35 |