

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II

SAM NUNN ATLANTA FEDERAL CENTER 61 FORSYTH STREET SW SUITE 23T85 ATLANTA, GEORGIA 30303-8931

April 10, 2003

SAFEGUARDS INFORMATION

Carolina Power and Light Company ATTN: Mr. J. S. Keenan Vice President Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461 SAFEGUARDS INFORMATION REMOVED

SUBJECT:

BRUNSWICK NUCLEAR PLANT - NRC SPECIAL INSPECTION

REPORT NO. 50-325/2003-07 AND 50-324/2003-07

Dear Mr. Keenan:

On February 27, 2003, the U.S. Nuclear Regulatory Commission (NRC) completed an inspection at your Brunswick Nuclear Plant. The enclosed inspection report documents the inspection findings, which were discussed on February 27, 2003, with you and other members of your staff.

The inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to security of your facility. The inspection used Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your responses dated March 14, 2002; May 17, 2002; and August 28, 2002. The inspection also reviewed selected aspects of an additional Security Order issued to the licensee October 3, 2002. Within these areas, the inspection consisted of selected examination of procedures and records, observation of activities, and interviews with personnel.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter, without the enclosed Safeguards Information, will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at http://www.nrc.gov/reading-rm/adams.html (the Public Electronic Reading Room).

Should you have any questions concerning this letter, please contact us.

Sincerely,

/RA/

Anne T. Boland, Chief Plant Support Branch Division of Reactor Safety

Docket Nos. 50-325, 50-324 License Nos. DPR-71, DPR-62

Enclosure: NRC Inspection Report

50-325/2003-07 and 50-324/2003-07

cc w/encl: See Page 3

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

cc w/Safeguards Information:

J. J. Lyash, Director Site Operations Brunswick Steam Electric Plant Carolina Power & Light Company P. O. Box 10429 Southport, NC 28461

cc w/o Safeguards Information:

W. C. Noll Plant Manager Brunswick Steam Electric Plant Carolina Power & Light Company P. O. Box 10429 Southport, NC 28461

Terry C. Morton, Manager Performance Evaluation and Regulatory Affairs CPB 7 Carolina Power & Light Company P. O. Box 1551 Raleigh, NC 27602-1551

Edward T. O'Neil, Manager Support Services Carolina Power & Light Company Brunswick Steam Electric Plant P. O. Box 10429 Southport, NC 28461

Licensing Supervisor Carolina Power & Light Company P. O. Box 10429 Southport, NC 28461

William D. Johnson Vice President & Corporate Secretary Carolina Power and Light Company P. O. Box 1551 Raleigh, NC 27602-1551 John H. O'Neill, Jr. Shaw, Pittman, Potts & Trowbridge 2300 N. Street, NW Washington, DC 20037-1128

Beverly Hall, Acting Director
Division of Radiation Protection
N. C. Department of Environmental
Commerce & Natural Resources
3825 Barrett Drive
Raleigh, NC 27609-7721

Peggy Force Assistant Attorney General State of North Carolina P. O. Box 629 Raleigh, NC 27602

Chairman of the North Carolina Utilities Commission P. O. Box 29510 Raleigh, NC 27626-0510

Robert P. Gruber Executive Director Public Staff NCUC 4326 Mail Service Center Raleigh, NC 27699-4326

Public Service Commission State of South Carolina P. O. Box 11649 Columbia, SC 29211

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

4

cc w/o Safeguards Information (cont.):

Donald E. Warren Brunswick County Board of Commissioners P. O. Box 249 Bolivia, NC 28422

Dan E. Summers
Emergency Management Coordinator
New Hanover County Department of
Emergency Management
P. O. Box 1525
Wilmington, NC 28402

5

Distribution w/o Safeguards Information:

- J. Peralta (encrypted copy)
- L. Olshan, NRR
- C. Evans (Part 72 Only)
- L. Slack, RII EICS

RIDSRIDSNRRDIPMLIPB

PUBLIC

OFFICE	RII:DRS		RII:DRS		RII:DRP		NSIR		RII:DRP		RII:DRS			
SIGNATURE	ATB for JDE		ATB for DBF		JC		Smith for JP		Desai for PF		ATB			
NAME	ENNIS		FORBES		CANADY		PERALTA		FREDRICKSON		BOLAND			
DATE	04/10/03		04/10/03		04/8/03		04/10/03		04/8/03		04/10/03			
E-MAIL COPY?	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO	YES	NO
PUBLIC DOCUMENT	YES	NO		•		•				•		•		

OFFICIAL RECORD COPY

DOCUMENT NAME: C:\ORPCheckout\FileNET\ML031010531.wpd

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

ENCLOSURE

U.S. NUCLEAR REGULATORY COMMISSION

REGION II

Docket Nos: 50-325, 50-324

License Nos: DPR-71, DPR-62

Report No.: 50-325, 324/2003-07

Licensee: Carolina Power and Light Company

Facility: Brunswick Nuclear Plant

Location: Southport, NC

Dates: February 24 - 27, 2003

Inspectors: Jerry D. Ennis, Senior Physical Security Inspector

Donald B. Forbes, Physical Security Inspector James L. Kreh, Emergency Preparedness Inspector James A. Canady, Acting Resident Inspector

Approved By: Anne T. Boland, Chief

Plant Support Branch Division of Reactor Safety

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

SUMMARY OF FINDINGS

IR 05000325/2003-007; IR 05000324/2003-007: Carolina Power and Light Company; 2/24-27/2003; Brunswick Nuclear Plant, Units 1 and 2; TI 2515/148, Verification of Compliance with Interim Compensatory Measures Order.

The report covered an announced inspection by two regional physical security inspectors, an emergency preparedness inspector, and the acting resident inspector. One unresolved item remains open pending further NRC review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 3, dated July 2000.

A. Inspector-Identified and Self-Revealing Findings

Cornerstone: Physical Security

None

B. <u>Licensee-Identified Violations</u>

An unresolved item was identified regarding failure to make telephone notification to the NRC within the required time frame preceding a shipment as required by Section II.B.2.b of an NRC Order issued October 3, 2002. (Section VII.A)

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION