

# UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA, SUITE 400 ARLINGTON, TEXAS 76011-4005

# DOCUMENT CONTAINS SAFEGUARD INFORMATION

June 25, 2003

Mr. C. L. Terry, Senior Vice President and Principal Nuclear Officer TXU Energy ATTN: Regulatory Affairs Comanche Peak Steam Electric Station P.O. Box 1002 Glen Rose, Texas 76043

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION NRC SAFEGUARDS

INSPECTION OF COMPLIANCE WITH ORDER - INSPECTION REPORT

50-445/03-05: 446/03-05

Dear Mr. Terry:

From May 19 to June 5, 2003, the NRC completed an inspection of your Comanche Peak Steam Electric Station. The enclosed report documents the inspection findings which were discussed on May 23, 2003, during a pre-brief and on June 5, 2003, at a telephonic exit meeting with you and other members of your staff.

This inspection examined activities conducted under your license as they relate to safety and compliance with an Order issued on February 25, 2002, which required your site to implement specific measures related to the security of your facility. The inspection utilized Temporary Instruction 2515/148, "Inspection of Nuclear Reactor Safeguards Interim Compensatory Measures," to verify implementation of the Order as clarified in your responses dated March 18, May 16, June 20, and August 30, 2002. Within these areas, the inspection consisted of selected examination of procedures and representative records, observations of activities, and interviews with personnel.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will <u>not</u> be placed in the Public Document Room.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of the non Safeguards Information portions of this letter, its enclosure, and your response will be made available electronically for public inspection in the NRC Public Document Room or from the

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <a href="http://www.nrc.gov/reading-rm/adams.html">http://www.nrc.gov/reading-rm/adams.html</a> (the Public Electronic Reading Room). Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

//RA//

Michael P. Shannon, Acting Chief Plant Support Branch Division of Reactor Safety

Dockets: 50-445

50-446

Licenses: NPF-87

NPF-89

Enclosure:

NRC Inspection Report 50-445/03-05; 50-446/03-05

# cc without safeguards enclosure:

Roger D. Walker Regulatory Affairs Manager TXU Generation Company LP P.O. Box 1002 Glen Rose, Texas 76043

George L. Edgar, Esq. Morgan, Lewis & Bockius 1800 M. Street, NW Washington, D.C. 20036-5869

Terry Parks, Chief Inspector Texas Department of Licensing & Regulation Boiler Program P.O. Box 12157 Austin, Texas 78711

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

County Judge P.O. Box 851 Glen Rose, Texas 76043

Chief, Bureau of Radiation Control Texas Department of Health 1100 West 49th Street Austin, Texas 78756-3189

Environmental and Natural Resources Policy Director Office of the Governor P.O. Box 12428 Austin, Texas 78711-3189

Brian Almon
Public Utility Commission
William B. Travis Building
P.O. Box 13326
1701 North Congress Avenue
Austin, Texas 78701-3326

Susan M. Jablonski
Office of Permitting, Remediation and Registration
Texas Commission on Environmental Quality
MC-122
P.O. Box 13087
Austin, TX 78711-3087

DOCUMENT CONTAINS SAFEGUARDS INFORMATION

### cc with safeguards enclosure:

Scott Morris (NSIR/DNS/RSS) (MS T4D8)
Barry Westreich (NSIR/DNS/SOS) (MS T4D8)
Elaine McNeil (NSIR/DNS/RSS) (MS T4D8)
RIV Docket File - File Room Custodian
Security Inspector (Pick)
Senior Resident Inspector (Allen)

Electronic distribution by RIV without safeguards enclosure:

Regional Administrator (TPG)

DRP Director (ATH)
DRS Director (TWP)

Branch Chief, DRP/A (WDJ)

Senior Project Engineer, DRP/A (TRF)

Staff Chief, DRP/TSS (PHH)

RITS Coordinator (NBH)

Mel Fields (MBF1)

Site Secretary (vacant)

Dale Thatcher (DFT)

W. A. Maier, RSLO (WAM)

	_ ` ` `			
ADAMS.	M Yes	□No	Initials:	.IIh

■ Publicly Available □ Non-Publicly Available □ Sensitive ■ Non-Sensitive

DOCUMENT: R:\CP2003-05gapSGI.wpd

RIV:PSB	DRP/A	DRP/B	NSIR/DNS/SOS	DRP/A
GAPick*	GLGuerra*	FLBrush*	BWestreich*	WDJohnson*
/RA/	GAP via E	GAP via E	GAP Via E	/RA/
6/5/03	6/5 /03	6/5 /03	6/12 /03	6/18/03
D:DRS	C:PSB			
D:DRS TWPruett*	C:PSB MPShannon			

OFFICIAL RECORD COPY T=Telephone E=E-mail

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

ENCLOSURE(S) CONTAIN(S)
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

F=Fax

# DOCUMENT CONTAINS SAFEGUARD INFORMATION

### **ENCLOSURE**

# U.S. NUCLEAR REGULATORY COMMISSION REGION IV

Dockets: 50-445

50-446

Licenses: NPF-87

NPF-89

Report No.: 50-445/03-05

50-446/03-05

Licensee: TXU Generation Company LP

Facility: Comanche Peak Steam Electric Station, Units 1 and 2

Location: FM-56, Glen Rose, Texas

Dates: May 19 through June 5, 2003

Inspectors: Gregory A. Pick, Senior Physical Security Inspector

Frank L. Brush, Senior Resident Inspector Gilbert L. Guerra, Resident Inspector

Accompanying Gregory Ahern, Intelligence Specialist Personnel: Jim Larsen, Physical Security Inspector

Approved By: Michael P. Shannon, Acting Chief, Plant Support Branch

Attachment: Supplemental Information

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

# DOCUMENT CONTAINS SAFEGUARD INFORMATION

#### SUMMARY OF FINDINGS

IR 05000445-03-05; IR 05000446-03-05; TXU Energy; on 5/19-6/5/2003; Comanche Peak Steam Electric Station, Units 1 & 2; TI 2515/148, Verification of Compliance With Interim Compensatory Measures Order.

The inspection was conducted by one senior physical security inspector, one senior resident inspector, and one resident inspector.

# **Cornerstone: Physical Security**

- On February 25, 2002, the NRC imposed by Order, Interim Compensatory Measures to enhance physical security. The inspectors determined that, overall, the licensee appropriately incorporated the Interim Compensatory Measures into the site protective strategy and access authorization program; developed and implemented relevant procedures; ensured that the emergency plan could be implemented; and established and effectively coordinated interface agreements with offsite organizations.
- The inspectors identified an unresolved item related to the failure to evaluate the impact of a waterborne threat as specified in Item B.1.c of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section II.C.2).
- The inspectors identified an unresolved item regarding loss of microwave intrusion detection system zones as required by Item B.2.a.(1) of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section III.A.2).
- The inspectors identified an unresolved item related to the failure to harden a vital area structure as required by Item B.4.g of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section V.G.2).
- The inspectors identified an unresolved item relating to the failure to evaluate the consequences of hazardous material transportation as specified in Item B.5.c of the Order. This item remains open pending review by the Office of Nuclear Security and Incident Response (Section VI.C.2).

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION

# DOCUMENT CONTAINS SAFEGUARD INFORMATION

#### **ATTACHMENT**

#### SUPPLEMENTAL INFORMATION

### PARTIAL LIST OF PERSONS CONTACTED

### Licensee

- D. R. Alps, Security Manager
- B. Bird, Plant Support Manager
- M. R. Blevins, Vice-President, Nuclear Operations
- M. D. Bozeman, Emergency Planning Manager
- J. B. Britt, Corporate Security Manager
- K. B. Britt, Compliance Security Coordinator
- S. Chakrabarti, Senior Engineer
- C. Cotton, Shift Manager
- R. Flores, Vice-President, Nuclear Operations
- P. A. Gunderson, Applications Support Manager
- B. D. Hammer, Corporate Security
- N. S. Harris, Principle Regulatory Affairs Technologist
- T. Hope, Regulatory Performance Manager
- F. L. Powers, Project Manager
- C. L. Terry, Senior Vice-President and Principal Nuclear Officer

# **NRC**

- G. Ahern, Intelligence Specialist
- J. Buchanan, Physical Security Inspector
- D. Powers, Senior Technical Advisor
- A. Sanchez, Resident Inspector

#### ITEMS OPENED

URI	50-445; 50-446/03-05-001	Failure to evaluate the impact of a waterborne threat (Section II.C.2).
URI	50-445; 50-446/03-05-002	Loss of microwave intrusion detection system zones (Section III.A.2).
URI	50-445; 50-446/03-05-003	Failure to harden a vital area structure (Section V.G.2).
URI	50-445; 50-446/03-05-004	Failure to evaluate the consequences of hazardous material transportation (Section VI.C.2).

### PARTIAL LIST OF DOCUMENTS REVIEWED

Letter CPSES-200200716, "Comanche Peak Steam Electric Station (CPSES) Docket Nos. 50-445 and 50-446, 20 Day Answer to NRC Order for Interim Safeguards and Security Compensatory Measures EA-02-026," dated March 18, 2002

Letter CPSES-200201936, "Comanche Peak Steam Electric Station (CPSES) Docket Nos. 50-445 and 50-446, Supplemental Response to NRC Order for Interim Safeguards and Security Compensatory Measures," dated May 16, 2002

Letter CPSES-200202442, "Comanche Peak Steam Electric Station (CPSES) Docket Nos. 50-445 and 50-446, Supplemental Response to NRC Order for Interim Safeguards and Security Compensatory Measures," dated June 20, 2002

Letter CPSES-200203021, "Comanche Peak Steam Electric Station (CPSES) Docket Nos. 50-445 and 50-446, Final Response to NRC Order for Interim Safeguards and Security Compensatory Measures," dated August 30, 2002

Letter CPSES-200301064, "Comanche Peak Steam Electric Station (CPSES) Docket Nos. 50-445 and 50-446, Response to Force-on-Force Pilot Open Items - Request for Additional Information," dated May 14, 2003

DOCUMENT CONTAINS
SAFEGUARDS INFORMATION