Mr. Waller mr. Coffing How close can

FLIGHT INFORMATION CENTER

ACTIVITY REPORT

BASE Udorn Date: 27 December 197
PILOT'S NAME Capt. E. Reid REPORTER'S NAME Capt. E. Reid
AIRCRAFT NO. XW-PFJ AIRCRAFT TYPE : 205
DATE/TIME OF ACTIVITY 26/12/70, 0825Z
AIRCRAFT LOCATION/COURSE TG 875 380
ALTITUDE (MSL) 5659 ft. (ABOVE TERRAIN) 10 ft.
A/C Hit X Near Miss Observed Fire/Flashes Heard Fire
ESTIMATE OF WEAPON LOCATION (COORDINATE):
Approximately 75 yards East of TG 875 388.
TYPE: Small Arms x Automatic Weapon AA Other
INTENSITY: Light X Moderate Heavy
DURATION OF FIRE 1 round.
PROBABLE CALIBER 7.62 mm.

REMARKS: (AIRCRAFT DAMAGE, EVASIVE ACTION, FLAK DESCRIPTION, TRACERS, TIME LAPSE BETWEEN FLASH & SOUND OF AAA, etc.)

XW-PFJ was in a 10 ft. hover over a friendly position at TG 675 380 delivering an external load when a single tracer bullet entered the cockpit through the right hand front window and struck the pilots seat. The pilot was not hit only because he was leaning over trying to observe something below the aircraft.

	· · /	' r/	ر ا
APPROVED FOR RELEASEDATE: /	- / /	41	
13-Mar-2009 4	//	//	/ (
	I	- 1	

DEBRIEFED BY R. H.

DISTRIBUTION:

VPFO - 1

BM OFF-BASE LIST -

BM -

FILE -

Western Union International, Inc.

NNNNOO2

MGDR WAS

TP1099 DECEMBER 28, 1970

BEC'D V. & DEC 28 1970

SUBJ UDORN INCIDENT REPORT

FOLLOWING RECEIVED:

+AAA TEN FOUR

BBB BELL 205 XW-PFJ

CCC TG 8838 LS15

DDD 0825Z 26 DECEMBER 1970

EEE PIC E/REID NONE X FM RS/CASIO NONE

FFF NONE

GGG MINOR X ONE HOLE THROUGH STRUCTURAL MEMBER OF CABIN AND OVERTEMP OF ENGINE TO 645 DEGREES CENTIGRADE

HHH B/D

III NOT A FACTOR

JJJ SMALL CALIBER PROJECTILE NARROWLY MISSED PILOT AND ENGINE
WAS OVERTEMPED DURING RAPID TAKE OFF FROM HELICOPTER
PAD. PROJECTILE CAUSED MINOR SKIN DAMAGE TO AIRCRAFT
AND PENETRATED A STRINGER PRIOR TO STRIKING ARMOUR SEAT.
AIRCRAFT RETURNED TO UTH FOR SHEET METAL WORK AND HOT
END INSPECTION. EXPECT RELEASE DECEMBER 27.

KKK P.C. GODDARD

LLL END SERIES+

BEVANS FOR PRES TPE

4 - 12/28/70