## U.S. Department of Labor

Mine Safety and Health Administration 1100 Wilson Boulevard Arlington, Virginia 22209-3939



February 23, 2009

MEMORANDUM FOR

MICHAEL A. DAVIS

Deputy Assistant Secretary for Operations Mine Safety and Health Administration

THROUGH:

CHARLES J. THOMAS

Director of Accountability

Mine Safety and Health Administration

FROM:

ARLIE A. WEBB (1). Shumae for Accountability Specialist

SUBJECT:

MSHA Office of Accountability Follow-Up Audit,

Hindman, Kentucky, Field Office, and

### Introduction

This memorandum summarizes the Office of Accountability follow-up audit of the subject field office and mine. Follow-up audit subjects included MSHA field activities, level of enforcement, Field Activity Reviews (FARs), Accompanied Activities (AAs), MSHA supervisory and managerial oversight, mine plans, Uniform Mine File (UMF), and the conditions and practices at the mine. The audit was conducted during the week by Arlie A. Webb, and Charles J. Thomas. District

6 managers and supervisors accompanying the audit team were

# Overview

The initial audit at this field office was conducted in April of 2009. Although that audit revealed several positive findings, there were also numerous issues that required corrective actions. The mine visit also revealed numerous issues requiring correction.

The follow-up audit revealed that issues documented during the first audit, including the level of enforcement, determination of gravity and negligence, documentation of FARs and AAs, and time usage, have been addressed. Likewise, the mine visit conducted during this follow-up audit revealed numerous improvements.

A highly commendable effort has been put forth by MSHA Coal District 6, and the resulting improvements in the safety and health of the miners is evident. Each area of concern from the initial report is addressed below. Those issues are addressed by this report.

# **Emergency Response Plan**

- 1. The emergency communication system was being maintained to meet plan requirements, and the visible warning light attached to the section mine phone operated properly.
- 2. The lifeline was being well-maintained, and there were no obstacles to impede passage of persons in the escapeways.

#### Enforcement and Resource Utilization

- 1. The term "unknown" was not found in any support documentation for citations and orders during a review of the two most recent E01 inspection reports.
- 2. The following time distribution figures represent the improvements made regarding inspector time distribution during E01 events at this field office:

Time Category	Initial Audit	Follow-up Audit
Travel	10% of total	8% of total
MMU	15% of total	23% of total
Outby	27% of total	38% of total
Surface	27% of total	13% of total
On site Citation Writing	3% of total	7% of total
Off site Citation Writing	1% of total	0% of total
Other	17% of total	11% of total
Total Inspection Time	100%	100%

- 3. The event calendar, time and activity records, inspection notes, and IPAL documentation were all in agreement regarding the number of days, day of the week, and shifts worked during inspection activities.
- 4. 103(i) Spot inspections (E02) were being conducted at irregular intervals and within the time frames established by MSHA policy.

5. At the time of the follow-up audit, the Hindman field office was composed of one supervisor and 13 inspectors. Nine of these inspectors received their AR cards in 2008.

### Mine Visit

A total of 12 citations were issued during this follow-up audit compared to 26 citations issued during the initial audit. The most notable reductions in violations were as follows:

Subject Area	Citations Issued	Citations Issued
Subject Area	On Initial Audit	On Follow-Up Audit
Accumulations in belt entries	4	2
Electrical	4	0
Ventilation	3	1
Haulage and Clearance	3	0

The overall conditions, practices, and attitude toward safety observed during the mine visit improved dramatically.

# MSHA Supervisory/Management Oversight

A comparison of in-mine conditions and practices, Field Activity Reviews, Second Level
Reviews, and Peer Review results indicate that MSHA supervision at the
level was not adequate. Issues related to the
level of enforcement and consistency of inspection activities were not always being
addressed, and there was not sufficient follow up on corrective action plans relative to
Peer Review results. This is evidenced by the continuing recurrence of identical issues
for three consecutive years of Peer Reviews.

The District Manager has instituted an "Enhanced Work-Product Review" process within the district. Review teams are composed of the

and other personnel if needed. Reviews conducted to date cover the following areas:

- a. Inspection events
- b. Citations, orders, and safeguards
- c. Level of enforcement
- d. Inspection documentation
- e. Comparison of approved plans to mine conditions
- f. Inspector time distribution
- g. Supervisory oversight

At the conclusion of each review, the discusses the team's findings with the field and a set of corrective actions and time lines are established. As of the date of this follow-up audit, there have been two Enhanced Work-Product Reviews conducted in District 6.

## Uniform Mine File

The UMF books were up to date and contained all applicable plans.

- 1. Inspector certification and supervisory reviews sheets were up to date.
- 2. Obsolete or outdated materials had been removed from the files.

Neither the Uniform Mine File Retention Schedules (MSHA Forms 2000-166 and 2000-167), nor the Uniform Mine File Handbook have been revised at this time. However, the district does not have the authority to correct either of these issues.

## Digitizing of Mine Plans

District 6 has completed the first phase of digitizing approved mine plans for mines within the district. Space has been set aside on the district's "T:/drive," with plans located in folders arranged by mine ID number. These folders are available to all inspection personnel within the district. Inspectors are encouraged to copy the appropriate folders to their laptop computers prior to traveling to the mine, so they will have instant access to them during the inspection process.

The second phase of the project will involve digitizing all approved mine maps into the appropriate folders. The district has requested additional hard drive space on their T:/drive for this purpose.

#### **Attachments**

A. Citations issued during follow-up audit

a.	75.400
b.	75.211(d)
c.	75.400
d.	75.1100-2(b)
e.	75.400
f.	75.202(a)
g.	75.202(a)
h.	75.1502
i.	75.400
j.	75.372(b)(9)
_	, , , ,

k. 75.1722(a) 1. 75.1502


Mine Citation/Order	U.S. Department of Labo Mine Safety and Health Ad	
Section (-Violation Data		
1. Date 12 Time /24 Hr Clock)	3	Citation/ Order Number
A. Sanged T	f Ocerative	
	<u>'</u>	
-	]1	(Contractor)
AND THE PROPERTY OF THE PROPER	تنبي ونكستني إسبوتها	8a. Written Notice (103g)
Located on the 001 MMU in the coal has been allowed to accumulate. R depth. (1) Starting in #1 entry at the feet inby to the face area. (2) Starti foot into the 2 left crosscut to the #	anging from 1 inc last open crossong in the # 2 ent	h to 12 inches in out and extending for 80
		See Continuation Form (MSHA Form 7000-3a)
	Part/Section of	
Safety of Act Other	Fittle 30 CFR	75.400
Section II- inspector's Evaluation		<u>a de la Participa de la Parti</u>
10. Gravity:	±	AND THE PROPERTY OF THE PROPER
A. Injury of Illness (has) (ls): No Likelihood Unlikely 🗸  B. Injury of Illness could rea-	Reasonably Likely [ ] Hig	hly Likely Cocurred
sonably be expected to be: No Lost Workdays Lost Work	lays Or Restricted Duty 📝 💮 F	Permanently Disabiling 🔲 💮 Fatal 🗌
C. Significant and Substantial: Yes No 🗹	D. 1	Number of Persons Affected: 010
11. Negligence (check one) A. None B. Low C. N	loderate 🗹 D. High 🗌	E. Reckless Disregard []
12. Type of Action 104(a) 13. Type of Issuance	e (check one) Citation 🗹 O	rder Safeguard Written Notice
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ Order Number	F. Dated Mo Da Yr
15. Area or Equipment	<u>, , , , , , , , , , , , , , , , , , , </u>	
		and the second s
16. Termination Due A. Date B. Time (24 Hr. Clock)		
Section III-Termination Action		
17. Action to Terminate The affected area has	been clean and r	ock dusted.
18. Terminated A, Date Mo Da Yr B. Time (24 Hr. Clock		
the standard and the standard of the standard		
Section IV-Automated Syste  19. Type of Inspection   20. Event Number	21. Primary or Mill	
(activity code) E01	- 17 / (III) - 17 / (III)	
22. Signature		23. AR Number
MSHA Form 700  Is of the Small  setablished a National Small Business and Agriculture Requisitory Cribudemen and 10 Re  enforcement actions. The Ombudsman and rule  enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write t Street, SW, MC 2120, Washington, DC 20416. Please note, however, that your right to  the right to contest cliations and proposed penalties and obtain a hearing before the Feder	agional Falmess Boards to receive com- es each agency's responsiveness to sm he Ombudsman at Small Business Adm le a comment with the Ombudeman is in	n addition to any other rights you may have, including

Mine Citation/Order Section I-Violetion Date	U.S. Department of Labor Mine Safety and Health Administra	ation
1. Date 17 Time (2) Us Circle)	3. Citation/	
4. Served To	Order Nu	mber
		<del></del>
·		(Contractor)
A bar for taking down loose mat	erial shall be availab	6a. Written Notice (103g)
place or on all face equipment for tak length and design that will allow the	ing down loose materia	l shall be of a
position that will not expose the pers		
falling material.  The Fletcher roof bolter located	on the left side of th	e 001 MMU was not
provided with a slate bar to take down		
9. Violation A. Health B. Section C.	See Con Part/Section of	tinuation Form (MSHA Form 7000-3a)
	Title 30 CFR 75.2	11(d)
Section IIInspector's Evaluation 10, Gravity:		
A. Injury or Iliness (has) (is): No Likelihood Unlikely 🗹	Reasonably Likely Highly Likely	Occurred
B. Injury or illness could reasonably be expected to be: No Lost Workdays Lost Workdays Lost Workdays	lays Or Restricted Duty 📝 Permanent	ly Disabling [] Fatal [
C. Significant and Substantial: Yes ☐ No 🗹	D. Number of	Persons Affected: 002
11. Negligence (check one) A. None B. Low C. M.	oderate 🗹 D. High 🗌 E	Reckless Disregard
12. Type of Action 104(a) 13. Type of issuence	(check one) Citation 🗸 Order 📋	Safeguard Written Notice
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ Order Number	F. Dated Mo Da Yr
15. Area or Equipment		
16. Termination Due		<del>.                                    </del>
A. Date  B. Time (24 Hr. Clock)  Section IIITermination Action		ing fire the second of the sec
	ided for the left side	roof bolter.
18: Terminated A. Date Mo Da Yr B. Time (24 Hr. Clock		And the Control of th
Section IV—Automated System Data		
Section IV-Automated System Data  19. Type of Inspection (arth/fix code)  20. Event Number	21. Primary or Mill	
		Number
19. Type of Inspection (activity code) E01 20. Event Number 22. Signature	23. AR	- المنافع المن
19. Type of Inspection (activity code) E01 20. Event Number 22. Signature	23. AR  Wisiness Regulatory Enforcement Fairness Act of 1 glional Fairness Boards to receive comments from is each agency's responsiveness to small business	996, the Small Business Administration has small businesses about federal agency . If you wish to comment on the


Mine Citation/Order	U.S. Department of Labor Mine Safety and Health Administration
Section IViolation Data	
1. Date	3. Citation/ Order Number
4. Served To	Order Hamilton
0.00-110-10-10-10-10-10-10-10-10-10-10-10-	(Contractor)
8. Condition or Practice	8a. Written Notice (103g) and drive, accumulation of gray and black
float coal dust was present on the fr	esh water line, tail piece, mine flooring in depth from paper thin to 3/8 of a
	•
	See Continuation Form (MSHA Form 7000-3a)
9. Violation A. Health B. Section of Act	C. Part/Section of Title 30 CFR 75,400
Section II-Inspector's Evaluation	
10. Gravity: A. Injury or Illness (has) (is): No Likelihood Unlikely	Reasonably Likely Highly Likely Occurred [
B. Injury of illness could rea-	rkdays Or Restricted Duty 📝 Permanently Disabling 🗋 💮 Fatal 📋
C. Significant and Substantial: Yes ☐ No. ✔	D. Number of Persons Affected: 001
11. Negligence (check one) A, None B, Low C	Moderate ☑ D. High ☐ E. Reckless Disregard ☐
12. Type of Action 104(a) 13. Type of Issua	nce (check one) Citation 📝 Order 📋 Safeguard 🗌 Written Notice 🗍
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ Order Number
15. Area or Equipment	
16. Termination Due A. Date B. Time (24 Hr. Clock	0)
Section III- Termination Action	
17. Action to Terminate	
18. Terminated A. Date Mo Da Yr B. Time (24 Hr. Clock	······································
Section IVAutomated System Data	
19. Type of inspection   20. Event Number	21. Primary or Mill
(activity code) E01	20 1510
22, Signature (	23. AR Number

MSHA Form 7000-3. Apr 08 (revised) In accompanios with upoper visions of the Small Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about tederal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to conteat citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

Mine Citation/Order	U.S. Department of Labor Mine Safety and Health Administration
Section I-Violation Data	
1. Date Mo Da Yr 2. Time (24 Hr. Clock)	3. Citation/ Order Number
4. Served To	Older (dalling)
	AND USE OF THE STATE OF THE STA
And the second s	(Contractor)
parallel to the entire length of belt firehose outlets with valves at 300-f and at tailpieces. At least 500 feet connection with each belt conveyor wa strategic locations along the belt co Located on the 3 west # 1 head d	
	See Continuation Form (MSHA Form 7000-3a)
9. Violation A. Health B. Section of Act Other:	C. Part/Section of Title 30 CFR 75.1100-2(b)
Section IIInspector's Evaluation	
10. Gravity: A. Injury or Illness (has) (is): No Likelihood ☐ Unlikely ✔	Brancopality (Boly   High), (Bigh), (Bigh)
B. Injury or illness could rea-	Reasonably Likely Highly Likely Occurred
company we expected to be:	rkdays Or Restricted Duty 🕢 Permanently Disabling 🗌 Fatal 🗌
C. Significant and Substantial: Yes No 🗹	D. Number of Persons Affected: 002
11. Negligence (check one) A. None B. Low C.	Moderate ☑ D. High ☐ E. Reckless Disregard ☐
12. Type of Action 104(a) 13. Type of Issuar	nce (check one) Citation 🗹 Order 🗌 Safeguard 🗌 Written Notice 📋
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ Order Number
15. Area or Equipment	
16. Termination Due A. Date Mo Da Yr B. Time (24 Hr. Clock	
Section III-Termination Action  17. Action to Terminate Another 100 foot o	f fire fighting hose was provided for
the 3 west # 1 head drive.	I Tite Tighting hose was provided for
18. Terminated A. Date B. Time (24 Hr. Clock	
Section NAutomated System Data	
19. Type of Inspection (activity code) E01 20. Event Number	21. Primary or Mill
22. Signature	23. AR Number
established a National Small Business and Agriculture Bégulatory Ombudaman and 10 enforcement actions. The Ombudaman annually evaluates enforcement activities and renforcement actions of MSHA; you may call 1-888-REG-FAIR (1-888-73-4-3247), or writ	te the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd office a comment with the Ombudsman is in addition to any other rights you may have, including



Mine Citation/Order	U.S. Department of Labor Mine Safety and Health Administration
Section IViolation Data	
1. Date 2. Time (24 Hr Clock)	3. Citation/ Order Number
	5 Operator
	A Section of the sect
· · · · · · · · · · · · · · · · · · ·	(Contractor) 8a. Written Notice (1039)
The roof, face and ribs of area	s where persons work or travel shall be
supported or otherwise controlled to p	protect persons from hazards related to
falls of the roof.	
	of the 004 MMU at crosscut # 2 survey
spad 456 has 2 bearing plates that slo sheared at the same area. Exposing a a	oughing has occurred and 1 bearing plate
length of un-supported mine roof.	irea of 96 inches wide by 108 inches
rengen of an supported withe root.	
	•
	See Continuation Form (MS) IA Form 7000-3a)
9 Violation A. Health B. Section C.	Part/Section of
Safety 🗸 of Act	Title 30 CFR 75.202(a)
Other Section II-inspectors Evaluation	
10. Gravity:	
A Injury or Illness (has) (is): No Likelihood Unlikely 🗹	Reasonably Likely Highly Likely Occurred
B. Injury or illness could rea- sonably be expected to be: No Lost Workdays : Lost Work	days Or Restricted Duty 🗸 Permanently Disabling 🗍 Fatal 🗍
C, Significant and Substantial: Yes ☐ No 📝	D. Number of Persons Affected: 001
11. Negligence (check one) A. None B. Low C. N	Moderate ☑ D. High ☐ E. Reckless Disregard ☐
12. Type of Action 104(a) 13. Type of Issuance	æ (check one) Citation 📝 Order 🗍 Safeguard 🗍 Written Notice 🗍
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ F. Dated Mo Da Yr Order Number
15. Area or Equipment	
16. Termination Due A. Date Mo Da Yr B. Time (24 Hr. Clock)	
Section III-Termination Action  17. Action to Terminate The operator tram a r	est between the the establish than and
installed permanent roof support.	oof bolter to the affected area and
ruscarred bermaneur root subbott.	
18. Terminated A. Date Mo Da Yr B. Time (24 Hr. Clock	
Section IV-Automated System Data	
19, Type of Inspection 20. Event Number	21. Primary or Mill
(activity code) E02	
22. Signature	23. AR Number
	Business Regulatory Enforcement Fairness Act of 1996, the Small Business Administration has
established a Number of the Combudsman and 10 F enforcement actions. The Ombudsman and range all all all all all all all all all al	tegional Fairness Boards to receive comments from small businesses about federal agency tes each agency's responsiveness to small business. If you wish to comment on the
enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write	the Ombudeman at Small Business Administration, Office of the National Ombudeman, 409 and file a comment with the Ombudeman is in addition to any other rights you may have, including
the right to contest citations and proposed penalties and obtain a hearing before the Fede	



The approved roof control plan for the 004 MMU is not being complied with. Located in the face area of the # 1 entry. Spacing between 2 permanent rows of roof support measured 52 inches to 56 inches in wide.


					See Cont	nuation Form (MSH	A Form 7000-3a)
9. Violation A. Health Safety Other	of Act		Part/Section of file 30 CFR		75.20	02(a)	
Section IIInspector's Evalua	tion		<del> </del>				
10. Gravity:	and the second s						
A. Injury or Illness (ha	Name of the last o	Unlikely	Reasonably L	ikely 🗸	Highly Likely	Occur	red 🗀
<ul> <li>B. Injury or illness cou sonably be expecte</li> </ul>		ys 🗌 🛮 Lost Workd	ays Or Restrict	ed Duty 🕢	Permanenti	y Disabling 🔲	Fetal 🗍
C. Significant and Sub	stantial: Yes 🗸	No:			D. Number of	Persons Affected	001
11. Negligence (check or	e) A. None	B. Low C. M	oderate 📝	D. High	□ E,	Reckless Disreg	ard 🗌
12. Type of Action 10	4(a)	13. Type of Issuance	(check one)	Citation 🗸	Order 🗍	Safeguard [	Written Notice
14. Initial Action A. Citation [] B. Ord	er C. Safeguard [	D. Written Notice	E. Citation/ Order Num	ber		F. Dated	Mo Da Yr
15. Area or Equipment  16. Termination Due	-M-Da-Ve-						
		B. Time (24 Hr. Clock)	n				
Section IIITermination Actio				· · · · · · · · · · · · · · · · · · ·	dentina 16 company		
17. Action to Terminate  18. Terminated A. Date Section IVAutomated Syste	Mo Da Yr	L roof suppo:	rt was i	nstalle	d to th	e affecte	d area.
19. Type of Inspection	20. Event Number	4 - <u>1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - </u>	21. Pri	mary or Mill	<del></del>	<del></del>	····
(activity <u>code)</u>	E02			.,,,			
22. Signatu			. <del> انسست.</del>		23, AR I	Number	
enforcement actions of MSHA Street, SW MC 2120, Wash	nbudsman innually evaluates en , you may call 1-888-REG-FAIR ington, DC 20418. Please note, nd proposed penalties and obtain	(1-888-734-3247), or write ti however, that your right to fil	gional Fairness B is each agency's i ne Ombudsman a e a comment with	cards to receive responsiveness t t Small Business the Ombudama	comments from a o small business. Administration, o n is in addition to	mall businesses ab If you wish to comr Office of the Nations	out federal agency nent on the Combudaman, 409 3rd

Attachment A - Citations Issued During Follow-Up Audit

Mine Citation/Order		U.S. Department of Mine Safety and He		
Section IViolation Data				
1. Date Mo Da Yr 2. Time (24 Hr. C	Clock)		3. Citation/ Order Number	
		le Automotive	100	
	· · · · · · · · · · · · · · · · · · ·			
				(Contracto
8. Condition or Practice  The Carbon Monoxide Mor	1 E - 7 - 8 - 1	6 6		Written Notice (103g)
Evacuation and Fire Fighti down wind of a belt drive west 2 conveyor tail pulle pulley and the 001 section belt fire which exposes peloose coal and coal fines of the 001 section belt ex	ng Plan which or tail pull by. The sensor belt drive. ersons to fir in contact w	th requires the ey is not compored to the condition of the ey of the condition of the ey of the	at the CO sens plied with at 30 ft. upwind ion can delay azards. Accumu	or be locate the number 3 of the tail detecting a lations of
			See Continuation For	m (MSHA Form 7000-3a)
9. Violation A. Health B. Section Safety V of Act		Part/Section of Title 30 GFR	75.1502	
Section II-Inspector's Evaluation				
10. Gravity: A. Injury or Illness (has) (is): No Likelihood	Unlikely 🗍	Reasonably Likely	Highly Likely	Occurred []
B. Injury or illness could rea- sonably be expected to be: No Lost Workd	lays Lost Work	days Or Restricted Duty	Permanently Disabling	Fatal 🗍
C. Significant and Substantial: Yes	No []		D. Number of Persons A	ffected: 002
11. Negligence (check one) A. None		loderate 🔽 D. Hig	h 📗 E. Reckless	Disregard [
12. Type of Action 104(a)	13. Type of Issuano	e (check one) Citation	Order Safeguar	d Written Notice
4. Initial Action A. Citation B. Order C. Safeguard	D. Written Notice	E. Citation/ Order Number	F. D.	ated Mo Da Yr
15. Area or Equipment			<u> جي پورځاده معمند په پې د پښتون کې د </u>	<u> </u>
Commence of company of the commence of the com				
6. Termination Due A. Date Mo Da Yr	B. Time (24 Hr. Clock)	. [ ]		V
Section IIITermination Action				
7. Action to Terminate The sensor : the belt drive.	is moved 15	ft. down wind	of the tail pu	ılley and
8. Terminated A. Date MoDa Yr B. Time	(24 Hr. Clock			(Sec. 10. 10. 10. 10. 10. 10. 10. 10. 10. 10
ection IVAutomated System Data		i i managaran ang ang ang ang ang ang ang ang ang a		
9. Type of Inspection 20. Event Number (activity code		21. Primary or Mill		
2. Signature	<del></del>		23. AR Number	
ISHA Form 7000- stablished a National Small Business and Agriculture Regula nforcement actions. The Orribudsman annually evaluates en inforcement actions of MSHA, you may call 1-888-REG-FAIR treet, SW MC 2120, Washington, DC 20416. Please note,	tory Ombudsman and 10 Re forcement activities and rate (1-885-734-3247), or write to	gional Falmess Boards to receive s each agency's responsiveness se Ombudsman at Small Busine	s to small business; If you wish t se Administration, Office of the I	ses about federal agency o comment on the lational Ombudsman, 409 3

Mine Citation/Order	U.S. Department of Mine Safety and He	TOTAL CONT. N. C
Section I-Violation Data		
1. Date Mo Da Yr 2. Time (24 Hr.	Clock	3. Citation/ Order Number
A Served To	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	
	<u>C</u>	
	7	(Contractor)
	The second secon	Written Notice (103g)
frame of the 001 section hp 575 volt electric drive which is fire resistant befines and belt drippings accumulations 10 inches desensor in this area is localized.		in contact with the 2 150 section of conveyor belt p of the motors with coal tors are air cooled and the impair the cooling. The CO could not be detected.
		\$
		See Confinuation Form (MSHA Form 7000-3a)
9. Violation A. Health B. Section of Act Other	C. Part/Section of Title 30 CFR	75.400
Section II-Inspector's Evaluation		
10. Gravity:  A. Injury or Illness (has) (is): No Likelihood	Unlikely Reasonably Likely	Highly Elkely Occurred
B. Injury or illness could rea-		
sonably be expected to be: No Lost Work		To 30 11 150 100 100
C. Significant and Substantial: Yes 🗸	No []	D. Number of Persons Affected: 007
11. Negligence (check one) A. None	B. Low D. Hig	h E. Reckless Disregard
12. Type of Action 104(a)	13. Type of Issuance (check one) Citation	Order Safeguard Written Notice
14. Initial Action A. Citation B. Order C. Safeguard	D. Written Notice	R. Dated Mo Da Yr
15. Area or Equipment		
		te.
A. Date Mo Da Yr	B. Time (24 Hr. Clock)	
Section III—Termination Action		
17. Action to Terminate The accumulat	ions are removed from the	belt drive.
18. Terminated A. Date MoDa Yr B. Time	e (24 Hr. Clock	
Section IV-Automated System Data		the spine of the s
9. Type of Inspection 20. Event Numbe (activity code)	21. Primary or Mill	<u></u>
2. Signature		23. AR Number
inforcement actions. The Ombudsman annually evaluates e inforcement actions of MSHA, you may call 1-888-REG-FAIF Street, SW MC 2120, Washington, DC 20416. Please note	atory Ombudsman and 10 Regional Fairness Boards to recei- nforcement activities and rates each agency's responsivenes	s to small business. If you wish to comment on the ess Administration, Office of the National Ombudsman, 409 Srd nan is in addition to any other rights you may have, including

Mine Citation/Order



Mine Citation/Order	U.S. Department of Labor Mine Safety and Health Administration
Section I-Violation Data	
1. Date	3. Citation/ Order Number
	(Contractor)
8. Condition or Practice	oa. Written Notice (103g)
installed on the 001 belt drive to pr frame of the drive. The roller is loc 5 ft. opening under the top belt wher the rotating roller. The mine floor i	persons can fall over and into the pinch
6 White IA Units II In Coales	See Continuation Form (MSHA Form 7000-3a)
Safety   Other  Other	Part/Section of Title 30 CFR 75.1722(a)
Section II-Inspector's Evaluation  10. Gravity:	
A. Injury or Illness (has) (is): No Likelihood Unlikely	Reasonably Likely Highly Likely Occurred
B. Injury or illness could reasonably be expected to be: No Lost Workdays Lost Workdays Lost Workdays	kdays Or Restricted Duty 🕢 Permanently Disabiling 🗌 Fatal 🗌
C. Significant and Substantial: Yes   ✓ No   ✓	D. Number of Persons Affected: 001
11. Negligence (check one) A. None B. Low C.	Moderate ☑ D. High ☐ E. Reckless Disregard ☐
12. Type of Action 104(a) 13. Type of Issuani	ce (check one) Citation 🗹 Order 🗌 Safeguard 🗌 Written Notice
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ F. Dated Mo Da Yr
15. Area or Equipment	
6. Termination Due A. Date	
Section IIITermination Action	
17. Action to Terminate An adequate guard is in	stalled to prevent contact by persons.
8. Terminated A. Date Time (24 Hr. Clock	

MSHA Form 7000-3,

e provisions of the Small Business Regulatory Enforcement Fairness Act of 1998, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal egency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may cell 1-888-REG-FAIR (1-888-734-2347), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20416. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contest citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.

21, Primary or Mill

23. AR Number

Attachment A - Citations Issued During Follow-Up Audit

19. Type of Inspection (activity code)

22. Signature

E01

Mine Citation/Order	U.S. Department of Labor Mine Safety and Health Administration
Section I-Violation Data	
1. Date	3. Citation/ Order Number
4. Served T	
	****
	(Contractor)
8. Condition or Practice	8a, Written Notice (103g)
The Carbon Monoxide Monitoring Syste	em of Operation section of the Approved
Mine Emergency Evacuation and Fire Figl	
air velocity in conveyor belt entries	
co monitoring systems are used is not o	complied with. Beginning 60 ft. inby
the 2 west belt drive and extending 280	00 ft. inby in the 3 west 1 belt entry
the air flow can not be measured with a	
can delay fire detection exposing person	ons to fire and smoke hazards.
	See Continuation Form (MSHA Form 7000-3a)
	Part/Section of title 30 CFR 75.1502
Section II-Inspector's Evaluation	
10. Gravity:	
A. injury or Illness (has) (is): No Likelihood Unlikely	Reasonably Likely Highly Likely Occurred
B. Injury or illness could rea- sonably be expected to be: No Lost Workdays \( \subseteq \text{Lost Workdays} \)	ays Or Restricted Duty 📝 Permanently Disabling 🗍 Fatal 🗍
C. Significant and Substantial: Yes ☐ No ☑	D. Number of Persons Affected: 007
11. Negligence (check one) A. None B. Low C. Mc	oderate 🗹 D. High 🗌 E. Reckless Disregard 🗍
12. Type of Action 104(a) 13. Type of Issuance	(check one) Citation 🗹 Order 🗌 Safeguard 🗍 Written Notice 🗍
14. Initial Action A. Citation B. Order C. Safeguard D. Written Notice	E. Citation/ Order Number  F. Dated Mo Da Yr
15. Area or Equipment	
16. Termination Due A. Date Mo. De Yr B. Time (24 Hr. Clock)	
Section III-Termination Action	
17. Action to Terminate	
18. Terminated A. Date Mo Da Yr B. Time (24 Hr. Clock	
Section IVAutomated System Data	
19. Type of Inspection (activity code) 20. Event Number	21. Primacy or Mill
22. Signature	23. AR Number

MSHA Form 7000-3.

rovisions of the Small Business Regulatory Enforcement Falmess Act of 1996, the Small Business Administration has established a National Small Business and Agriculture Regulatory Ombudsman and 10 Regional Fairness Boards to receive comments from small businesses about federal agency enforcement actions. The Ombudsman annually evaluates enforcement activities and rates each agency's responsiveness to small business. If you wish to comment on the enforcement actions of MSHA, you may call 1-888-REG-FAIR (1-888-734-3247), or write the Ombudsman at Small Business Administration, Office of the National Ombudsman, 409 3rd Street, SW MC 2120, Washington, DC 20418. Please note, however, that your right to file a comment with the Ombudsman is in addition to any other rights you may have, including the right to contast citations and proposed penalties and obtain a hearing before the Federal Mine Safety and Health Review Commission.