

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 28

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 28

Facility Name: Beaver Valley 1 Docket (050- 00334)

Details	Department	Work Type	Docket/Report
Procedures & Reference Document / IR			
111 - Procedure / reference document technical content	D - Emergency Planning	Q - Fire Protection	050-00334/2006-008
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Problem Identification & Resolution / IR			
142 - Operating experience (OE) review LTA	I - Instrumentation & Control	T - Testing	050-00334/2006-002
146 - Evaluation LTA	G - Engineering	G - Design	050-00334/2006-004
146 - Evaluation LTA	G - Engineering	G - Design	050-00334/2006-004
148 - Action not yet started or untimely	I - Instrumentation & Control	T - Testing	050-00334/2006-002
150 - Programmatic deficiency	D - Emergency Planning	D - Emergency Drill	050-00334/2006-009
150 - Programmatic deficiency	H - Health Physics	H - Health Physics	050-00334/2006-009
150 - Programmatic deficiency	I - Instrumentation & Control	T - Testing	050-00334/2006-002
Number of Items for this Docket: 7			
Percent of Total for this Docket: 25			
Work Planning & Practices / IR			
185 - Procedural adherence LTA	D - Emergency Planning	Q - Fire Protection	050-00334/2006-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2006-002
185 - Procedural adherence LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2006-004
187 - Action implementation LTA	G - Engineering	F - Modification	050-00334/2006-004
187 - Action implementation LTA	G - Engineering	G - Design	050-00334/2006-003
187 - Action implementation LTA	H - Health Physics	H - Health Physics	050-00334/2006-003
189 - Recognition of adverse condition / questioning attitude LTA	M - Mechanical	M - Maintenance / Repair	050-00334/2006-002
Number of Items for this Docket: 7			
Percent of Total for this Docket: 25			
Oversight / LER			
130 - Inadequate supervision / command and control	O - Operations	A - Administrative	050-00334/2006-003-00
130 - Inadequate supervision / command and control	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00334/2006-003-00
Number of Items for this Docket: 2			
Percent of Total for this Docket: 7			
Procedures & Reference Document / LER			
111 - Procedure / reference document technical content	O - Operations	O - Control Room Ops	050-00334/2006-005-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			

**U.S. Nuclear Regulatory Commission
Human Factors Information System (HFIS)
IR/LER Category Analysis by Docket Report**

Total Number of Hits: 28

National Average: 43

2x National Average: 86

National Median: 24

Average for Selected Dockets: 28

Facility Name: Beaver Valley 1 Docket (050- 00334)

Details	Department	Work Type	Docket/Report
Training / LER			
100 - Training LTA	O - Operations	O - Control Room Ops	050-00334/2006-005-00
Number of Items for this Docket: 1			
Percent of Total for this Docket: 4			
Work Planning & Practices / LER			
182 - Work package quality LTA	O - Operations	B - Bal of Plant Ops	050-00334/2006-003-00
183 - Pre-job activities LTA	O - Operations	B - Bal of Plant Ops	050-00334/2006-003-00
187 - Action implementation LTA	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00334/2006-003-00
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	A - Administrative	050-00334/2006-003-00
189 - Recognition of adverse condition / questioning attitude LTA	O - Operations	O - Control Room Ops	050-00334/2006-005-00
189 - Recognition of adverse condition / questioning attitude LTA	P - Procedure Writers	P - Procedure Dev	050-00334/2006-005-00
196 - Independent verification / plant tours LTA	O - Operations	A - Administrative	050-00334/2006-003-00
196 - Independent verification / plant tours LTA	P - Procedure Writers	P - Procedure Dev	050-00334/2006-005-00
196 - Independent verification / plant tours LTA	W - Work Control / Scheduling Outage Pla	A - Administrative	050-00334/2006-003-00
Number of Items for this Docket: 9			
Percent of Total for this Docket: 32			
Total Items for this Docket: 28			
