Page No. B-1 of 93 Wyle Test Report No. T58650.01-01

APPENDIX B

PHOTOGRAPHS

Page No. B-2 of 93 Wyle Test Report No. T58650.01-01



Page No. B-3 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 1 OVO S/N UNI000036 Accuracy Test – 1

Page No. B-4 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 2 OVO S/N UN000044 Accuracy Test – 2

Page No. B-5 of 93 Wyle Test Report No. T58650.01-01

ELECTROMAGNETIC RADIATION ANALYSIS PHOTOGRAPHS

Page No. B-6 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 3 OVI S/n UNI150012 Electromagnetic Radiation FCC -1

Page No. B-7 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 4 Electromagnetic Radiation FCC -2

Page No. B-8 of 93 Wyle Test Report No. T58650.01-01

SYSTEM INTEGRATION PHOTOGRAPHS

Page No. B-9 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 5 OVI S/N UNI150037, Firmware Ver: 1.1 System Integration Test -1


Page No. B-10 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 6 OpenElect Voting System 1.1 OVO S/N UNI000029 Firmware Ver: 1.1



Photograph No. 7 OVO S/N UNI000044, Firmware Ver: 1.1 System Integration Test – 2




Photograph No. 8 OVI S/N UNI150012, Firmware Ver: 1.1 System Integration Test

Page No. B-13 of 93 Wyle Test Report No. T58650.01-01

CONDUCTED RF IMMUNITY PHOTOGRAPHS

Page No. B-14 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 9 OVI S/N UNI150022 Conducted RF Immunity -1


Page No. B-15 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 10 OVI S/N UN150012 Conducted RF Immunity – 2


Page No. B-16 of 93 Wyle Test Report No. T58650.01-01 **ELECTROMAGNETIC RADIATION ANALYSIS PHOTOGRAPHS**

Page No. B-17 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 11 Electromagnetic Radiation Analysis – 1

Page No. B-18 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 12 Electromagnetic Radiation Anaylsis – 2

Page No. B-19 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 13 Electromagnetic Radiation Analysis - 3



Photograph No. 14 Electromagnetic Radiation Analysis – 4


Page No. B-21 of 93 Wyle Test Report No. T58650.01-01

ELECTROMAGNETIC SUSCEPTIBILITY PHOTOGRAPHS	




Photograph No. 15 Electromagnetic Susceptibility - 1

Page No. B-23 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 16 Electromagnetic Susceptibility - 2

Page No. B-24 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 17 Electromagnetic Susceptibility - 3

Page No. B-25 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 18 Electromagnetic Susceptibility – 4

Page No. B-26 of 93 Wyle Test Report No. T58650.01-01


ESD PHOTOGRAPHS

Page No. B-27 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 19 ESD-1

Page No. B-28 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 20 ESD-2

Page No. B-29 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 21 ESD-3

Page No. B-30 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 22 ESD-4

Page No. B-31 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 23 ESD-5

Page No. B-32 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 24 ESD-5

Page No. B-33 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 25 ESD-6

Page No. B-34 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 26 ESD-7

Page No. B-35 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 27 ESD-8

Page No. B-36 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 28 ESD-9

Page No. B-37 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 29 ESD-10

Page No. B-38 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 30 ESD-11

Page No. B-39 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 31 ESD-12

Page No. B-40 of 93 Wyle Test Report No. T58650.01-01 PHYSICAL CONFIGURATION AUDIT PHOTOGRAPHS



Photograph No. 32 Ballot Box – Plastic S/N BB-T58650-01




Photograph No. 33 OVO S/N UNI000039 – Hard Drive

Page No. B-43 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 34 OVO S/N UNI000039 – Compact Flash

Page No. B-44 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 35 OVO S/N UNI000039 - RAM

Page No. B-45 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 36 OVO S/N UNI000039 - Motherboard

Page No. B-46 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 37 OVO S/N UNI000039 -Scanner

Page No. B-47 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 38 OpenElect Voting System 1.1 OVO S/N UNI000039

Page No. B-48 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 39 OpenElect Voting System 1.1 OVO S/N UNI000039

Page No. B-49 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 40 OpenElect Voting System 1.1 Minuteman UPS P: ETR1600; SN: AES80906PA10




Photograph No. 41 OVI S/N UNI150012 – Hard Drive

Page No. B-51 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 42 OVI S/N UN150012 – 15" LCD Touchscreen

Page No. B-52 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 43 OVI S/N UNI150012 15" LCD Touchscreen

Page No. B-53 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 44 OVI S/N UN150012 15" LCD Touchscreen

Page No. B-54 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 45 OVI S/N UNI150012 AC Adapter for LCD Touchscreen

Page No. B-55 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 46 OVI S/N UNI150012 - RAM

Page No. B-56 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 47 OVI S/N UNI150012 - Motherboard

Page No. B-57 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 48 OpenElect Voting System 1.1 OVI S/N UNI150012

Page No. B-58 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 49 OpenElect Voting System 1.1 OVI S/N UNI150012



Photograph No. 50 OVO S/N UNI000044 – Hard Drive

Page No. B-60 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 51 OVO S/N UNI000029 Seasonic Power Adapter




Photograph No. 52 OVO S/N UNI000029 – Hard Drive

Page No. B-62 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 53 OVO S/N UNI000044 - Scanner

Page No. B-63 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 54 OVO S/N UNI000044 - Motherboard

Page No. B-64 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 55 OVO S/N UNI000044 - RAM

Page No. B-65 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 56 OVO S/N UNI000044 – Compact Flash

Page No. B-66 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 57 OpenElect Voting System 1.1 OVO S/N UNI000044

Page No. B-67 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 58 OpenElect Voting System 1.1 OVO S/N UNI000029

Page No. B-68 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 59 OVO S/N UNI000029 - Scanner

Page No. B-69 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 60 OVO S/N UNI000029 - Motherboard

Page No. B-70 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 61 OVO S/N UNI000029 - RAM


Page No. B-71 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 62 OVO S/N UNI000029 — Compact Flash




Photograph No. 63 OVO S/N UNI000036 – Hard Drive




Photograph No. 64 OpenElect Voting System 1.1 OVO S/N UNI000036

Page No. B-74 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 65 OVO S/N UNI000036 - Motherboard

Page No. B-75 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 66 OVO S/N UNI000036 - RAM

Page No. B-76 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 67 OVO S/N UNI000036 — Compact Flash

Page No. B-77 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 68 OVO S/N UNI000036 - Scanner



Photograph No. 69 OpenElect Voting System 1.1 OVI S/N UNI150049

WYLE LABORATORIES, INC. Huntsville Facility

Page No. B-79 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 70 OVI S/N UNI150049 - Motherboard




Photograph No. 71 OVI S/N UNI150049 – Hard Drive

Page No. B-81 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 72 OVI S/N UNI150049 - RAM



Photograph No. 73 OVI S/N UNI150037 - Motherboard

Page No. B-83 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 74 OpenElect Voting System 1.1 OVI S/N UNI150037

Page No. B-84 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 75 OVI S/N UNI150037 -RAM

Page No. B-85 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 76 OVI S/N UNI150037 – Hard Drive

Page No. B-86 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 77 OpenElect Voting System 1.1 Dell Precision T3500 S/N 3Y20Z011


> WYLE LABORATORIES, INC. Huntsville Facility

Page No. B-87 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 78 Dell E1911F LCD Monitor

Page No. B-88 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 79 OpenElect Voting System 1.1 Koss KPHS Headphones S/N HP-58650-002

Page No. B-89 of 93 Wyle Test Report No. T58650.01-01




Photograph No. 80 OpenElect Voting System 1.1 Koss KPHS Headphones S/N HP-T58650-001

Page No. B-90 of 93 Wyle Test Report No. T58650.01-01

SECURITY PHOTOGRAPHS

Page No. B-91 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 81 Security Setup

Page No. B-91 of 93 Wyle Test Report No. T58650.01-01

TRANSPORTATION VIBRATION PHOTOGRAPHS

Page No. B-92 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 82 OpenElect Voting System OVI S/N UNI150012

Page No. B-93 of 93 Wyle Test Report No. T58650.01-01



Photograph No. 83 OpenElect Voting System OVI S/N UNI150012