

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4227	6-2-78	231	Rpl vent system & gas water heater and furnace
	4612	810	material
	3705	7056	Ext and Int Repair 2 doors 4 window screens
	2492	405	make unit repair, Rplc gulleys adjust oven door
3349	1-9-81	256 ⁵⁵	Amend to 3349 Furn. Wdg Reps. to new lodge
3351	Comp	1930	Make rps. to ext. int. prime new wood.
5081	1-28-82	1169	Replace LP gas lines
3214	1-14-82	182	Make rps. int & ext
3333	7-24-81	5457	Replace 4 gas furnaces & 4 gas hot water heaters
4071	6-12-81	870	Repair broken water lines
3614	6-11-82	7053	Repair Fire damage
3196	3-14-83	9148	Repair Walls, doors, Windows, cabinets.
3177	3-11-83	4459	Replace ceramic floor tile.
3956	1-7-82	962	Repair & paint interior.
3027	10/5/83	977	Rpl Shower unit
3784	3-4-83	6575	Demolish Becholds
3270	11-29-83	1062	Rpr JST EXT
3191		6188	make interior & exterior repairs
3518	2-24-84	2304	Replace Rusted water piping & P traps
3233	11-23-84	312	Repair windows & screens
4026	5-17-85	8810	Rplc burst hot water piping & P-Traps in walls, under bldg & re-insulate water lines
3498	6-21-85	4146	Rpr apts & ext stair ways & decking
3262	3-22-85	158	Rplc damaged handrails & foot boards on walkway & stairs
3593	1-24-86	3861	MAKE STRUCTURAL REPAIRS TO BLDG INT & EXT
3191	2-12-87	6188	MAKE INTERIOR & EXTERIOR REPAIRS
3402	10-3-87	231	REPLACE (2) GLASS WOOD DOOR & KEY A KNOB

BLDG NO

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

BA-144

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
NB4-05132-22	2/17/64		Renov
NB6-108-664-039	FY 66		Renovation of Bldg
HQ7-187-577-190	6/23/67	145	Replace 8 exhaust shutters
A 170-595-240	4/28/67	1,774	Carp, Masonry, plumb, elect + paint Repairs
AAA-23-XX-31383	1/24/69		Replace gas water heater control valves
AAA-23-XX-31703	5/16/69	2,227	Repairs + paint int complete
AA7-23-XX-31712	4/25/69	1,068	Paint ext trim
AAA-23-469723*	4/14/72		repairs + paint interior
AAA-23-4704	4/14/72		repair + paint exterior
4029	3-30-73	350	PM to gas fired equip
0175	12-15-72	346	Install indiv cut off valves
3431	10-5-73	367	PM to gas fired equip
3598	9-29-72	349	PM to gas fired equip
3632	1-11-73	350	"
4005		508	Exposure deteriorated metal shutters
4518	6-28-74	1139	Repair + paint ext
4702	5-4-73	1995	Misc Repairs to Bldg
4744	5-4-73	2029	Repair + paint int
4635	8-13-76	2680	Repair + paint interior
4828	4-25-75	1968	Gen repair + paint
3507	7-12-74	2801	Int repairs structural mech + paint
5212	5-16-75	3677	Install asphalt roof shingles
4652	12/23/75	4348	ext repairs + paint
3816	5-20-77	6407	Repair and paint interior + exterior
4227	12-22-78	6,200	Make necessary repairs and paint
	12-22-78	6,200	Make necessary repairs and paint