BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
5A-21					

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
023-03145-82	5/28/62	E 1406	Subst old pumping units with new
76-	1-7-66	179	Install Pole with 2 flood lights
74-4096	12-14-73	24	Replace fuel filters on fuel separator
3305	10-4-74	524	Replace Water separator filters (sal ea FK
4332	5-16-75	1975	Remove old worn out loading Assemblies
2049	11-16-84	1927	Install O/H Elect Lines to New Security Light

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD
A-25					MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
023-02722-82	7/62	E 162	Paint exterior
72-4785	548-72	685	Replace (1) Window unit
72-4595	2472	9E	Replace water line at boat basin
~~72-4007~~ 71-4008	3-12-71	186	Replace service main switch
3384	8-16-74	1112	Repair, Int & Ext & Paint

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION