



JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
3636	2-13-81	1261	Patch Plaster, Scrape, sand and paint
3718	3-6-81	1286	RPR and paint
3851	4-6-81	<del>28</del> 268	PAINT (2) shower stalls
4013	7-17-81	1211	Remove and install cond. receiver
4325	Comp	399	Cleanup leaves by sweeping parking lots and raking grounds
3050	Comp	5737	Plaster Rprs and paint
3196	Comp	1878	Clean roof, gutters and down spouts
3027	Comp	450	Provide Contract to Clean & inspect Chimneys
3132	Comp	1594	INT. Rprs. and paint
3119	8-6-82	659	Sand Scrape and paint
9020	9-25-85	1130	Inspect, clean, rpr #52 boiler
1197	1-10-86	1396	RENOVATE INTERIOR - (2nd Amend) TO JO #1197 Added Time for Handling doors
E852	Compl	12977	Perform recurring cyclic MAINT
3641	1-31-86	1066	INT PAINT
3668	3-3-86	5671	INT PAINT
3708	3-12-86	1186	ISSUE MATERIAL
1197	3-14-86	630	(3RD Amend TO JO #1197) - Remove & install <del>INT</del> <del>SPRINKLER</del> HEADS
1197	12-18-85	5948	(1ST Amend TO JO #1197) RENOVATE INT OF BLDG
2084	11-10-89	252	PROVIDE CONTRACT TO MAINTAIN INTRUSION ALARM SYST
8282	9-25-92	929	CONST PARTITIONS
1078	7-21-95	409	Install circuit for PLUGGED 99

BLDG NO  
2604

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD

MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED Signed	COST	DESCRIPTION
48-62	7/3/61	2,482.84	Repair and replaster BOQ rooms (C 11/9/61)
99-62	7/3/61	946.63	Paint lounges and hallways (C 11/9/61)
NB4-05508-22	5/20/64	277.78	Fabricate downspouts (C 6/2/64)
3981	9-20-73	465	sand floor & paint
5200	6-30-72	1226	paint as per attached
3501	5-3-74	556	remove dirt from pavement of parking lot
4270	12-20-73	246	vacant paint room 128
4139	11-2-73	145	paint, sand & refinish floor - room 141
4190		116	paint room 206 - compl
4033	10-4-73	144	paint, clean & refinish floor in Rm 139
4639	3-15-73	158	paint & sand floor of room 232
4890	3-30-73	55	sand & refinish room 224
4402	1-12-73	287	paint rooms 114-209 & 240 complete one coat
4297	1-3-73	155	paint & sand floor
4210	11-27-72	159	paint room 143 complete, sand & refinish floor
4148	11-9-72	13	touch-up int paint rm 137
3957	9-12-72	158	paint & sand floor in room 235
2611	12-8-72	430	Refit dresser drawers
5073	5-29-73	144	Int paint & refinish floor
4443	2-1-73	159	paint & sand floor rm 236
4889	3-30-73	325	paint rooms 227 & 244 in BOQ 2604
4867	3-26-73	167	paint rooms 239 & sand floor
4862	3-30-73	371	misc repairs to condensate ret. syst.
4544	11-26-75	158	Paint interior of Rm (119)
4944	3-6-75	133	Paint Rm 239
4940	3-6-75	269	Plaster 90 S.F. Ceiling & paint

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
4087	10-11-74	131	Paint Rm 224
4083	10-11-74	130	Paint Rm 134 & sand floor
4208	10-21-74	845	Int paint & floor work
3781	1-3-75	4082	Repair & paint
4628	1-17-75	197	Paint Rm sand & finish floor
4465	12-20-74	290	Repair plaster & paint
4454	11-7-75	154	Paint Rm 126, 500
3615	7-7-75	222	Paint Rm #146 sand & finish floor
4698	1-6-76	155	Paint Rm 244
4919	2-20-76	239	Paint Rm & refinish floor Room 139
4974	2-27-76	238	Paint Rm 226
5066	4-12-76	515	Paint Rooms 210 + 243
3688	12/15/76	257	Paint Room, clean & finish floor
3540	11/19/76	165	Paint Rm
3496	11/9/76	257	Paint Rm
3343	10/20/76	186	Paint int.
3358	10/20/76	194	Paint int
3485	11/3/76	168	Paint Rm
3466	10-28-77	285	Paint int. of room - refinish floor
3389	10-19-77	288	" " " " " "
3259	10-18-77	191	" " " " (1) coat
3255	10-18-77	191	" " " " " "
3206	10-7-77	185	Paint int. of room light beige
4898	9-16-77	457	" room #244 - Refinish floor & paint room #135
4739	8-10-77	232	and scrape, paint (1) coat - Rm. 225
3867	8-5-77	902	Paint public area in bldg.
4699	8-1-77	187	Paint int. of rooms in PP 2604
4622	7-12-77	281	sand, refinish floors & paint int. of room
4585	7-7-77	328	Plaster, paint, clean, refinish floors in room 213