#21

BLDG NO	INT. PAINT SQ FT	EXT. PAINT SQ FT	ROOF SQ FT	CONDEN. LINES LIN FT	FACILITY HISTORY RECORD MCBCL 11011/3
636					

JOB ORDER NO	DATE COMPLETED signed	COST	DESCRIPTION
4169	10-31-73	853	Rpr well pump
4052	8-9-71	741	" " "
4278	2-11-71		" " "
Cont # 80-2011	5-25-80		Ext Paint
0402	1-6-78	40	Furnish 1 piece of metal found as per sketch attached
2162	7-8-83	860	Install Load center
1299	11-21-86	835	Construct (5) Security storage Cages + Security Divider
2262	11-29-85	1101	Cut 3 windows 3ea/deck, move to outside parking area
1003	10-8-85	2993	Harden Security on MAP room
3543	6-12-86	50	Perform INTERIOR REPAIRS

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION