

BLDG NO
BB-52

INT. PAINT SQ FT

EXT. PAINT SQ FT

ROOF SQ FT

CONDEN. LINES LIN FT

FACILITY HISTORY RECORD
MCBCL 11011/3

JOB ORDER NO	DATE COMPLETED	COST	DESCRIPTION
Contract	Nov. 9, 61	21,880	Electric Power to Bldg
HQ8-CH-ONA-119	4/26/68	1,787	Replace gravel steps, solder joints, paint fascia
AA9-23-XX-30619	10/11/68	1,508	Exterior structural repairs to masonry + windows. Paint (51) windows
1213	9-30-71	0/E	Concr retaining wall in lubrication pit
4523	6-30-70	259	Minor roof repair
3935	12-12-69	492	Paint int
3778	5-15-70	1894	Maint & repair to steam heating system
1108	3-27-73	1365	Install security light in front
3674	12-17-71	298	Remove & re-install floor tiles
1135	8-31-71	0/E	Concr concrete sidewalk near 3 Bldg
3812	10-3-69	479	Replace (1) compressor motor
3188	2-1-74	2631	Repair & paint ext
0184	2-12-74	0/E	Repair & modification
3766	9-18-70	226	Replace water heater
4400	1-2-72	153	Repair roof
3689	11-16-73	1198	Structural repair & paint
3750	12-14-73	6570	Repair & paint int
2623		6946	disconnect all photo equip.
5556	8-20-76	253	Repl door framing & paint
79-2620 Cont'd	1979	1222	Ext paint
1028	8-15-79	1170	Troop training: Construct 3 storage shelves for compressed gas bottles
4128	1-2-79	412	Self Help: do necessary painting as per inspection rpt
5460	11-3-78	2880	Rpl 9 Horizontal unit heaters with new units
2576	3-7-79	10,590	Rem. welder booths. fire pld
4336	5-24-79	11,572	Repl exhaust system

