

**SONGS Unit 2 Steam Generators
Wear Depths Summary**

Steam Generator SG2E88 (Through- Wall Wear)	Anti-Vibration Bar	Tube Support Plate	Tube-to- Tube Wear	Retainer Bar	Foreign Object	Total Indications	Tubes with Indications (out of 9727 total per SG)
≥ 50%	0	0	0	1	0	1	1
35 - 49%	2	0	0	1	0	3	3
20 - 34%	86	0	0	0	2	86	74
10 - 19%	705	108	0	0	0	813	406
< 10%	964	117	0	0	0	1081	600
TOTAL	1757	225	0	2	2	1984	734*

* This value is the number of tubes with wear indications of any depth and at any location. Since many tubes have indications in more than one depth and location, the total number of tubes is less than the total number of indications.

Steam Generator SG2E89 (Through- Wall Wear)	Anti-Vibration Bar	Tube Support Plate	Tube-to- Tube Wear	Retainer Bar	Foreign Object	Total Indications	Tubes with Indications (out of 9727 total per SG)
≥ 50%	0	0	0	1	0	1	1
35 - 49%	0	0	0	1	0	1	1
20 - 34%	78	1	0	3	0	82	67
10 - 19%	1014	85	2	0	0	1101	496
< 10%	1499	53	0	0	0	1552	768
TOTAL	2591	139	2	5	0	2737	861*

* This value is the number of tubes with wear indications of any depth and at any location. Since many tubes have indications in more than one depth and location, the total number of tubes is less than the total number of indications.